

Staley

C.53/ASM1800 3040

Waz

31001

Surveyor:

Wilson

DOI:

23/2/18

Date / Time:

14/2/18

Registered in Merimen:

Pre-assign / CCU / FTE

YP6485P



Insured Vehicle No.:

Claim No.:

J8m008Ru

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A: 9/2/18

Place of Accident:

Is driver the owner? (YES / NO) Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: % Final? Yes / No

MBM7512



INSRS:

WSP:

Tel:

Liability:

RMKS:

JHWCAR



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

26/2/18 MBM7512 - X; YP6485P - X
Banks price incomplete - pending for PA.

26/2/18 WSP informed Wilson - they will engaged independent surveyor.

1/3/18 Email to ARA to submit PMS report.

Typist: Please upload estimate in Views.

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

RECEIVED 07 MAR 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: \$\$ (days) Reduction: %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability: % (Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost: \$\$

Loss of Rental (LOR): \$\$ (days)

Loss of Use (LOU): \$\$ (\$ x days)

Loss of Income (LOI): \$\$ (\$ x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

Medical: \$\$

Disbursement: \$\$ (e.g. Tow/ Independent)

Legal Cost: \$\$

Total: \$\$

Global Sum \$\$:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

PRS

\$100.

FINAL PAYMENT Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: \$\$

Name 1:

Payee 2: (Strike if N.A.) \$\$

Name 2:

Payee 3: (Strike if N.A.) \$\$

Name 3:

Search W:lon
P2S

REF AXA

INCIDENT


Date 23/2/18

MBM 7512

Estimated Cost
CD ☒ PWS/TP RES/OD RES/EVA/INV/MV
To: Insured Vehicle MBM 7512
Ethicarz
56 boyang way #04-04
Insured
Policy No
Claims No
Sum Insured Excess
Deductible
Make of Van

Vehicle Make Isuzu
Color White
No. 424433
Engine
C/Vo
Gear Drive Good ☒ Gear Drive
Steering ☒ Jammed ☐ Locked ☐ Burnt
Brake ☒ Jammed ☐ Locked ☐ Burnt
Mod ☒ 3R- STD A/RH

Policy Condition
Remarks: The van had commenced its repair at the time of inspection



Ball or Market Value
C/O Accident Report Consistent? Yes or No
C/A PR Seen Consistent? Yes or No
Est. Repairs days Res. Yes or No
LIT Sum % 3 val Yes or No
CA / REV / REP / 24 HRS
Date Person Contacted

Tyre Size R 7.00 R16 LT
R 7.00 R16
BS/DUN/EXNOVA/GH FS/LIZA MID/O-TS PR/SUN
TOYO/YOKO ~~TOYO~~ Yokohama (R)
RPR 4 -- RPR 4
LPR 4 -- LPR 4
DOA 23/2/2018
Surveyed on 11-514hr
Des of Damages ☒ ☒ ☐ ☐ ☐ ☐ ☐ ☐
The U/C Chassis/frame Body Structure affected due to collision

28/2/2018 Repair Estimate Given During Survey
28/2/2018. Workshop Informed they have changed their mind - to engage with their own Independent Surveyor.

Date/Time File Pass 1	☐ Prelim. Report	Days Of Report	Resurvey No. of Trip	Survey File
Date/Time File Report	☐ Final Report			
Add Fee	☐	Site Fee	☐	
	☐	Travel Fee	☐	
	☐	Test Fee	☐	
	☐	Equip Fee	☐	
Report Format				
Auto Sum				

F&F
Only
For
Reference.

LKK Auto Consultants henceforth the Repairer of the following:
 Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04
 Loyang Enterprise Building, Email: johnong@ethicarz.sg
 Tel: 63844404, FAX: 63840444

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts once accepted subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

VEHICLE NUM:	MBM7512
MAKE & MODEL:	HINO
MILEAGE:	
TYRE:	
CHASSIS NUM:	XZU423R-HKMMB3

ATTN:		Acknowledged by Repairer		
QTY		Signature:	DESCRIPTION - PARTS	PRICE
1	TAILGATE		(UPPER)	
4	TAILGATE HINGE			
4	TAILGATE LOCK			
1	TAILGATE			
4	TAILGATE HINGE			
1	TAILGATE HINGE BRACKET			
2	TAILGATE LOCK (L+R)			
1	TAILGATE STEP BAR			
2	TAIL LIGHTS			
2	TAIL LIGHTS BRACKET			
1	FLOOR PANEL			
1	NUMBER PLATE BRACKET			
2	NUMBER PLATE LAMP LH+RH			
1	CHASSIS MEMBER			
6	CHASSIS MEMBER U-BOLT			
1	REAR AXLE			
2	PROF SHAFT			
2	PROF SHAFT MOUNTING			
1	ENGINE MOUNTING			
1	FRONT BUMPER			
1	FRONT BUMPER REINFORCEMENT			
2	FRONT BUMPER FOG LAMP LH+RH			
2	HEADLAMP LH+RH			
2	HEADLAMP SEAL LH+RH			
8	HEADLAMP SEAL CLIPS			
1	FRONT GRILLE			
1	FRONT GRILLE LOGO			
1	FRONT PANEL			
2	FRONT SIDE PANEL LH+RH			

1	AIR FILTER HOUSING ASSY OUTER	
1	AIR FILTER HOUSING ASSY INNER	
1	AIR DUCT INTAKE UPPER	
1	AIR DUCT INTAKE LOWER	
1	CABIN LOCK ASSY	
1	CABIN BRACKET	
1	FRONT MUDFLAP LH	
1	CABIN RELEASE BRACKET	
1	WHEEL ARCH LH	
QTY	DESCRIPTION - SPECIAL NETT	PRICE
1	TAILGATE LOWER STICKER (70/80 KMJ)	50
1	TAILGATE LOWER STICKER (REFLECTOR)	100
1	REAR CARPLATE	80
2	FRONT CARPLATE	80
2	REAR CARPLATE BRACKET	200
1	REVERSE BUZZER SIREN	400
1	REAR STEPBAR	1500
QTY	DESCRIPTION - LABOUR	PRICE
1	TO RNR ACCIDENT AFFECTED AREA	3000
1	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	2500
1	TO RUST PROOF ACCIDENT AFFECTED AREA	300
1	TO RNR ENGINE ASSY	2500
1	TO RNR UNDERCARRIAGE ASSY	2500
1	TO RNR PROF SHAFT	1200
1	TO RNR RADIATOR AIR CON ASSY AND REFILL GAS	200
1	TO CHECK CHASSIS ALIGNMENT	1500
1	TO RNR REAR CABIN	6000
1	TO CHECK WIRING AND HEADLAMP FOCUS FUNCTION	150
1	TO CHECK WIRING AND TAILLAMP FUNCTION	150
1	TO CHECK WIRING AND REVERSE SIREN FUNCTION	150
1	TO CHECK WATER SEEPAGE	150
1	TO RNR REAR CABIN COMPARTMENT	1200
1	TO RNR TAILGATE MECHINISM	120
<i>Without Prejudice.</i>		
<i>Wilson, LKK</i>		
<i>23/2/2018</i>		
<i>* To Dovent Back For Consistency</i>		


**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT			
AXA INSURANCE PTE LTD		Ref: CS3/ASM18003040/Wa3s2	
8 SHENTON WAY #24-01		Date: 12-03-2018	
AXA TOWERSINGAPORE 068811			
ATTN: STACEY		Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	YP 6485P	Veh. Inspected	MBM 7512
Policy No.	P1993413	Coverage (\$)	0.00
Claim No.	S8M006RU	Excess (\$)	0.00
Assign From		Assign Date	14/02/2018
2. Vehicle Particulars & Condition			
Make & Model	ISUZU	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	WHITE
Odometer	424433 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	7.00 R16 LT	BRIDGESTONE	4 mm
L/H Front Tyre	7.00 R16 LT	BRIDGESTONE	4 mm
R/H Rear Tyre	7.00 R16	YOKOHAMA	4 mm
L/H Rear Tyre	7.00 R16	YOKOHAMA	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.			
5. General Information			
Accident Date	09/02/2018	Inspect Date / Time	23/02/2018 (11:51 AM)
Survey held at	ETHICARZ PTE LTD 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/ASM18003040/Wa3s2

Inspected By



WILSON TEO CHENG MING

Automotive Assessor



K.K. LAU CPT (RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.



Service Request Details

Claim
S8M008RU

Reference
CS3/ASM18003040/Wa3

Loss Date
February 9, 2018

Request Date
February 14, 2018

Due Date
February 14, 2019

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pending verification - Direct Settlement

Actions

Next Step
Finish the work

Complete Work

More

Vehicle Information

Incident Vehicle Registration #
MBM7512



Service Request Details

Claim
S8M008RU

Reference
CS3/ASM18003040/Wa3

Loss Date
February 9, 2018

Request Date
February 14, 2018

Due Date
February 14, 2019

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pending verification - Direct Settlement

Actions

Next Step
Finish the work

Complete Work

More

Vehicle Information

Incident Vehicle Registration #
MBM7512

LKK AUTO CONSULTANTS PTE LTD (TP)

March 7, 2018

SJT1163H TP GIA RPT.PDF

Reports & Statement

GIA Report

TEO Kitty

February 14, 2018

YP6485P INSD GIA RPT.PDF

Reports & Statement

GIA Report

TEO Kitty

February 14, 2018

EMAIL RECEIVED FROM WORKSHOP
INCLUDING POLICE REPORT PRI FOR
MBM7512.msg

Letters and Correspondence

Workshop

NIKAM Santosh Pandurang

February 14, 2018



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)[General Details](#)

Involving

TPV LORRY (MBM7512)

Date of Loss

February 9, 2018

Time of Loss

16.40

Loss Description

YP6485P (INSD) > MBM7512 > SJT1163H

Comment

Workshop Details

Total Rebate Amount

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Target Date of Completion *

Days of work completion *



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)[Vehicle & Driver Details](#)

Vehicle Registration#

MBM7512

Registration State

Mileage

Purchase Date

mm/dd/yyyy

Registration Date *

mm/dd/yyyy

Age of Vehicle

18

Manufacturing Year

2016

Make

MITSUBISHI

Market Value

0

Driver Details

Driver Name

UNKNOWN

Date of Birth

Age

0

Occupation

Unknown

Education Qualification

Other

Primary ▼

Gender

Unknown

Female ▼

Marital status

Unknown

Single ▼

Identification #



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary
- Detailed Assessment

Inspection Date *

mm/dd/yyyy

Total Loss

Towing Charges

Voluntary Excess

Compulsory Excess

Young/Inexperienced/Unnamed Driver Excess

Other Excess

Condition of Vehicle at time of survey

General condition

Excellent

Steering (Serviceable)

