

22/03/2002

ASS. REC. BY:

REF: CS/FCI18003059/Atd302

Special Instruction:

Surveyor:

Adnan

ASSIGNMENT (Office)

From (Person):

Lurene Jaw

of

FCI

Date/Time:

14/00/18 @

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 9381Y

Insured:

SHC 7080L

at Workshop m/s

Progressive Automotive

Tel:

67415336

of

Blk 3022A Ubi Rd 1 # 01-15/46

Policy No:

Claim No:

D18001322 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/02/2018

CA / REV / REP. / REV 24 HRS

'DS'

H.O.D. Endorsement:

Date/Time:

1:50pm @ 14/2/18

Person Contacted:

Peiwen

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

called

wks

closed

for

CNY

SJS 9381Y-X

SHC 7080L - CS/FCI18003059/M14/3m2

D.O.A: 23/24/2017

Confirm \$1276.68. 3days.

(Red: 2252.12'63%)

FBI

Report Date 27/2/18 File No. SJS9381Y Date of Loss 2009 Sept

Estimated Cost

02 TP WBS TP RES CO RES LEVA INVT INV

To insure: SJS 9381Y
at: Progressive Automotive
Policy No: Slk 3022 A Ubr Rd 1 # 01-45/46

Insured

Policy No

Damage

Sum Insured


Excess

Claims Record

Name of Ins

Policy Condition

Remark: The veh had commenced its repair at the time of inspection



Est. or Market Value

DAC Accident Form Consistent? Yes or No

GA TP Spec Consistent? Yes or No

Est. Repairs days Fee Yes or No

Lim Sum to \$ Yes Yes or No

CA REP REP 24 HRS Wp

Date Person Contacted

Vehicle In Out

Make Toyota Camry Year 1998

Color Silver VIN 77177

Engine No MRO53BK4107048090

Make

Model

Body Type 4 Dr Sedan

Steering Left Driven Left

Brake Hyd Driven Left

Use SP STD

Tire Size 215/60R16

BS CON EXC NA GS FS LZA MC CHTS FF SUM

TOYO YOKO

Front

Rear

REB

REB

LEB

LEB

DCA

DCA

Surveyed by

Des or Damages TP CS MS LO Repaired

The UO Chassis frame Body Structure affected due to loss

Date Time Action Instruction

TP 1st Cap.

RECEIVED

Date Time File Pass

28/2 Typist

Date Time File Pass



Prelim. Report

Final Report

Days Of Repair 3

Resurvey No of Trk 2

Time Rep

130

Time Rep

60

Time Rep

50/150

Time Rep

22

Add Fee

Site Fee

Test Fee

Test Fee

Test Fee

Record Form

Record Form

TP

1276.68

Estimated Cost of Loss

202



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18003059/Atd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 15-02-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7080L	Veh. Inspected	SJS 9381Y
Policy No.		Coverage (\$)	0.00
Claim No.	D18001322MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	15/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	09/02/2018	Inspection Date	
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/02/2018 17:19
Date Of Accident	09/02/2018 23:05
Exact Location Of Accident	PIE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS9381Y
Insured/Policyholder	
Name Of Registered Owner	WONG SING LUAN
NRIC No	S2721836I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90285727
Alternative Phone No	OTHERS-81388326

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100390057
Cover Note Number	

Driver

Name of Driver	YAP CHEE MING
NRIC No	S2738746B
Date Of Birth	26/06/1964
Occupation	INDOOR
Date Of Driving Pass	06/08/2003
Driving Experience	14 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81388326
Fax Number	
Contact Number	
EMail Address	ANDREW.YAP@STTELEMEDIAGDC.COM

Address	BLK 714 BEDOK RES RD #11-3030
Postcode	470714
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : YAP CHIA SHEN
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE AUTOMOTIVE PTE LTD 67415336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC7080L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	ONG ENG KOON
NRIC/Passport Number	
Contact Number	93870287
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHC5321C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that entry on this report will for a while be made available to other interested parties.
7. By the submission of this report to the Insurers, you hereby consent to the archiving of this report and its copying for the purpose of carrying out its intended use.
8. **Consent under the Personal Data Protection Act (PDPA)**

I, the undersigned, acknowledge, agree and consent that:

- a) The information, work developed and/or received by the Association of Singapore (GIA) Insurers is limited to that which is necessary and relevant to the accident and that the information is not to be used for any other purpose, including but not limited to, marketing, research, or other purposes. The information is to be used for the purpose of the accident and for the purpose of the accident only.
- b) If the information is used for any other purpose, it shall be effective and valid to the extent that the information is used for the purpose of the accident and for the purpose of the accident only.

I hereby consent to the information being used for the purpose of the accident and for the purpose of the accident only.

I hereby consent to the information being used for the purpose of the accident and for the purpose of the accident only.

I hereby consent to the information being used for the purpose of the accident and for the purpose of the accident only.

I hereby consent to the information being used for the purpose of the accident and for the purpose of the accident only.

I hereby consent to the information being used for the purpose of the accident and for the purpose of the accident only.

- a) The information is to be used for the purpose of the accident and for the purpose of the accident only.
- b) The information is to be used for the purpose of the accident and for the purpose of the accident only.

I hereby consent to the information being used for the purpose of the accident and for the purpose of the accident only.

I hereby consent to the information being used for the purpose of the accident and for the purpose of the accident only.

I hereby consent to the information being used for the purpose of the accident and for the purpose of the accident only.

I hereby consent to the information being used for the purpose of the accident and for the purpose of the accident only.

I hereby consent to the information being used for the purpose of the accident and for the purpose of the accident only.

Policyholder's Signature
Date & Time

Driver's Signature

If driver is not the policyholder
Date & Time

FEB 12 2013
1510/115

Reporting Centre Personnel's Signature
Name
Date & Time

Sketch Plan #2

SKETCH PLAN

Towards KUNDA FLYOVER					Vehicle No
					A - SJS9381Y
					B - SHC7080L
					C - SHC5331C
					Legend
					Vehicle A
					Bike A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving vehicle # SJS9381Y on PIE (CHANGI MISCET) at around 11:08 pm on Feb 10, 2018. As I was approaching the Kunda Flyover a few vehicles travelling in front of me stopped in Lane 1. I quickly attempted to stop and managed to brake and come to a stop. A car (SHC7080L) could not stop in time hit my car followed by another almost immediately. We all (from the affected vehicles) came down to check. I exchange particulars with the driver of the car (SHC7080L). I left the scene and went to lodge a police report at Bedok police station.

DECLARATION

I/We declare the foregoing particulars are true in every respect. Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 165 12 Dec 18

1510115

Reporting Centre Personnel's Signature

Name:

NRIC/PIN No.:

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road I #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
 GST:201006949C RCB NO:201006949C

M/S : WONG SING LUAN
 714 BEDOK RESERVOIR ROAD
 #11-3030 SINGAPORE 470714

Estimate No: EST1503297
 Date: 12 Feb 2018
 Policy No: 2100390057
 Veh Reg No: SJS9381Y
 Make/Model: TOYOTA CAMRY 2.0
 AUTO ABS AIRBAG
 Chassis No: MR053BK4107048090
 Engine No: 1AZE144693
 Reg. Date: 16/09/2009

ATTN: FIRST CAPITAL

Your Ref No: TP 0218-4956
 Claim Type: Third Party
 Accident Date: 09/02/2018
 TP Veh Reg No: SHC 7080 L

Estimate Repair Cost to Vehicle No :SJS9381Y

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BOOT TOYOTA LOGO	79.8000	1 PC	79.80 ✓	
2 REAR BOOT CAMRY WORDING	68.4000	1 PCS	68.40 ✓	
3 REAR BOOT 2.0 WORDING	71.6000	1 PCS	71.60 ✓	
4 REAR BOOT OUTER CHROME MOULDING - CENTRE	310.5000	1 PC	310.50 ✓	
5 REAR PANEL	480.6000	1 PC	480.60 ✓	
6 REAR PANEL TOP GARNISH	320.4000	1 PCS	320.40 ✓	
7 REAR BUMPER	418.7000	1 PC	418.70 ✓	
8 REAR BUMPER CLIPS	9.8000	10 PC	98.00 ✓	
9 REAR BUMPER SIDE HOLDER - LH	85.4000	1 PCS	85.40 ✓	
10 REAR BUMPER SIDE HOLDER - RH	85.4000	1 PCS	85.40 ✓	
11 REAR BUMPER CENTRE BRACKET - LH	69.8000	1 PCS	69.80 ✓	
12 REAR BUMPER CENTRE BRACKET - RH	69.8000	1 PCS	69.80 ✓	
13 REAR BUMPER REINFORCEMENT	280.4000	1 PC	280.40 ✓	
14 REAR BUMPER REFLECTORS - LH	79.8000	1 PC	79.80 ✓	
15 REAR BUMPER REFLECTORS - RH	79.8000	1 PC	79.80 ✓	
			2,598.40	
Reverse Sensor Snapped 200 (SN) ✓		Less 25%	649.60	1,948.80
Labour				
16 TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	600.0000	1 JOB	600.00 ✓	
17 TO RESPRAY PAINT ON ACCIDENT PORTIONS	750.0000	1 JOB	750.00 ✓	
18 TO CHECK WIRING	20.0000	1 JOB	20.00 ✓	
19 TO REMOVE, REFIX REAR GARNISH & RELATED PARTS	100.0000	1 JOB	100.00 ✓	
20 TO TRANSFER REAR BUMPER SENSOR	50.0000	1 JOB	50.00 ✓	
21 TO TUFF-KOTE	60.0000	1 JOB	60.00 ✓	
			1,580.00	1,580.00

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : WONG SING LUAN
714 BEDOK RESERVOIR ROAD
#11-3030 SINGAPORE 470714

ATTN: FIRST CAPITAL

Your Ref No: TP 0218-4956
Claim Type: Third Party
Accident Date: 09/02/2018
TP Veh Reg No: SHC 7080 L

Estimate No: EST1503297
Date: 12 Feb 2018
Policy No: 2100390057
Veh Reg No: SJS9381Y
Make/Model: TOYOTA CAMRY 2.0
AUTO ABS AIRBAG
Chassis No: MR053BK4107048090
Engine No: 1AZE144693
Reg. Date: 16/09/2009

Estimate Repair Cost to Vehicle No :SJS9381Y

Description	U/Price	Quantity	Price S\$	Amount S\$
			Total	S\$ 3,528.80
			Add GST @ 7%	247.02
			Total Amount Payable	S\$ 3,775.82

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SEVEN HUNDRED SEVENTY FIVE AND CENTS EIGHTY TWO ONLY

Adrian Ly
27/02/18.
P/P 0300p.

For PROGRESSIVE AUTOMOTIVE PTE LTD

AUTHORISED SIGNATURE

3775.80

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : WONG SING LUAN
714 BEDOK RESERVOIR ROAD
#11-3030 SINGAPORE 470714

Estimate No: EST1503297
Date: 12 Feb 2018
Policy No: 2100390057
Veh Reg No: SJS9381Y
Make/Model: TOYOTA CAMRY 2.0
AUTO ABS AIRBAG
Chassis No: MR053BK4107048090
Engine No: 1AZE144693
Reg. Date: 16/09/2009

ATTN: FIRST CAPITAL

Your Ref No: TP 0218-4956
Claim Type: Third Party
Accident Date: 09/02/2018
TP Veh Reg No: SHC 7080 L

Estimate Repair Cost to Vehicle No :SJS9381Y

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BOOT TOYOTA LOGO	79.8000	1 PC	79.80	✓
2 REAR BOOT CAMRY WORDING	68.4000	1 PCS	68.40	✓
3 REAR BOOT 2.0 WORDING	71.6000	1 PCS	71.60	✓
4 REAR BOOT OUTER CHROME MOULDING - CENTRE	310.5000	1 PC	310.50	✓
5 REAR PANEL	180.6000	1 PC	180.60	✓
6 REAR PANEL TOP GARNISH	320.4000	1 PCS	320.40	✓
7 REAR BUMPER	418.7000	1 PC	418.70	✓ ✓
8 REAR BUMPER CLIPS	9.8000	10 PC	98.00	20 ✓
9 REAR BUMPER SIDE HOLDER - LH	85.4000	1 PCS	85.40	✓
10 REAR BUMPER SIDE HOLDER - RH	85.4000	1 PCS	85.40	✓
11 REAR BUMPER CENTRE BRACKET - LH	69.8000	1 PCS	69.80	✓
12 REAR BUMPER CENTRE BRACKET - RH	69.8000	1 PCS	69.80	✓
13 REAR BUMPER REINFORCEMENT	280.4000	1 PC	280.40	✓ ✓
14 REAR BUMPER REFLECTORS - LH	79.8000	1 PC	79.80	✓ ✓
15 REAR BUMPER REFLECTORS - RH	79.8000	1 PC	79.80	✓ ✓
Reverse Sensor snapped	250 2w (SN) ✓	Less 25%	2,598.40 649.60	808.90 1,948.80
Labour				
16 TO KNOCK OUT DENTS, CUT/WELD REAR PANEL REMOVE REPLACE ACCIDENT PARTS	600.0000	1 JOB	600.00	200 ✓
17 TO RESPRAY PAINT ON ACCIDENT PORTIONS	750.0000	1 JOB	750.00	200 ✓
18 TO CHECK WIRING	20.0000	1 JOB	20.00	✓ ✓
19 TO REMOVE, REFIN REAR GARNISH & RELATED PARTS	100.0000	1 JOB	100.00	✓ ✓
20 TO TRANSFER REAR BUMPER SENSOR	50.0000	1 JOB	50.00	✓ ✓
21 TO TUFF NOTE	60.0000	1 JOB	60.00	✓
				1,580.00 1,580.00 470
				SN 200.00
				Parts 606.68
				LAB. 470.00
				1,276.68



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18003059/Atd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7080L	Veh. Inspected	SJS 9381Y	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001322MFSH	Excess (\$)	0.00	
Assign From	LURENE JAW	Assign Date	14/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053BK4107048090	Colour	SILVER	
Odometer	77177	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	MICHELIN	6 mm	
L/H Front Tyre	215/60 R16	MICHELIN	6 mm	
R/H Rear Tyre	215/60 R16	MICHELIN	6 mm	
L/H Rear Tyre	215/60 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/02/2018	Inspection Date	27/02/2018	
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 9381Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT TOYOTA LOGO	NOT NECESSARY	79.80	-
1	REAR BOOT CAMRY WORDING	NOT NECESSARY	68.40	-
1	REAR BOOT 2.0 WORDING	NOT NECESSARY	71.60	-
1	REAR BOOT OUTER CHROME MOULDING - CENTRE	NOT NECESSARY	310.50	-
1	REAR PANEL	TO REPAIR SEE LABOUR	480.60	-
1	REAR PANEL TOP GARNISH	NOT NECESSARY	320.40	-
1	REAR BUMPER	DEFORMED	418.70	418.70
10	REAR BUMPER CLIPS @\$9.80	NECESSARY	98.00	30.00
1	REAR BUMPER SIDE HOLDER - LH	NOT NECESSARY	85.40	-
1	REAR BUMPER SIDE HOLDER - RH	NOT NECESSARY	85.40	-
1	REAR BUMPER CENTRE BRACKET - LH	NOT NECESSARY	69.80	-
1	REAR BUMPER CENTRE BRACKET - RH	NOT NECESSARY	69.80	-
1	REAR BUMPER REINFORCEMENT	BENT	280.40	280.40
1	REAR BUMPER REFLECTORS - LH	CUT	79.80	79.80
1	REAR BUMPER REFLECTORS - RH	NOT NECESSARY	79.80	-
	LESS 25% DISCOUNT		-649.60	-202.22
			1,948.80	606.68
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	SNAPPED	200.00	200.00
			200.00	200.00
	<u>LABOUR</u>			
	TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF REAR PANEL.		600.00	200.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		750.00	200.00
	TO CHECK WIRING.		20.00	20.00
	TO REMOVE, REFIX REAR GARNISH & RELATED PARTS.	NOT NECESSARY	100.00	-
	TO TRANSFER REAR BUMPER SENSOR.		50.00	50.00
	TO TUFF - KOTE.	NOT NECESSARY	60.00	-
			1,580.00	470.00

Report Ref No. CS/FCI18003059/Atd3e2



GRAND TOTAL		3,728.80	1,276.68
RECOMMENDED COST OF REPAIRS			1,276.68

Report Ref No. CS/FCI18003059/Atd3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.