

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)Survey & repair
12.03 @ 9.00amAll insured GIM
Filed as claiming TP
AG is trying to contact
their insured to discuss
28/02/18

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

17 FEB 2018

Estimate No.	: b1 45934	Page No. : 1 of 2
Date Estimated	: 14/02/2018	
Prepared By	: Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Loh Chye Ling (Luo CaiLing) 119 Pemimpin Place Singapore 576116	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJM8771T	P836666	27/11/2015	216d G TOURER	0

DESCRIPTIONVALUE

To replace rear right door, attachment, repair front right door, rear right fender and rear bumper.

2975 4,250.00

Painting front right door, rear right door, rear right fender and rear bumper.

3323 3,693.00

To check electrical wiring systems for proper function

150 177.00

To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).

451 531.00

To supply and install rear left or right window glass solar film.

✓ 425.00

To carry out body cavity preservation (Per panel).

100 118.00

Sundries.

? 150.00

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time _____ Excess S\$ _____

Surveyor's Name _____ Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____ Total Labour 1:

No. of Working Days Recommend _____

9,344.00

DESCRIPTIONQTY PRICVALUE

ALLOY RIM 7.5X17 DOUBLE SPK 385

1 759.55

out 759.55

RR RH DOOR

1 1,103.65

ht 1,103.65

RH FIXED DOOR WINDOW

1 127.30

ner 127.30

REAR DOOR EDGE PROTECTION

1 153.30

ne 153.30

Total Parts : 2,143.80

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 45934**
Date Estimated : **14/02/2018**
Prepared By : **Inthiran A/L Thurasamy**

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJM8771T	P836666	27/11/2015	216d G TOURER	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date/Time 13/3/18 Excess S\$ _____

Surveyor's Name Taufik Sign [Signature]

Surveyor's Tel 97498749 Authorised Yes / No _____

Appraised by - WP Time _____

OTO BY SURVEYOR ☒ / No PML Yes / No _____

Surveyor's E-mail taufik@lkkauto.com

No of Working Days Recommended 7 days

LKK Auto Consultants hence notify**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Labour 1	:	9,344.00
Parts	:	2,143.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	804.15
Grand Total	:	12,291.95

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **