

1980101

INS. CASE OWNER

Jaclyn

CC3 / AIG18003077

IT/Kes

LKK

IDAC

Surveyor:

TAUFIKH

DOI:

19/02/18

Date / Time:

14/02/18

Registered in Merimen:

15/02/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKT 402M

Claim No.:

76047219759

Name of Insured:

DAMLER FLEET MANAGEMENT
SINGAPORE PTE. LTD

Policy No.:

999994749

Insured Tel No.:

HP:

Make / Model:

MERCEDES-BENZ A180 (217)

Excess Sec II :\$S

D.O.A.:

12/02/18

Place of Accident:

ALONG PIE (TURNS) AFTER PATA

Is driver the owner?

(YES / NO)

Nature of Accident:

LEGAR EXIT

If NO, Driver Name / Age: FONG JIA WEI MGRVYN

OI GIA REPORT: YES / NO, TP GIA REPORT: YES / NO

Driver Tel No.: 9220 3199

(VA) YES / NO

Insured Liability:

% Final ? Yes / No

SKK 2464T



INSRS:

WSP: WSP Group

Tel: Alexandra

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time:

01/03/18 (Zain)

01/03/2018 @
4:17pm

SKK 2464T - X ; SKT 402M - X
 spoke to OIC (Mr Mervyn) - confirmed accident
 at 1400 and OIC rear-ended TP. OIC sent an
 additional photos via email. Informed about
 claim, OIC of WSP rules and agreed to settle.
 Send letter to OIC.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OIC:

After call ltr to OIC:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OIC:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time: 23-3-18

Confirm with: CHAPMAN

Confirm by: MTH

Repair Cost:

P/P \$54,935.55

3 days Reduction:

44 %

Email

Call

FINAL SETTLEMENT

Date/Time: 17/4/18

Confirm with: CHAPMAN

Email

Call

Final Liability:

\$100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

OIC rear-ended TP.

Repair Cost:

\$55,378.38

Loss of Rental (LOR):

\$5 -

(days)

Loss of Use (LOU):

\$5 -

(\$50 x 3 days)

Loss of Income (LOI):

\$5 -

(\$5 x 3 days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LO ☐ (Tick only one)

GLA/LTA Search:

\$57.95

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tuw/ Independent)

Legal Cost:

\$5 -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$320 + \$20

Total:

\$55,526.03

Global Sum \$S:

FINAL PAYMENT

Date/Time: 17/4/18

Confirm with: CHAPMAN

Email

Call

Payee 1:

\$55,286.03

Name 1: YOUNGKHEEN CENTRE SINGAPORE

Payee 2: (Strike if N.A.)

\$5 240.00

Name 2: TAN CHIA KIAN VINCENT

Payee 3: (Strike if N.A.)

\$5

Name 3:

Summary

Tanphm

REF: ALG

ASSIGNMENT

From: _____ Date: 19-02-2018

Estimated Cost: _____

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKK 2464T

at Workshop m/s Volkswagen

of 247 Alexandra Road

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

2:30pm



Est. or Market Value: _____

IDAC Accident Report: _____ Consistent? Yes or No

GIA / PR. Seen: _____ Consistent? Yes or No

Est. Repairs: 3 days Res: Yes or No

Lump Sum: — % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKK 2464T Yr Regn: 243 June

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Passat cc 1798

Colour: Black A/C Insured / Std / NI / NA

Sp. Reading: 37540 T. Radio: Insured / Std / NI / NA

Eng. No: _____

C/N: WWZEZ3CEPP040705

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size: F: 235 / 45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR SUMI /

TOYO / YOKO or

Front

R.Bal: 6 mm

L.Bal: 6 mm

D.O.A: _____

Survey held at: VW Alexandra

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

(P/p: 74933-25 / Red: 33830.98 / 44%)

Date/Time: File Pass to:

☐ : Prel. Report
☐ : Final Report

Date/Time: File Return to:

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp \$

☐ : Interview \$

☐ : Tech. Insp \$

☐ : Weekend \$

☐ : S-RS \$

☐ : Photo

☐ : Other

Report Format: _____

Lump Sum / I.B.I: \$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18003077/T1ks3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 15-02-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKT 402M	Veh. Inspected	SKK 2464T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	15/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	12/02/2018	Inspection Date	19/02/2018
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Service Order Confirmation

SERVICE ORDER NO: 16IP0588
 CUSTOMER NO.: CV022833
 CUSTOMER NAME: TAN CHOK KWANG
 TELEPHONE NO.:
 ADDRESS: 36 CHAY YAN STREET #11-05
 Singapore

VEH No.: SKK2464T

Order Date: 01/03/18
 Reg Date: 21/06/13 KML 40.061
 VIN NO.: WVVZZZ3CZDP040765 ENGINE NO:
 MODEL: Passat B7 1.8 TSI (DSG7)+PEL MODEL NO.: 3624H7

SA: Cheong Peatlyn

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P DIAG	PROGRAMMING & CALIBRATION- NETT	1	TU	480	480
2	B&P MECH	ELECT WIRING & MECH COMPONENT CHECK NETT	1	TU	280	280
3	B&P ALEX LABOUR	LABOUR	1	UNIT	840	840
4	B&P ALEX PAINT	SPRAY PAINT	1	UNIT	600	600
5	B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	ST	80	80
6	EXT00037	Tow SVC- Quality Recovery Services	1	UNIT	0	0
7	EXT00037	Tow SVC- Quality Recovery Services	1	UNIT	0	0
Item						
8	3AE807417R GRU	REAR BUMPER	1	PCS	1,751.89	1,751.89
9	3AE807521A 9B9	SPOILER	1	PCS	295.04	295.04
10	3AE807853	REAR CENTER STRIP	1	PCS	58.42	58.42
11	3AE807460 2ZZ	MOLDING RHS	1	PCS	141.72	141.72
12	3AE298490	SENSOR BRACKET	1	PCS	49.47	49.47
13	1T0919130C 9B9	PARKING SENSOR O RING	4	PCS	0.65	2.60
14	D 822150A1	BONDAGENT	1	PCS	64.27	64.27
15	D 180KJ2A1	2KADHESIVE	1	PCS	89.84	89.84

Remarks: AIG DIRECT SETTLEMENT

DOA 12.2.2018

SURVEYOR LXX

TP VEHICLE SKT403M

Service Order Confirmation

SERVICE ORDER NO: 18P0588

CUSTOMER NO.: CV022833

CUSTOMER NAME: TAN CHOK KWANG

TELEPHONE NO.:

ADDRESS: 38 CHAY YAN STREET #11-05
Singapore

VEH No.: SKK2464T

Order Date: 01/03/18

Reg Date: 21/06/13 KM: 40,061

VIN NO.: WVGZZZ3CZDP040765

ENGINE NO:

SA: Cheong Peatlyn

MODEL: Passat B7 1.8 TSI (DSG7)+PEL MODEL NO.: 3604H7

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
-----	-------------	-----	-----	------------	--------	--------

TOTAL	4,933.25
GST AMOUNT	345.30
TOTAL AMOUNT	5,278.58

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

PDI TUAS

PDI TUAS

TAN CHOK KWANG
VINCENT
38 CHAY YAN STREET
#11-05
Singapore, 169907
Singapore

Tanfu 9749544
-wp-

19/2/18 @ 1430.

3 days

Sur @ lkhauto.com

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV022833
Quote No. SER/QUO/1800271
QuoteDate 13/02/18
Salesperson Xiao Li Na Helena
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Passat B7 1.8 TSI (DSG7)+PEL	31,002	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SKK2464T	WVWZZZ3CZDP040765	21/06/13	Xiao Li Na Helena
Engine Code	Labor Type	Engine No.	Model Code
	1P	CDA 399564	3624H7

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	3	UNIT		840 2,520.00
P B&P ALEX PAINT	SPRAY PAINT	3	UNIT		800 2,400.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	pcs	- Change plate	80.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un	don't need	480.00
P B&P MECH	ELECT WIRING & MECH COMPO Nett	1	Time Un	Bump.	280.00
	Sum Labor				5,760.00
P 1T0919133C 9B9	PARKING SENSOR O RING	4	Pieces		2.60
P 3AA807305	BUMPER REINFORCEMENT	1	Pieces		335.54
P 3AE807393A	BUMPER BRACKET LHS Use Predecessor 3AE807393	1	Pieces		36.86
P 3AE807394A	BUMPER BRACKET RHS Use Predecessor 3AE807394	1	Pieces		36.86
P 3AE807417R GRU	REAR BUMPER	1	Pieces		1,751.89
P 3AE807459 2ZZ	MOLDING LHS	1	Pieces		141.72
P 3AE807460 2ZZ	MOLDING RHS	1	Pieces		141.72
P 3AE807521A 9B9	SPOILER	1	Pieces		295.04
P 3AE807863	REAR CENTER STRIP	1	Pieces		58.42
P 3AE998490	SENSOR BRACKET	1	Pieces		49.47
P D 180KU2A1	2KADHESIVE	1	Pieces		89.84
P D 822150A1	BONDAGENT	1	Pieces		64.27
	Sum carried forward				8,764.23

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

TAN CHOK KWANG
VINCENT
38 CHAY YAN STREET
#11-05
Singapore, 169907
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV022833
Quote No. SER/QUO/1800271
QuoteDate 13/02/18
Salesperson Xiao Li Na Helena
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Passat B7 1.8 TSI (DSG7)+PEL	31,002	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SKK2464T	WVWZZZ3CZDP040765	21/06/13	Xiao Li Na Helena
Engine Code	Labor Type	Engine No.	Model Code
	1P	CDA 399564	3624H7
Continued			8,764.23
Sum Item			3,004.23
Sum Labor			5,760.00
Sum Item			3,004.23
Total SGD			8,764.23
7% GST			613.50
Total SGD Incl. GST			9,377.73

Explanations

P = Proportionately Charged

Payment Terms No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Payments to: - BBN: - Acc.-No.:

PAYMENT ADVICE

Your ref: AIG Insurance Vehicle No. CC3 / AIG / 2003077 / T1K23

Claimant's Vehicle No. SKK2464T

Accident on 12-2-18 involving vehicle/s No. _____

_____ along/at _____

BREAKDOWN OF PAYMENT/S

1. Repair Cost S\$ 5278.58 Payable to Volkswagen Centre Singapore

2. Loss-of-Use/
Car Rental S\$ 300 Payable to TAN CHOK KWANG VINCENT

3. Medical and
Search Fees S\$ 7.45 Payable to Volkswagen Centre Singapore

Remarks : _____

Service Adviser _____

Contact No./H/P. _____



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3/AIG18003077/T1ks3

07 MARCH 2018

DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531
ATTN: HR / MANAGEMENT

Dear Sir/Madam,

ACCIDENT INVOLVING SKT 402M AND SKK 2464T ON 12.02.2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Zaini
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: Zaini@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Provide always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect or preclude me from making a further claim for general and special damages for my personal injuries sustained in the accident.

AUTHORIZATION TO ACT
(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

I, TAN CHOK KWANG ("the third party claimant")
of 38 CHAY YAN STREET #11-05 S 169907 (address),
owner of SKK24647 (vehicle no.) hereby authorize
Volkswagen Centre Singapore
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SKK24647 that was
damaged pursuant to the accident which occurred on 12/02/18 (date) along
PIE TOWARDS TUAH NEAR CTE EXIT (location)
involving vehicle no/s SKT402M ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 19 day of FEB (month) 20 18 (year)


Signed by "the third party claimant"


Signed by "the workshop"

Provide always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect or preclude me from making a further claim for general and special damages for my personal injuries sustained in the same accident

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I, VolksWAGEN CENTRE SINGAPORE ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK AUTO CONSULTANCY PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 5,318.58 (repair costs), S\$ 340.00 (loss of use/rental) S\$ 1.45 (search fees) for vehicle no. SKK 2464T that was damaged pursuant to the accident which occurred on 12.02.18 (date) along PIE TOWARDS TMAIS NEAR GTE EXIT (location) involving vehicle no/s SKT 400M.

This is pursuant to the inspection conducted on 19.03.2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TAN CHOK KHYANG VINCENT ("third party claimant") of vehicle no. SKK 2464T to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKK 2464T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 17 day of 04 (month) 20 18



MTH

Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

Volkswagen Centre Singapore



Service Tax Invoice No. SV18P10870

Br Reg. No. 531C3069E
GST No. M20098505-2

SERVICE ORDER NO.: 18IP0588
SERVICE CUSTOMER NO.: F01089R
SERVICE CUSTOMER NAME: AIG ASIA PACIFIC INSURANCE P/L
TELEPHONE NO.:
ADDRESS: 78 Shelton Way
#07-16 AIG Building
Singapore
Post Code: 079120

VEH NO.: SKK2464T
DATE: 09/03/18 Pickup:
VIN NO.: WVGZZZ3CZ0P040765 KM: 40,061
GEARBOX CODE: PMJ Engine No.:
MODEL: Passat 07 1.8 TSI (DSG7)-PCL
SA: Cheong Puatlyn
Next Appointment Date :
Next Appointment Mileage : 0

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT
AIG DIRECT SETTLEMENT DOA 12.2.2018 SURVEYOR LKK TP VEHICLE SKT402M					
	Labor				
1	LABOUR	1.00	UNIT	840.00	840.00
2	SPRAY PAINT	1.00	UNIT	800.00	800.00
3	R&P NUMBER PLATE -NETT	1.00	ST	80.00	80.00
4	Tow SVC- Quality Recovery Services	1.00	UNIT		
5	Tow SVC- Quality Recovery Services	1.00	UNIT		
6	PROGRAMMING & CALIBRATION- NETT	1.00	TU	480.00	480.00
7	ELECT WIRING & MECH COMPONENT CHECK NE	1.00	TU	280.00	280.00
	Item				
8	PARKING SENSOR O RING	4.00	PCS	0.55	2.20
9	REAR BUMPER	1.00	PCS	1,751.89	1,751.89
10	MOLDING RHS	1.00	PCS	141.72	141.72
11	SPOILER	1.00	PCS	295.04	295.04
12	REAR CENTER STRIP	1.00	PCS	58.42	58.42
13	SENSOR BRACKET	1.00	PCS	49.47	49.47
14	2KADHESIVE	1.00	PCS	89.84	89.84

Volkswagen Centre Singapore



Service Tax Invoice No. SV18P10870

Biz Reg. No. 531030698
GST No. M20098505-2

SERVICE ORDER NO: 18IP0588
SERVICE CUSTOMER NO.: F01088R
SERVICE CUSTOMER NAME: AIG ASIA PACIFIC INSURANCE P/L
TELEPHONE NO.:
ADDRESS: 78 Serangoon Way
#07-16 AIG Building
Singapore
Post Code: 579120

VEH NO.: SKK2464T
DATE: 09/03/18 Pickup:
VIN NO.: WVGZZZ3GZ0P043765 KM: 42,061
GEARBOX CODE: PMJ Engine No.:
MODEL: Passat GT 1.8 TSI (DSGT)-PEL
SA: Cheong Pearllyn
Next Appointment Date :
Next Appointment Mileage : 0

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT
15	SONDAGENT	1.00	PCS	54.27	54.27

Sub Total 4,933.25
GST (7%) AMOUNT 345.33
TOTAL AMOUNT 5,278.58



Customer

Phone : Fax :



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 13 Feb 2018 / 14:44:20

Receipt Date/Time : 13 Feb 2018 / 14:44:20

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180213-001223

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-----	--	-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SKT402M

As at 12 Feb 2018/17:45:00

Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.

1 Insurance Enquiry - SKT402M

Enquiry Fee

20180213144251615502

Sub-Total	7.00	0.49	7.49
Total Before Rounding	7.00	0.49	7.49
Rounding Difference			0.04
Total Amount Payable			7.45

Paid By

20180213144304694	Direct Debit: eNETS Debit (Internet Banking)	7.45
-------------------	---	------

Total	7.45
Cash Change	0.00
Tendered Amount	7.45
Excess Refundable Amount	0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Feb 2018 Edit Reg		19 Feb 2018 00:00 Edit Adj Rpt	\$44,933.25 Edit Estimates	\$44,933.25 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 199803778Z		
Main Claimant:	TAN CHOK KWANG VINCENT, ID: S1801566H		
Vehicle Reg. No.:	SKK2464T	Date of Loss:	12/02/2018 17:00 - :59 [55 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7601472197SG	Policy/Cover Note No.:	09999994749
Vehicle Reg. No. (Insured):	SKT402M	Policy No. (Claimant):	10590194
		Excess:	
Repairer:	Volkswagen Centre Singapore (HQ) 247 Alexandra Road, 159934 Alexandra - Tel: 63057288		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com		
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 27/02/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKK2464T (7601472197SG)

[SKT402M]

TP

TAN CHOK KWANG VINCENT

Feb 12 2018 5:00PM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Volkswagen Centre Singapore

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Letters/Correspondences															1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown													Edit			
Assessment Reports															1 per page		☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print		
1	01/03/18 10:09	Accident Statement From: SC - Reg. No: SKT402M, Claimant: DAIHLER FLEET MANAGEMENT SINGAPORE PTE. LTD.													Load HTM			
Photos/Images															3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	23/03/18 09:43	Odometer Reading													Load JPG	☒		
2	23/03/18 09:43	Chassis Number													Load JPG	☒		
3	23/03/18 09:43	General View													Load JPG	☒		
4	23/03/18 09:43	General View													Load JPG	☒		
5	23/03/18 09:43	General View													Load JPG	☒		
6	23/03/18 09:43	General View													Load JPG	☒		
7	23/03/18 09:43	General View													Load JPG	☒		
8	23/03/18 09:43	General View													Load JPG	☒		
9	23/03/18 09:43	General View													Load JPG	☒		
10	23/03/18 09:43	General View													Load JPG	☒		
11	23/03/18 09:43	General View													Load JPG	☒		
12	23/03/18 09:43	General View													Load JPG	☒		
13	23/03/18 09:43	General View													Load JPG	☒		
14	23/03/18 09:43	General View													Load JPG	☒		
15	23/03/18 09:43	General View													Load JPG	☒		
16	23/03/18 09:43	General View													Load JPG	☒		
17	23/03/18 09:43	General View													Load JPG	☒		
18	23/03/18 09:43	General View													Load JPG	☒		
19	23/03/18 09:43	General View													Load JPG	☒		
20	23/03/18 09:43	General View													Load JPG	☒		
21	23/03/18 09:43	General View													Load JPG	☒		
22	23/03/18 09:43	General View													Load JPG	☒		
23	23/03/18 09:43	General View													Load JPG	☒		
24	23/03/18 09:43	General View													Load JPG	☒		
25	23/03/18 09:43	General View													Load JPG	☒		
26	23/03/18 09:43	General View													Load JPG	☒		
27	23/03/18 09:43	General View													Load JPG	☒		
28	23/03/18 09:43	General View													Load JPG	☒		
29	23/03/18 09:43	General View													Load JPG	☒		
30	23/03/18 09:43	General View													Load JPG	☒		

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation				
			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/02/18 09:49	NOTIFICATION FROM WORKSHOP + TP ESTIMATE	 Load PDF	
2	15/02/18 09:55	TP GIA REPORT 1	 Load PDF	
3	15/02/18 09:56	TP GIA REPORT 2	 Load PDF	
4	15/02/18 10:05	TP GIA REPORT 3	 Load PDF	
5	15/02/18 10:05	TP GIA REPORT 4	 Load PDF	
6	15/02/18 10:06	TP GIA REPORT 5	 Load PDF	
7	15/02/18 10:06	TP GIA REPORT 6	 Load PDF	
8	15/02/18 10:06	TP GIA REPORT 7	 Load PDF	
9	15/02/18 10:07	TP GIA REPORT 8	 Load PDF	
10	21/02/18 10:53	TP ESTIMATE- MARKED	 Load PDF	
11	17/04/18 09:25	CLAIMANT NRIC	 Load PDF	
12	19/04/18 14:36	WORKSHOP INVOICE	 Load PDF	
13	19/04/18 14:36	AUTHORISATION TO ACT FORM	 Load PDF	
14	19/04/18 14:36	Release Voucher	 Load PDF	
15	19/04/18 14:36	LTA SEARCH	 Load PDF	
16	19/04/18 14:36	LETTER TO OI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKT402M (Insd veh)	Model:	VOLKSWAGEN PASSAT CC
	SKK2464T (TP veh)		TSI 1.8 TSI AT 3624H7 HID
Date of Accident:	12/02/2018		(A)

Global Sum Settlement	: ☐ Yes	: ☒ No	
Repair Estimate	: \$		9,377.73
Final Repair Cost	: \$		5,278.58
Loss of Use	: \$	240.00	3.00 days at \$80.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	7.45	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	5,526.03	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Volkswagen Centre Singapore	: \$	5,286.03
2)	Tan Chok Kwang Vincent	: \$	240.00
3)		: \$	

JOANNE LEE KHANG MIN

19 Apr
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18003077/T1EA3Q2

Date: 19/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994749
Claimant Vehicle No : SKK2464T **Insured Vehicle No :** SKT402M
 Date of Loss: 12/02/2018 Nature of Claim: TP Claim No: 7601472197SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKK2464T**
 Make & Model: VOLKSWAGEN PASSAT CC TSI, 1.8 TSI AT 3624H7 HID (A) Engine No: CDA399564
 Reg. Date: 21/06/2013 (Man. Year: 2013) Chassis No: WVVZZZ3CZDP040765
 Colour: Black Odometer: 39540 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/45 R17 Rear Tyre Size: 235/45 R17
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,084.23	2,533.25	550.98	17.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	2,400.00	3,280.00	57.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,764.23	4,933.25	3,830.98	43.71
+ GST 7.00/7.00% (S\$)	613.50	345.33	268.17	43.71
Nett Amount (S\$)	9,377.73	5,278.58	4,099.15	43.71
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,526.03		

INSPECTION

Date of Assignment: 19/02/2018
 Date Inspected: 19/02/2018 Inspected At: Volkswagen Centre Singapore (HQ)
 247 Alexandra Road
 Singapore 159934
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*B&P NUMBER PLATE	Bent	80.00 FS	*80.00 FS
2	4		*PARKING SENSOR O RING	Necessary	2.60 FS	*2.60 FS
3	1		*BUMPER REINFORCEMENT	Not Necessary	335.54 FS	*- FS
4	1		*BUMPER BRACKET LHS	Not Necessary	36.86 FS	*- FS
5	1		*BUMPER BRACKET RHS	Not Necessary	36.86 FS	*- FS
6	1		*REAR BUMPER	Deformed	1,751.89 FS	*1,751.89 FS
7	1		*MOLDING LHS	Not Necessary	141.72 FS	*- FS
8	1		*MOLDING RHS	Cut	141.72 FS	*141.72 FS
9	1		*SPOILER	Cut	295.04 FS	*295.04 FS
10	1		*REAR CENTER STRIP	Necessary	58.42 FS	*58.42 FS
11	1		*SENSOR BRACKET	Necessary	49.47 FS	*49.47 FS
12	1		*2KADHESIVE	Necessary	89.84 FS	*89.84 FS
13	1		*BONDAGENT	Necessary	64.27 FS	*64.27 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	3,084.23	2,533.25
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	2,520.00	840.00
2	SPRAY PAINT	New	2,400.00	800.00
3	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	New	480.00	480.00
4	ELECT WIRING & MECH COMPO	New	280.00	280.00
Gross Labour Cost (\$\$)			5,680.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >