

PDI TUAS

PDI TUAS

TAN CHOK KWANG
VINCENT
38 CHAY YAN STREET
#11-05
Singapore, 169907
Singapore

Tanfu 97495749
-wp-

19/2/18 @ 1430.

3 days.

See @ lkhando.com

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV022833
Quote No. SER/QUO/1800271
QuoteDate 13/02/18
Salesperson Xiao Li Na Helena
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Passat B7 1.8 TSI (DSG7)+PEL	31,002	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SKK2464T	WVWZZZ3CZDP040765	21/06/13	Xiao Li Na Helena
Engine Code	Labor Type	Engine No.	Model Code
	1P	CDA 399564	3624H7

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	3	UNIT		840 2,520.00
P B&P ALEX PAINT	SPRAY PAINT	3	UNIT		800 2,400.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	pcs	Change / done mis	80.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un	don't need	✓ 480.00
P B&P MECH	COMPULSORY TO DO AFTER AC			Bump.	
	ELECT WIRING & MECH COMPO	1	Time Un		✓ 280.00
	Nett				
	Sum Labor				5,760.00
P 1T0919133C 9B9	PARKING SENSOR O RING	4	Pieces		✓ 2.60
P 3AA807305	BUMPER REINFORCEMENT	1	Pieces		? 335.54
P 3AE807393A	BUMPER BRACKET LHS	1	Pieces		? 36.86
	Use Predecessor 3AE807393				
P 3AE807394A	BUMPER BRACKET RHS	1	Pieces		? 36.86
	Use Predecessor 3AE807394				
P 3AE807417R GRU	REAR BUMPER	1	Pieces		de 1,751.89
P 3AE807459 2ZZ	MOLDING LHS	1	Pieces		? 141.72
P 3AE807460 2ZZ	MOLDING RHS	1	Pieces		aut 141.72
P 3AE807521A 9B9	SPOILER	1	Pieces		aut 295.04
P 3AE807863	REAR CENTER STRIP	1	Pieces		net 58.42
P 3AE998490	SENSOR BRACKET	1	Pieces		net 49.47
P D 180KU2A1	2KADHESIVE	1	Pieces		net 89.84
P D 822150A1	BONDAGENT	1	Pieces		net 64.27

Sum carried forward 8,764.23

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

TAN CHOK KWANG
VINCENT
38 CHAY YAN STREET
#11-05
Singapore, 169907
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV022833
Quote No. SER/QUO/1800271
QuoteDate 13/02/18
Salesperson Xiao Li Na Helena
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Passat B7 1.8 TSI (DSG7)+PEL	31,002	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SKK2464T	WVWZZZ3CZDP040765	21/06/13	Xiao Li Na Helena
Engine Code	Labor Type	Engine No.	Model Code
	1P	CDA 399564	3624H7

	Continued	8,764.23
Sum Item		3,004.23

	Sum Labor	5,760.00
	Sum Item	3,004.23
	Total SGD	8,764.23
	7% GST	8,764.23 613.50
	Total SGD Incl. GST	9,377.73

Explanations

P = Proportionately Charged

Payment Terms No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Payments to: - BBN: - Acc.-No.: