



SERVICE REQUESTS

MESSAGES

CLAIMS

<< Service Request Details

Claim	S8M0090F
Reference	CC4/ASM18003096/Gfb3s2
Loss Date	February 13, 2018
Report Date	Feb 14, 2018 12:00:00 AM
Request Date	May 30, 2019
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step Wait for: Approve invoice

Vehicle Information

Incident Vehicle	SCE899L
Registration #	
Make	TPVD HONDA
Model	CIVIC-1.6 (A)

Service Address

...

Primary Contact/Insured

BUTCHER III BYRON THOMAS
 BLK 725 BEDOK RESERVOIR ROAD, #04-5204,
 470725, Singapore
 96431745

Claim Handler

KHONG Lynn
 68804892
 lynn.khong@axa.com.sg

Additional Instructions

Messages Invoices History Documents **Assessment** Metrics Notes

Document Type Document SubType

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1[1].pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	June 20, 2019
LKKAdjustment1a[1].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 20, 2019
LKKInspection[1].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 20, 2019
EMAIL.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 20, 2019
LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	February 28, 2018
TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	February 26, 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Preliminary Advice.PDF	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	February 23, 2018
 EMAIL RECEIVED FROM WORKSHOP WITH ESTIMATE.msg	Other	Other	DHIWAR Namrata	February 15, 2018
 SCE899L TP GIA REPORT.PDF	Reports & Statement	GIA Report	DHIWAR Namrata	February 15, 2018
 SJT584H INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHIWAR Namrata	February 15, 2018