

ASS. REC. BY:

REF: cslmsg18003125 / R18 d3n2

Special Instruction:

Surveyor:
Merimen

R18U1

ASSIGNMENT (Office)

From (Person):

Fievel Foo

of

MSIG

Date/Time:

15/2/18 @ 9.17am

Estimated Cost:

Bill to:

OD (IP) / WS / IP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 3583K

Insured:

SLC 3869H

at Workshop m/s

Borneo Motors

Tel:

66 3 11 857

of

2 pandan Crescent

Policy No:

A28742952QMY

Claim No:

519761

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 13/02/2018

CA / REV / REP. / REV 24 HRS

04052018

H.O.D. Endorsement:

Date/Time:

15/2/18 @ 9.54am

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	called No answer - wasp closed for CNY
	SLG 3583K - X
	SLC 3869H - X
08/05/18	@ 11:43 a.m. Revised to Fievel Foo Wengso via merimen.


Surveyor P. Ram

REF:

7514R
~~2586~~

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLG 3583K
at Workshop m/s: Borneo
of _____
Insured: msk/up
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLG 3583K Yr Regn: 2014 / APR
Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: TOYOTA CAMRY 2.5 A C.C. 2494
Colour: Green A/C: Insured / Std / NI / NA
Sp. Reading: 5782 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MR053 AK 5004007574
Gen. Cond: Good / Fail / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/50R17
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or MEMBAX

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>13/02/18</u>	D.O.I. <u>04/05/18</u>

Survey held at BORNEO MOTUL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/08/18 Confirmed P/P \$ 1,997.33 @ 3 days with Rescu1.

(\$ 1,853.47 Red - 48%)

RECEIVED 29 AUG 2018

Date/Time, File Pass to?

29/08/18

1) Typist
Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation: _____ \$ + RS, _____ \$

• Photos

• Others

TOTAL

200
10
210

Report Format :

Lump Sum / I.B.I: (\$ 1,997.33 P/P)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2018		15 Feb 2018 09:17 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LI GUO' AN, ID: S8439026G, Tel: +6582022518, Email: skyguoan@gmail.com		
Main Claimant:	E TONG PTE LTD, Co. Reg. No.: 200407514R		
Vehicle Reg. No.:	SLG3583K	Date of Loss:	13/02/2018 08:00 - :59
Claim Type:	TP / 549761	Policy/Cover Note No.:	A28742952QMY (Comprehensive) Coverage: 12/05/2017 - 11/05/2018
Vehicle Reg. No. (Insured):	SLC3869H	Policy No. (Claimant):	
		Excess:	
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/02/2018]		
Driver/Custodian (Insured):	LI GUO' AN (33 / Male), NRIC: S8439026G, Tel: +6582022518		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wenyaoy

Date: 08 May 2018

Preliminary Advice

Insured Vehicle No	: SLC3869H	Accident Date	: 13/02/2018
TP Vehicle No	: SLG3583K	Assignment Date	: 15/02/2018
Make	: TOYOTA CAMRY	Est. Duration of Repair	: 3 days
Date of Inspection	: 04/05/2018		
Inspection At	: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,850.80
Revised Amount	:S\$	1,453.50
Check Items (Estimated)	:S\$	493.50
Total	:S\$	1,947.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

TYPE OF CLAIM: ☐ OD ☐ OD/UL ☒ DS

MCA:

Shashy

MOTOR ACCIDENT REPORT

Date Of Report: 14/02/2018 Time: 1430 PM Date Of Accident: 13/02/2018 Time: 0830 am
Exact Location Of Accident: Bukit Batok Road towards Jurong Town Hall Road
Country/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ /

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SLG 3583K Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No:
Name Of Registered Owner: E.TONG PTE LTD
Mobile Number: 96236339 Alternative No: Email Address: melvin.chang@etong.com.sg

Vehicle Particulars

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model: Camry
Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):
Are you claiming under your own insurance policy for repair to your vehicle? Yes ☐ Reporting Only ☐ Third Party ☒
Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

Insurance Company

Name of Insurance Company: AXA
Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐
Fleet Policy: Yes ☐ No ☐ Policy / Cover Note No: GA282800/1

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: CHONG HON MUN NRIC/ Passport / FIN No: S1812861F
Date Of Birth: 28/04/1967 Occupation: Indoor ☒ Outdoor ☐
Date Of Driving Pass: 29/09/2003 Gender: Male ☒ Female ☐
Mobile Number: 96236339 Fax No: Alternative No:
Address: BLK 554 Choa Chu Kang North 6 #07-38 Postal Code: 680554
Email Address: melvin.chang@etong.com.sg
Was driver an employee of the Insured's Company? Yes ☐ No ☐ State relationship of the driver with the insured:
Vehicle Registration Number of Driver's Own Vehicle (if applicable):
Insurance Company of Driver's Own Vehicle (if applicable):

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: Rear Collision
Number of Passengers in the above vehicle (Including Driver): 01 / If more than 2 Pax Please fill ANNEX B

PASSENGER 1

Name: Gender: Male ☐ Female ☐
Weather Conditions: Clear ☒ Raining ☐ Others ☐ (If others, please state condition):
Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):
Was any body injured in the Accident? No ☐ Yes ☒
Was any injured conveyed to hospital by ambulance? No ☒ Yes ☐
Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:
Number of vehicles involved in the accident: 02
Was there any witness? No ☒ Yes ☐ If yes, please furnish witness details column below
Witness Name: | Contact No.: | Email:
Was there any other vehicle or property damaged? No ☐ Yes ☐
Was there any video captured by Car Camera? No ☒ Yes ☐ Are accident scene photos available for attachment? No ☐ Yes ☒
Was the accident reported to the police? No ☒ Yes ☐ (If yes, please state which Police Station):
Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):
I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: SLC 3869H Vehicle Make/Model/Colour: Mazda
Details Of Properties Damage in Accident:
Vehicle Category:
Name of Driver: Sky Li
NRIC/Passport/FIN Number: Contact Number: 8202 2518
Address: Postal Code:
Insurance Company Name:
Nature Of Damage: No. Of Passenger (Including Driver):

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident:

about 0830 am

on 13/02/2018 Morning, I was traveling along Bukit Batok Road towards Jurong Town Hall Road, before the PIE flyover. I stopped the car due to the morning traffic. The traffic was slow due to the morning peak hours, the front car stopped and I slow down my car and stopped. Suddenly, I heard a knocked on the rear of my car. I get down the car to check and found my rear bumper was damaged.

We declare the foregoing particulars are true in every respect.

Driver's Signature (If driver is not the policyholder) // Date & Time

Witnessed by Reporting Centre Personnel



redefining / insurance

AXA Insurance Pte Ltd

1800 880 4888 (Within Singapore)
(65) 6880 4888 (International)

(65) 6880 4740

customer.care@axa.com.sg

www.axa.com.sg

Certificate of Insurance

account number
03944

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)
-Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	E. TONG PTE. LTD.	Certificate number	GA282800 / 1
Cover	Comprehensive	Chassis number	MR053AK5004007574
Plan name	Peace	Engine number	2ARU127113
NCD applicable	50%		
Vehicle registration number	SLG3583K		
Period of Insurance	from 24/10/2017 to 23/10/2018 (both dates inclusive)		
Finance loan company	Nil		

Persons or classes of persons entitled to drive*

(a) Any Named Driver as stated in the Policy.

1. CHEN LIXIN

(b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia); are not to be included under these headings:

EXCESS	Basic Own Damage Excess	SGD 400.00
	Windscreen Excess	SGD 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if you have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Online Service Booking :
www.toyptasingapore.com.sg
Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1188

Account Detail		Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM		
	Document No	0	
	Document Date	14/02/2018	
			M/s E Tong Pte Ltd 48 Toh Guan Road East #03-141 Enterprise Hub Singapore 608586 Mobile: 96236339

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
14	JETEK	E3	23/04/2014	SLG3583K	0	29665	6TP/SLG3583K/12081
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053AK5004007574	2ARU127113	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP VEH NO.: ACC DATE:14/02/18 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:			net	50 80.00
2	B	BP-LAB CHECK WIRING AND CONDUCT LEAK TEST				169.50
3	B	BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR				678 1256.00
4	B	BP-LAB REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA				556 1212.00
5	1	BP-RES RESRPAY ACC AFF AREA				386.60
6	2	S52023-06081 REAR BPR REINFORCEMENT,	1.00	386.60		386.60
7	3	S52159-06974 COVER, RR BUMPER	1.00	639.80		639.80
		S52576-06131 RETAINER, RR BUMPER	1.00	106.90		106.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on a strict 7 day basis. Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors

Acknowledged by Repairer
 Signature:
 Date:

Please acknowledge receipt of vehicle

Change Summary
 Parts 1,133.30
 Labour 2,717.50
 Materials 0.00
 Lubrication/Fluid 0.00
 Others 0.00

Total 3,850.80
 GST 7.00% 269.56
 Less 0.00
 Amount Due 4,120.36

PLEASE TEAR ALONG PERFORATED LINE

3620378

3620378

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLG3583K

CUSTOMER

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Do Reg No : 196700086Z
3ST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Page 2 of 2
Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	M/s E Tong Pte Ltd 48 Toh Guan Road East #03-141 Enterprise Hub Singapore 608586 Mobile: 96236339
	Document No 0	
	Document Date 15/08/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
14	JETEXT E3	ASV50R	23/04/2014	SLG3583K	55245	29665	6TP/SLG3583K/12081
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
4R053AK5004007574	2ARU127113	60	Shashitharan	30/07/2018	8.00	01/08/2018	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP VEH NO.: ACC DATE:14/02/18 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: 2 days BY: AUTHORIZED ON: 2 B BP-LAB CHECK WIRING AND CONDUCT LEAK TEST 08 169.50 3 B BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR 08 678.00 4 B BP-LAB REPL ACC AFF PARTS AND PANEL 5 B BP-RES STRAIGHTEN AND REALIGN ACC AFF AREA * 556.00 5 1 BP-RES RESRPAY ACC AFF AREA 1.00 639.80 15.00 543.83 5 1 S52159-06974 COVER, RR BUMPER				
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 543.83 Labour 1,453.50 Materials 0.00 Lubrication/Fluid 0.00 Others 0.00	1,997.33 GST 7.00% 139.81 Less 0.00 Amount Due 2,137.14

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLG3583K

DATE 15/08/2018
TIME 10:56

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

CUSTOMER

3748022

3748022

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003125/R1SD3N2

Date: 30/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28742952QMY
Claimant Vehicle No :	SLG3583K	Insured Vehicle No :	SLC3869H
Date of Loss:	13/02/2018	Nature of Claim:	TP
		Claim No:	549761

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG3583K	Engine No:	2ARU127113
Make & Model:	TOYOTA CAMRY, 2.5 (A)	Chassis No:	MR053AK5004007574
Reg. Date:	23/04/2014 (Man. Year: 2014)	Odometer:	5782 km
Colour:	Grey		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Membat 6 mm	Rear Left Side:	Membat 6 mm
Front Right Side:	Membat 6 mm	Rear Right Side:	Membat 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,213.30	593.83	619.47	51.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,637.50	1,403.50	1,234.00	46.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,850.80	1,997.33	1,853.47	48.13
+ GST 7.00/7.00% (S\$)	269.56	139.81	129.75	48.13
Nett Amount (S\$)	4,120.36	2,137.14	1,983.22	48.13

INSPECTION

Date of Assignment:	15/02/2018	
Date Inspected:	04/05/2018	Inspected At: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Aug 2018)
Parts: 143	TOYOTA CAMRY 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLG3583K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BPR REINFORCEMENT	Serviceable	386.60 FS	*- FS
2	1		*COVER,RR BUMPER	Deformed	639.80 FS	*543.83 FS
3	1		*RETAINER,RR BUMPER	Serviceable	106.90 FS	*- FS
4	1		*SUNDRIES	Necessary	80.00 FS	*50.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					1,213.30	593.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND CONDUCT LEAK TEST DRILL HOLE AND INSTALL REVERSE SENSOR	New	169.50	169.50
2	REPL ACC AFF PARTS AND PANEL STRAIGHTEN ABD REALIGN ACC AFF AREA	New	1,356.00	678.00
3	RESPRAY ACC AFF AREA	New	1,112.00	556.00
Gross Labour Cost (\$\$)			2,637.50	1,403.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >