

ASS. REC. BY:

REF: CS / CTI18003126 / M1rd31/

Special Instructions:

INVEST  
Merrin

MA

ASSIGNMENT (Office)

From (Person): Irene Tay

of CTI

Date/Time: 15/2/18 @ 9.04am

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 9625H

Insured:

SJC7797D

at Workshop m/s

Eco Automobile

Tel:

63847515

of

13 Kaki Bukit Rd 4 # 03-29

Policy No:

DM HCSN1756201700

Claim No:

SNM18000862002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 12/02/2018

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time: 15/2/18 @ 11:34am

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	No answer. Workshop closed for CNY
	GBF 9625H - X
	SJC7797D - CS3/CTI18001992/d3
	D.O.A. 28/01/18

REF:

## ASSIGNMENT

From \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s: **ECO Auto**  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

Bal. or Market Value

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: **2** days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle IN / OUT

Veh No: **GBT9625H** Vr Regn: **APR 17**  
 Type: M.Car / M.Cycle / Bus / Van / **Loxy** / Taxi / Prime Mover /  
 Truck / Trailer or

Make: **TOYOTA DYNA** s.c. **2982**  
 Colour: **SILVER** A/C: Insured / Std / NI / NA  
 Sp Reading: **13563** T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_

C/No: **JTFAT35450207801**Gen. Cond: **Good** / Fair / Poor / BurntSteering: **Order** / Jammed / Leaked / Burnt orBrake: **Order** / Jammed / Leaked / Burnt orModi: **Nil** / S/Rim / STD A/Rim orTyre Size: F: **195/75/R15**R: **155/R12**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: **8** mmL/Bal: **8** mmD.O.A: **Block**

Rear

R/Bal: **8** mmL/Bal: **8** mmD.O.L: **19/03/2018**

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

**FRT. OS**

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

**NO DIRECT / PRS. only.****26/4 Submit LS \$1200f without Analyse. (Ref. 3261.37, 732)**

RECEIVED 27 APR 2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

/)

Date/Time, File Return to?

2)

Days Of Repair: **2**Resurvey No. of Trip: **-**

Survey Fee:

Transportation

) \$ - PR - \$

) Thru

) Other

Report Format: **TP**Lump Sum / I.B.I: (\$) **1200f**Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Insp (\$)☐ Workshop (\$)

TOTAL

# Survey Department Check List (Case Handler)

Reference No. : C9/CT118003156/M1rd3  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin** ( Nivitha ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor** ( Ma ): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

## (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

## (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

## (4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: Celine 27/4/18  
Case Handler Date

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2018		15 Feb 2018 09:09 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SPR REALTY PTE LTD, Co. Reg. No.: 200604094Z		
Main Claimant:	CA FASHION		
Vehicle Reg. No.:	GBF9625H	Date of Loss:	12/02/2018 12:00 - :59
Claim Type:	TP / SNM18D00862C02	Policy/Cover Note No.:	DMHCSN1756201700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJC7797D	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Eco Automobile Claims And Repair Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4, #03-29, 417807 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/02/2018]		
Adj Asg. Remarks:	EST \$3943.75, ASSIGN MARCUS CHUA AS SJE		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI18003126/M1d3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 19-02-2018



Code : CTI

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJC 7797D	Veh. Inspected	GBF 9625H
Policy No.	DMHCSN1756201700	Coverage (\$)	0.00
Claim No.	SNM18D00862C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	19/02/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	12/02/2018	Inspection Date
Survey held at	ECO AUTOMOBILE CLAIMS & REPAIR PTE LTD 13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807	

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	9859E
<b>Vehicle Details</b>	
Vehicle No.:	GBF9625H
Vehicle to be Exported:	No
Intended De-registration Date:	26 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 SMT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	1KD2692939
Chassis No.:	JTFAT35Y50K207801
Maximum Power Output:	-
Open Market Value:	\$26,436.00
Original Registration Date:	24 Apr 2017
First Registration Date:	24 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$1,322.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	23 Apr 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$14,093.00
COE Rebate Amount:	\$12,675.00
<b>Total Rebate Amount:</b>	<b>\$12,675.00</b>

The information contained herein is correct as at 26 Apr 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/02/2018 16:57
Date Of Accident	12/02/2018 12:35
Exact Location Of Accident	CARPARK AT BLK 442 PASIR RIS DRIVE 06
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF9625H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CA FASHION
Co Reg No	53069859E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5090643141
Cover Note Number	

### Driver

Name of Driver	ONG KOK BENG
NRIC No	S1538107H
Date Of Birth	28/08/1962
Occupation	OUTDOOR
Date Of Driving Pass	19/06/1980
Driving Experience	37 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96398582
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 411 HOUGANG AVE 10 #08-1010
Postcode	530411
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJC7797D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Tel: 67410097  
NRIC/FIN No.: 67492305  
Email: yock@vaccinsg.com.sg

12 FEB 2018

IDAC KAKI BUKIT (VACC)  
TRAFFIC POLICE ALICE

### SKETCH PLAN



Vehicle A : GBF962SH  
Vehicle B : SJC7797D

Blk 442 Pasir Ris Drive 6

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12/02/18 at about 1235pm, I was stationary in the carpark at Blk 442 Pasir Ris Drive 6, waiting for a parking lot. Suddenly vehicle B, SJL77977, reversed and bang into the front right portion of my vehicle, GBF9625H.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_  
Date & Time: \_\_\_\_\_

Driver's Signature \_\_\_\_\_  
 (If driver is not the policyholder)  
 Date & Time: \_\_\_\_\_

12 FEB 2018 IDAC KAKI BUKIT (VAC)  
21 KAKI BUKIT AVE 4  
Singapore 415933

Reporting Centre Personnel's Signature:  
Name: Fax: 67492305  
NRIC/FIN No: Email: [usd@u.singapore.com.sg](mailto:usd@u.singapore.com.sg)

Your ref. SJC7797D

Our ref. GBF9625H

To: China Taiping Insurance (S) Pte Ltd

CC Motor Claims Dept

Email

Fax

Date: 12-02-18

From: Alfie Chong

Fax: 67024202

Contact: 91765733

Make / Model: TOYOTA DYNA

Chassis No.: JTFAT35Y50K207801

Engine No.: 1KD-FTV 2982

Accident Date: 12-02-18

ESTIMATE FOR VEHICLE NO. : GBF9625H

**DESCRIPTION**

Front bumper

Front bumper bracket RH

Front bumper spotlight cover RH

Front fender RH

Front wiper panel

Headlamp RH

Front grille

Front grille clips

Front grille logo

Front panel RH

Front panel screw

Carplate

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

Date:

QTY	LIST PRICE	792.8
1	\$ 1,200.00	✓
1	\$ 80.00	X
1	\$ 80.00	X
1	\$ 180.00	X
1	\$ 350.00	X
1	\$ 750.00	✓
1	\$ 180.00	X
10	\$ 10.00	X
1	\$ 65.00	X
1	\$ 450.00	X
6	\$ 6.00	X
1	\$ 35.00	X

Total: \$ 3,386.00

Less 25%: \$ (846.50)

Parts Total: \$ 2,539.50

**LABOUR**

To remove & install damage area

To rust proofing damage area

To spray painting on affected area

To check wiring & lighting

\$ 800.00

\$ 80.00

\$ 700.00

\$ 50.00

Total: \$ 4,169.50

7% GST: \$ 291.87

Grand Total: \$ 4,461.37

Please survey the vehicle at 13 Kaki Bukit Road 4  
Bartley Biz Center #03-29 S417807  
(Kindly contact us @ 9176 5733)

NA Authon  
HS Repair  
After paint  
Lbb Auto  
20/3/2018  
2w/1day

HS Repair  
\$1200  
No Settlement

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2018		15 Feb 2018 09:09 <a href="#">Edit Adj Rpt</a>	<b>S\$1,200.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,200.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	SPR REALTY PTE LTD, Co. Reg. No.: 200604094Z								
Main Claimant:	CA FASHION								
Vehicle Reg. No.:	GBF9625H	Date of Loss:	12/02/2018 12:00 - :59 [9 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D00862C02	Policy/Cover Note No.:	DMHCSN1756201700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJC7797D	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Eco Automobile Claims And Repair Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4, #03-29, 417807 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 27/02/2018]								
Adj Asg. Remarks:	EST \$3943.75, ASSIGN MARCUS CHUA AS SJE								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GBF9625H (SNM18D00862C02)

[SJC7797D]




TP

CA FASHION

Feb 12 2018 12:00PM

[SPR REALTY PTE LTD]

Eco Automobile Claims And Repair Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	13/02/18 16:20	Accident Statement	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	13/02/18 16:17	3RD PARTY LORRY [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	13/02/18 16:17	ACCIDENT SCENE [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	13/02/18 16:17	ACCIDENT SCENE [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	13/02/18 16:17	ACCIDENT SCENE [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	13/02/18 16:17	ACCIDENT SCENE [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	13/02/18 16:17	INSURED CAR [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	13/02/18 16:17	INSURED CAR [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	13/02/18 16:17	INSURED CAR CHASSIS NUMBER [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	13/02/18 16:17	INSURED CAR [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	13/02/18 16:17	INSURED CAR [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
11	13/02/18 16:17	INSURED CAR [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
12	13/02/18 16:17	INSURED CAR [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
13	13/02/18 16:17	INSURED CAR [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
14	13/02/18 16:17	INSURED CAR DECAL [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
15	13/02/18 16:17	INSURED CAR [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
16	13/02/18 16:17	INSURED CAR [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
17	13/02/18 16:17	INSURED CAR [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
18	13/02/18 16:17	INSURED CAR [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/04/18 09:39	General View	 Load PDF	
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/02/18 09:07	REPAIR EST	 Load PDF	
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	13/02/18 16:13	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	13/02/18 16:13	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	13/02/18 16:14	RENTAL AGREEMENT	 Load TIF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
		[Linked Accident Report Documents]		
4	13/02/18 16:14	CI [Linked Accident Report Documents]	Load TIF	
5	13/02/18 16:14	HIRER IC N DL [Linked Accident Report Documents]	Load TIF	
6	13/02/18 16:14	HIRER VDL [Linked Accident Report Documents]	Load TIF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	13/02/18 16:20	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	13/02/18 16:17	3RD PARTY LORRY	Load JPG	<input checked="" type="checkbox"/>
2	13/02/18 16:17	ACCIDENT SCENE	Load JPG	<input checked="" type="checkbox"/>
3	13/02/18 16:17	ACCIDENT SCENE	Load JPG	<input checked="" type="checkbox"/>
4	13/02/18 16:17	ACCIDENT SCENE	Load JPG	<input checked="" type="checkbox"/>
5	13/02/18 16:17	ACCIDENT SCENE	Load JPG	<input checked="" type="checkbox"/>
6	13/02/18 16:17	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>
7	13/02/18 16:17	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>
8	13/02/18 16:17	INSURED CAR CHASSIS NUMBER	Load JPG	<input checked="" type="checkbox"/>
9	13/02/18 16:17	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>
10	13/02/18 16:17	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>
11	13/02/18 16:17	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>
12	13/02/18 16:17	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>
13	13/02/18 16:17	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>
14	13/02/18 16:17	INSURED CAR DECAL	Load JPG	<input checked="" type="checkbox"/>
15	13/02/18 16:17	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>
16	13/02/18 16:17	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>
17	13/02/18 16:17	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>
18	13/02/18 16:17	INSURED CAR	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	13/02/18 16:13	Sketch Plan	Load TIF	
2	13/02/18 16:13	Sketch Plan #2	Load TIF	
3	13/02/18 16:14	RENTAL AGREEMENT	Load TIF	
4	13/02/18 16:14	CI	Load TIF	
5	13/02/18 16:14	HIRER IC N DL	Load TIF	
6	13/02/18 16:14	HIRER VDL	Load TIF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b> <span>Reset</span> <span>Save</span> <span>Print</span>
There are no document checklists configured.
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18003126/M1RD3Q2

Date: 04/05/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMHCSN1756201700

Claimant Vehicle  
No: GBF9625HInsured Vehicle  
No: SJC7797D

Date of Loss: 12/02/2018

Nature of Claim: TP

Claim  
No: SNM18D00862C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GBF9625H

Make &amp; Model: TOYOTA DYNA 150, 3.0 D (M)

Engine No: 1KD2692939

Reg. Date: 24/04/2017 (Man. Year: 2017)

Chassis No: JTFAT35Y50K207801

Colour: Silver

Odometer: 13563 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/75 R15	Rear Tyre Size:	155 R12
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,539.50	1,079.02	1,460.48	57.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	430.00	1,200.00	73.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,169.50</b>	<b>1,509.02</b>	<b>2,660.48</b>	<b>63.81</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,200.00</b>		
<b>(S\$)</b>	<b>4,169.50</b>	<b>1,200.00</b>	<b>2,969.50</b>	<b>71.22</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>291.87</b>	<b>84.00</b>	<b>207.87</b>	<b>71.22</b>
<b>Nett Amount (S\$)</b>	<b>4,461.37</b>	<b>1,284.00</b>	<b>3,177.37</b>	<b>71.22</b>

## INSPECTION

Date of Assignment: 15/02/2018

Date Inspected: 19/03/2018 Inspected At:

Eco Automobile Claims And Repair Pte Ltd  
(HQ)  
13 KAKI BUKIT ROAD 4, #03-29  
Singapore 417807

Estimated Period of Repair: 2.0 days



---

**Adjuster:** MA CHIN FOOK**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 04 May 2018)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBF9625H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,200.00 FL	*792.88 FL
2	1		*FRONT BUMPER BRACKET RH	Repair	80.00 FL	*- FL
3	1		*FRONT BUMPER SPOTLIGHT COVER RH	Repair	80.00 FL	*- FL
4	1		*FRONT FENDER RH	Serviceable	180.00 FL	*- FL
5	1		*FRONT WIPER PANEL	Serviceable	350.00 FL	*- FL
6	1		*HEADLAMP RH	Cut	750.00 FL	*645.81 FL
7	1		*FRONT GRILLE	Serviceable	180.00 FL	*- FL
8	10		*FRONT GRILLE CLIPS	Not Necessary	10.00 FL	*- FL
9	1		*FRONT GRILLE LOGO	Not Necessary	65.00 FL	*- FL
10	1		*FRONT PANEL RH	Serviceable	450.00 FL	*- FL
11	6		*FRONT PANEL SCREW	Not Necessary	6.00 FL	*- FL
12	1		*CARPLATE	Not Necessary	35.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,386.00</b>	<b>1,438.69</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>846.50</b>	<b>359.67</b>
<b>Total Parts (\$\$)</b>	<b>2,539.50</b>	<b>1,079.02</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & INSTALL DAMAGE AREA	New	800.00	200.00
2	TO RUST RPOOFING DAMAGE AREA	New	80.00	0.00
3	TO SPRAY PAINTING ON AFFECTED AREA	New	700.00	200.00
4	TO CHECK WIRING & LIGHTING	New	50.00	30.00
Gross Labour Cost (S\$)			<b>1,630.00</b>	<b>430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >