

ASS. REC. BY:

REP: CS/MSG/8003127/ R/rd3n2 Special Instruction:

Sub/Viol
Menmen

Rasul

ASSIGNMENT (Office)

From (Person):

Fievel FOO

of

M81G

Date/Time:

14/2/18 @ 5.25pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 3787Z

Insured:

XD 5479P

at Workshop in/s

GoldBell Engineering

Tel:

8481 1099

of

Blk K, Pandan Loop Ind. Est # 01-12

Policy No:

B28670147MCC

Claim No:

519608

Sum Insured:

Excess:

Make of Veh:

D.O.A

13/2/2018

(Client's Record)

20/02/2018

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time:

15/2/18 @ 11.35am

Person Contacted:

Sya Sya

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SKP 3787Z-X
	XD 5479P-CS 3/MSG/600566/K/H/c2
	D.O.A: 08/01/16
	Sent preli thru menmen
	Confirm L/S \$2600, 5 days (Red: \$2660.50, 50%.)

Parane

REF: MSIG

62366

ASSIGNMENT

Date: 20/2/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV:

Tracked Vehicle No: **SKQ 37872**

at Workshop No: **Goldbell Engineering**

at: **Blk K, Pandan loop Ind Est # 01-12**

Insured:

Policy No:

Claim No:

Sum Insured: Excess:

Claims Report: **Sya sya**

Make of Veh:



(Policy Condition)

Remark: The Veh had commenced its repair at the time of inspection.

Ballon/Market Value:

CAO Accident Report: Consistent? : Yes or No:

QA / PR Report: Consistent? : Yes or No:

Est. Repairs: days Repair: Yes or No:

Lift Sum: % 3 Val: Yes or No:

CA / REV / REP / 24 HRS 'up'

Date: Person Contacted:

Vehicle IN / OUT

SKQ 37872 2011 SEP

Type: **C** 11 Cyls. Bus/Truck / Lorry / Taxi / Private Motor

Truck / Trailer:

Make: **Andi A41-8 TFS1 MU** 1798

Colour: **Black** F.R. Insured (Stor N)

So. Rating: **162637** F.R. Insured (Stor N)

Engine:

CNO: **WAN 2228K0CA 021496**

Gen. Cond: Good **C** Poor / Burnt:

Steering: **C** Jammed / Leaked / Burnt:

Brake: **C** Jammed / Leaked / Burnt:

Model: **NI** STD A/RUN

Type Size: **R 225/50R17**

BS / DUN / EXNOVA / GY / PS / LIZA / MID / OHTSU / RIR / SUM:

TOYO / YOKO of: **CONTINENTAL**

Front	Rear
R.Ra. 6 mm	R.Ra. 6 mm
L.Ra. 6 mm	L.Ra. 6 mm
O.O.A. 13/02/18	O.O. 20/02/18

Survey held at: **GAROKU**

Des. of Damages: **Front / Rear / OS / NS / L/O / Roof top**

0/3 Rear

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time / Action / Instruction

RECEIVED 17 APR 2018

CaseTime File Pass:

typist

CaseTime File Return:

☐ : Prelim. Report

☒ : Final Report

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Sub. No:

Add Fee:

Site fee:

Inter:

Rec:

Lease:

Project Format: **7P**

Lifted Sum: **2600**

Sub. Fee	200
Transport	10
Lift Fee	
Other	
Total	210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18003127/R1rd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 19-02-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 5479P	Veh. Inspected	SKQ 3787Z	
Policy No.	B28670147MKC	Coverage (\$)	0.00	
Claim No.	549608	Excess (\$)	0.00	
Assign From	MERIMEN (FIEVEL FOO)	Assign Date	19/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/02/2018	Inspection Date		
Survey held at	GOLDBELL ENGINEERING PTE LTD BLK K, PANDAN LOOP IND. EST #01-12			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Feb 2018		14 Feb 2018 17:25 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SAMWOH CORPORATION PTE LTD, Co. Reg. No.: 198502202Z		
Main Claimant:	SREDEVAN S/O ANDOOR RAVINDRAN, ID: S8126236E		
Vehicle Reg. No.:	SKQ3787Z	Date of Loss:	13/02/2018 14:00 - :59
Claim Type:	TP / 549608	Policy/Cover Note No.:	B28670147MKC (Comprehensive) Coverage: 01/03/2017 - 28/02/2018
Vehicle Reg. No. (Insured):	XD5479P	Policy No. (Claimant):	
		Excess:	
Repairer:	Goldbell Engineering Pte Ltd (Pandan) Blk K, Pandan Loop Industrial Estate, #01-12, 128219 Tuas - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wen Yao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/02/2018]		
Driver/Custodian (Insured):	CHAN WAI CHOONG (), NRIC: S0170194J, Tel: +6584813688		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Eileen Ang

Subject: FW: Accident case between SKQ3787Z(SOMPO) and XD5479P(MSIG) at JALAN AHMAD IBRAHIM TOWARDS JURONG PORT ROAD claim ref no. 549608
Attachments: 14022018170626-0001.pdf

Have a great day!

Eileen Ang

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2561 | Direct fax +65 6225 7402 | eileen_ang@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Ramesh S/O Somasundrem [mailto:Ramesh@goldbell.com.sg]

Sent: Wednesday, 14 February, 2018 5:16 PM

To: Fievel Foo <Fievel_Foo@sg.msig-asia.com>; Chua Syahirul Syazwani Binte Irwan <ChuaSyaSya@goldbell.com.sg>

Cc: Andy Ooi Lee Keong <AndyOoiLK@goldbell.com.sg>; Eileen Ang <eileen_ang@sg.msig-asia.com>; Sam Tan <sam_tan@sg.msig-asia.com>; William Oh Soon Lee <WilliamOhSL@goldbell.com.sg>

Subject: RE: Accident case between SKQ3787Z(SOMPO) and XD5479P(MSIG) at JALAN AHMAD IBRAHIM TOWARDS JURONG PORT ROAD claim ref no. 549608

Dear Fievel Foo and Eileen Ang,

GOLDBELL Engineering and MISG have a very strong business relationship and we dearly cherish it. Therefore I feel no need to follow NIMA Protocol wasting your time.

We go for 3rd party claim - direct settlement. (Attached is the estimate)

Please arrange your surveyor to meet us on coming Monday morning at GOLDBELL Pandan BLK K PANDAN LOOP IND EST #01-12 S(128230).

Feel free to call

Ms. Sya Sya @ 8481 4099 or

Mr. Ramesh @ 8157 8014


Also be informed we are close tomorrow 15 Feb and be back to office on Monday 19 Feb.

Best Regards,

May Best and Most Heartfelt Wishes on Your Way

This Coming Chinese New Year
Wishing You a Peaceful and Blessed New Year.

Gong Xi Fa Cai



GOLDBELL
ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

Ramesh S/O Somasundrem | Goldbell Engineering Pte Ltd
Senior Executive, Motor Claims

DID: +65 6864 0695 | Tel: +65 6861 0007 | Fax: +65 6863 0425 |
Mobile: +65 8157 8014 | Web: <http://www.goldbell.com.sg>
Address: Goldbell Engineering Pte Ltd (Tanjong Penjuru)
29 Tanjong Penjuru Singapore 609026

Sales | Leasing | Financing | Insurance | Fuel Card | Advanced Fleet Management System

GOLDBELL
ENGINEERING
Industrial Vehicles.
20,000 Served. And Counting.

Booking Hotline
6864 0698
www.goldbell.com.sg

Our Service Centre is located
29 Tanjong Penjuru
Singapore 609026

From: Fievel Foo [mailto:Fievel_Foo@sg.msig-asia.com]

Sent: Wednesday, February 14, 2018 4:46 PM

To: Chua Syahirul Syazwani Binte Irwan <ChuaSyaSya@goldbell.com.sg>

Cc: Ramesh S/O Somasundrem <Ramesh@goldbell.com.sg>; Andy Ooi Lee Keong <AndyOoiLK@goldbell.com.sg>; Eileen Ang <eileen_ang@sg.msig-asia.com>

Subject: RE: Accident case between SKQ3787Z(SOMPO) and XD5479P(MSIG) at JALAN AHMAD IBRAHIM TOWARDS JURONG PORT ROAD claim ref no. 549608

Without Prejudice

Dear Syahirul

We are agreeable with direct settlement under MCF.

Thanks & regards

Fievel Foo Wenyao

Executive, Claim Services (Motor)

Direct line +65 6643 1316 | Direct fax +65 6225 7402 | Fievel_foo@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/>

A member of **MS&AD** INSURANCE GROUP

MS&AD Insurance Group | 2011 General Insurance Company of the Year | Asia Insurance Industry Awards

From: Chua Syahirul Syazwani Binte Irwan [mailto:ChuaSyaSya@goldbell.com.sg]

Sent: Wednesday, February 14, 2018 11:53 AM

To: Claims <claims@sg.msig-asia.com>

Cc: Ramesh S/O Somasundrem <Ramesh@goldbell.com.sg>; Andy Ooi Lee Keong <AndyOoiLK@goldbell.com.sg>

Subject: Accident case between SKQ3787Z(SOMPO) and XD5479P(MSIG) at JALAN AHMAD IBRAHIM TOWARDS JURONG PORT ROAD

Dear MSIG INSURANCE,

Enclose here with Form 1 and GIA report for your necessary action.

Please revert within 2 working days.

Fyi, the vehicle is at GOLDBELL PANDAN, BLK K PANDAN LOOP IND EST #01-12 S(128230).

Best Regards.

Chua Syahirul Syazwani Binte Irwan | Goldbell Engineering Pte Ltd
Customer Service Advisor, Motor Claims

DID: +65 6458 9596 | Tel: +65 6458 9596 | Fax: +65 6458 7172 |
Mobile: | Web: <http://www.goldbell.com.sg>
Address: Goldbell Engineering Pte Ltd (Ang Mo Kio)
Blk 5035 Ang Mo Kio Industrial Park 2, #01-345
Singapore 569538

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 26 Feb 2018

Preliminary Advice

Insured Vehicle No : XD5479P

TP Vehicle No : SKQ3787Z

Make : AUDI A4

Date of Inspection : 20/02/2018

Inspection At : GOLDBELL ENGINEERING PTE LTD (PANDAN)
BLK K, PANDAN LOOP INDUSTRIAL ESTATE, #01-12
SINGAPORE 128219

Accident Date : 13/02/2018

Assignment Date : 14/02/2018

Est. Duration of Repair : 5.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,260.50
Revised Amount	:S\$	3,328.50
Check Items (Estimated)	:S\$	80.00
Total	:S\$	3,408.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6236E
Vehicle Details	
Vehicle No.:	SKQ3787Z
Vehicle to be Exported:	No
Intended De-registration Date:	26 Feb 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.8 TFSI MU
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	CDH142046
Chassis No.:	WAUZZZ8K0CA021496
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$31,669.00
Original Registration Date:	29 Sep 2011
First Registration Date:	29 Sep 2011
Transfer Count:	1
Actual ARF Paid:	\$31,669.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Sep 2021
PARF Rebate Amount:	\$20,584.00
Intended COE Rebate Details	
COE Expiry Date:	28 Sep 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$62,502.00
COE Rebate Amount:	\$22,431.00
Total Rebate Amount:	\$43,015.00

The information contained herein is correct as at 26 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/02/2018 16:49
Date Of Accident	13/02/2018 14:30
Exact Location Of Accident	ALONG JALAN AHMAD IBRAHIM TOWARD JURONG PORT ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ3787Z
Insured/Policyholder	
Name Of Registered Owner	SREEDEVAN S/O ANDOOR RAVINDRAN
NRIC No	S8126236E
Email Address	ANDOORRAVINDRAN.SREEDEVAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-87526414
Alternative Phone No	OFFICE-98372358

Vehicle Particulars

Manufacturer	AUDI
Model	A4-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01006341
Cover Note Number	

Driver

Name of Driver	SREEDEVAN S/O ANDOOR RAVINDRAN
NRIC No	S8126236E
Date Of Birth	25/08/1981
Occupation	INDOOR
Date Of Driving Pass	12/03/2009
Driving Experience	8 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87526414
Fax Number	
Contact Number	OFFICE-98372358
Email Address	ANDOORRAVINDRAN.SREEDEVAN@GMAIL.COM

Address

28 WOODLANDS CRESCENT #11-19 SINGAPORE 738085

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

KINDLY REFER TO ATTACHED SKETCH PLAN -1

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XD5479P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver CHAN WAI CHOONG

NRIC/Passport Number S0170194J

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
 Date & Time: 13/02/2018
 1700

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 13/02/2018
 1700

Reporting Centre Personnel's Signature
 Name: GUY KEOH
 NRIC/FIN No.:


Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was traveling along Jalan Ahmad Ibrahim on the left most lane. Vehicle number XD 5479P abruptly changed lane and hit my back ~~side~~ side and has caused extensive damage from the right back passenger door to the rear bumper and lights.


Accident Date : 13/02/2018
Time : 14 30 Hrs.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time: 13/02/2018
1700 Hrs



Driver's Signature
(If driver is not the policyholder)
Date & Time: 13/02/2018
1700 Hrs.



Reporting Centre Personnel's Signature
Name: GO LEE WEON
NRIC/FIN No.:

Identity card & Driving licence Pg. 1

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3A Motor cars without clutch pedals (Auto) ≤3000kg
with ≤7 passengers, exclusive of the driver, and
other motor vehicles without clutch pedals ≤2500kg

PASS DATE 12 Mar 2012

NP 428A

Licence No: S8126236E

4904403

NRIC No: S8126236E

Date of issue 12-11-2012

28 WOODLANDS CRESCENT #11-19
SINGAPORE 738085

NRIC No: S8126236E Date: 22/04/2013 No: 7315997

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S8126236E

Name: SREEDEVAN S/O ANDOOR RAVINDRAN

Birth Date: 25 Aug 1981

Issue Date: 12 Mar 2009

001715300J

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8126236E

Name: SREEDEVAN S/O ANDOOR RAVINDRAN

Race: MALAYALEE

Date of birth: 25-08-1981

Country of birth: SINGAPORE

Sex: M

S8126236E

Certificate of insurance Pg. 1

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3A Motor cars without clutch pedals (Auto) <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles without clutch pedals <= 2500kg

PASS DATE 12 Mar 2012

NP 428A



4804403

NRIC No: S8126236E

Date of issue 12-11-2012

23 WOODLANDS CRESCENT #11-19
SINGAPORE 738085

NRIC No: S8126236E Date: 22/04/2013 No: 7315997

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S8126236E

Name: SREEDEVAN S/O ANDOOR RAVINDRAN

Birth Date: 25 Aug 1981

Issue Date: 12 Mar 2009

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8126236E

Name: SREEDEVAN S/O ANDOOR RAVINDRAN

Race: MALAYALEE

Date of birth: 25-08-1981

Country of birth: SINGAPORE

Sex: M

8126236E

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





GOLDBELL ENGINEERING

GOLDBELL ENGINEERING PTE LTD

Main Office: 10 Tuas Avenue 18 Singapore 638894 Tel: 6861 0007 Fax: 6861 3676

Finance: 18 Tuas Avenue 10 Singapore 639142 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

Industrial Vehicles.

20,000 Served. And Counting.

DATE : 14/2/2018

TO : MSIG INSURANCE

ATTN : MOTOR CLAIMS DEPT

OFFICE / MOBILE :

EMAIL ADDRESS :

FROM : GOLDBELL ENGINEERING PTE LTD (PANDAN)

ATTN : CHUA SYASYA

MOBILE/ EMAIL : 8481 4099

FAX NO. : 6581 9237

VEHICLE NO. : SKQ3787Z

MODEL NO. : AUDI A4 1.8 TFSI MU

CHASSIS NO. : WAUZZZ8K0CA021496

ENGINE NO. : CDH142046

REG. DATE : 29/9/2011

REF. NO. : GBP/SVC/SALES-

D.O.A. : 13/2/2018

POLICY NO. : D17MTPV01006341

CLAIM TYPE : TP CLAIM

WORKSHOP : BLK K PANDAN LOOP IND EST #01-12 S(128230)

S/N	PART NO.	DESCRIPTION	QUANTITY	PRICE
1		REAR BUMPER	1	\$ 550.00 MIS
2		REAR BUMPER SIDE RETAINER RH	1	\$ 15.00
3		REVERSE SENSOR	1	\$ 360.00 X
4		REAR BUMPER BRACKET RH	1	\$ 85.00
5		REAR BUMPER INNER PLASTIC REINFORCEMENT	1	\$ 220.00 X
6		REAR FENDER RH	1	\$ 1,000.00
7		REAR FENDER INNER SHEILD RH	1	\$ 85.00
8		TAILLAMP RH	1	\$ 130.00 CRA

TOTAL :	\$ 2,445.00
LESS 10% :	\$ 244.50
PARTS TOTAL :	\$ 2,200.50

SPECIAL-NETT ITEMS

1	REAR BUMPER REVERSE SENSOR ASSY (4PCS)	1	\$ 480.00
2	REAR WINDSCREEN GLASS SEALANT	1	\$ 50.00
3	REAR WINDSCREEN GLASS INNER SEAL	1	\$ 30.00

SPECIAL-NETT TOTAL :	\$ 560.00
----------------------	-----------

LABOUR CHARGES

1	TO REMOVE & REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	1	\$ 1,400.00
2	TO CHECK FOR & RECTIFY WIRING FAULT, ETC	1	\$ 100.00
3	TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC	1	\$ 900.00
4	RUST PROOFING	1	\$ 100.00
5	TO REMOVE & REFIT REAR WINDSCREEN GLASS TO ASSIST REPAIRS	1	\$ 120.00
6	TOWING CHARGES	1	\$ 80.00

LABOUR TOTAL :	\$ 2,700.00
----------------	-------------

TOTAL :	\$ 5,280.50
7% GST :	\$ 368.24
GRAND TOTAL :	\$ 5,628.74

bizSAFE

ST R



Certificate No. AJA150101243 Certificate No. AJA150101243



GOLDBELL ENGINEERING

GOLDBELL ENGINEERING PTE LTD

Main Office: 10 Tuas Avenue 18 Singapore 638894 Tel: 6861 0007 Fax: 6861 3676

Finance: 18 Tuas Avenue 10 Singapore 639142 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg. No.: 199003963G

Industrial Vehicles.

20,000 Served. And Counting.

PREPARED BY : CHUA SYASYA

DATE / TIME : 20/02/18 @ 1610 hrs

SURVEYOR : RASUL

MOBILE NO. : 90010068

OFFICE FAX NO. :

EMAIL ADDRESS : rasul@lkkauto.com

REPAIR TYPE : PART-BY-PART / LUMPSUM

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 5 days

REMARKS :

[Handwritten signature]
21/2/18

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

bizSAFE
STARS



Certificate No: AJA(S)1Q1243

Certificate No: AJA17884

CASH SALES / INVOICE



JOO KEONG TOWING SERVICE

Blk 424 #01-235 Bukit Batok West Ave 2, Singapore 650424

DID: 6563 5620 Office: 6566 8259 Fax: 6563 3054

Email: jookeong@singnet.com.sg

Reg. No. 464097008

SAT

No.

Date: 13/2/18

有號

Messrs

PUAN CHEW MOTOR

車號

Vehicle No.

SKQ 3787 Z

車型

Model No.

Audi A4

由

From:

22 JIN Terusan

到

To:

Pandan Loop

時間(日/夜)

Time (day / night)

15:30pm

15:40pm

16:05pm

其他

Other

CASH

50+

CHEQUE

ADDITIONAL SERVICES:

- | | | | | |
|---|--|---|--|---|
| <input type="checkbox"/> Accident Case | <input type="checkbox"/> Release Brake | <input type="checkbox"/> Dismantle Shaft | <input type="checkbox"/> Sunday / P.Holiday | <input type="checkbox"/> Low Bumper Spoiler |
| <input type="checkbox"/> Multi Storey Car Park | <input type="checkbox"/> Basement Car Park | <input type="checkbox"/> Jump Start | <input type="checkbox"/> Stand by / Waiting Time | <input type="checkbox"/> Collection Car Key |
| <input type="checkbox"/> Using King Dolly | <input type="checkbox"/> Use Car Carrier | <input type="checkbox"/> Change Type & Towing | <input type="checkbox"/> Mid-Night Service | <input type="checkbox"/> Use Winch |
| <input type="checkbox"/> Laded Cargo | <input type="checkbox"/> Unloading Cargo | <input type="checkbox"/> Door Opening Service | <input type="checkbox"/> Cancellation of Service | <input type="checkbox"/> Over Turn |
| <input type="checkbox"/> Jurong Island & PSA Port | <input type="checkbox"/> Sentosa & Cargo Complex | <input type="checkbox"/> Causeway / 2nd Link | <input type="checkbox"/> Transport Charged | <input type="checkbox"/> Crane Up |

ERP Charged \$

Car Parking Charged \$

Note: Vehicle is towed to nearest safe place. The company is not responsible for any damage to the vehicle or its contents during towing.

收貨人

Received by

Mobile No:

經手人

Issued by

Vehicle No:

7.221

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003127/R1RD3N2

Date: 17/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B28670147MKC
Claimant Vehicle No :	SKQ3787Z	Insured Vehicle No :	XD5479P
Date of Loss:	13/02/2018	Nature of Claim:	TP
		Claim No:	549608

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ3787Z	Engine No:	CDH142046
Make & Model:	AUDI A4, 1.8 (A)	Chassis No:	WAUZZZ8K0CA021496
Reg. Date:	29/09/2011 (Man. Year: 2011)	Odometer:	162637 km
Colour:	Black		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,760.50	2,008.50	752.00	27.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,370.00	1,330.00	49.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,460.50	3,378.50	2,082.00	38.13
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	5,460.50	2,600.00	2,860.50	52.39
+ GST 7.00/7.00% (S\$)	382.24	182.00	200.24	52.39
Nett Amount (S\$)	5,842.74	2,782.00	3,060.74	52.39

INSPECTION

Date of Assignment: 14/02/2018

Date Inspected: 20/02/2018 Inspected At:

Goldbell Engineering Pte Ltd (Pandan)
Blk K, Pandan Loop Industrial Estate,
#01-12
Singapore 128219

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2018)
Parts: 143	AUDI A4 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKQ3787Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Missing	550.00 FL	*550.00 FL
2	1	*REAR BUMPER SIDE RETAINER RH	Necessary	15.00 FL	*15.00 FL
3	1	*REVERSE SENSOR	Not Necessary	360.00 FL	*- FL
4	1	*REAR BUMPER BRACKET RH	Cracked	85.00 FL	*85.00 FL
5	1	*REAR BUMPER INNER PLASTIC REINFORCEMENT	Not Necessary	220.00 FL	*- FL
6	1	*REAR FENDER RH	Bent	1,000.00 FL	*1,000.00 FL
7	1	*REAR FENDER INNER SHIELD RH	Deformed	85.00 FL	*85.00 FL
8	1	*TAILLAMP RH	Cracked	130.00 FL	*130.00 FL
9	1	*REAR BUMPER REVERSE SENSOR ASSY (4 PCS)	Not Working	480.00 FS	*250.00 FS
10	1	*REAR WINDSCREEN GLASS SEALANT	Necessary	50.00 FS	*50.00 FS
11	1	*REAR WINDSCREEN GLASS INNER SEAL	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,005.00	2,195.00
- List Item Discount on L Items 10.00/10.00% (S\$)	244.50	186.50
Total Parts (S\$)	2,760.50	2,008.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT DAMAGED PARTS,CUT,WELD,PANEL BEAT,STRAIGHTEN & REALIGN ETC	New	1,400.00	600.00
2	TO CHECK FOR & RECTIFY WIRING FAULT,ETC	New	100.00	60.00
3	TO PUTTY,CLEAN,SPRAY PAINT & POLISH,ETC	New	900.00	500.00
4	RUST PROOFING	New	100.00	40.00
5	TO REMOVE & REFIT REAR WINDSCREEN GLASS TO ASSIST REPAIRS	New	120.00	120.00
6	TOWING CHARGES	New	80.00	50.00
Gross Labour Cost (S\$)			2,700.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >