


ASS. REC. BY:



Survivor
Menmen
From (Person)

Rahul
Muhd Ashik

ASSIGNMENT (Office)



Estimated Cost: _____ Bill to: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SLM39D Insured: SJR 9019A

at Workshop m/s: Weelmes Automotive Tel: 8126 1237

of: 249 Alexandra Rd

Policy No: A29063462 TMP Claim No: 549413

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 10/02/18

(Client's Record) 20/02/2018 @ Morning; 45 Jeng Kee Rd.

CA / REV / REP. / REV 24 HRS ^{wp} H.O.D. Endorsment: _____

Date/Time: 17/2/18 @ 11am Person Contacted: Paul Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJM 39D - X
	SJR 9019A - r06 / CII 17018124 / Aeb352
	D.O.A.: 23/9/2017
23/2/18	Send preli revised by menmen

MS119

MS119

94032

ASSIGNMENT

Date 20/02/18


TP WE/TP RES/DO RES/EVA/INV/ MV

To inspect vehicle No: SLM 39D
at Workshop No: Wearnes Automotive
15 Long Kee Rd

Insured: _____
Policy No: _____
Claim No: _____

Subscribed: _____ Excess: _____
Client Record: Morning paul
Make of Van: _____

Policy Condition: Remain. The van had commenced its repair at the time of inspection.



Est. of Vehicle Value: _____
C/O Accident Room: _____ Consistent? Yes or No
C/O PR Seen: _____ Consistent? Yes or No
Est. Repair: _____ days Fee: _____ Yes or No
Lift Sum: _____ by _____ 3 val: Yes or No

24 HRS REP. 24 HRS hrs
Date: _____ Person Contacted: _____
Vehicle IN/OUT

Table with 2 columns: Date/Time, Action/Instruction

Vehicle: SLM 390
Type: 2014 maxy
Track: Trailer

Make: JAGUAR XJ 2.0 TSD 1999
Color: MAROON
Seating: 75610

Eng No: _____
Chassis: SAJAC12M2EPV65528

Steering: Jammed/Leaked: _____
Brake: Jammed/Leaked: _____
Mod: STD ARMOR

Tyre Size: F 275/40ZR19
R _____

BS/DUN/EXNOVA/GY/PS/LIZA/MIC/OHTEL/FR/SUM/TOYOT/YOKO

DOB: 6/6/6
DOB: 6/6/6
C/O: 10/02/18
C/O: 20/02/18
Surveyed by: WEARNES

Des. of Damage: Fr _____ CS _____ NS _____ UC _____
The U/C Chassis frame Body Structure affected could be for

RECEIVED 2-5 MAR 2018

Cost The Fix Pass: Prel. Report
 Final Report

Days Of Repair: 3
Resurvey No. of Trc: 1
Surv Fee: _____

x/3- typst
Record Return: merimen
Lift Sum: P/P \$ 9714.98

Add Fee:

Survey Department Check List (Case Handler)

Reference No. : CS | MSG | 800 3131 | R/vc/3
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (_____ **):** Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (_____ **):** Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 26/3/18
 Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003131/R1vd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 19-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJR 9019A	Veh. Inspected	SLM 39D
Policy No.	A29063462TMP	Coverage (\$)	0.00
Claim No.	549413	Excess (\$)	0.00
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	19/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/02/2018	Inspection Date	
Survey held at	45 LENG KEE ROAD		
Repairer	WEARNES AUTOMOTIVE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Feb 2018		19 Feb 2018 10:34 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	CHUA IDRIS MOHD SHAFIQ, ID: S8311081C, Tel: +6592217206, Email: chua_idris_mohd_shafiq@moe.edu.sg		
Main Claimant:	SUPERIOR LINK MARKETING PTE LTD, Co. Reg. No.: 201409403R		
Vehicle Reg. No.:	SLM39D	Date of Loss:	10/02/2018 12:00 - :59
Claim Type:	TP / 549413	Policy/Cover Note No.:	A29063462TMP (Third Party Only) Coverage: 20/12/2017 - 19/12/2018
Vehicle Reg. No. (Insured):	SJR9019A	Policy No. (Claimant):	
		Excess:	
Repairer:	Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road, 159935 Alexandra - Tel: 63789370		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muid Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/02/2018]		
Driver/Custodian (Insured):	CHUA IDRIS MOHD SHAFIQ (34 / Male), NRIC: S8311081C, Tel: +6592217206		
Adj Asg. Remarks:	kindly arrange for a survey after 11am on 20th Feb, venue is at 45 Leng Kee		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Muhd Ashik B Madi

From: Muhd Ashik B Madi
Sent: Tuesday, 13 February, 2018 11:13 AM
To: 'paul.ong@wearnes.com'
Cc: Eileen Ang
Subject: RE: TP Claim - SLM39D; TP Vehicle SJR9019A (MSIG ref: 549413)

Sensitivity: Confidential

Dear Paul,

BOLA chain collision is applicable & we are prepared for a direct settlement.

Kindly allow our surveyor to survey your client's vehicle.

Thank you.

Ashik Madi

Executive, Claims Services (Motor)

Direct line +65 6594 2548 | Direct fax +65 6225 7402 | ashik_madi@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Paul Ong Qing Yong [<mailto:paul.ong@wearnes.com>]

Sent: Monday, February 12, 2018 5:50 PM

To: Claims <claims@sg.msig-asia.com>

Subject: TP Claim - SLM39D; TP Vehicle SJR9019A

Sensitivity: Confidential

Hi,

Attached for TP Claim,

Kindly advise if direct settlement is possible.

Best Regards,

Paul Ong

Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 8126 1237 D (65) 6378 9336
www.wearnesauto.com paul.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Muhd Ashik B Madi	
Date: 23 Feb 2018	
<u>Preliminary Advice</u>	

Insured Vehicle No : SJR9019A	
TP Vehicle No : SLM39D	Accident Date : 10/02/2018
Make : JAGUAR XJ	Assignment Date : 19/02/2018
Date of Inspection : 20/02/2018	Est. Duration of Repair : 3.00
Inspection At : WEARNES AUTOMOTIVE PTE LTD (ALEXANDRA ROAD) 249 ALEXANDRA ROAD SINGAPORE 159935	

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,902.00
Revised Amount	:S\$	8,987.20
Check Items (Estimated)	:S\$	6,314.80
Total	:S\$	15,302.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1277226B



Name
LING YEW TECK
林友德
Race
CHINESE
Date of Birth
28-05-1957 Sex
M
Country of Birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: **S1277226B**
Name
LING YEW TECK
Valid Date: **28 May 1957**
Issue Date: **16 Jun 2017**

002694786J

0440470



Ident. No. **S1277226B**

Medical Group: **D+** Date of issue: **23-07-1992**

33 PAVILION VIEW
SINGAPORE 658453
NRC No: **S1277226B** Date: **26/04/2012** No: **7057861**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

CLASS	VEHICLE CLASSIFICATION	EFFECTIVE DATE
Class 3A	Motor cars without clutch pedals (Auto) with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight \leq 2500kg	16 Jun 2017

License No: S1277226B



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/02/2018 14:27
Date Of Accident	10/02/2018 12:00
Exact Location Of Accident	PIE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM39D
Insured/Policyholder	
Name Of Registered Owner	SUPERIOR LINK MARKETING PTE LTD
Co Reg No	201409403R
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96739028
Alternative Phone No	OFFICE-96739028

Vehicle Particulars

Manufacturer	JAGUAR
Model	XJ-2.0 TSS (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5090974034 (PREMIUM)
Cover Note Number	

Driver

Name of Driver	LING YEW TECK
NRIC No	S1277226B
Date Of Birth	28/05/1957
Occupation	OUTDOOR
Date Of Driving Pass	16/06/2017
Driving Experience	0 YEAR AND 7 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96739028
Fax Number	
Contact Number	OFFICE-96739028
EMail Address	NOEMAIL

Address	39 PAVILION VIEW
Postcode	S658453
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN. ATTENDED BY : SUSAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR9019A
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHUA IDRIS MOHD SHAFIQ
NRIC/Passport Number	S8311081C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJH5992T
Vehicle Make/Model/Colour	HONDA FIT

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

TAN KOK MENG

NRIC/Passport Number

F1798666W

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

SUPERIOR LINK MARKETING PTE. LTD.



Policyholder's Signature
Date & Time:




Driver's Signature
(if driver is not the policyholder)
Date & Time:

10 FEB 2018

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: accident@idac.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 10 February 2018 at about 12pm, I was driving from PIE to Changi (before Thomson Road Exit Lane One) I was the first car. The second car SJR 9019A bump into my car back. And the 3rd car SJH 5992 T bump into the 2nd car. My car plate number is SLM39D.

IBAC BUKIT BATOK (VAC)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

SUPERIOR LINK MARKETING PTE. LTD.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Handwritten Signature]
10 FEB 2018

IBAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SERVICE ESTIMATE

81890 - C00001 SL: SERVICE SALES - PC

Superior Link Marketing Pte. Ltd.
120 Hillview Avenue
#03-01/3 Kewalram Hillview

Singapore 669594

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1

Inv.date. : 12/02/2018

WIP No. . : 45143

Veh.In/Out:

*Tel.No. . : Mobile: 81277217 MsLi

Reg.No. . : SLM39D

Reg.date . : 15/05/2014

Mileage . : 0

Chassis No: SAJAC12M2EPV65528

Closed by . . . : Paul Ong Qing Yong
Svc Consultant :
Remarks : Superior Link Market

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BUMPER, BUMPER UNDERTRAY, REVERSE SENSORS, BUMPER BEAM	0	4800.00	0		4,800.00 S 1200 ✓	
800	TO PUTTY SPRAYPAINT ON REAR BUMPER, BOOTLID, ETC	0	3000.00	0		3,000.00 S 2000 ✓	
802	TO REPLACE REAR EXHAUST ASSY	0	2400.00	0		2,400.00 S 1200? x n	
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00 S ✓	
R06	NUMBER PLATE & HOLDER	0	60.00	0		60.00 S CR ✓	
1	BUMPER COVER REAR XJ 2295.81	1.0 EA	2380.80			2,380.80 S DE ✓	
2	BUMPER MOULDING CHRO 32103	1.0 EA	301.90			301.90 S ✓	
3	BUMPER BRACKET REAR	1.0 EA	84.40			84.40 S ? x } see	
4	BUMPER BRACKET REAR	1.0 EA	84.40			84.40 S ? x } see	
5	BUMPER BRACKET REAR	1.0 EA	37.80			37.80 S ? x } see	
6	BUMPER BRACKET REAR	1.0 EA	37.80			37.80 S ? x } see	
7	BUMPER SHIELD REAR X 34164	1.0 EA	321.20			321.20 S see ✓	
8	BUMPER BEAM REAR XJL 124416	1.0 EA	1290.20			1,290.20 S ? ✓ PA ✓	

SERVICE ESTIMATE

81890 - C00001 SL: SERVICE SALES - PC
 Superior Link Marketing Pte. Ltd.
 120 Hillview Avenue
 #03-01/3 Kewalram Hillview

Singapore 669594

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 2
 Inv.date. : 12/02/2018
 WIP No. . : 45143
 Veh.In/Out:
 *Tel.No. . : Mobile: 81277217 MsLi
 Reg.No. . : SLM39D
 Reg.date. : 15/05/2014
 Mileage . : 0
 Chassis No: SAJAC12M2EPV65528

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Superior Link Market

Op.No Description Mech Qty Price Disc% Pkg Amount G

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
9	PARKING AID 90 Degre ^(13 pcs)		1.0	264.70			1,058.80	S
10	SILENCER-EXH RH ^{476.46}	EA	1.0	774.50			774.50	S
11	SILENCER-EXH LH	EA	1.0	877.50			877.50	S
12	EXHAUST FINISHER DPF	EA	1.0	364.10			364.10	S
13	EXHAUST FINISHER DPF	EA	1.0	364.10			364.10	S
14	ADHESIVE SEALER FL2 ^{382.56}	EA	1.0	358.30			358.30	S
15	BODY PANEL SEALANT X ^{790.92}	EA	1.0	820.20			820.20	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
Labour Total 10,746.00
Parts Total 9,156.00
Package Total 0.00

Handwritten notes:
 23/2/18
 Reay b4 part
 20,061.79
 3 days
 20/02/18 @ 1135
 Paper
 Hp 90010068

Gross Total.	19,902.00
Net.....	19,902.00
GST @ 7.0%	1,393.14
Total.....	21,295.15
Paid.....	0.00
Please Pay..	21,295.15

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - A00003	SL: MSIG INSURANCE (SINGAPORE) PTE. LTD	GST Reg.No:M28920628X
MSIG INSURANCE (SINGAPORE) PTE. LTD.		0 Page 1
4 SHENTON WAY #21-01	Inv.No. . : B&P	
SGX CENTRE 2	Inv.date. : 26/03/2018	
SINGAPORE 068807	WIP No. . : 45143	
	Veh.In/Out: 20/02/2018 02/03/2018	
	*Tel.No. . : 68277888	
	Reg.No. . : SLM39D	
Closed by : Paul Ong Qing Yong	Reg.date . : 15/05/2014	
Svc Consultant : ACC	Mileage .. : 75,610	
Remarks : Superior Link Market	Chassis No: SAJAC12M2EPV65528	

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BUMPER, BUMPER UNDERTRAY, REVERSE SENSORS	0	1200.00	0		1,200.00	S
800	TO PUTTY SPRAYPAINT ON REAR BUMPER, BOOTLID, ETC	0	2000.00	0		2,000.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00	S
R06	NUMBER PLATE & HOLDER	0	60.00	0		60.00	S
	BUMPER COVER REAR XJ	1.0 EA	2550.90	10		2,295.81	S
	BUMPER MOULDING CHRO	1.0 EA	356.70	10		321.03	S
	BUMPER SHIELD REAR X	1.0 EA	379.60	10		341.64	S
	ADHESIVE SEALER FL2	1.0 EA	425.40	10		382.86	S
	BODY PANEL SEALANT X	1.0 EA	878.80	10		790.92	S
	PARKING AID 90 Degre	2.0 EA	264.70	10		476.46	S
	BUMPER BEAM REAR XJL	1.0 EA	1382.40	10		1,244.16	S
	BULB SIDELAMP 5W CLE	2.0 EA	3.60	10		6.48	S ^{spec}
	NUMBER PLATE LAMP BA	2.0 EA	60.90	10		109.62	S ^{spec}

Gross Total. 9,714.98

Labour Total	3,746.00	Net.....	9,714.98
Parts Total	5,968.98	GST @ 7.0%	680.05
Package Total	0.00	Total.....	10,395.03
		Paid.....	0.00
		Please Pay..	10,395.03

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Supp

SERVICE ESTIMATE

0 - A00003 SL: MSIG INSURANCE (SINGAPORE) PTE. LTD
 MSIG INSURANCE (SINGAPORE) PTE. LTD. GST Reg.No:M28920628X
 4 SHENTON WAY #21-01 Inv.No. . : B&P 0 Page 1
 SGX CENTRE 2 Inv.date. : 26/03/2018
 SINGAPORE 068807 WIP No. . : 45143
 Veh.In/Out: 20/02/2018 02/03/2018
 *Tel.No. . : 68277888
 Reg.No. . : SLM39D
 Closed by : Paul Ong Qing Yong Reg.date .: 15/05/2014
 Svc Consultant : ACC Mileage ..: 75,610
 Remarks : Superior Link Market Chassis No: SAJAC12M2EPV65528

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BULB SIDELAMP SW CLE	2.0 EA	3.60	10		6.48	S <i>NK Ban</i>
	NUMBER PLATE LAMP BA	2.0 EA	60.90	10		109.62	S <i>gao</i>

			Gross Total.			116.10	
Labour	Total	0.00	Net.....			116.10	
Parts	Total	116.10	GST @ 7.0%			8.13	
Package	Total	0.00	Total.....			124.23	
			Paid.....			0.00	
			Please Pay..			124.23	

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 26 March 2018 10:40 AM
To: Paul Ong Qing Yong; Rasul (LKKAuto)
Cc: SUR
Subject: RE: SLM39D Finalise

Sensitivity: Confidential

Dear Paul,

Confirmed finalize amount \$9714.98 before GST

No of days: 3 days

Final invoice and all supporting documents sent over to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Paul Ong Qing Yong [mailto:paul.ong@wearnes.com]
Sent: Monday, 26 March 2018 8:56 AM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: SLM39D Finalise
Sensitivity: Confidential

Attached for finalise

Best Regards,

Paul Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 8126 1237 D (65) 6378 9336
www.wearnesauto.com paul.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Feb 2018		19 Feb 2018 10:34 Edit Adj Rpt	S\$9,714.98 Edit Estimates	S\$9,714.98 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	CHUA IDRIS MOHD SHAFIQ , ID: S8311081C, Tel: +6592217206, Email: chua_idris_mohd_shafiq@moe.edu.sg								
Main Claimant:	SUPERIOR LINK MARKETING PTE LTD , Co. Reg. No.: 201409403R								
Vehicle Reg. No.:	SLM39D	Date of Loss:	10/02/2018 12:00 - :59						
Claim Type:	TP / 549413	Policy/Cover Note No.:	A29063462TMP (Third Party Only) Coverage: 20/12/2017 - 19/12/2018						
Vehicle Reg. No. (Insured):	SJR9019A	Policy No. (Claimant):							
		Excess:							
Repairer:	Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road, 159935 Alexandra - Tel: 63789370								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 21/03/2018]								
Driver/Custodian (Insured):	CHUA IDRIS MOHD SHAFIQ (34 / Male) , NRIC: S8311081C, Tel: +6592217206								
Adj Asg. Remarks:	kindly arrange for a survey after 11am on 20th Feb, venue is at 45 Leng Kee								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLM39D (549413)
[SJR9019A]
TP
SUPERIOR LINK MARKETING PTE LTD
Feb 10 2018 12:00PM
[CHUA IDRIS MOHD SHAFIQ]
Wearnes Automotive Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print		
1	13/02/18 09:52	Accident Statement From:SC - Reg. No: SJR9019A, Claimant: CHUA IDRIS MOHD SHAFIQ		 Load HTM	<input type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	23/02/18 14:09	Adjuster Immediate Advice		 Load HTM	<input type="checkbox"/>		
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
2	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
3	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
4	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
5	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
6	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
7	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
8	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
9	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
10	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
11	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
12	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
13	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
14	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
15	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
16	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
17	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
18	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
19	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
20	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
21	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
22	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
23	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
24	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
25	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
26	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
27	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
28	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
29	23/02/18 14:12	General View		 Load JPG	<input checked="" type="checkbox"/>		
30	23/02/18 14:12	General View		 Load JPG	<input type="checkbox"/>		

					<input checked="" type="checkbox"/>
31	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
32	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
33	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
34	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
35	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
36	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
37	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
38	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
39	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
40	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
41	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
42	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
43	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
44	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
45	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
46	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
47	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
48	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
49	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
50	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
51	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
52	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
53	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
54	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
55	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
56	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
57	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
58	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
59	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
60	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
61	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
62	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
63	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
64	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
65	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
66	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
67	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
68	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
69	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
70	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
71	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
72	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
73	23/02/18 14:12	General View	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
74	26/03/18 10:32	Reinspection Photo	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
75	26/03/18 10:32	Reinspection Photo	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
76	26/03/18 10:32	Reinspection Photo	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
77	26/03/18 10:32	Reinspection Photo	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
78	26/03/18 10:32	Reinspection Photo	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>
79	26/03/18 10:32	Reinspection Photo	<input checked="" type="checkbox"/>	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	13/02/18 09:52	SLM39D E-FILE Report From: SC - Reg. No: SJR9019A, Claimant: CHUA IDRIS MOHD SHAFTQ		Load PDF	
2	13/02/18 09:56	Estimate		Load PDF	
3	13/02/18 11:13	Email to third party workshop for direct settlement		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/03/18 14:47	SUPPLEMENTARY PART		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003131/R1VD3Q2

Date: 26/03/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A29063462TMP
 Claimant Vehicle No: SLM39D Insured Vehicle No: SJR9019A
 Date of Loss: 10/02/2018 Nature of Claim: TP Claim No: 549413

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM39D
 Make & Model: JAGUAR XJ, 2.0 TSS (A) Engine No: 031013101947204PT
 Reg. Date: 15/05/2014 (Man. Year: 2013) Chassis No: SAJAC12M2EPV65528
 Colour: Maroon Odometer: 75610 km
 Engine Capacity: 1999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/40Z R19 Rear Tyre Size: 275/40Z R19
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,377.10	6,028.98	3,348.12	35.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,686.00	3,686.00	7,000.00	65.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,063.10	9,714.98	10,348.12	51.58
+ GST 7.00/7.00% (S\$)	1,404.42	680.05	724.37	51.58
Nett Amount (S\$)	21,467.52	10,395.03	11,072.49	51.58

INSPECTION

Date of Assignment: 19/02/2018
 Date Inspected: 20/02/2018 Inspected At: 45 LENG KEE ROAD SINGAPORE
 159103
 Repairer: Wearnes Automotive Pte Ltd
 (Alexandra Road)
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2018)
Parts: 143	JAGUAR XJ 2.0 TSS (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM39D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR XJ	Deformed	2,380.80 FS	*2,295.81 FS
2	1		*NUMBER PLATE & HOLDER	Cracked	60.00 FS	*60.00 FS
3	1		*BUMPER MOULDING CHRO	Cut	301.90 FS	*321.03 FS
4	1		*BUMPER BRACKET REAR	Serviceable	84.40 FS	*- FS
5	1		*BUMPER BRACKET REAR	Serviceable	84.40 FS	*- FS
6	1		*BUMPER BRACKET REAR	Serviceable	37.80 FS	*- FS
7	1		*BUMPER BRACKET REAR	Serviceable	37.80 FS	*- FS
8	1		*BUMPER SHIELD REAR X	Scratched	341.64 FS	*341.64 FS
9	1		*BUMPER BEAM REAR XJL	Bent	1,290.20 FS	*1,244.16 FS
10	1		*PARKING AID 90 DEGRE (4 PCS)	Missing (2 PCS ONLY)	1,058.80 FS	*476.46 FS
11	1		*SILENCER -EXH RH	Serviceable	774.50 FS	*- FS
12	1		*SILENCER -EXH LH	Serviceable	877.50 FS	*- FS
13	1		*EXHAUST FINISHER DPF	Serviceable	364.10 FS	*- FS
14	1		*EXHAUST FINISHER DPF	Serviceable	364.10 FS	*- FS
15	1		*ADHESIVE SEALER FL2	Necessary	382.86 FS	*382.86 FS
16	1		*BODY PANEL SEALANT X	Necessary	820.20 FS	*790.92 FS
17	2		*BULB SIDELAMP 5W CLE	Broken	6.48 FS	*6.48 FS
18	2		*NUMBER PLATE LAMP BA	Broken	109.62 FS	*109.62 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 9,377.10 6,028.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER,BUMPER UNDERTRY,REVERSE SENSORS,BUMPER BEAM	New	4,800.00	1,200.00
2	TO PUTTY SPRAYPAINT ON REAR BUMPER,BOOTLID ,ETC	New	3,000.00	2,000.00
3	TO REPLACE REAR EXHAUST ASSY	New	2,400.00	0.00
4	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	486.00	486.00
Gross Labour Cost (\$\$)			10,686.00	3,686.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >