

22/02/2002

ASS. REC. BY:

REF: CS3/CTI18003132/ Sd3er

Special Instruction:

Surveyor:

Menmen

ASSIGNMENT (Office)

From (Person):

Joel Goh

of

CTI

Date/Time:

19/2/18 @ 1:39 pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJX 1798F

Insured:

SLR 948D

at Workshop m/s

Kent Seng Car Services

Tel:

67588367

of

B1K 1017, Yishun Ind. Park A #01-240

Policy No:

BMPCS N3084831700

Claim No:

SNM18D00886C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/2/18

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time:

19/2/18 @ 1:47 pm

Person Contacted:

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (X) Estimate	Repairer scolded 'shut up la you' when I called.
	SJX 1798F - CC3/AIG 11015834 / Avn	D.O.A: 5/8/2011
	SLR 948D - X	
	Dismantle: 23/2/2018	
	After repair: 27/2/2018	

REF:

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

9

days

Res.:

Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

53X1798E

Yr Regn:

2010

May 21

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Teana 2.5 CRT

c.c

2496

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

108130

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1B54J32Z0002108

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F: 225/50R17 Proxes

R: 225/50R17 Bridgestone

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

14/2/18

D.O.I.

21/2/18

Survey held at

Kent Seng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt - Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Estimated repair ~~repair~~ <sup>range</sup> \$10,000 - \$12,000

9 days.

RECEIVED 12 JUN 2018

Date/Time, File Pass to?



Preli. Report

Days Of Repair:

9

1)



Final Report

Resurvey No. of Trip:

2

Date/Time, File Return to?

Survey Fee:

150

Transportation

S + PS \$

Photos

Others

TOTAL

150

Report Format:

PRE

Lump Sum / I.B.I: (\$)

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Feb 2018		19 Feb 2018 13:39 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	NAHALINGAM S/O ANANTHAM, ID: S8603709B		
Main Claimant:	REVATHY D/O KRISHNAMOORTHY, ID: S8202916H		
Vehicle Reg. No.:	SJX1798E	Date of Loss:	14/02/2018 07:00 - :59
Claim Type:	TP / SNM18D00886C02	Policy/Cover Note No.:	DMPCSN3084831700 (Comprehensive)
Vehicle Reg. No. (Insured):	SLR948D	Policy No. (Claimant):	GA205961
		Excess:	S\$0.00
Repairer:	Kent Seng Car Service () Blk 1017 Yishun Industrial Park A, #01-240, 768759 Yishun - Tel: 67588367		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/02/2018]		
Driver/Custodian (Insured):	NAHALINGAM S/O ANANTHAM (32 / Male), NRIC: S8603709B		
Adj Asg. Remarks:	NO EST, CASE W/O SJE		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MALM18022552 / Ah Lim Motor Company - AMK  
 ENTRY DATE & TIME: 14/02/2018 11:03  
 SUBMITTED BY: Eileen Chua

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/02/2018 11:03
Date Of Accident	14/02/2018 07:45
Exact Location Of Accident	OPEN SPACE CAR PARK BLK 322 YISHUN RING RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX1798E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	REVATHY D/O KRISHNAMOORTHY
NRIC No	S8202916H
Email Address	KARTHIG@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-81835292
Alternative Phone No	Others-83223105

### Vehicle Particulars

Manufacturer	NISSAN
Model	TEANA 2.5 CVT ABS D/AB HID 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA205961
Cover Note Number	27/05/2017 - 26/05/2018

### Driver

Name of Driver	KARTHIGESAN S/O MANIAM
NRIC No	S8222672I
Date Of Birth	16/07/1982
Occupation	INDOOR
Date Of Driving Pass	21/07/2005
Driving Experience	12 YEARS AND 6 MONTHS

Gender	MALE
Mobile Number	(LOCAL) +65-83223105
Fax Number	
Contact Number	
EMail Address	KARTHIG@HOTMAIL.COM
Address	BLK 326 YISHUN RING RD #02-1352
Postcode	760326
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER TO THE ATTACHED SKETCH PLAN BY DRIVER.

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SLR948D
Vehicle Make/Model/Colour	
Détails Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name


Nature Of Damage

No. Of Passenger (Including Driver)

**Sketch Plan**

Date of accident: 14/2/18 Time: 7.45am Location: Open Space Carpark at BIK 322 Yishun Ring Rd  
 My Vehicle A: SJX 1798E Vehicle B: SLR 948D Vehicle C: \_\_\_\_\_

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Being the driver of SJX1798E, I was driving straight towards the carpark exit. Then, I was hit by another vehicle, SLR 948D, who was coming out from the small road leading to the main road. Rightfully, the driver of SLR 948D should stop and look out for blind spots but overlooked the situation and turned left. This made the driver hit my left <sup>part</sup> of my car damaging my left wheel, rims, body kit, headlight & my bonnet.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

Email address:

& myself:

Email address: ikarthig@hotmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 14/2/18

10:24am

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

AH LIM MOTOR COMPANY

## SKETCH PLAN



**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 14/2/18

10.24am

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2018		19 Feb 2018 13:39 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	NAHALINGAM S/O ANANTHAM, ID: S8603709B								
Main Claimant:	REVATHY D/O KRISHNAMOORTHY, ID: S8202916H								
Vehicle Reg. No.:	SJX1798E	Date of Loss:	14/02/2018 07:00 - :59 [92 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D00886C02	Policy/Cover Note No.:	DMPCSN3084831700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLR948D	Policy No. (Claimant):	GA205961						
		Excess:	S\$0.00						
Repairer:	Kent Seng Car Service ( ) Blk 1017 Yishun Industrial Park A, #01-240, 768759 Yishun - Tel: 67588367								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 28/02/2018]								
Driver/Custodian (Insured):	NAHALINGAM S/O ANANTHAM (32 / Male), NRIC: S8603709B								
Adj Asg. Remarks:	NO EST, CASE W/O SJE								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

















\*SJX1798E (SNM18D00886C02)  
[SLR948D]

TP  
REVATHY D/O KRISHNAMOORTHY  
Feb 14 2018 7:00AM  
[NAHALINGAM S/O ANANTHAM]  
Kent Seng Car Service

Upload Documents			Upload Photos			Compose New Letter			View <span>View in Browser</span>		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)						Thumbnail	Print		
1	14/02/18 11:38	Accident Statement							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)						Thumbnail	Print		
1	14/02/18 11:36	Accident Photo [Linked Accident Report Documents]							Load JPG <input checked="" type="checkbox"/>		
2	14/02/18 11:36	Accident Photo [Linked Accident Report Documents]							Load JPG <input checked="" type="checkbox"/>		
3	14/02/18 11:36	Accident Photo [Linked Accident Report Documents]							Load JPG <input checked="" type="checkbox"/>		
4	14/02/18 11:36	Accident Photo [Linked Accident Report Documents]							Load JPG <input checked="" type="checkbox"/>		
5	14/02/18 11:36	Accident Photo [Linked Accident Report Documents]							Load JPG <input checked="" type="checkbox"/>		
6	14/02/18 11:36	Accident Photo [Linked Accident Report Documents]							Load JPG <input checked="" type="checkbox"/>		
7	14/02/18 11:36	Accident Photo [Linked Accident Report Documents]							Load JPG <input checked="" type="checkbox"/>		
8	14/02/18 11:36	Accident Photo [Linked Accident Report Documents]							Load JPG <input checked="" type="checkbox"/>		
9	14/02/18 11:36	Accident Photo [Linked Accident Report Documents]							Load JPG <input checked="" type="checkbox"/>		
10	14/02/18 11:36	Accident Photo [Linked Accident Report Documents]							Load JPG <input checked="" type="checkbox"/>		
11	14/02/18 11:36	Accident Photo [Linked Accident Report Documents]							Load JPG <input checked="" type="checkbox"/>		
12	14/02/18 11:36	Accident Photo [Linked Accident Report Documents]							Load JPG <input checked="" type="checkbox"/>		
13	14/02/18 11:36	Accident Photo [Linked Accident Report Documents]							Load JPG <input checked="" type="checkbox"/>		
14	14/02/18 11:36	Accident Photo [Linked Accident Report Documents]							Load JPG <input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	12/06/18 14:27	General View							Load PDF		
2	12/06/18 14:27	Photographs of Damaged Parts							Load PDF		
3	12/06/18 14:27	Photo After Spray							Load PDF		
Documentation									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print		
1	19/02/18 13:38	PRS							Load PDF		
2	19/02/18 13:38	OI GIA REPORT							Load PDF		
No	Finalized On	Ah Lim Motor Company (AMK)						Thumbnail	Print		
1	14/02/18 11:35	Sketch Plan [Linked Accident Report Documents]							Load TIF		

## Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	14/02/18 11:38	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	14/02/18 11:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	14/02/18 11:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	14/02/18 11:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	14/02/18 11:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	14/02/18 11:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	14/02/18 11:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	14/02/18 11:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	14/02/18 11:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	14/02/18 11:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	14/02/18 11:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	14/02/18 11:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	14/02/18 11:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	14/02/18 11:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	14/02/18 11:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (AMK)	Thumbnail	Print
1	14/02/18 11:35	Sketch Plan	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118003132/SD3E2

Date: 14/06/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3084831700

Claimant Vehicle  
No : SJX1798EInsured Vehicle  
No : SLR948D

Date of Loss: 14/02/2018

Nature of Claim: TP

Claim  
No: SNM18D00886C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SJX1798E**Make & Model: NISSAN TEANA, 2.5 CVT ABS D/AB HID 2WD 4DR  
(A)

Engine No: VQ25516495A

Reg. Date: 21/05/2010 (Man. Year: 2009)

Chassis No: JN1BBUJ32Z0002608

Colour: Grey

Odometer: 108130 km

Engine Capacity: 2496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/50 R17

Rear Tyre Size: 225/50 R17

Front Left Side: PROXES 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: PROXES 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 19/02/2018

Date Inspected: 21/02/2018 Inspected At:

Kent Seng Car Service  
Blk 1017 Yishun Industrial Park A, #01-240  
Singapore 768759

Estimated Period of Repair: 9.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Nivitha Govindasamy

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000.00 -\$12,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jun 2018)
<b>Parts:</b>	143	NISSAN TEANA 2.5 CVT ABS D/AB HID 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJX1798E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >