

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC3/MSG18003/41/ur39

MSIC

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimate Cost: \_\_\_\_\_

OD ☒ TP ☒ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. 2809291 QMY

Claims No. 55037

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJR 144E

Yr Regn: 4/6, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Mazda

MX5

c.c

1999

Colour: Grey

A/C:

Insured / Std / NI / NA

Sp. Reading: 79578

T/Radio:

Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JMONC 30F 290200040

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40ZR18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6

Rear: 6

R/Bal. \_\_\_\_\_ mm

R/Bal. \_\_\_\_\_ mm

L/Bal. \_\_\_\_\_ mm

L/Bal. \_\_\_\_\_ mm

D.O.A. 13/2/18

D.O.I. 19/2/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/3/18

Email GIA to Christina Hasriyah

7/6/18

4/5 of 13.800 confirmed with Ather.

Ref: 841, 123.10, 751.

RECEIVED 08 JUN 2018

Date/Time, File Pass to?



: Prel. Report



: Final Report

1) tgsat

Date/Time, File Return to?

2)

Days Of Repair: 16

Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: P.

Lump Sum / I.B.I: (\$ 8500 )

# Enquire PARF/COE Rebate for Registered Vehicle

|                                |                          |
|--------------------------------|--------------------------|
| Vehicle Owner Particulars      |                          |
| Owner ID Type:                 | Singapore NRIC           |
| Owner ID:                      | 2402J                    |
| Vehicle Details                |                          |
| Vehicle No.:                   | SJR144E                  |
| Vehicle to be Exported:        | No                       |
| Intended De-registration Date: | 19 Feb 2018              |
| Vehicle Make:                  | MAZDA                    |
| Vehicle Model:                 | MX5 2L AT RHT            |
| Primary Colour:                | Silver                   |
| Manufacturing Year:            | 2009                     |
| Engine No.:                    | LF10755883               |
| Chassis No.:                   | JM0NC30F290200040        |
| Maximum Power Output:          | 118.0 kW (158 bhp)       |
| Open Market Value:             | \$38,539.00              |
| Original Registration Date:    | 04 Jun 2009              |
| First Registration Date:       | 04 Jun 2009              |
| Transfer Count:                | 0                        |
| Actual ARF Paid:               | \$38,539.00 19269        |
| Intended PARF Rebate Details   |                          |
| PARF Eligibility:              | Yes                      |
| PARF Eligibility Expiry Date:  | 03 Jun 2019              |
| PARF Rebate Amount:            | \$21,196.00              |
| Intended COE Rebate Details    |                          |
| COE Expiry Date:               | 03 Jun 2019              |
| COE Category:                  | B - Car (1601cc & above) |
| COE Period(Years):             | 10                       |
| QP Paid:                       | \$7,552.00               |
| COE Rebate Amount:             | \$974.00                 |
| Total Rebate Amount:           | \$22,170.00              |

The information contained herein is correct as at 19 Feb 2018

OK



however...  
claim against  
NIG...

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                      |
|----------------------------|--------------------------------------|
| Date Of Report             | 14/02/2018 10:08                     |
| Date Of Accident           | 13/02/2018 17:30                     |
| Exact Location Of Accident | EXP TWDS CHANGI AFTER TANJONG KATONG |
| Country/State of Loss      | SINGAPORE                            |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SJR144E              |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | LEONG KOK CHUN       |
| NRIC No                     | S2622402J            |
| Email Address               | NOEMAIL              |
| Mobile Phone No             | (LOCAL) +65-98225779 |
| Alternative Phone No        | OTHERS-98225779      |

### Vehicle Particulars

|                                                                    |               |
|--------------------------------------------------------------------|---------------|
| Manufacturer                                                       | MAZDA         |
| Model                                                              | MX5 2L AT RHT |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE USE   |

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

|                           |                       |
|---------------------------|-----------------------|
| Name of Insurance Company | AXA INSURANCE PTE LTD |
| Type Of Coverage          | COMPREHENSIVE         |
| Fleet Policy              | NO                    |
| Policy Number             | GA212318/1            |
| Cover Note Number         |                       |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | LEONG KOK CHUN        |
| NRIC No              | S2622402J             |
| Date Of Birth        | 18/10/1960            |
| Occupation           | INDOOR                |
| Date Of Driving Pass | 23/10/1993            |
| Driving Experience   | 24 YEARS AND 3 MONTHS |
| Gender               | FEMALE                |
| Mobile Number        | (LOCAL) +65-98225779  |
| Fax Number           |                       |
| Contact Number       | OTHERS-98225779       |
| Email Address        | NOEMAIL               |

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6

#01-46/48/50 Autobay

SINGAPORE 417883

VEHICLE NO: SJR 144E

| QTY   | PARTICULAR                                        | AMOUNT                      |
|-------|---------------------------------------------------|-----------------------------|
| 1 PCS | BOOTLID 1125.00                                   | Sur \$1,423.80 ✓            |
| 1 PCS | BOOTLID REAR LOGO 26.00                           | Sur \$60.80 ✓               |
| 2 PCS | BOOTLID LICENCE LAMPS @\$95.00                    | 11 \$190.00 X               |
| 1 PCS | BOOTLID LOCK 266.20                               | Sur \$329.30 ✓              |
| 2 PCS | BOOTLID HINGES @\$112.80                          | 11 \$225.60 X               |
| 2 PCS | BOOTLID DAMPERS @\$240.50                         | 11 \$481.00 X               |
| 1 PCS | BOOTLID WEATHERSTRIP 186.20                       | Sur \$219.60 ✓              |
| 1 PCS | REAR BUMPER 1061.30                               | Dis \$1,458.20 ✓            |
| 1 PCS | REAR BUMPER TOW COVER                             | To. 1 \$35.50 ✓             |
| 1 PCS | REAR BUMPER REINFORCEMENT 465.30                  | Dis \$721.30 ✓              |
| 2 PCS | REAR BUMPER SIDE RETAINERS @\$66.50               | Sur \$133.00 ✓              |
| 1 SET | REAR BUMPER CLIPS                                 | Sur \$50.00 ✓               |
| 1 PCS | REAR END PANEL 465.10                             | 306500 \$688.20 ✓           |
| 1 PCS | REAR END PANEL TOP GARNISH 188.30                 | De/ Sur \$345.30 ✓          |
| 1 PCS | REAR FENDER N/S                                   | 11 \$1,123.60 X             |
| 1 PCS | REAR FENDER O/S                                   | 11 \$1,123.60 X             |
| 2 PCS | REAR FENDER INNER TRIMS @\$485.20 366.20x2=732.40 | De/ Sur \$970.40 ✓          |
| 2 PCS | REAR FENDER UNDER COVERS @\$112.30                | 11 \$224.60 X               |
| 1 PCS | REAR FLOOR PANEL 1139.60                          | cramped/ Sur \$1,488.20 ✓   |
| 1 PCS | REAR FLOOR PANEL TOP BOARD                        | 11 \$642.30 X               |
| 2 PCS | REAR TAILLAMPS @\$680.50 625x2=1250               | n/s Sur d/ Sur \$1,361.00 ✓ |
| 2 PCS | REAR TAILLAMP HOUSING PANELS @\$266.50            | n/s m \$533.00 12C          |
| 1 PCS | REAR EXHAUST MUFFLER 1150                         | no/ Sur \$1,280.00 ✓        |
| 3 PCS | REAR EXHAUST MUFFLER MOUNTINGS @\$50.00           | Sur \$150.00 ✓              |
| 1 PCS | REAR EXHAUST HEAT SHIELD 285.30                   | Sur \$366.80 ✓              |
| 1 PCS | BONNET 1215.40                                    | Sur/ Sur \$1,265.30 ✓       |
| 1 PCS | FRONT BUMPER 1266.20                              | Dis \$1,488.20 ✓            |
| 1 PCS | FRONT BUMPER LOGO                                 | Sur \$60.80 ✓               |
| 1 PCS | FRONT BUMPER REINFORCEMENT                        | 11 \$644.30 X               |
| 1 PCS | FRONT BUMPER SIDE RETAINERS @\$66.50              | n/s m \$133.00 12C          |
| 1 PCS | FRONT BUMPER FOG LAMP COVER N/S 115.30            | Sur \$450.80 ✓              |
| 1 PCS | HEADLAMP N/S 1038.10                              | one \$1,660.50 ✓            |
| 1 PCS | FRONT SUPPORT PANEL                               | 11 \$665.80 X               |

(202)

Not Allowed  
Hale  
d/s 13.800  
16dy.

|       |                                         |         |
|-------|-----------------------------------------|---------|
| 1 PCS | FRONT FENDER N/S                        | 665.30  |
| 1 PCS | FRONT FENDER INNER SHIELD N/S           | 216.20  |
| 1 SET | FRONT FENDER INNER SHIELD CLIPS N/S     |         |
| 1 PCS | FRONT FENDER SIGNAL LAMP N/S            |         |
| 1 PCS | FRONT DOOR N/S                          | 1026.70 |
| 1 PCS | ROCK PANEL GARNISH N/S                  | 645.50  |
| 1 PCS | FRONT DOOR OUTER PILLAR N/S             |         |
| 1 PCS | FRONT WINDSCREEN                        |         |
| 1 PCS | FRONT SHOCK ABSORBER (HIGH PERFORMANCE) |         |
| 1 PCS | FRONT LOWER ARM N/S                     | 485.30  |
| 1 PCS | FRONT KNUCKLE ARM N/S                   | 566.20  |
| 1 PCS | FRONT KNUCKLE ARM BEARING N/S           | 215.30  |
| 1 PCS | FRONT TOP ARM N/S                       |         |
| 1 PCS | FRONT ABS SENSOR N/S                    |         |
| 1 PCS | FRONT STEERING RACK ASSY                |         |
| 1 PCS | FRONT BRAKE CALIPER N/S                 |         |
| 1 PCS | FRONT DISK ROTOR N/S                    |         |
| 1 PCS | FRONT WHEEL HOUSING PANEL N/S           |         |
| 1 PCS | CENTRE EXHAUST PIPE                     |         |
| 1 PCS | REAR AXLE BEAM                          |         |
| 2 PCS | REAR CHASSIS MEMBERS @\$800.00          |         |

|        |             |   |
|--------|-------------|---|
| Dis    | \$945.30    | ✓ |
| Torn   | \$288.50    | ✓ |
| ru     | \$50.00     | ✓ |
| 11     | \$62.00     | X |
| 20/Ref | \$1,220.80  | ✓ |
| Torn   | \$820.10    | ✓ |
| ru     | \$844.30    | X |
| 11     | \$1,265.20  | X |
| 3rd/ru | \$1,080.00  | ✓ |
| 3rd    | \$599.20    | ✓ |
| 3rd    | \$622.30    | ✓ |
| ru     | \$388.50    | ✓ |
| 3rd    | \$325.30    | ✓ |
| 11     | \$220.00    | X |
| 8u     | \$1,899.30  | X |
| 11     | \$611.40    | X |
| 11     | \$385.00    | X |
| 2      | \$922.30    | X |
| ru     | \$899.50    | X |
| 11     | \$2,110.30  | X |
| R.     | \$1,600.00  | ✓ |
|        | \$39,153.10 |   |

#### S.NETT

|       |                           |
|-------|---------------------------|
| 1 PCS | REAR LICENCE PLATE        |
| 1 PCS | REAR END PANEL SEALANT    |
| 1 SET | FRONT SPORT RIM '18 INCH' |
| 1 PCS | FRONT TYRE N/S            |
| 1 BOT | RADIATOR COOLANT          |
| 1 BOT | BRAKE FLUID               |

14143.8  
1451504

|        |            |     |
|--------|------------|-----|
| one    | \$20.00    | 14  |
| ru     | \$50.00    | ✓   |
| 20/3rd | \$6,000.00 | 100 |
| 150    | \$250.00   | 602 |
| 11     | \$50.00    | X   |
| 11     | \$50.00    | X   |

#### LABOUR CHARGES:

|                                               |          |     |
|-----------------------------------------------|----------|-----|
| TOWING KING ROLLER                            | \$150.00 | 120 |
| TO CHECK WIRING                               | \$80.00  | 30  |
| TO DISMENTLE & REFIX PETROL TANK              | \$100.00 | 60  |
| TO DISMENTLE & REFIX SEAT, CUSHION UPHOLSTERY | \$180.00 | 80  |
| TO MOUNT VEHICLE ON CAR O-LINER               | \$380.00 | X   |
| TO SPRAY RUST PROOFING                        | \$180.00 | 120 |
| TO DISMENTLE & REPLACING REAR EXHAUST         | \$180.00 | 80  |
| TO DISMENTLE & REPLACING FRONT UNDERCARRIAGE  | \$500.00 | 150 |
| TO TRANSFER FRONT DOOR MECHANISM              | \$120.00 | 60  |
| TO DISMENTLE & REFIX FRONT WINDSCREEN         | \$150.00 | X   |
| TO DISMENTLE & REFIX FRONT DASHBOARDS         | \$380.00 | X   |

TO REFILL AIR CON GAS  
LABOUR FOR PANEL BEATING,CUT,WEILD,STRAIGHTEN  
& REPLACING PARTS  
TO PUTTY & SPRAY PAINTING

11 \$150.00 X  
\$3,800.00 1800  
\$3,000.00 2000

TOTAL \$54,923.10

2022 8.04

1. K. AUT. Insurances hence notify  
the Repairer of the following:
- To resurvey before/after spray painting
  - To replace damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |             |               |                                                      |                                                       |                                                 |             |                                                                 |
|--------------------------|-------------|---------------|------------------------------------------------------|-------------------------------------------------------|-------------------------------------------------|-------------|-----------------------------------------------------------------|
| Case                     | Notified    | Est Submitted | Adj Assigned                                         | Adj Rpt                                               | Adj Submitted                                   | Ins Auth'ed | Status                                                          |
| Main                     | 20 Feb 2018 |               | 13 Apr 2018<br>11:27<br><a href="#">Edit Adj Rpt</a> | <b>S\$13,800.00</b><br><a href="#">Edit Estimates</a> | <b>S\$13,800.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

  

| Main                                                                                                                                                                          | Reference | Claim Details                                      | Documents                                          | Show All |         |             |              |            |       |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------------------------------------------------|----------------------------------------------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>                                                                                        |           |                                                    |                                                    |          |         |             |              |            |       |
| Insured: <b>SARANPAL SINGH</b> , ID: S8438086E, Tel: +6591811470, Email: NOEMAIL                                                                                              |           |                                                    |                                                    |          |         |             |              |            |       |
| Main Claimant: <b>LEONG KOK CHUN</b> , ID: S2622402J                                                                                                                          |           |                                                    |                                                    |          |         |             |              |            |       |
| Vehicle Reg. No.: <b>SJR144E</b>                                                                                                                                              |           | Date of Loss: 13/02/2018 18:00 - :59               | [104 Months and 9 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type: <b>TP / 550037</b>                                                                                                                                                |           | Policy/Cover Note No.: 28809291QMY (Comprehensive) | Coverage: 05/01/2018 - 04/01/2019                  |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured): <b>SLH57C</b>                                                                                                                                     |           | Policy No. (Claimant):                             |                                                    |          |         |             |              |            |       |
|                                                                                                                                                                               |           | Excess:                                            | S\$500.00                                          |          |         |             |              |            |       |
| Repairer: <b>Fastech Auto Pte Ltd (HQ)</b> 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405                                                        |           |                                                    |                                                    |          |         |             |              |            |       |
| Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]                                    |           |                                                    |                                                    |          |         |             |              |            |       |
| Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Imm.Advice due 14/04/2018]                                      |           |                                                    |                                                    |          |         |             |              |            |       |
| Driver/Custodian (Insured): <b>SARANPAL SINGH (33 / Male)</b> , NRIC: S8438086E, Tel: +6591811470                                                                             |           |                                                    |                                                    |          |         |             |              |            |       |
| Adj Asg. Remarks: Direct survey done on 19/2/2018                                                                                                                             |           |                                                    |                                                    |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>                                                 |           |                                                    |                                                    |          |         |             |              |            |       |
| There are no mail for this case.                                                                                                                                              |           |                                                    |                                                    |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |           |                                                    |                                                    |          |         |             |              |            |       |
| Due Date                                                                                                                                                                      | Priority  | Type                                               | Task Group                                         | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                                                   |           |                                                    |                                                    |          |         |             |              |            |       |

## Claim Documents

\*SJR144E (550037)  
[SLH57C]  
TP  
LEONG KOK CHUN  
Feb 13 2018 6:00PM  
[SARANPAL SINGH]  
Fastech Auto Pte Ltd

|                    |                 |                                                                            |  |                    |  |                                                                                                |  |                                     |  |
|--------------------|-----------------|----------------------------------------------------------------------------|--|--------------------|--|------------------------------------------------------------------------------------------------|--|-------------------------------------|--|
| Upload Documents   |                 | Upload Photos                                                              |  | Compose New Letter |  | View                                                                                           |  | View in Browser                     |  |
| Assessment Reports |                 |                                                                            |  |                    |  | 1 per page                                                                                     |  | <input checked="" type="checkbox"/> |  |
| No                 | Finalized On    | MSIG Insurance (Singapore) Pte. Ltd. (HQ)                                  |  |                    |  | Thumbnail                                                                                      |  | Print                               |  |
| 1                  | 13/04/18 11:27  | Accident Statement<br>From: OD - Reg. No: SLH57C, Claimant: SARANPAL SINGH |  |                    |  |  Load HTM   |  |                                     |  |
| Photos/Images      |                 |                                                                            |  |                    |  | 3 per page                                                                                     |  | <input checked="" type="checkbox"/> |  |
| No                 | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                                          |  |                    |  | Thumbnail                                                                                      |  | Print                               |  |
| 1                  | 08/06/18 15:09  | General View                                                               |  |                    |  |  Load JPG   |  | <input checked="" type="checkbox"/> |  |
| 2                  | 08/06/18 15:09  | General View                                                               |  |                    |  |  Load JPG   |  | <input checked="" type="checkbox"/> |  |
| 3                  | 08/06/18 15:09  | General View                                                               |  |                    |  |  Load JPG   |  | <input checked="" type="checkbox"/> |  |
| 4                  | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG   |  | <input checked="" type="checkbox"/> |  |
| 5                  | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG   |  | <input checked="" type="checkbox"/> |  |
| 6                  | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG  |  | <input checked="" type="checkbox"/> |  |
| 7                  | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 8                  | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 9                  | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 10                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 11                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 12                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 13                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 14                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 15                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 16                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 17                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 18                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 19                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 20                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 21                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 22                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 23                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 24                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 25                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 26                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 27                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 28                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 29                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 30                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 31                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 32                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |
| 33                 | 08/06/18 15:10  | General View                                                               |  |                    |  |  Load JPG |  | <input checked="" type="checkbox"/> |  |

| Assessment Reports |                |                                           | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|----------------|-------------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail                                                                                      | Print                               |
| 34                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 35                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 36                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 37                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 38                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 39                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 40                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 48                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 49                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 50                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 51                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 52                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 53                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 54                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 55                 | 08/06/18 15:10 | General View                              |  Load JPG  | <input checked="" type="checkbox"/> |
| 56                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 57                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 58                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 59                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 60                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 61                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 62                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 63                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 64                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 65                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 66                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 67                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 68                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 69                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 70                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 71                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 72                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 73                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 74                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 75                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 76                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 77                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 78                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 79                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 80                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 81                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 82                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 83                 | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports |                |                                           | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|----------------|-------------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail                                                                                      | Print                               |
| 84                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 85                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 86                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 87                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 88                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 89                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 90                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 91                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 92                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 93                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 94                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 95                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 96                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 97                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 98                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 99                 | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 100                | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 101                | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 102                | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 103                | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 104                | 08/06/18 15:10 | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 105                | 08/06/18 15:10 | General View                              |  Load JPG  | <input checked="" type="checkbox"/> |
| 106                | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 107                | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 108                | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 109                | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 110                | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 111                | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 112                | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 113                | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 114                | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 115                | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 116                | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 117                | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 118                | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 119                | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 120                | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 121                | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 122                | 08/06/18 15:10 | General View                              |  Load JPG | <input checked="" type="checkbox"/> |
| 123                | 08/06/18 15:16 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 124                | 08/06/18 15:16 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 125                | 08/06/18 15:16 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 126                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 127                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 128                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 129                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 130                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 131                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 132                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 133                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports |                |                                           | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|----------------|-------------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail                                                                                      | Print                               |
| 134                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 135                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 136                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 137                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 138                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 139                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 140                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 141                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 142                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 143                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 144                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 145                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 146                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 147                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 148                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 149                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 150                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 151                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 152                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 153                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 154                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 155                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG  | <input checked="" type="checkbox"/> |
| 156                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 157                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 158                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 159                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 160                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 161                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 162                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 163                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 164                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 165                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 166                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 167                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 168                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 169                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 170                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 171                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 172                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 173                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 174                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 175                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 176                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 177                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 178                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 179                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 180                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 181                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 182                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 183                | 08/06/18 15:17 | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports |                |                                                                                     | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|----------------|-------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (HQ)                                           | Thumbnail                                                                                      | Print                               |
| 184                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 185                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 186                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 187                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 188                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 189                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 190                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 191                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 192                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 193                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 194                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 195                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 196                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 197                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 198                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 199                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 200                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 201                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 202                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 203                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 204                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG   | <input checked="" type="checkbox"/> |
| 205                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG  | <input checked="" type="checkbox"/> |
| 206                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 207                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 208                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 209                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 210                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 211                | 08/06/18 15:17 | Reinspection Photo                                                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 212                | 08/06/18 15:18 | Reinspection Photo 2                                                                |  Load JPG | <input checked="" type="checkbox"/> |
| 213                | 08/06/18 15:18 | Reinspection Photo 2                                                                |  Load JPG | <input checked="" type="checkbox"/> |
| 214                | 08/06/18 15:18 | Reinspection Photo 2                                                                |  Load JPG | <input checked="" type="checkbox"/> |
| 215                | 08/06/18 15:18 | Reinspection Photo 2                                                                |  Load JPG | <input checked="" type="checkbox"/> |
| 216                | 08/06/18 15:18 | Reinspection Photo 2                                                                |  Load JPG | <input checked="" type="checkbox"/> |
| 217                | 08/06/18 15:18 | Reinspection Photo 2                                                                |  Load JPG | <input checked="" type="checkbox"/> |
| 218                | 08/06/18 15:18 | Reinspection Photo 2                                                                |  Load JPG | <input checked="" type="checkbox"/> |
| 219                | 08/06/18 15:18 | Reinspection Photo 2                                                                |  Load JPG | <input checked="" type="checkbox"/> |
| 220                | 08/06/18 15:18 | Reinspection Photo 2                                                                |  Load JPG | <input checked="" type="checkbox"/> |
| 221                | 08/06/18 15:18 | Reinspection Photo 2                                                                |  Load JPG | <input checked="" type="checkbox"/> |
| 222                | 08/06/18 15:18 | Reinspection Photo 2                                                                |  Load JPG | <input checked="" type="checkbox"/> |
| 223                | 08/06/18 15:18 | Reinspection Photo 2                                                                |  Load JPG | <input checked="" type="checkbox"/> |
| 224                | 08/06/18 15:18 | Reinspection Photo 2                                                                |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation      |                |                                                                                     | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (HQ)                                           | Thumbnail                                                                                      | Print                               |
| 1                  | 13/04/18 11:27 | TP SLP853D (1/3) GIA Report<br>From: OD - Reg. No: SLH57C, Claimant: SARANPAL SINGH |  Load PDF |                                     |
| 2                  | 13/04/18 11:27 | TP SJR144E (2/3) GIA Report<br>From: OD - Reg. No: SLH57C, Claimant: SARANPAL SINGH |  Load PDF |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                                                           | Reset | Save | Print |
|-------------------------------------------------------------------------------|-------|------|-------|
| There are no document checklists configured.                                  |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>              |       |      |       |
| <div></div>                                                                   |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer             |       |      |       |
| <small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18003141/URD3Q2

Date: 12/06/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28809291QMY

Claimant Vehicle No : SJR144E

Insured Vehicle No : SLH57C

Date of Loss: 13/02/2018

Nature of Claim: TP

Claim No: 550037

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR144E**

Make &amp; Model: MAZDA MX-5, 2.0 RHT (NC3) (A)

Engine No: LF10755883

Reg. Date: 04/06/2009 (Man. Year: 2009)

Chassis No: JM0NC30F290200040

Colour: Grey

Odometer: 79518 km

Engine Capacity: 1601 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

Front Tyre Size: 225/40Z R18

Rear Tyre Size: 225/40Z R18

Front Left Side: Nexen 6 mm

Rear Left Side: Nexen 6 mm

Front Right Side: Nexen 6 mm

Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                           | Repairer's       | Adjuster's       | Difference       | Diff %       |
|------------------------------------------|------------------|------------------|------------------|--------------|
| Parts                                    | 37,742.48        | 15,529.04        | 22,213.44        | 58.86        |
| Miscellaneous Items                      | 0.00             | 0.00             | 0.00             |              |
| Labour                                   | 9,350.00         | 4,500.00         | 4,850.00         | 51.87        |
| Paintwork Labour                         | 0.00             | 0.00             | 0.00             |              |
| Towing                                   | 0.00             | 0.00             | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>47,092.48</b> | <b>20,029.04</b> | <b>27,063.44</b> | <b>57.47</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>13,800.00</b> |                  |              |
| <b>(S\$)</b>                             | 47,092.48        | 13,800.00        | 33,292.48        | 70.70        |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 3,296.47         | 966.00           | 2,330.47         | 70.70        |
| <b>Nett Amount (S\$)</b>                 | <b>50,388.95</b> | <b>14,766.00</b> | <b>35,622.95</b> | <b>70.70</b> |

### INSPECTION

Date of Assignment: 13/04/2018

Date Inspected: 19/02/2018 Inspected At:

Fastech Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #01-46/48/50 Autobay  
Singapore 417883

Estimated Period of Repair: 16.0 days

**Adjuster:** MARCUS CHUA

**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

|                      |                                                                                                                                                                              |                                                                |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|
| <b>Part Source:</b>  | (Last Synchronised: 12 Jun 2018)                                                                                                                                             |                                                                |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | MAZDA MX-5 2.0 RHT (NC3) (A) (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                              |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SJR144E)                                                                                                                                     |                                                                |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                |

## Recommended Parts

| No. | Qty | Part No. | Particulars                              | Condition                | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------------|--------------------------|-------------|--------------|
| 1   | 1   |          | *BOOTLID                                 | Buckled                  | 1,423.80 FL | *1,125.00 FL |
| 2   | 1   |          | *BOOTLID REAR LOGO                       | Necessary                | 60.80 FL    | *56.00 FL    |
| 3   | 2   |          | *BOOTLID LICENCE LAMPS                   | Not Necessary            | 190.00 FL   | *- FL        |
| 4   | 1   |          | *BOOTLID LOCK                            | Twisted                  | 329.30 FL   | *266.20 FL   |
| 5   | 2   |          | *BOOTLID HINGES                          | Repair                   | 225.60 FL   | *- FL        |
| 6   | 2   |          | *BOOTLID DAMPERS                         | Not Necessary            | 481.00 FL   | *- FL        |
| 7   | 1   |          | *BOOTLID WEATHERSTRIP                    | Twisted                  | 219.60 FL   | *186.20 FL   |
| 8   | 1   |          | *REAR BUMPER                             | Distorted                | 1,458.20 FL | *1,061.30 FL |
| 9   | 1   |          | *REAR BUMPER TOW COVER                   | Torn                     | 35.50 FL    | *35.50 FL    |
| 10  | 1   |          | *REAR BUMPER REINFORCEMENT               | Distorted                | 721.30 FL   | *565.30 FL   |
| 11  | 2   |          | *REAR BUMPER SIDE RETAINERS              | Bent                     | 133.00 FL   | *133.00 FL   |
| 12  | 1   |          | *SET REAR BUMPER CLIPS                   | Necessary                | 50.00 FL    | *50.00 FL    |
| 13  | 1   |          | *REAR END PANEL                          | Badly Dented             | 688.20 FL   | *465.10 FL   |
| 14  | 1   |          | *REAR END PANEL TOP GARNISH              | Deformed / Twisted       | 345.30 FL   | *188.30 FL   |
| 15  | 1   |          | *REAR FENDER N/S                         | Repair                   | 1,123.60 FL | *- FL        |
| 16  | 1   |          | *REAR FENDER O/S                         | Repair                   | 1,123.60 FL | *- FL        |
| 17  | 2   |          | *REAR FENDER INNER TRIMS                 | Deformed / Twisted       | 970.40 FL   | *732.40 FL   |
| 18  | 2   |          | *REAR FENDER UNDER COVERS                | Not Necessary            | 224.60 FL   | *- FL        |
| 19  | 1   |          | *REAR FLOOR PANEL                        | Crumpled / Buckled       | 1,488.20 FL | *1,139.60 FL |
| 20  | 1   |          | *REAR FLOOR PANEL TOP BOARD              | Not Necessary            | 642.30 FL   | *- FL        |
| 21  | 2   |          | *REAR TAILLAMPS                          | N/S Broken / O/S Cracked | 1,361.00 FL | *1,250.00 FL |
| 22  | 1   |          | *REAR TAILLAMP HOUSING PANELS            | N/S Dented               | 533.00 FL   | *266.50 FL   |
| 23  | 1   |          | *REAR EXHAUST MUFFLER                    | Dented / Bent            | 1,280.00 FL | *1,150.00 FL |
| 24  | 3   |          | *REAR EXHAUST MUFFLER MOUNTINGS          | Necessary                | 150.00 FL   | *150.00 FL   |
| 25  | 1   |          | *REAR EXHAUST HEAT SHIELD                | Bent                     | 366.80 FL   | *285.30 FL   |
| 26  | 1   |          | *BONNET                                  | Bent / Cut               | 1,265.30 FL | *1,215.40 FL |
| 27  | 1   |          | *FRONT BUMPER                            | Distorted                | 1,488.20 FL | *1,266.20 FL |
| 28  | 1   |          | *FRONT BUMPER LOGO                       | Necessary                | 60.80 FL    | *60.80 FL    |
| 29  | 1   |          | *FRONT BUMPER REINFORCEMENT              | Not Necessary            | 644.30 FL   | *- FL        |
| 30  | 1   |          | *FRONT BUMPER SIDE RETAINERS             | N/S Cracked              | 133.00 FL   | *66.50 FL    |
| 31  | 1   |          | *FRONT BUMPER FOG LAMP COVER N/S         | Grazed                   | 450.80 FL   | *115.30 FL   |
| 32  | 1   |          | *HEADLAMP N/S                            | Cracked                  | 1,660.50 FL | *1,038.10 FL |
| 33  | 1   |          | *FRONT SUPPORT PANEL                     | Repair                   | 665.80 FL   | *- FL        |
| 34  | 1   |          | *FRONT FENDER N/S                        | Distorted                | 945.30 FL   | *665.30 FL   |
| 35  | 1   |          | *FRONT FENDER INNER SHIELD N/S           | Torn                     | 288.50 FL   | *216.20 FL   |
| 36  | 1   |          | *SET FRONT FENDER INNER SHIELD CLIPS N/S | Necessary                | 50.00 FL    | *50.00 FL    |
| 37  | 1   |          | *FRONT FENDER SIGNAL LAMP N/S            | Not Necessary            | 62.00 FL    | *- FL        |
| 38  | 1   |          | *FRONT DOOR N/S                          | Dented / Bent            | 1,220.80 FL | *1,026.70 FL |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                              | Condition                  | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------------|----------------------------|-------------|--------------|
| 39  | 1   |          | *ROCKER PANEL GARNISH N/S                | Torn                       | 820.10 FL   | *645.50 FL   |
| 40  | 1   |          | *FRONT DOOR OUTER PILLAR N/S             | Repair                     | 844.30 FL   | *- FL        |
| 41  | 1   |          | *FRONT WINDSCREEN                        | Not Necessary              | 1,265.20 FL | *- FL        |
| 42  | 1   |          | *FRONT SHOCK ABSORBER (HIGH PERFORMANCE) | Bent / Twisted             | 1,080.00 FL | *1,080.00 FL |
| 43  | 1   |          | *FRONT LOWER ARM N/S                     | Bent                       | 599.20 FL   | *485.30 FL   |
| 44  | 1   |          | *FRONT KNUCKLE ARM N/S                   | Bent                       | 622.30 FL   | *566.20 FL   |
| 45  | 1   |          | *FRONT KNUCKLE ARM BEARING N/S           | Necessary                  | 388.50 FL   | *215.30 FL   |
| 46  | 1   |          | *FRONT TOP ARM N/S                       | Bent                       | 325.30 FL   | *325.30 FL   |
| 47  | 1   |          | *FRONT ABS SENSOR N/S                    | Not Necessary              | 220.00 FL   | *- FL        |
| 48  | 1   |          | *FRONT STEERING RACK ASSY                | Serviceable                | 1,899.30 FL | *- FL        |
| 49  | 1   |          | *FRONT BRAKE CALIPER N/S                 | Not Necessary              | 611.40 FL   | *- FL        |
| 50  | 1   |          | *FRONT DISK ROTOR N/S                    | Not Necessary              | 385.00 FL   | *- FL        |
| 51  | 1   |          | *FRONT WHEEL HOUSING PANEL N/S           | Repair                     | 922.30 FL   | *- FL        |
| 52  | 1   |          | *CENTRE EXHAUST PIPE                     | Repair                     | 899.50 FL   | *- FL        |
| 53  | 2   |          | *REAR CHASSIS MEMBERS                    | Repair                     | 1,600.00 FL | *- FL        |
| 54  | 1   |          | *REAR AXLE BEAM                          | Not Necessary              | 2,110.30 FL | *- FL        |
| 55  | 1   |          | *REAR LICENCE PLATE                      | Cracked                    | 20.00 FS    | *14.00 FS    |
| 56  | 1   |          | *REAR END PANEL SEALANT                  | Necessary                  | 50.00 FS    | *50.00 FS    |
| 57  | 1   |          | *BOT BRAKE FLUID                         | Not Necessary              | 50.00 FS    | *- FS        |
| 58  | 1   |          | *BOT RADIATOR COOLANT                    | Not Necessary              | 50.00 FS    | *- FS        |
| 59  | 1   |          | *SET FRONT SPORT RIM 18 INCH             | Dented / Bent (1 PCS ONLY) | 6,000.00 FS | *800.00 FS   |
| 60  | 1   |          | *FRONT TYRE N/S (60%)                    | Cut                        | 250.00 FS   | *150.00 FS   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **45,573.10**    **19,157.80**  
 - List Item Discount on L Items 20.00/20.00% (S\$)    7,830.62    3,628.76

Total Parts (S\$) **37,742.48**    **15,529.04**

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                       | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                   |          |                 |                 |
| 1                               | TOWING KING ROLLER                                                | New      | 150.00          | 120.00          |
| 2                               | TO CHECK WIRING                                                   | New      | 80.00           | 30.00           |
| 3                               | TO DISMANTLE & REFIX PETROL TANK                                  | New      | 100.00          | 60.00           |
| 4                               | TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY                     | New      | 180.00          | 80.00           |
| 5                               | TO MOUNT VEHICLE ON REAR CAR O-LINER                              | New      | 380.00          | 0.00            |
| 6                               | TO SPRAY RUST PROOFING                                            | New      | 180.00          | 120.00          |
| 7                               | TO DISMANTLE & REPLACING REAR EXHAUST                             | New      | 180.00          | 80.00           |
| 8                               | TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE                      | New      | 500.00          | 150.00          |
| 9                               | TO TRANSFER FRONT DOOR MECHANISM                                  | New      | 120.00          | 60.00           |
| 10                              | TO DISMANTLE & REFIX FRONT DASHBOARD                              | New      | 380.00          | 0.00            |
| 11                              | TO DISMANTLE & REFIX FRONT WINDSCREEN                             | New      | 150.00          | 0.00            |
| 12                              | TO REFILL AIR CON GAS                                             | New      | 150.00          | 0.00            |
| 13                              | LABOUR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS | New      | 3,800.00        | 1,800.00        |
| 14                              | TO PUTTY & SPRAY PAINTING                                         | New      | 3,000.00        | 2,000.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                                                   |          | <b>9,350.00</b> | <b>4,500.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >