



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham ecribe

|                                                                                                                                        |                                                                          |                 |                  |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|-----------------|------------------|-------------------------------------------------------------------------------------|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18003188/R1vd3e2                                                                     |                                                                          |                 |                  |                                                                                     |
| 73 BRAS BASAH ROAD<br>#05-01 NTUC TRADE UNION HOUSESINGAPORE<br>189556                                                                 |                                                                          |                 | Date: 05-03-2018 |  |
|                                                                                                                                        |                                                                          |                 | Code: INC4       |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                          |                 |                  |                                                                                     |
| Insured Veh.                                                                                                                           | SJR 3977Z                                                                | Veh. Inspected  | SHC 3778J        |                                                                                     |
| Policy No.                                                                                                                             | 5094398905                                                               | Coverage (\$)   | 0.00             |                                                                                     |
| Claim No.                                                                                                                              | MT/0982542-002                                                           | Excess (\$)     | 0.00             |                                                                                     |
| Assign From                                                                                                                            |                                                                          | Assign Date     | 19/02/2018       |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                          |                 |                  |                                                                                     |
| Make & Model                                                                                                                           | HYUNDAI I40 1.7                                                          | c.c             | 1685             |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                   | Year of Reg.    | 2014             |                                                                                     |
| Chassis No.                                                                                                                            | KMHLB41UMEU057756                                                        | Colour          | BLUE             |                                                                                     |
| Odometer                                                                                                                               | 385148                                                                   | Steering        | IN ORDER         |                                                                                     |
| Brakes                                                                                                                                 | IN ORDER                                                                 | Modification    | NIL              |                                                                                     |
| General                                                                                                                                | FAIR                                                                     |                 |                  |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                          |                 |                  |                                                                                     |
|                                                                                                                                        | Size                                                                     | Make            | Balance          |                                                                                     |
| R/H Front Tyre                                                                                                                         | 205/60 R16                                                               | WEST LAKE       | 5 mm             |                                                                                     |
| L/H Front Tyre                                                                                                                         | 205/60 R16                                                               | WEST LAKE       | 5 mm             |                                                                                     |
| R/H Rear Tyre                                                                                                                          | 205/60 R16                                                               | WEST LAKE       | 5 mm             |                                                                                     |
| L/H Rear Tyre                                                                                                                          | 205/60 R16                                                               | WEST LAKE       | 5 mm             |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                          |                 |                  |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                             |                                                                          |                 |                  |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                          |                 |                  |                                                                                     |
| Accident Date                                                                                                                          | 15/02/2018                                                               | Inspection Date | 19/02/2018       |                                                                                     |
| Survey held at                                                                                                                         | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                 |                  |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                          |                 |                  |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                          |                 |                  |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                          |                 |                  |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                          | 2 Working Days  |                  |                                                                                     |