Surveyor Rajne | REF: III | 6919B

ASSIGNMENT

From: | Date: 07/3/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJN 7870S

at Workshop m/s Cycle & Carriage

of 209 Pandan Gardens

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh: Andre

(Policy Condition) 4pm

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted:

Veh No: SJN 7870S | Yr Regn: 2009 / PGB

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: MITSUBISHI I-CAR 4A | c.c 659

Colour PURPLE | A/C: Insured / Std / NI / NA

Sp.Reading 194320 | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JMYLRHA1W9U000224

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Worder / Jammed / Leaked / Burnt or

Brake: Worder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 145/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.	10/02/18	D.O.I.	07/03/18

Survey held at C&C (PG)

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction

Date/Time. File Pass to? 1) ☐ : Preli. Report ☐ : Final Report

Date/Time. File Return to? 2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insc ($) ☐ Interview ($) ☐ Tech. Invs ($) ☐ Weekend ($)

Survey Fee:

Transportation: $ + PS $

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: ($)