

ASS. REC. BY:

REF: CS3/CTI18 003209/M1d302

T.M.P. &amp; guys

Surveyor  
Reimer

MA

ASSIGNMENT (Office)

From (Person):

Sharon Han

of

CTI

Date/Time:

19/2/18 @ 10:55am

Estimated Cost:

Bill to:

OD ~~TP~~/WS/TP RES/OD RES/EVA/INV/MV7CS

To Inspect Vehicle No:

FBH 6330 S

Insured:

SJH 65897

at Workshop m/s

Speedy motorcycle

Tel:

9790 4440

of

107 Amk Ind. Prk 2A #05-21

Policy No:

DMHC SN1736231700

Claim No:

SNM18D00761002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/02/18

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

11:02am @ 20/2/18

Person Contacted:

Ah Sam

Vehicle ~~IN~~ OUT

Date/Time

Action/Instruction (X) Estimate

FBH 6330S - X

SJH 65897 - X

Diamondle: 21/2/2018


REF:

## ASSIGNMENT

From \_\_\_\_\_ Date \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV \_\_\_\_\_  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Ball or Market Value: \_\_\_\_\_  
 (DAC Accident Report) Consistent? : Yes or No  
 GIA / PR Seen: Consistent? : Yes or No  
 Est. Repairs: 5 days Res: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: 7BH 6330S Yr Regn: APR 2012  
 Type: M.Car / 3 / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: KAWASAKI VERSYS 650 649  
 Colour: yellow/black \* O Insured / Std / NI / NA  
 So. Reading: 88797 T Radio Insured / Std / NI / NA  
 Eng No: \_\_\_\_\_  
 C/No: JKALE650DDPA02508  
 Gen. Cond: 3 / Good / Fair / Poor / Burnt  
 Steering: 3 / In order / Jammed / Leaked / Burnt or  
 Brake: 3 / In order / Jammed / Leaked / Burnt or  
 Mod: Nil / 3 (S/Rim) / STD A/Rim or  
 Tyre Size: F: 120/70/R17.  
 R: 160/60/R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front Rear  
 R/Bal: 8 mm R/Bal: 8 mm  
 L/Bal: 8 mm L/Bal: 8 mm  
 D.O.A: 7/2/2018 D.O.A: 20/2/2018

Survey held at: \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
NS BODY OS BODY.  
 The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

NO ESTIMATE upon Survey.

\* Repair Estimate : \$7,000 ~ \$9,000

5 days

RECEIVED 12 JUN 2018

6/6/2018

Data/Time File Pass to? ☐ : Preli. ReportY: ☐ : Final Report

Data/Time File Return to?

2: \_\_\_\_\_

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee

Transported

Price

Date

Time

Signature

Add Fee: ☐ Site Insp: \$☐ Interview: \$☐ Test Drive: \$☐ Witnessing: \$Report Format: PRS

Lump Sum / I.B.I: \$

150

150

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'ed | Status   |
|------|-------------|---------------|--|---------|---------------|-------------|--|
| Main | 13 Feb 2018 |               | 19 Feb 2018<br>10:55<br><a href="#">Assign</a> |         |               |             | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                             |   |                        |                                     |
|-----------------------------|---|------------------------|-------------------------------------|
| Insured:                    | SG CAR LEASING PTE LTD, Co. Reg. No.: 201215889G  |                        |                                     |
| Main Claimant:              | LIM WAI ROON, ID: S7911125B   |                        |                                     |
| Vehicle Reg. No.:           | FBH6330S  | Date of Loss:          | 07/02/2018 22:00 - :59              |
| Claim Type:                 | TP / SNM18D00761C02   | Policy/Cover Note No.: | DMHCSN1736231700 (TP, Fire & Theft) |
| Vehicle Reg. No. (Insured): | SJH6589T  | Policy No. (Claimant): | MC/100153570/04                     |
|                             |   | Excess:                | S\$0.00                             |
| Repairer:                   | Speedy Motor Cycle Service Centre (HQ) 10 ANG MO KIO IND PARK 2A #05-21, 568047 Ang Mo Kio - Tel:       |                        |                                     |
| Handling Insurer:           | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896] |                        |                                     |
| Claimant's Insurer:         | Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888  |                        |                                     |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/02/2018]                       |                        |                                     |
| Driver/Custodian (Insured): | PHUA LUO TING ROWENA (33 / Female), NRIC: S8406169G, Tel: +6592986184                                   |                        |                                     |
| Adj Asg. Remarks:           | NO EST, CASE W/O SJE.   |                        |                                     |

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|----------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
|----------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|

No results.

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                   |
|-------------------------------------|-------------------|
| <b>Vehicle Owner Particulars</b>    |                   |
| Owner ID Type:                      | Singapore NRIC    |
| Owner ID:                           | 1125B             |
| <b>Vehicle Details</b>              |                   |
| Vehicle No.:                        | FBH6330S          |
| Vehicle to be Exported:             | No                |
| Intended De-registration Date:      | 02 May 2018       |
| Vehicle Make:                       | KAWASAKI          |
| Vehicle Model:                      | VERSYS 650 M      |
| Primary Colour:                     | Yellow            |
| Manufacturing Year:                 | 2012              |
| Engine No.:                         | ER650AEA88661     |
| Chassis No.:                        | JKALE650CDDA02508 |
| Maximum Power Output:               | -                 |
| Open Market Value:                  | \$11,297.00       |
| Original Registration Date:         | 03 Apr 2012       |
| First Registration Date:            | 14 May 2012       |
| Transfer Count:                     | 1                 |
| Actual ARF Paid:                    | \$1,695.00        |
| <b>Intended PARF Rebate Details</b> |                   |
| PARF Eligibility:                   | No                |
| PARF Eligibility Expiry Date:       | -                 |
| PARF Rebate Amount:                 | \$0.00            |
| <b>Intended COE Rebate Details</b>  |                   |
| COE Expiry Date:                    | 13 May 2022       |
| COE Category:                       | D - Motorcycle    |
| COE Period(Years):                  | 10                |
| QP Paid:                            | \$2,021.00        |
| COE Rebate Amount:                  | \$814.00          |
| <b>Total Rebate Amount:</b>         | <b>\$814.00</b>   |

The information contained herein is correct as at 02 May 2018

OK



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI18003209/M1d3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 20-02-2018



Code : CTI

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

|              |                      |                |            |
|--------------|----------------------|----------------|------------|
| Insured Veh. | SJH 6589T            | Veh. Inspected | FBH 6330S  |
| Policy No.   | DMHCSN1736231700     | Coverage (\$)  | 0.00       |
| Claim No.    | SNM18D00761C02       | Excess (\$)    | 0.00       |
| Assign From  | MERIMEN (SHARON HAN) | Assign Date    | 20/02/2018 |

### 2. Vehicle Particulars & Condition

|              |        |              |
|--------------|--------|--------------|
| Make & Model | c.c    | 0            |
| Engine No.   | HIDDEN | Year of Reg. |
| Chassis No.  |        | Colour       |
| Odometer     | -      | Steering     |
| Brakes       |        | Modification |
| General      |        |              |

### 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

### 4. Description of Damages

|  |
|--|
|  |
|--|

### 5. General Information

|                |   |                 |            |
|----------------|---|-----------------|------------|
| Accident Date  | 07/02/2018  | Inspection Date | 20/02/2018 |
| Survey held at | SPEEDY MOTOR CYCLE SERVICE CENTRE<br>BLK 10 ANG MO KIO IND. PARK 2A #05-21 SINGAPORE 568047 |                 |            |

### 5a. Remarks

|  |
|--|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |
|--|

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |   |
|----------------------------|---|
| Date Of Report             | 09/02/2018 18:07                          |
| Date Of Accident           | 07/02/2018 22:30                          |
| Exact Location Of Accident | JUNCTION OF YISHUN AVE 3 AND YISHUN ST 71 |
| Country/State of Loss      | SINGAPORE                                 |

### DETAILS OF OWN VEHICLE

|                             |                          |
|-----------------------------|--------------------------|
| Vehicle Registration Number | FBH6330S                 |
| <b>Insured/Policyholder</b> |                          |
| Name Of Registered Owner    | LIM WAI ROON             |
| NRIC No                     | S7911125B                |
| Email Address               | WILLIAM.LIM.SG@GMAIL.COM |
| Mobile Phone No             | (LOCAL) +65-96928466     |
| Alternative Phone No        | OFFICE-96928466          |

### Vehicle Particulars

|  |              |
|--|--------------|
| Manufacturer   | KAWASAKI     |
| Model  | VERSYS 650 M |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE      |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO           |
| If No, Please state action to be taken                                       | THIRD PARTY  |
| Vehicle Category   | MOTORCYCLE   |

### Insurance Company

|                           |   |
|---------------------------|---|
| Name of Insurance Company | DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD |
| Type Of Coverage          | COMPREHENSIVE                             |
| Fleet Policy              | NO  |
| Policy Number             | MC/100153570/04                           |
| Cover Note Number         | N.A.                                      |

### Driver

|                      |                          |
|----------------------|--------------------------|
| Name of Driver       | LIM WAI ROON             |
| NRIC No              | S7911125B                |
| Date Of Birth        | 06/04/1979               |
| Occupation           | INDOOR                   |
| Date Of Driving Pass | 05/12/1997               |
| Driving Experience   | 20 YEARS AND 2 MONTHS    |
| Gender               | MALE                     |
| Mobile Number        | (LOCAL) +65-96928466     |
| Fax Number           |                          |
| Contact Number       | OFFICE-96928466          |
| EMail Address        | WILLIAM.LIM.SG@GMAIL.COM |

|   |       |
|---|-------|
| Address   | NIL   |
| Postcode  |       |
| Was driver an employee of the Insured's Company     | NO    |
| If No, Relationship of the Driver with the Insured  | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | -     |
|   | -     |
|   | -     |
| Insurance Company of Driver's Own Vehicle           | -     |
|   | -     |
|   | -     |

#### General Information of the Accident

|                    |                            |
|--------------------|----------------------------|
| Type Of Accident   | COLLISION - CROSS JUNCTION |
| Weather Conditions | CLEAR                      |
| Road Surface       | DRY                        |

#### Other Information

|   |     |
|---|-----|
| Was any foreign vehicle involved in this accident?  | NO  |
| Number of vehicles involved in the accident   | 2   |
| Was any body injured in the Accident?   | YES |
| Was any injured conveyed to hospital by ambulance?  | YES |
| Was any other material or property damaged?   | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)   | 1   |

#### Details of Police Action

|   |                    |
|---|--------------------|
| Was the accident reported to the police?  | YES                |
| If Yes, Please state which Police Station |                    |
| POLICE STATION NAME [OTHER]               | INSURED WILL EMAIL |
| Was notice of intended Prosecution given? | NO                 |
| If Yes, against whom?                     |                    |

#### Circumstances of Accident

I was traveling along Yishun Ave 3. Approaching junction of Yishun St 71, car SJH6589T turned out without stopping at the stop line. I tried to brake and swerved to my right but could not avoid and car SJH6589T collided onto my motorcycle front left side, causing myself to flew forward and the motorcycle to fall on the right side. I was injured and was conveyed to the hospital by ambulance.

#### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                                     |             |
|-------------------------------------|-------------|
| Vehicle Registration Number         | SJH6589T    |
| Vehicle Make/Model/Colour           | MAZDA/ 3SP  |
| Details Of Properties               | NA          |
| Vehicle Category                    | PRIVATE CAR |
| Name of Driver                      | UNKNOWN     |
| NRIC/Passport Number                |             |
| Contact Number                      | NA          |
| Address                             | NA          |
| Postcode                            |             |
| Insurance Company Name              |             |
| Nature Of Damage                    |             |
| No. Of Passenger (Including Driver) |             |

**DETAILS OF INJURED PERSON 1**

Name LIM WAI ROON

Approximate Age

Injuries Sustain

Injured person in which vehicle? FBH6330S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

## ACCIDENT STATEMENT (2000 characters)

I was traveling along Yishun Ave 3. Approaching junction of Yishun St 71, car SJH6589T turned out without stopping at the stop line. I tried to brake and swerved to my right but could not avoid and car SJH6589T collided onto my motorcycle front left side, causing myself to flew forward and the motorcycle to fall on the right side. I was injured and was conveyed to the hospital by ambulance.

Taxi Voucher No.:

## DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
MUHAMMAD FAIZAL BIN PABILA

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

9 February 2018 at 3:44 PM

Date/Time:

9 February 2018 at 3:44 PM

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |             |               |  |  |  |             |   |
|--------------------------|-------------|---------------|--|--|--|-------------|---|
| Case                     | Notified    | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                              | Ins Auth'ed | Status  |
| Main                     | 13 Feb 2018 |               | 19 Feb 2018<br>10:55<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main  | Reference   | Claim Details          | Documents   | Show All |         |             |              |            |       |
|---|---|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>  |   |                        |   |          |         |             |              |            |       |
| Insured:  | <b>SG CAR LEASING PTE LTD</b> , Co. Reg. No.: 201215889G  |                        |   |          |         |             |              |            |       |
| Main Claimant:  | <b>LIM WAI ROON</b> , ID: S7911125B   |                        |   |          |         |             |              |            |       |
| Vehicle Reg. No.:   | <b>FBH6330S</b>   | Date of Loss:          | 07/02/2018 22:00 - :59<br>[70 Months and 4 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:   | <b>TP / SNM18D00761C02</b>  | Policy/Cover Note No.: | DMHCSN1736231700 (TP, Fire & Theft)   |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):   | <b>SJH6589T</b>   | Policy No. (Claimant): | MC/100153570/04   |          |         |             |              |            |       |
|   |   | Excess:                | S\$0.00   |          |         |             |              |            |       |
| Repairer:   | <b>Speedy Motor Cycle Service Centre (HQ)</b> 10 ANG MO KIO IND PARK 2A #05-21, 568047 Ang Mo Kio - Tel:                              |                        |   |          |         |             |              |            |       |
| Handling Insurer:   | <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Sharon Han</b> - 63896]                 |                        |   |          |         |             |              |            |       |
| Claimant's Insurer:   | <b>Direct Asia Insurance (Singapore) Pte Ltd (HQ)</b> - Tel: 65322888   |                        |   |          |         |             |              |            |       |
| Adjuster:   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MA CHIN FOOK</b> ] ... <b>[Final Rpt due 28/02/2018]</b> |                        |   |          |         |             |              |            |       |
| Driver/Custodian (Insured):   | PHUA LUO TING ROWENA (33 / Female), NRIC: S8406169G, Tel: +6592986184   |                        |   |          |         |             |              |            |       |
| Adj Asg. Remarks:   | NO EST, CASE W/O SJE.   |                        |   |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>   |   |                        |   |          |         |             |              |            |       |
| There are no mail for this case.  |   |                        |   |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |   |                        |   |          |         |             |              |            |       |
| Due Date  | Priority  | Type                   | Task Group  | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.   |   |                        |   |          |         |             |              |            |       |

## Claim Documents






\*FBH6330S (SNM18D00761C02)  
[SJH6589T]  
TP  
LIM WAI ROON  
Feb 7 2018 10:00PM  
[SG CAR LEASING PTE LTD]  
Speedy Motor Cycle Service Centre

|                    |                |  |               |  |                    |  |            |           |                                     |  |  |
|--------------------|----------------|--|---------------|--|--------------------|--|------------|-----------|-------------------------------------|--|--|
| Upload Documents   |                |  | Upload Photos |  | Compose New Letter |  | View       |           | View in Browser                     |  |  |
| Assessment Reports |                |  |               |  |                    |  | 1 per page |           | <input checked="" type="checkbox"/> |  |  |
| No                 | Finalized On   | Ajax Mars Pte Ltd (Bukit Merah)                      |               |  |                    |  |            | Thumbnail | Print                               |  |  |
| 1                  | 09/02/18 18:38 | Accident Statement                                   |               |  |                    |  | 1          | Load HTM  |                                     |  |  |
|                    |                |  |               |  |                    |  |            |           |                                     |  |  |
| Photos/Images      |                |  |               |  |                    |  | 3 per page |           | <input checked="" type="checkbox"/> |  |  |
| No                 | Finalized On   | Ajax Mars Pte Ltd (Bukit Merah)                      |               |  |                    |  |            | Thumbnail | Print                               |  |  |
| 1                  | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 2                  | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 3                  | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 4                  | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 5                  | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 6                  | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 7                  | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 8                  | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 9                  | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 10                 | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 11                 | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 12                 | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 13                 | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 14                 | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 15                 | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 16                 | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 17                 | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 18                 | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 19                 | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 20                 | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 21                 | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 22                 | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 23                 | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 24                 | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |
| 25                 | 09/02/18 18:28 | Accident Photo<br>[Linked Accident Report Documents] |               |  |                    |  | 1          | Load JPG  | <input checked="" type="checkbox"/> |  |  |

| Assessment Reports |                 |  |  | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|-----------------|--|--|------------|-------------------------------------|
| No                 | Finalized On    | Ajax Mars Pte Ltd (Bukit Merah)                                  |  | Thumbnail  | Print                               |
| 26                 | 09/02/18 18:28  | <b>Identification Card</b><br>[Linked Accident Report Documents] |  | Load JPG   | <input checked="" type="checkbox"/> |
| 27                 | 09/02/18 18:28  | <b>Identification Card</b><br>[Linked Accident Report Documents] |  | Load JPG   | <input checked="" type="checkbox"/> |
| 28                 | 09/02/18 18:28  | <b>Driving License</b><br>[Linked Accident Report Documents]     |  | Load JPG   | <input checked="" type="checkbox"/> |
| 29                 | 09/02/18 18:28  | <b>Driving License</b><br>[Linked Accident Report Documents]     |  | Load JPG   | <input checked="" type="checkbox"/> |
| No                 | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                                |  | Thumbnail  | Print                               |
| 1                  | 02/05/18 11:59  | <b>General View</b>  |  | Load PDF   |                                     |
| 2                  | 02/05/18 11:59  | <b>Photographs of Damaged Parts</b>                              |  | Load PDF   |                                     |
| Documentation      |                 |  |  | 1 per page | <input checked="" type="checkbox"/> |
| No                 | Finalized On    | China Taiping Insurance (Singapore) Pte. Ltd. (HQ)               |  | Thumbnail  | Print                               |
| 1                  | 19/02/18 10:52  | <b>OI GIA REPORT</b>   |  | Load PDF   |                                     |
| No                 | Finalized On    | Ajax Mars Pte Ltd (Bukit Merah)                                  |  | Thumbnail  | Print                               |
| 1                  | 09/02/18 18:26  | <b>Sketch Plan</b><br>[Linked Accident Report Documents]         |  | Load JPG   | <input checked="" type="checkbox"/> |
| 2                  | 09/02/18 18:26  | <b>Sketch Plan #2</b><br>[Linked Accident Report Documents]      |  | Load JPG   | <input checked="" type="checkbox"/> |

## Linked Accident Report Documents

| Assessment Reports |                |                                 |  | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|---------------------------------|--|------------|-------------------------------------|
| No                 | Finalized On   | Ajax Mars Pte Ltd (Bukit Merah) |  | Thumbnail  | Print                               |
| 1                  | 09/02/18 18:38 | <b>Accident Statement</b>       |  | Load HTM   |                                     |
| Photos/Images      |                |                                 |  | 3 per page | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | Ajax Mars Pte Ltd (Bukit Merah) |  | Thumbnail  | Print                               |
| 1                  | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 2                  | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 3                  | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 4                  | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 5                  | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 6                  | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 7                  | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 8                  | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 9                  | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 10                 | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 11                 | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 12                 | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 13                 | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 14                 | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 15                 | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 16                 | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 17                 | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 18                 | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 19                 | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 20                 | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 21                 | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 22                 | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 23                 | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 24                 | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 25                 | 09/02/18 18:28 | <b>Accident Photo</b>           |  | Load JPG   | <input checked="" type="checkbox"/> |
| 26                 | 09/02/18 18:28 | <b>Identification Card</b>      |  | Load JPG   | <input checked="" type="checkbox"/> |

| Assessment Reports |                |                                 | 1 per page   | <input checked="" type="checkbox"/> |
|--------------------|----------------|---------------------------------|--|-------------------------------------|
| No                 | Finalized On   | Ajax Mars Pte Ltd (Bukit Merah) |  |                                     |
| 27                 | 09/02/18 18:28 | Identification Card             |  Load JPG | <input checked="" type="checkbox"/> |
| 28                 | 09/02/18 18:28 | Driving License                 |  Load JPG | <input checked="" type="checkbox"/> |
| 29                 | 09/02/18 18:28 | Driving License                 |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation      |                |                                 | 1 per page   | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | Ajax Mars Pte Ltd (Bukit Merah) |  |                                     |
| 1                  | 09/02/18 18:26 | Sketch Plan                     |  Load JPG | <input checked="" type="checkbox"/> |
| 2                  | 09/02/18 18:26 | Sketch Plan #2                  |  Load JPG | <input checked="" type="checkbox"/> |

## Documents Checklist

|   |                       |                      |                       |
|---|-----------------------|----------------------|-----------------------|
| <b>DOCUMENTS CHECKLIST</b>  | <a href="#">Reset</a> | <a href="#">Save</a> | <a href="#">Print</a> |
| There are no document checklists configured.                      |                       |                      |                       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>  |                       |                      |                       |
| <div></div>   |                       |                      |                       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer |                       |                      |                       |
| Note: Remarks are private unless you show it to other parties.    |                       |                      |                       |

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18003209/M1D3E2

Date: 14/06/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMHCSN1736231700

Claimant Vehicle  
No : FBH6330SInsured Vehicle  
No : SJH6589T

Date of Loss: 07/02/2018

Nature of Claim: TP

Claim  
No: SNM18D00761C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBH6330S

Make &amp; Model: KAWASAKI VERSYS, 649cc 650 M

Engine No: ER650AEA88661

Reg. Date: 03/04/2012 (Man. Year: 2012)

Chassis No: JKALE650CDDA02508

Colour: Yellow/Black

Odometer: 88797 km

Engine Capacity: 649 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

Front Tyre Size: 120/70 R17

Rear Tyre Size: 160/60 R17

Front Left Side: Bridgestone 8 mm

Rear Left Side: Bridgestone 8 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS            | Repairer's  | Adjuster's  | Difference  | Diff % |
|---------------------------|-------------|-------------|-------------|--------|
| Parts                     | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items       | 0.00        | 0.00        | 0.00        |        |
| Labour                    | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour          | 0.00        | 0.00        | 0.00        |        |
| Towing                    | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (\$\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

## INSPECTION

Date of Assignment: 19/02/2018

Date Inspected: 20/02/2018 Inspected At:

Speedy Motor Cycle Service Centre (HQ)  
10 ANG MO KIO IND PARK 2A #05-21  
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: MA CHIN FOOK

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 -\$9,000.00

## REPAIR DETAILS

|                      |  |   |
|----------------------|--|---|
| <b>Reference</b>     |  |   |
| <b>Part Source:</b>  | (Last Synchronised: 14 Jun 2018)   |   |
| <b>Parts:</b>        | N/A  | KAWASAKI VERSYS 649cc 650 M (Model not available in database) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                             |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for FBH6330S)  |   |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |   |

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >