

Staley

CC4 / ASM1800

3223

/ T1 K0352

LKK:

IDAC:

31149

Surveyor:

MTH

DOI:

2/2/18

Date / Time:

20/2/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGX 4192T

Claim No.:

SGM 00946

Name of Insured:

YU XIN MEI

Policy No.:

GAR583201

Insured Tel No.:

HP:

88291090

Make / Model:

Toyota WISH

Excess Sec II :SS

D.O.A.:

18/2/2018

Place of Accident:

Sentosa Gateway

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

%

Final ? Yes / No

SGX 8633P



INSRS:

WSP:

Tel:

Liability:

RMKS:

W/LGrafen



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

26/2

2min

SGX 8633P - X; SGX 4192T - X

* Pending verification of S.

26/2/2018 @
10:04am.

Spoke to OI (Mr Yuxinmei) - confirmed accident details and OI's stationary vehicle. OI will send any additional photos via email. Informed and TP claim, aware of who will settle and agree to settle. Sent letter to OI.

Email liability claim

27/2/2018: File pass to typist mandate report.

RECEIVED 27 MAR 2018

RECEIVED 15 AUG 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 26/2/2018

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

23/2

Sent By:

Hun

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

PIP S\$ 4,302.59

(3 days)

Reduction:

50

%

Email

Call

FINAL SETTLEMENT

Date/Time: 26.7.18

Confirm with MEIY

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : -W/L

Repair Cost:

W/LST S\$ 4,603.77

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ 180.00

(\$ 60 x 3 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐ LOU only ☒

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$ -

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 4,783.77

Global Sum S\$:

FINAL PAYMENT

Date/Time: 26.7.18

Confirm with: MEIY

Email

Call

Payee 1:

S\$ 4,783.77

Name 1:

VOLKSWAGEN CENTRE SINGAPORE

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$350

15/8/2018

Taufku

AXASm

3223/11ca3

ASSIGNMENT

Date 21/02/18

SKX 8633P 2015 Dec.

Remarks Date

CC TP WS TP RES / CD RES / EVA / INV / MV

To inspect Vehicle No SKX 8633P

at Workshop this Volkswagen

at 247 Alexandru Rd

Insured

Policy No

Claims No


Sum Insured Excess

Client's Record 10am @ owner waiting

Make of Ven

Policy Condition

Remark: The veh had commenced its repair at the time of inspection.



Bel or Market Value

ICAD Accident Report Consistent? Yes or No

GA PP Seen Consistent? Yes or No

Est. Repairs 3 days Rep: Yes or No

LT Sum 1 day O Val: Yes or No

CA / REV / REP / 24 HRS / WP

Date Person Contacted Vehicle IN / OUT

Date Time Action / Instruction

Type of Car M/C/D/S/E/EV/Van/Lorry/Taxi/Prime Mover

Truck Trailer

Make Volkswagen Jetta 1390

Colour Black

Bo Reading 33563

Engine

C No WVVZZZ-1676 M006991

Gen Cond Good Paint Poor Burnt

Steering In order Jammed / Leaked / Burnt or

Brake In order Jammed / Leaked / Burnt or

Mod N/A / STD A/B/C or

Tyre Size 225/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / SUMI

TOYO / YOKO or

Front Rear

PSA 6 6

PSA 6 6

PSA 6 6

DOA 2/2/18 2015

Surveyed at VW Alexander

Des of Damages Fr / Rear / OS / NS / LC / Roof / or

Rear 2's N/S

The U/C / Chassis frame Body Structure affected due to collision

(P/P: \$4302.59 / red: \$4249.22 / 50%)

Date Time File Pass of Preli. Report

Date Time File Return of Final Report

Days Of Repair

Resurvey No. of Trip

Report Format

LT Sum AB 1/15

Add Fee: ☐ Site Fee \$ ☐ Test Fee \$ ☐ Test Fee \$ ☐ Test Fee \$

Surve Fee

Transport

Light

Other

Total

Blank box for signature or stamp.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18003223/T1ka3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 20-02-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGX 4192T	Veh. Inspected	SKX 8633P	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00946	Excess (\$)	0.00	
Assign From		Assign Date	20/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/02/2018	Inspection Date	21/02/2018	
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Service Order Confirmation

SERVICE ORDER NO.: 18IP0554

CUSTOMER NO.: QV031863

CUSTOMER NAME: PHUA KOK FONG

TELEPHONE NO.:

ADDRESS: 27A JALAN MEMBINA #20-138

Singapore

VEH No.: SKX8633P

Order Date: 27/02/18

Reg Date: 30/12/15

KM: 34,726

VIN NO.: WVVZZZ16ZGM006996

ENGINE NO:

SA: Kong Charmaine

MODEL: JETTA TSI (DSG) HIGHLINE HHC MODEL NO.: 1634G7

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P DIAG PROGRAMMING & CALIBRATION- NETT	✓ 1	TU	480		480
2	B&P MECH ELECT WIRING & MECH COMPONENT CHECK NETT	✓ 1	TU	280		280
3	B&P ALEX LABOUR LABOUR	✓ 1	UNIT	840		840
4	B&P ALEX PAINT SPRAY PAINT	✓ 1	UNIT	800		800
5	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
6	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
Item						
7	5C6807421H GRU REAR BUMPER - IMPROVE	✓ 1	PCS	1,256.64		1,256.64
8	5C6807863B STRIP	✓ 1	PCS	96.99		96.99
9	5C6807375 BUMPER BRACKET LH	✓ 1	PCS	83.31		83.31
10	5C6807393D BUMPER GUIDE LH	✓ 1	PCS	69.79		69.79
11	5C6919491D SENSOR BRACKET	✓ 1	PCS	23.79		23.79
12	5C6919491E SENSOR BRACKET	✓ 1	PCS	23.79		23.79
13	5C6919491E SENSOR BRACKET	✓ 1	PCS	23.79		23.79
14	5C6919492D SENSOR BRACKET	✓ 1	PCS	23.79		23.79
15	5Q0919133 SENSOR O-RING	✓ 1	PCS	0.20		0.20
16	5Q0919275B GRU SENSOR	✓ 1	PCS	144.39		144.39
17	D 622150A1 BONDAGENT	✓ 1	PCS	64.27		64.27
18	D 180KU2A1 2KADHESIVE	✓ 1	PCS	89.84		89.84

Remarks : AXA DIRECT SETTLEMENT

DOA 18/02/2018

SURVEYOR LKK

TP VEHICLE SGX4192T

Service Order Confirmation

SERVICE ORDER NO: 18IP0554

CUSTOMER NO.: GV031863

CUSTOMER NAME: PHUA KOK FONG

TELEPHONE NO.:

ADDRESS: 27A JALAN MEMBINA #20-138

Singapore

VEH No.: SKX8633P

Order Date: 27/02/18

Reg Date: 30/12/15

KM: 34,726

VIN NO.: WVVWZZZ1E2GM006996

ENGINE NO:

SA: Kong Charmaine

MODEL: JETTA TSI (DSG) HIGHLINE HHC MODEL NO.: 1634G7

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
-----	-------------	-----	-----	------------	--------	--------

TOTAL	4,302.59
-------	----------

GST AMOUNT	301.18
------------	--------

TOTAL AMOUNT	4,603.77
--------------	----------

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

PDI TUAS

PDI TUAS

PHUA KOK FONG
(PAN GUOFENG)
27A JALAN MEMBINA
#20-138
Singapore, 163027
Singapore

Tanjil 97495749
21/2/18 @ 1010
3 days 'wp'
sur @ luhants. am
Reusing hufe paint

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV031863
Quote No. SER/QUO/1800301
QuoteDate 19/02/18
Salesperson Shawn Lim
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) HIGHLINE HIDC	27,967	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SKX8633P	WVWZZZ16ZGM006996	30/12/15	Shawn Lim
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX F82976	1634G7

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	3	UNIT		840 2,520.00
P B&P ALEX PAINT	SPRAY PAINT	3	UNIT		800 2,400.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		✓ 480.00
P B&P MECH	ELECT WIRING & MECH COMPO	1	Time Un		✓ 280.00
	Nett				
	Sum Labor				5,680.00
P 5C6807251E	FOAM INSERT	1	Pieces		un X 142.24
P 5C6807305	BUMPER REINFORCEMENT	1	Pieces		un X 445.64
P 5C6807375	BUMPER BRACKET LH	1	Pieces		rel 83.31
P 5C6807376	BUMPER BRACKET RH	1	Pieces		un X 83.31
P 5C6807393D	BUMPER GUIDE LH	1	Pieces		rel 69.79
P 5C6807394D	BUMPER GUIDE RH	1	Pieces		un X 69.79
P 5C6807417J GRU	REAR BUMPER COVER	1	Pieces		1,258.64 de 1,020.21
P 5C6807433J	SPOILER	1	Pieces		un X 412.75
P 5C6807863B	STRIP	1	Pieces		rel 96.99
P 5C6919491D	SENSOR BRACKET	1	Pieces		23.79
P 5C6919491E	SENSOR BRACKET	1	Pieces		rel 23.79
P 5C6919491E	SENSOR BRACKET	1	Pieces		✓ 23.79
P 5C6919492D	SENSOR BRACKET	1	Pieces		un X 23.79
P 5C6945105B	LH REAR REFLECTOR	1	Pieces		rel X 53.98
P 5Q0919133	SENSOR O-RING	1	Pieces		rel 0.20
P 5Q0919275B GRU	SENSOR	1	Pieces		mis 144.39
	Use Predecessor 5Q0919275 GR				
P D 180KU2A1	2KADHESIVE	1	Pieces		rel 89.84
Sum carried forward					8,487.60

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

PHUA KOK FONG
(PAN GUOFENG)
27A JALAN MEMBINA
#20-138
Singapore, 163027
Singapore

Phone No.

Fax No.

E-Mail

VAT Registration No. M20098505-2

Tax No. 199101494Z

Service Quote

Customer No. CV031863
Quote No. SER/QUO/1800301
QuoteDate 19/02/18
Salesperson Shawn Lim
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) HIGHLINE HIDC	27,967	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SKX8633P	WWWZZZ16ZGM006996	30/12/15	Shawn Lim
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX F82976	1634G7
Continued			8,487.60
P D 822150A1	BONDAGENT	1 Pieces	64.27
	Sum Item		2,871.87
Sum Labor			5,680.00
Sum Item			2,871.87
Total SGD			8,551.87
7% GST			598.63
Total SGD Incl. GST			9,150.50

Explanations

P = Proportionately Charged

Payment Terms

No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Payments to: - BBN: - Acc.-No...



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M00946
Our ref: CC4/ASM18003223/T1ka3

Date: 23.02.2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKX 8633P


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21.02.2018 at the premises of M/s Volkswagen Centre Singapore and have the following to report:-

Workshop Estimate Amount	: S\$	8,551.87
Revised Estimate Amount	: S\$	3,974.32
"Check" Items Amount	: S\$	698.81
Total (Including Check Items)	: S\$	4,673.13
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

OneCare Clinic Tiong Bahru
11A Boon Tiong Road #01-08 Singapore 161011
Tel: 63582568

MEDICAL CERTIFICATE

This is to certify that **PHUA KOK FONG(PAN GUOFENG) (S7615701D)** is under treatment by me.

Unfit For Duty

Outpatient Leave: 1 Day From 19-02-2018 To 19-02-2018

Certified By:
Dr. Trina Tay (M17569B)

Certificate No: MC/96458

Date of Visit: 19-02-2018

Date of Issue: 19-02-2018

Note:

This certificate is not valid for absence from court.

This certificate is electronically generated. No signature is required.

 OneCare Clinic Tiong Bahru Pte Ltd
11A Boon Tiong Road Tel: 6358 2568
SG 161011 Fax: 6358 2569

◀ Re:MANDATE REQUEST FOR S8M00946

Type

📘 Information

Message

Pls proceed

Reply



MANDATE REQUEST FOR S8M00946

Smsy

Type

🔗 Question

Message

Liability: Insured rear ended third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$4,603.77 (w/GST) Loss of Use: \$180.00 (3days x \$60) Total: \$4,783.77 Revised Immediate Advice with Mandate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (04/06/2018)

Reply

Volkswagen Centre Singapore



Biz Reg. No. 53103069E
GST No. M20098505-2

DISCHARGE VOUCHER

I / We PHUA KOK FOAY (Passport No. S7615701D) the
owner of vehicle number SKX 8633P hereby accept from
_____ (Insurance Company) the sum of
_____ (total repair cost) in full and final settlement for the cost of repairs
arising from the loss damage of property as a result of the accident involving
SKX 8633P & SGX 41927 along WEST COAST HIGHWAY
on 18/02/2018.

Please pay to Volkswagen Group Singapore Pte Ltd who is authorized to receive
only on the total cost of repair on my/our behalf.

The lost of use (transport allowance / rental receipts) to be payable to
_____.

Dated this on 14/03/2018 (DD/MM/YYYY)


(Signature of owner / Company stamp)

Name : Phua Kok Foy

NRIC No: S7615701D

Date : 17/3/18

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGX 4192T (Insd veh)	Model:	VOLKSWAGEN
	SKX 8633P (TP veh)		JETTA GP 1.4 TSI 90 A/T HL
Date of Accident:	18/02/2018		HID 1634G5

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	9,150.50
Final Repair Cost	:	\$	4,603.77
Loss of Use	:	\$	180.00
Rental (if any)	:	\$	3 days at \$60.00 per day
LTA / GIA Search Fee	:	\$	days

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	4,783.77

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop:	Agreed Liability	100	(%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No	BOLA Scenario No:	
	BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)	

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

Payment Instruction: Payee's Breakdown			
1)	VOLKSWAGEN CENTRE SINGAPORE	:	\$ 4,783.77

NUR SHAQILAH BTE ABDOL
WAHAB

03/09/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

<< Service Request Details

Claim

SBM00946

Reference

CC4/ASM18003223/TTea3s2  Loss Date

Request Date

February 18, 2018

Due Date

February 20, 2018

Vendor Name

February 23, 2019

Type of Loss

LKK AUTO CONSULTANTS PTE LTD (TP)

Services

Third Party Vehicle Damage

Pending verification - Direct Settlement

Additional Instructions

Actions

Next Step

Finish the work

Complete (link)

More

Document Type

Document Sub Type

Upload Documents

Vehicle Information

Incident Vehicle Registration #

SKX8633P

Service Address

Make

TPVD VOLKSWAGEN

Model

...

Primary Contact/Insured

JETTA TSI (DSG) HIGHLINE HIDC

YU XINMEI

9 ROSEWOOD DRIVE, #09-20, 737938, Singapore

98291090

xinmei7192@163.com

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Messages

Assessment

Invoices

History

Documents

DATE UPLOADED

June 4, 2018

NAME

TYPE

SUB-TYPE

AUTHOR

Immediate Advice with Mandate.pdf

Reports & Statement

Others

LKK AUTO CONSULTANTS PTE LTD (TP)

SERVICE REQUESTSMESSAGESCLAIMS

Service Request Details

Claim S8M00946

Reference

CC4/ASM18003223/T1es3s2 Loss Date

February 18, 2018 Request Date

February 20, 2018 Due Date

February 23, 2019 Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP) Type of Loss

Third Party Vehicle Damage Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

More

Add

Vehicle Information

Incident Vehicle Registration # SKX8633P

Make Service Address

TPVD VOLKSWAGEN Model

JETTA TSI (DSG) HIGHLINE HIDC Primary Contact/Insured

YU XINMEI

9 ROSEWOOD DRIVE, #09-20, 737938, Singapore 98291090

xinmei7192@163.com

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
NIKAM Santosh Pandurang	2/20/18 9:45 AM	4302.59	4302.59	Open	Share	Clone

Assessment Details

General & Workshop Details Vehicle & Driver Details Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	SI0XB633P	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	12/30/2015
Mileage	33563	Age of Vehicle	2

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	POST SURVEY INFORMATION
Manufacturing Year		2015	
Make	TPVD VOLKSWAGEN	VOLKSWAGEN	Driver Name KOK FONG PHUA
Model	JETTA TSI (DSG) HIGHLINE HIDC	JETTA GP 1.4 TSI 90 A/	Date of Birth May 25, 1976
Type			Age 42
Type of Paint			Occupation Unknown
Chassis No		WVWZZZ16ZGM00695	Education Qualification Other
Engine No		CAXF82976	Driving Experience 0
Engine Capacity		1390 cc	Driver License #

<< Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *	02/21/2018	
Total Loss	Yes	No
Towing Charges	0	
Voluntary Excess	0	
Compulsory Excess	0	
Young/Inexperienced/Unarmed Driver Excess	0	
Other Excess		
General condition	Good	
Steering (Serviceable)	Yes	No
Footbrake (Serviceable)	Yes	No
Handbrake (Serviceable)	Yes	No
Engine Modification	Yes	No
Pre-accident condition	Good	

Tyre Condition

Age of Tyres		
Front Tyre Size	225/40R18	225/40R18
Front left side	PIRELLI 6mm	PIRELLI 6mm
Front right side	PIRELLI 6mm	PIRELLI 6mm
Spare wheel		
Rear Tyre Size	225/40R18	
Rear left side	PIRELLI 6mm	
Rear right side	PIRELLI 6mm	

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Auto

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		3	
	2	FOAM INSER	Reviewing	0	NOT NECESSARY	
	3	BUMPER REINFORCEMENT	Reviewing	0	NOT NECESSARY	
	4	BUMPER BRACKET LH	Reviewing	83.31	NECESSARY	
	5	BUMPER BRACKET RH	Reviewing	0	NOT NECESSARY	
	6	BUMPER GUIDE LH	Reviewing	69.79	NECESSARY	
	7	BUMPER GUIDE RH	Reviewing	0	NOT NECESSARY	
	8	REAR BUMPER COVER	Reviewing	1258.64	DEFORMED	
	9	SPOILER	Reviewing	0	NOT NECESSARY	
	10	STRIP	Reviewing	96.99	NECESSARY	
	11	SENSOR BRACKET	Reviewing	23.79	NECESSARY	

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Claim Amount \$4,302.59

Claim Amount \$4,302.59

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$2,400.00	\$2,400.00
Miscellaneous	\$1,902.59	\$1,902.59

Submit for Review