

76

CC 4 / ASM1800 3224

/ R1 KAS

IDAC

51203

Surveyor

DOI

ASSIGNMENT

21/1/2018

Date / Time

Registered in

20/1/18

Pre-assign / CCU / FTE

Insured Vehicle No.

Name of Insured

Insured Tel No.

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

PIP S\$13,582.74

( 7 days) Reduction:

21 %

Email

Call

FINAL SETTLEMENT

Date/Time: 02.2.18

Confirm with: SIA

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

01/01

S\$14,583.53

010 re-issued TP

Loss of Rental (LOR):

S\$

( days) :

Loss of Use (LOU):

S\$ 720.00

(\$80 x 9 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$15,355.53

Global Sum S\$:

FINAL PAYMENT

Date/Time: 12.2.18

Confirm with: SIA

Email

Call

Payee 1:

S\$15,355.53

Name 1:

VOUCHER GROUP SINGAPORE PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

RECEIVED 17 APR 2018

21/1/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Rame


248514

## ASSIGNMENT

From \_\_\_\_\_ Date \_\_\_\_\_  
 Estimated Cost \_\_\_\_\_  
 OO: TP WS TPRES OO: RES / EVA / INV / MV  
 To: Insured Vehicle No. SLN 994R  
 at Workshop no. Volkswagen  
 of KA AMPAT  
 Insured MSK/PP  
 Policy No. \_\_\_\_\_  
 Date No. \_\_\_\_\_  
 Sum Insured \_\_\_\_\_ Excess \_\_\_\_\_  
 Clients Record \_\_\_\_\_  
 Make of Van \_\_\_\_\_

Policy Condition:

Remark: The veh had commenced its repair at the time of inspection.



Est. of Market Value \_\_\_\_\_  
 OAC Accident Report \_\_\_\_\_ Consistent? Yes or No  
 OAC PR Seen \_\_\_\_\_ Consistent? Yes or No  
 Est. Repairs 1 days Res. Yes or No  
 Lim Sum - \$ 3 val. Yes or No

CA / REV / REF / 24 HRS

Date \_\_\_\_\_ Person Contacted \_\_\_\_\_ Vehicle IN / OUT

Date / Time Action / Instruction

PP: +13,580.74 CRED: +3,500.99 21/1

SLN 994R 2017 APR

Type: M/Cat M/Cycle: E/B/Van: Lorry: Taxi: Prime/Novan:

Truck: Transport:

Make: Volkswagen PASSAT 1.8 cc 1798Color: GREEN AC Insured: Std / N / NASo: Passeng: 6144 T: Pass Insured: Std / N / NA

Eng No:

Ch: WVWZZZ3CZGE114429Ser: Cond: Good ☒ Poor: BurntSteering: ☒ Jammed: Leaked: Burnt: orBrake: ☒ Jammed: Leaked: Burnt: orMod: Nil ☒ STD: A/R: orTyre Size: R 215/55R17

R \_\_\_\_\_

BS / DUN / EXNOVA / GY / PS / LIZA / MIO / OHTS ☒ P / SUM

TOYO / YOKO: or

Front:

R/Sa: 6 --- R/Sa: 6 ---L/Sa: 6 --- L/Sa: 6 ---D/OA: 21/02/18 D/O: 21/02/18Surveyed at: Volkswagen KA AMPATDet. of Damages: Fr: ☒ D/S: NS: UC: Referred: or

The U/C / Chassis/frame Body Structure affected due to collision

Date/Time File Pass of: ☐ Prel. Report  
☐ Final Report

Date/Time File Return of:

Days Of Repair:

Resurvey No. of Trip:

Date: Fee:

Transport:

L: + \$:

Fuel:

Other:

Total:

Date:

Add Fee:

☐

Eng: Insp: or

☐

Tech: or

☐

Tech: or

☐

Tech: or

☐

Tech: or

Report Format:

Date: Time: or

Date: Time: or




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18003229/R1ka3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 20-02-2018	
			Code : ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKP 9890Z	Veh. Inspected	SLN 994R	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M0096W	Excess (\$)	0.00	
Assign From		Assign Date	20/02/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	20/02/2018	Inspection Date	21/02/2018	
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 1 KAMPONG AMPAT OFF MACPHERSON ROAD SINGAPORE 368314			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

## PDI TUAS

PDI TUAS

YONG TUCK CHEE  
156 JALAN TECK WHYE  
#08-55  
Singapore, 680156  
Singapore

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

## Service Quote

Customer No. CV039595  
Quote No. SER/QUO/1800308  
QuoteDate 20/02/18  
Salesperson Reeve Hiah  
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Passat 1.8 TSI Comfortline	1,721	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SLN994R	WVWZZZ3CZGE114429	21/04/17	Reeve Hiah
Engine Code	Labor Type	Engine No.	Model Code
	1P	CJS 130884	3G24JZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P MACP LABOUR	LABOUR <del>1 REPAIRER 5000 TRAIL</del>	5	UNIT		1680 3,360.00
P B&P MACP PAINT	SPRAY PAINT <del>5000 TRAIL</del>	5	UNIT		3,200 2400 4,000.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	pcs		74 80.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		480.00
P B&P MECH	ELECT WIRING & MECH COMPO Nett	1	Time Un		280.00
	<b>Sum Labor</b>				<b>9,040.00</b>
P 3G0807521B GRU	SPOILER	✓	Pieces		cut 124.44
P 3G0853675F JZQ	TSI EMBLEM	✓	Pieces		net 51.65
P 3G0853687 2ZZ	PASSAT EMBLEM	✓	Pieces		net 55.86
P 3G0853835 2ZZ	CENTRE BUMPER MOLDING	✓	Pieces		cut 174.41
P 3G0853841 2ZZ	LHR BUMPER MOULDING Use Predecessor 3G0807367 9B9	✓	Pieces		cut 138.17
P 3G0853842 2ZZ	RHR BUMPER MOULDING	✓	Pieces		net 138.17
P 3G0945103A	LHR INNER REFLECTOR	✓	Pieces		net 39.29
P 3G0945104A	RHR INNER REFLECTOR	✓	Pieces		SUL X 60.61
P 3G0945105A	LHR OUTER REFLECTOR	✓	Pieces		net 39.29
P 3G0945106A	RHR OUTER REFLECTOR	✓	Pieces		SUL X 60.61
P 3G0998491	REAR SENSOR BRACKET	✓	Pieces		net 55.40
P 3G5807417 GRU	REAR BUMPER	✓	Pieces		net 972.08
P 3G5827025A	BOOT LID	✓	Pieces		R 1,431.69
P 510853617A FOD	VW SIGN	✓	Pieces		net 82.51
P 5G0853675APCWB	BLUEMOTION EMBLEM Use Predecessor 5G0853675ALC	✓	Pieces		net 50.05

Sum carried forward

12,514.21

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

YONG TUCK CHEE  
156 JALAN TECK WHYE  
#08-55  
Singapore, 680156  
Singapore

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

## Service Quote

Customer No. CV039595  
Quote No. SER/QUO/1800308  
QuoteDate 20/02/18  
Salesperson Reeve Hiah  
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Passat 1.8 TSI Comfortline	1,721	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SLN994R	WVWZZZ3CZGE114429	21/04/17	Reeve Hiah
Engine Code	Labor Type	Engine No.	Model Code
	1P	CJS 130884	3G24JZ

		Continued	12,514.21
P 5Q0919133 9B9	REAR SENSOR O RING	2 Pieces	3.43
P 5Q0919275B GRU	REAR CENTRE SENSOR	2 Pieces	288.80
	Use Predecessor 5Q0919275 GR		
P WHT005263	POP-RIVET	5 Pieces	7.35
	Sum Item		3,773.78

Sum Labor	9,040.00
Sum Item	3,773.78

Total SGD	12,813.78
7% GST	896.99
Total SGD Incl. GST	13,710.78

### Explanations

P = Proportionately Charged

### Payment Terms

No Credit

*Rashu*  
*Hp 90010068*  
*7 days*  
*21/02/18 @ 15:00*  
*Reg by paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Payments to:

- BBN: - Acc.-No.:

## Service Order Confirmation

SERVICE ORDER NO: 18IP0590  
 CUSTOMER NO.: CV038585  
 CUSTOMER NAME: YONG TUCK CHEE  
 TELEPHONE NO.:  
 ADDRESS: 156 JALAN TECK WHYE #08-55  
 Singapore

VEH No.: SLN994R

Order Date: 01/03/18  
 Reg Date: 21/04/17 KM: 6,943  
 VIN NO.: WVVZZZCZGE114428 ENGINE NO:  
 MODEL: Passat 1.8 TSI Comfortline MODEL NO.: 3G34JZ

SA: Tang Shu Shi

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
<b>Labor</b>						
1	B&P DIAG	1	TU	480		480
2	B&P MECH	1	TU	280		280
3	B&P MACP LABOUR	4	UNIT	840		3,360
4	B&P MACP PAINT	4	UNIT	500		2,000
5	B&P NUMBER PLATE	1	ST	60		60
6	EXT00037	1	UNIT	0		0
7	EXT00037	1	UNIT	0		0
8	B&P MACP LABOUR	1	UNIT	840		840
<b>Item</b>						
9	3G5807417 GRU	✓	PCS	972.08		972.08
10	3G0907521B GRU	✓	PCS	124.44		124.44
11	WHT005263	✓	PCS	1.47		7.35
12	3G0853841 ZZZ	✓	PCS	138.17		138.17
13	3G0853842 ZZZ	✓	PCS	138.17		138.17
14	3G0853835 ZZZ	✓	PCS	174.41		174.41
15	5Q0919133 3008	✓	PCS	1.72		3.43
16	3G0908491	✓	PCS	55.40		55.40
17	3G0945105A	✓	PCS	39.29		39.29
18	3G0853887 ZZZ	✓	PCS	55.86		55.86
19	3G0853875F JZQ	✓	PCS	51.85		51.85
20	5G08538754PCWB	✓	PCS	50.05		50.05
21	510853817A FOD	✓	PCS	82.51		82.51
22	3G5813315	1	PCS	318.30		318.30
23	D 007800A1	1	PCS	67.97		67.97
24	D 18000M2	1	PCS	286.20		286.20
25	D 478K01M2	1	PCS	77.38		77.38
26	3G5807863	1	PCS	47.60		47.60
27	3G0945103A	1	PCS	39.29		39.29
28	8K0973703G	1	PCS	10.29		10.29

## Service Order Confirmation

SERVICE ORDER NO.: 18P0590

CUSTOMER NO.: CV038885

CUSTOMER NAME: YONG TUCK CHEE

TELEPHONE NO.:

ADDRESS: 156 JALAN TECK WHYE #08-55  
Singapore

VEH No.: SLN994R

Order Date: 01/03/18

Reg Date: 21/04/17 KM: 6,943

VIN NO.: WYVWZZZ3CZG2114428

ENGINE NO:

SA: Tang Shi Shi

MODEL: Passat 1.8 TSi Comfortline

MODEL NO.: 3Q24J2

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
29	3Q2250809M REAR SILENCER	1	PCS	684.98	BT ✓	684.98
30	1K0253141T CLAMP	2	PCS	69.13	nee ✓	138.26
31	3Q0807305T REAR REINFORCEMENT	1	PCS	540.99	BT ✓	540.99
32	3Q2250409H CENTRE SILENCER	1	PCS	1,134.90	BT ✓	1,134.90
33	3Q0825711 REAR SILENCER HEAT SHIELD	1	PCS	103.60	BT ✓	103.60

Remarks: AXA DIRECT SETTLEMENT

DOA: 25/02/2018

TP VEHICLE: SKP98902

SURVEY BY: RASUL (LKK)

SPRAY REAR BUMPER, REAR BOOTLID, END PANEL, REAR SPOILER

NO OF REPAIR WORKING DAYS: 3 WORKING DAYS

TOTAL	13,582.76
GST AMOUNT	900.79
TOTAL AMOUNT	14,533.55

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

ERNEST



## MANDATE REQUEST FOR S8M0096W

Type

Question

Message

Liability: Insured rear ended third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$14,533.53 (w/GST) Loss of Use: \$720.00 (9days x \$80) GIA Search: \$2.00 Total: \$15,255.53 Revised Immediate Advice with Mandate and marked estimate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (18/07/2018)

Include





## Re:MANDATE REQUEST FOR S8M0096W / S8M0098E

Type

🔗 Question

Message

Hi, we agree to the COR but however for the LOU, we will propose \$60 per day. Thank you.

Reply



## RE: Re:MANDATE REQUEST FOR S8M0096W / S8M0098E

Type

🔗 Question

Message

Hi, TP disagreed with our of LOU @ \$60/day, please refer to TP email and let us have the approval / instruction if any. Thanks - Asher Sng - 10/01/19

Reply



## Re:RE: Re:MANDATE REQUEST FOR S8M0096W / S8M0098E

Type

🔗 Question

Message

Hi, pls propose \$80 up to \$100 for the LOU. TY.

Reply



**LETTER OF DEMAND**

Your Ref: SKP 98902

Our Ref: SLN994R

To: AXA INSURANCE PTE LTD

Dear Sirs,

ACCIDENT INVOLVING SLN994R & SKP 98902 ON 20-03-2018

We are claiming on behalf of our client Yong Tuck Chee owner of

vehicle number SLN994R involved in accident on 20-03-2018

with vehicle SKP 98902 along/at CTE towards Clementine Ave.

Description of claims:

Cost of Repairs \$ 13,982.74 + 7% GST = \$ 14,533.53

Loss of Use/Rental \$ 120 + 7% GST X 9 Days = \$ 1,080

Medical Fee \$ \_\_\_\_\_ + 7% GST = \$ \_\_\_\_\_

Search Fee \$ 2 + 7% GST = \$ 2

TOTAL \$ 15,615.53

We are claiming in full and final settlement of \$ 15,615.53.

Cost of repair & search fee \$ 14,533.53 to be payable to Volkswagen Group Singapore Pte Ltd.

Loss of use/Rental amount/Medical fee of \$ 1,080 to be payable to

Yong Tuck Chee

Kindly send us a written acknowledgement within 14 days from receipt of this document. Please note that finalization/settlement offer of this claim should be within 8 weeks from the date of this document. Please email all settlement offers to [shushi.tang@vw.com.sg](mailto:shushi.tang@vw.com.sg)

Dated this



06 APR 2018



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

07 MARCH 2018

ERLIN YEO YUAN NEE  
BLOCK 75C REDHILL ROAD  
#05-74  
SINGAPORE 153075

Dear Sir/Madam,

**OUR REF : CC4/ASM18003229/R1ka3**

**YOUR REF : SKP 9890Z**

**ACCIDENT INVOLVING SKP 9890Z AND SLN 994R ALONG CTE TOWARDS  
MERCHANT ROAD ON 20.02.2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from VOLKSWAGEN CENTRE SINGAPORE, acting on behalf of the owner of SLN 994R against your motor insurance policy.

Based on the accident report, accident scenario, it was reported that your vehicle had rear-ended the Third Party vehicle SLN 994R. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to [Zaini@lkkauto.com](mailto:Zaini@lkkauto.com) within 10 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 / TEL : (065) 62563561 / FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [Zaini@lkkauto.com](mailto:Zaini@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,



Zaini  
Case Handler  
DID: 6841 2132  
FAX: 6741 4108  
Email: [Zaini@lkkauto.com](mailto:Zaini@lkkauto.com)

c.c. AXA Insurance Pte Ltd (AXA)  
(Motor Claims Dept)

# Volkswagen Centre Singapore



Biz Reg. No. 53103069E  
GST No. M20098505-2

## LETTER OF AUTHORITY

ACCIDENT INVOLVING SLN994R and SKP 9890Z on 20/07/18  
along CTE towards Clementine Ave  
Own vehicle's number Other vehicle's number Date of accident  
Accident location

BY THE LETTER OF AUTHORITY, I/we, Yong Tuck Choo  
of BLK 156 JIN TECK WHYE #108-55 S 680156 Name of Policy Holder & IC / Passport number  
owner of Vehicle Registration

Number SLN994R Own vehicle's number hereby irrevocable appoint **Volkswagen Centre Singapore**

(hereinafter refer to VGS), a company incorporated in Singapore and having its registered office at **247 Alexandra Road, Singapore 159934**, its agents of any person authorized by VGS to be \*my / our Attorney and in \* my / our name(s) on \*my / our behalf to do all or any of the following:

1. To submit, resolve and make any claim(s) (including the commencement of legal proceedings) which \*I/we may have against the other \*party/parties to the Accident and under the insurance \*policy/policies taken up by such \*party/parties or **alternatively** under Insurance Policy number GA303729/1 taken up by \*me/us and pay the **compulsory excess** in respect of the cost repairs suffered by \*me/us arising from the Accident (loss and damage)/.
2. To collect payment(s) due in respect of any such claim(s) for the loss and damage, such payment to be made by way of Cheque in favour of **Volkswagen Centre Singapore** and give a valid receipt and discharge therefore.
3. For any of the purpose aforesaid, to execute, sign and deliver all documents whatsoever in relation thereto.
4. Generally do all such acts as it shall deem necessary for the purpose of settling such claim.

\*I/We hereby declare that all acts, instruments and documents done by virtue of this letter of authority on \*my/our behalf by the Attorney, its agents or any person authorized by VGS in that behalf shall be as good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by \*me/us in \*my/our own proper person(s) and \*I/we hereby ratify and confirm, all acts, instruments and documents done or executed by virtue of the authority and powers hereby conferred.

\*I/We hereby further declare that the **letter of authority hereby conferred shall remain irrevocable.**

\*I/We further confirm that the acceptance by VGS of the settlement amount in respect of such constitute the full discharge of \*my/our claim(s) in respect of such loss and damage.

IN WITNESS WHEREOF, \*I/we have hereunto to set \*my/our hand and sign this 16 of the month 3 Year 18.

Signed & Delivered By:

  
Policy Holder

Witness By:




redefining / insurance

CLAIM REF : S8M0096W  
INSURED : ERLIN YEO YUAN NEE

DISCHARGE VOUCHER

We/I [YONG TUCK CHEE, NRIC NO. S1622489H] hereby agree to accept the sum of [FIFTEEN THOUSAND TWO HUNDRED FIFTY FIVE AND CENTS FIFTY THREE ONLY.] [S\$15,255.53] to ~~us~~/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property and all costs and expenses that we/I have or may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. [SKP 98902] as a result of an accident at [CTE TOWARDS CLEMENCEAU AVE (OUTRUM EXIT)] on [20/02/2018] of which we/I were/was the ~~hmr~~/owner/driver/pillion/Passenger/ Insurer of motor vehicle [SLN 994R].

We/I hereby declare that the said insurer or owner and/or driver of Insured vehicle shall not be liable for all claim(s) whatsoever and whosoever present or future that we/I have or may have against the said Insurer, owner and/or driver of vehicle no. [SKP 98902] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [SKP 98902]

Dated this 14 day of February 2019

Claimant's Signature

[Signature]

NRIC no./ Company Stamp

: S 1622489 H

Occupation/ Business

: Assistant General Manager

Address

: Blk 156, Jalan Tekong Whye #08-55, S(680156)

Telephone No.

: 90027602

Witness's Name

: \_\_\_\_\_

Witness's Signature

: \_\_\_\_\_

Witness's NRIC No.

: \_\_\_\_\_





# Volkswagen Centre Singapore



Service Tax Invoice No. SV18P12425

Biz Reg. No. 53103069E  
GST No. M20098505-2

SERVICE ORDER NO: 18IP0590

SERVICE CUSTOMER NO.: CV000066

SERVICE CUSTOMER NAME: AXA INSURANCE SINGAPORE PL

TELEPHONE NO.:

ADDRESS: 8 SHENTON WAY  
#27-01 AXA TOWER  
Singapore

Post Code: 068811

VEH NO.: SLN994R

DATE: 19/03/18 Pickup:  
VIN NO.: WVVWZZ3CZGE114429 KM: 5,943  
GEARBOX CODE: Engine No.:  
MODEL: Passat 1.8 TSI Comfortline  
SA: Tang Siu Shi  
Next Appointment Date :  
Next Appointment Mileage : 0

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT
AXA DIRECT SETTLEMENT					
DOA: 20/02/2018					
TP VEHICLE: SKP9890Z					
SURVEY BY: RASUL (LKK)					
SPRAY REAR BUMPER, REAR BOOTLID, END PANEL, REA					
NO OF REPAIR WORKING DAYS : 9 WORKING DAYS					
Labor					
1	LABOUR + 3 DAYS (REPLACED END PANEL)	4.00	UNIT	840.00	3,360.00
2	R&R EXHAUST PIPE	1.00	UNIT	840.00	840.00
3	SPRAY PAINT + END PANEL	4.00	UNIT	600.00	2,400.00
4	B&P NUMBER PLATE -NETT	1.00	ST	80.00	80.00
5	Tow SVC- Quality Recovery Services	1.00	UNIT		
6	Tow SVC- Quality Recovery Services	1.00	UNIT		
7	PROGRAMMING & CALIBRATION- NETT	1.00	TU	480.00	480.00
8	ELECT WIRING & MECH COMPONENT CHECK NE	1.00	TU	260.00	260.00
Item					
9	CLAMP	2.00	PCS	69.13	138.26
10	REAR SILENCER	1.00	PCS	664.98	664.98
11	REAR REINFORCEMENT	1.00	PCS	540.99	540.99
12	SPOILER	1.00	PCS	124.44	124.44

# Volkswagen Centre Singapore



Service Tax Invoice No. SV18P12425

Biz Reg. No. 53103069E  
GST No. M30096505-2

SERVICE ORDER NO: 18IP0590

SERVICE CUSTOMER NO: CV000086

SERVICE CUSTOMER NAME: AXA INSURANCE SINGAPORE PL

TELEPHONE NO:

ADDRESS: 8 SHENTON WAY  
#27-01 AXA TOWER  
Singapore

Post Code: 068811

VEH NO.: SLN994R

DATE: 19/03/18

Pickup:

VIN NO.: WVVZZZ3CZGE114429

KM: 6,943

GEARBOX CODE:

Engine No:

MODEL: Passat 1.8 TSI Comfortline

SA: Tang Shu Shi

Next Appointment Date:

Next Appointment Mileage: 0

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT
13	TSI EMBLEM	1.00	PCS	51.85	51.85
14	PASSAT EMBLEM	1.00	PCS	55.86	55.86
15	CENTRE BUMPER MOLDING	1.00	PCS	174.41	174.40
16	LHR BUMPER MOULDING	1.00	PCS	136.17	136.17
17	RHR BUMPER MOULDING	1.00	PCS	136.17	136.16
18	REFLECTOR OUTER LH	1.00	PCS	39.26	39.26
19	LHR OUTER REFLECTOR	1.00	PCS	39.29	39.29
20	REAR SENSOR BRACKET	1.00	PCS	55.40	55.40
21	REAR BUMPER	1.00	PCS	972.08	972.08
22	BUMPER CENTRE BRACKET	1.00	PCS	47.80	47.80
23	REAR END PANEL	1.00	PCS	316.30	316.30
24	CENTRE SILENCER	1.00	PCS	1,134.90	1,134.90
25	REAR SILENCER HEAT SHIELD	1.00	PCS	103.60	103.60
26	VW SIGN	1.00	PCS	82.51	82.52
27	BLUEMOTION EMBLEM	1.00	PCS	50.05	50.05
28	REAR SENSOR O RING	2.00	PCS	1.72	3.43
29	WIRE HOUSING	1.00	PCS	10.29	10.29
30	INKSPRAY	1.00	PCS	67.97	67.97

# Volkswagen Centre Singapore



Service Tax Invoice No. SV18P12425

Biz Reg. No. 53103069E  
GST No. M20098505-2

SERVICE ORDER NO: 18IP0590

SERVICE CUSTOMER NO.: CV000066

SERVICE CUSTOMER NAME: AXA INSURANCE SINGAPORE PL

TELEPHONE NO.:

ADDRESS: 8 SHENTON WAY  
#27-01 AXA TOWER  
Singapore

Post Code: 068811

VEH NO.: SLN994R

DATE: 19/03/18 Pickup:

VIN NO.: WYVZZZ3CZGE114429 KM: 6,943

GEARBOX CODE: Engine No.:

MODEL: Passat 1.8 TSI Comfortline

SA: Tang Shu Shi

Next Appointment Date:

Next Appointment Mileage: 0

NO.	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT
31	2KADHESIV	1.00	PCS	286.20	286.20
32	SEALANT	1.00	PCS	77.38	77.38
33	POP-RIVET	5.00	PCS	1.47	7.34

Sub Total 13,582.74  
GST (7%) AMOUNT 950.79  
TOTAL AMOUNT 14,533.53

for Volkswagen Centre Singapore

Customer

Phone : Fax :



05 APR 2018

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-026255

Date of Request: 20/02/2018

Your Ref No: Online Purchase

Volkswagen Centre Singapore  
247 Alexandra Road  
Singapore 159934

Dear Sir/Madam,

Enquiry Date 20/02/2018

Enquiry By Tang Shu Shi

TP Vehicle No. SKP9890Z

Accident Date 20/02/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKP9890Z	AXA Insurance Pte Ltd	10/02/2018-09/02/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-026255

Date of Request: 20/02/2018

Your Ref No: Online Purchase

Volkswagen Centre Singapore  
247 Alexandra Road  
Singapore 159934

Dear Sir/Madam,

Enquiry Date 20/02/2018  
Enquiry By Tang Shu Shi  
TP Vehicle No. SKP9890Z  
Accident Date 20/02/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKP 9890Z (Insd veh)	Model:	VOLKSWAGEN PASSAT
	SLN 994R (TP veh)		1.8
Date of Accident:	20/02/2018		

Global Sum Settlement	: [ ] Yes	[ X ] No
Repair Estimate	: \$	18,301.03
Final Repair Cost	: \$	14,533.53
Loss of Use	: \$	720.00
Rental (if any)	: \$	
LTA / GIA Search Fee	: \$	2.00

Others:	: \$	0.00
---------	------	------

	: \$	
Final Settlement Sum	: \$	15,255.53

Is Third Party Workshop GIA Registered? [ ] YES [ X ] NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability ____ 100 ____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: ____
BOLA Liability: ____ (%)	Assessed Liability (*): ____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown		
1)	VOLKSWAGEN GROUP SINGAPORE PTE LTD	: \$ 15,255.53

JOANNE LEE KHANG MIN  
LKK Auto Consultants Pte Ltd

22/02/2019  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18003229/R1ea3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:ERNEST TAY

Date : 22-02-2019



Code : ASM

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SKP 9890Z	Veh. Inspected	SLN 994R
Policy No.	GA162817/1	Coverage (\$)	0.00
Claim No.	S8M0096W	Excess (\$)	0.00
Assign From		Assign Date	20/02/2018

**2. Vehicle Particulars & Condition**

Make & Model	VOLKSWAGEN PASSAT 1.8	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WWZZZ3CZGE114429	Colour	GREY
Odometer	6144	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	215/55 R17	PIRELLI	6 mm
L/H Front Tyre	215/55 R17	PIRELLI	6 mm
R/H Rear Tyre	215/55 R17	PIRELLI	6 mm
L/H Rear Tyre	215/55 R17	PIRELLI	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION, DAMAGES SEE DETAILS:
--

**5. General Information**

Accident Date	20/02/2018	Inspection Date	21/02/2018
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 1 KAMPONG AMPAT OFF MACPHERSON ROAD SINGAPORE 368314		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 994R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	B&P NUMBER PLATE (SN) (CONSISTENT)	BENT	✓ 80.00	80.00
1	SPOILER (SN) (CONSISTENT)	CUT	✓ 124.44	124.44
1	TSI EMBLEM (SN) (CONSISTENT)	NECESSARY	✓ 51.65	51.65
1	PASSAT EMBLEM (SN) (CONSISTENT)	NECESSARY	✓ 55.86	55.86
1	CENTRE BUMPER MOLDING (SN) (CONSISTENT)	CUT	✓ 174.41	174.40
1	LHR BUMPER MOULDING (SN) (CONSISTENT)	CUT	✓ 138.17	138.17
1	RHR BUMPER MOULDING (SN) (CONSISTENT)	NECESSARY	✓ 138.17	138.16
1	LHR INNER REFLECTOR (SN) (CONSISTENT)	SERVICEABLE	✓ 39.29	-
1	RHR INNER REFLECTOR (SN) (CONSISTENT)	SERVICEABLE	✓ 60.61	-
1	LHR OUTER REFLECTOR (SN) (CONSISTENT)	CRACKED	✓ 39.29	39.29
1	RHR OUTER REFLECTOR (SN) (CONSISTENT)	SERVICEABLE	✓ 60.61	-
1	REAR SENSOR BRACKET (SN) (CONSISTENT)	NECESSARY	✓ 55.40	55.40
1	REAR BUMPER (SN) (CONSISTENT)	DEFORMED	✓ 972.08	972.08
1	BOOT LID (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	✓ 1,431.69	-
1	VW SIGN (SN) (CONSISTENT)	NECESSARY	✓ 82.52	82.52
1	BLUEMOTION EMBLEM (SN) (CONSISTENT)	NECESSARY	✓ 50.05	50.05
2	REAR SENSOR O RING (SN) (CONSISTENT)	NECESSARY	✓ 3.43	3.43
2	REAR CENTRE SENSOR (SN) (CONSISTENT)	SERVICEABLE	✓ 288.80	-
5	POP-RIVET (SN) (CONSISTENT)	NECESSARY	✓ 7.35	7.34
1	REAR END PANEL (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	✓ 318.30	318.30
1	INOXSPRAY (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	✓ 67.97	67.97
1	2KADHESIV (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	✓ 286.20	286.20
1	SEALANT (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	✓ 77.38	77.38
1	BUMPER CENTRE BRACKET (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	✓ 47.80	47.80
1	REFLECTOR OUTER LH (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	✓ 39.28	39.28
1	WIRE HOUSING (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	✓ 10.29	10.29
1	REAR SILENCER (SN) (CONSISTENT) (ADDITIONAL)	BENT	✓ 684.98	684.98
2	CLAMP (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	✓ 138.26	138.26

Report Ref No. CC4/ASM18003229/R1ea3q2



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR REINFORCEMENT (SN) (CONSISTENT) (ADDITIONAL)	BENT	✓ 540.99	540.99
1	CENTRE SILENCER (SN) (CONSISTENT) (ADDITIONAL)	BENT	✓ 1,134.90	1,134.90
1	REAR SILENCER HEAT SHIELD (SN) (CONSISTENT) (ADDITIONAL)	BENT	✓ 103.60	103.60
			7,303.77	5,422.74
	<b>LABOUR</b>			
	R&R EXHAUST PIPE (ADDITIONAL)		✓ 840.00	840.00
	LABOUR INCLUSIVE OF THE REPAIR OF BOOT LID		✓ 4,200.00	3,360.00
	SPRAY PAINT		✓ 4,000.00	3,200.00
	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC		✓ 480.00	480.00
	ELECT WIRING & MECH COMPO.		✓ 280.00	280.00
			✓ 9,800.00	8,160.00
	<b>GRAND TOTAL</b>		<b>17,103.77</b>	<b>13,582.74</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>13,582.74</b>

Report Ref No. CC4/ASM18003229/R1ea3q2

**MOHAMMED RASUL BIN MOHD YUNUS**

Automotive Assessor

**HO LEONG CHUAN**

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



SERVICE REQUESTS

MESSAGES

CLAIMS

Service Request Details

Claim	58M0098E
Reference	CC4/ASA418003229/R1ea3a2
Loss Date	20 February 2018
Report Date	22 Feb 2018 12:00:00 AM
Request Date	21 August 2018
Due Date	
Vendor Name	L&K AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step

Wait for Approve Invoice

Add images

Vehicle Information

Incident Vehicle Registration #	SLMP94R
Make	TPVO VOLKSWAGEN
Model	PASSAT 1.8 TSI COMFORTLINE
Service Address	BLK 75C REDHILL ROAD, 153075

Primary Contact/Insured

ERLUN YEO YUAN NEE  
BLK 75C REDHILL ROAD, #05-74, 153075, Singapore  
389REN@GMAIL.COM

Claim Handler

ANG Richard  
richard.angbo@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

Document Type Document SubType















Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	---------------

Reports & Statement

GIA Report

Meritmen

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKXInvoice 1 (1).pdf	Invoice	Surveyor/ Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2019
 payment breakdown.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2019
 LOG.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2019
 LKXInspection (1).pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2019
 LKXAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2019
 LKX PHOTO-2.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2019
 LKX PHOTO.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2019
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2019
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	PCA / Authority Letter	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2019
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2019
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKX AUTO CONSULTANTS PTE LTD (TP)	26 February 2019
 EMAIL FROM WSP DD 040119.pdf	Letters and Correspondence	Workshop	LKX AUTO CONSULTANTS PTE LTD (TP)	30 January 2019
 Request direct settlement for SLN9948, SKD916902 ON 20022018.mng	Letters and Correspondence	Third Party	TAY Ernest	28 February 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 TP ESTIMATE - MARKED.pdf	Other	Other	TAY Ernest	26 February 2018
 Preliminary Advice.pdf	Other	Other	TAY Ernest	26 February 2018
 SLH9948 TP GIA.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	22 February 2018
 GA162017-Policy Schedule.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	TEO Killy	22 February 2018
 GA162017-Certificate of Insurance.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	TEO Killy	22 February 2018