

22/03/2002

ASS. REC. BY:

REF:

CG/MSA18D03291/TIRB 02

Special Instruction:

ASSIGNMENT (Office)

SUBJECT:

Taufik

From (Person):

Menmen Pearllyn Kang

of

MSIG

Date/Time: 21/2/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKX7997X

Insured:

Tel: 66311857

at Workshop m/s

Borneo Motor

of 2 Pandan Crescent

Policy No: 29054644 ATJ

Claim No:

549040

Excess:

500

Sum Insured:

D.O.A.

4/2/18

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 21/2/18

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKX7997X-X
22/2/18	Sent poli thm menimen ; seek mandate
26/2/18	Inform repiner to proceed to repair.

Source: Tanpin

REF: MS/G.

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop this _____
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: \$500
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$83K.
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Suh Vehicle: IN / OUT

Van No: SKX7997X Yr Regn: 2015 Dec.
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Pugeot Affis. cc: 1598
Colour: Blue A/C: Insured / Std / NI / NA
So Reading: 39860 T.Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MR053REH104540028
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size F: 205/55R16
R: 2 4
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 21/2/18 @ 3pm
Survey held at Soromo funder.
Des. of Damages FR / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

Confirm \$5455.15, 5 days
Red: \$640.06, 54%

RECEIVED 23 MAY 2018

Date/Time File Pass to? ☐ : Preli. Report
1) typist ☒ : Final Report
Date/Time File Return to? _____

Days Of Repair: 5
Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Insp (\$)
☐ Weekend (\$)

Survey Fee: _____
Transportation: _____
S + RS: _____
Photos: _____
Chart: _____

Report Format: OD
Lump Sum / I.B.I: (\$ 5455.15)

300
10
310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003291/T1rb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE
048581

Date : 21-02-2018



Code : MSG

Policy Particulars :- OWN DAMAGE

1.	Insured Veh.	Veh. Inspected	SKX 7997X
	Policy No. 29054644AT2	Coverage (\$)	0.00
	Claim No. 549040	Excess (\$)	500.00
	Assign From MERIMEN (PEARLYN KANG)	Assign Date	21/02/2018

Vehicle Particulars & Condition

2.	Make & Model	c.c	0
	Engine No. HIDDEN	Year of Reg.	
	Chassis No.	Colour	
	Odometer	Steering	
	Brakes	Modification	
	General		

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

Description of Damages

4.

General Information

5.	Accident Date 04/02/2018	Inspection Date 22/02/2018
	Survey held at BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462	

Remarks

5a.

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	
Main	06 Feb 2018		21 Feb 2018 09:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
[Created by insurer]									
CLAIM SUBFOLDER DETAILS									
Insured:	TAN GEK HWA, ID: S1561632F, Tel: +6598353396, Email: IVYTAN23@YAHOO.COM								
Vehicle Reg. No.:	SKX7997X	Date of Loss:	04/02/2018 12:00 - :59						
Claim Type:	OD / 549040	Policy/Cover Note No.:	29054644AT2 (Comprehensive) Coverage: 29/12/2017 - 28/12/2018						
		Excess:	S\$500.00						
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pearllyn Kang Yen Lin - 6594 2588]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/02/2018]								
Driver/Custodian:	TAN GEK HWA (55 / Female), NRIC: S1561632F, Tel: +6598353396								
Adj Asg. Remarks:	Car in. Please survey and revert. Thank you.								
			View All	Compose Case Mail					
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pearlyn Kang Yen Lin

Date: 22 Feb 2018

Preliminary Advice

Vehicle No	: SKX7997X	Accident Date	: 04/02/2018
Make	: TOYOTA COROLLA ALTIS	Policy No.	: 29054644AT2
Assignment Date	: 21/02/2018	Excess	: S\$500.00
Date of Inspection	: 21/02/2018	Est. Duration of Repair	: 5.00
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,865.21
Revised Amount	:S\$	5,455.15
Check Items (Estimated)	:S\$	1,300.91
Total	:S\$	6,756.06

Lump Sum Repair

:S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	83,000.00
COE / PARF Rebate	:S\$	56,180.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,820.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Print Received Message

This mail is associated with :

*SKX7997X (549040)

OD

Feb 4 2018 12:00PM

[TAN GEK HWA]

Borneo Motors (S) Pte Ltd

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 23/02/2018 09:45 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5455.15) - SKX7997X - Claim Handler: Pearlyn Kang Yen Lin

Approved:5455.15:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Monday, February 26, 2018 9:55 AM
To: 'Shashitharan@borneomotors.com.sg'
Cc: SUR
Subject: SKX 7997X OD MSIG DOA: 04.02.2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKX 7997X (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1632F
Vehicle Details	
Vehicle No.:	SKX7997X
Vehicle to be Exported:	No
Intended De-registration Date:	08 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1ZRY218100
Chassis No.:	MR053REH104540028
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,804.00
Original Registration Date:	29 Dec 2015
First Registration Date:	29 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$17,804.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2025
PARF Rebate Amount:	\$13,353.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):	10
QP Paid:	\$54,301.00
COE Rebate Amount:	\$42,827.00
Total Rebate Amount:	\$56,180.00

The information contained herein is correct as at 08 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 06/02/2018 10:43
Date Of Accident 04/02/2018 12:40
Exact Location Of Accident PIE TOWARDS TUAS BEFORE EXIT 12
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKX7997X

Insured/Policyholder

Name Of Registered Owner TAN GEK HWA
NRIC No S1561632F
Email Address IVYTAN23@YAHOO.COM
Mobile Phone No (LOCAL) +65-98353396
Alternative Phone No Office-98353396

Vehicle Particulars

Manufacturer TOYOTA
Model COROLLA ALTIS-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number A29054644AT2
Cover Note Number

Driver

Name of Driver TAN GEK HWA
NRIC No S1561632F
Date Of Birth 11/04/1962
Occupation INDOOR
Date Of Driving Pass 22/08/1985
Driving Experience 32 YEARS AND 5 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-98353396

Fax Number	OFFICE-98353396
Contact Number	IVYTAN23@YAHOO.COM
EMail Address	BLK 682 CHOA CHU KANG CRESCENT #10-516
Address	680682
Postcode	NO
Was driver an employee of the Insured's Company	OWNER
If No, Relationship of the Driver with the Insured	-
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA4542Y
Vehicle Make/Model/Colour	SUZUKI / GREY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MUHAMMAD ZAID BIN ROSLI
NRIC/Passport Number	S8715070D
Contact Number	88081708
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)


2

Accident Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date &
Time

6/2/18 8:42 AM


Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Sketch Plan

	66R9642A
	SKX799FX

Describe Circumstances of the Accident

I was travelling at around 20km/hr behind vehicle no. G8A45027 as traffic was heavy. Vehicle G8A45027 stopped suddenly, I then stepped on my brake immediately however my vehicle still knocked slightly on the back of G8A45027.

Unable to leave car for repair now. Need for work + car. *[Signature]*

Declaration

We declare the foregoing particulars are true in every respect.

[Signature] 6/5/18 8:10 AM

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]

Witnessed by Reporting Centre Personnel

MCA: Shuh,TYPE OF CLAIM: ☒ OD ☐ OD/UL ☐ DS

MOTOR ACCIDENT REPORT

Date Of Report: 6/2/2018 Time: 8.10 AM Date Of Accident: 4/2/2018 Time: 12.40 PMExact Location Of Accident: PIE TOWARDS TUA BEFORE EXIT 12
Country/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ /

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SKX 7997Y Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No: S1561632FName Of Registered Owner: TAN GER HWA Email Address: ivytan23@yahoo.comMobile Number: 98353396 Alternative No:

Vehicle Particulars

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model:Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):Are you claiming under your own insurance policy for repair to your vehicle? Yes ☒ Reporting Only ☐ Third Party ☐Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

Insurance Company

Name of Insurance Company:

Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: A29054644 AT2

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: TAN GER HWA NRIC/ Passport / FIN No: S1561632FDate Of Birth: 11/4/1962 Occupation: Indoor ☒ Outdoor ☐Date Of Driving Pass: 22/8/1985 Gender: Male ☐ Female ☒Mobile Number: 98353396 Fax No: Alternative No:Address: BLK 882 CHOA CHU KANG CRESCENT #10-516 Postal Code: 686682Email Address: ivytan23@yahoo.comWas driver an employee of the Insured's Company? Yes ☐ No ☐ State relationship of the driver with the insured:

Vehicle Registration Number of Driver's Own Vehicle (if applicable):

Insurance Company of Driver's Own Vehicle (if applicable):

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: Frontal collision

Number of Passengers in the above vehicle (Including Driver): / If more than 2 Pax Please fill ANNEX B

PASSENGER 1

Name: ONG CHEE CHEE Gender: Male ☒ Female ☐Weather Conditions: Clear ☒ Raining ☐ Others ☐ (If others, please state condition):Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):Was any body injured in the Accident? No ☒ Yes ☐Was any injured conveyed to hospital by ambulance? No ☒ Yes ☐Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No: Vehicle type:Number of vehicles involved in the accident: TwoWas there any witness? No ☒ Yes ☐ If yes, please furnish witness details column below.

Witness Name: Contact No.: Email:

Was there any other vehicle or property damaged? No ☐ Yes ☒Was there any video captured by Car Camera? No ☒ Yes ☐ Are accident scene photos available for attachment? No ☐ Yes ☒Was the accident reported to the police? No ☒ Yes ☐ (If yes, please state which Police Station):Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: G8A 4542Y Vehicle Make/Model/Colour: SUZUKI / GREY

Details Of Properties Damage in Accident:

Vehicle Category:

Name of Driver: MUHAMMAD ZAID BIN ROSLINRIC/Passport/FIN Number: S8715070D

Address:

Insurance Company Name:

Nature Of Damage:

No. Of Passenger (Including Driver): Two

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:



- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 6/2/18 8:10 AM
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan

	68A4543A
	5KX799FX



MSIG

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

Toyota DriveElite 360
Comprehensive

Certificate No. A 29054644 AT2

Excess : SGD500
Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SKX7997X

2. Name of Policyholder
Tan Gek Hwa

3. Effective Date of the Commencement of Insurance for the purposes of the Act
29/12/2017

4. Date of Expiry of Insurance
28/12/2018

5. Persons or Classes of Persons entitled to drive*

Tan Gek Hwa

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.


* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT BORNEO MOTORS (S) PTE LTD OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).


I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers


for Chief Executive Officer


Describe Circumstances of the Accident

I was traveling at around 30km/hr behind vehicle no. GB4542Y as traffic was heavy. Vehicle GB4542Y stopped suddenly, I stepped on my brake immediately however my vehicle still knocked slightly on the back of GB4542Y.

Unable to leave car for repair now. Need for work & end. 

Declaration

We declare the foregoing particulars are true in every respect.

 6/2/18 8:10 AM
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

5805811



NRIC No. S1561632F

Date of issue
26-09-2017

Address

APT BLK 682 CHOA CHU KANG CRESCENT
#10-516
SINGAPORE 660682

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3

Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

22 Aug 1985



Licence No: S1561632F

NP 428A

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1561632F

Name

TAN GEK HWA

陈玉华

Race
CHINESEDate of birth
11-04-1962Country/Place of birth
SINGAPORESex
F

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S1561632F
Name:

TAN GEK HWA

Birth Date: 11 Apr 1962
Issue Date: 05 May 2004

001212205H

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Ms Tan Gek Hwa 682 Choa Chu Kang Crescent #10-516 Singapore 680682 Mobile: 98353396
	Document No	
	0	
	Document Date	
	21/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ C2	ZRE171R	29/12/2015	SKX7997X	0	29695	60D/SKX7997X/20021:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

MR053REH104540028 1ZRY218100 60 Shashitharan --/--/---- 0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:A29054644AT2 ACC DATE:04/02/18 DRIVE IN:20/02/18 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 - 100.00 net
2	B	BP-LAB CHECK WIRING AND REFOCUS HEADLAMP				✓ 154.00 net
3	L	BP-LPO SUPPLY REGN PLATE (P04)				✓ 80.00 net
4	Z	BP-SLANT SUPPLY SEALANT (NETT)				✓ 80.00 net
5	B	BP-MECH R/I AIRCOND PIPE VACCUM AND REGAS				X 308.00
6	B	BP-LAB REPL ACC AFF PARTS AND PANEL				1232 2464.00
7	B	STRAIGHTEN AND REALIGN ACC AFF AREA RESRPAY ACC AFF AREA				1012 2024.00
8	1	S52119-0Z955 COVER, FR BUMPER	1.00	514.90	15.00	✓ 437.66
9	2	S52161-OK040 PIECE, RR BUMPER	10.00	3.90	15.00	✓ 33.10 net
10	3	S52116-02270 SUPPORT, FR BUMPER LH	1.00	83.30	15.00	? 70.80
11	4	S52115-02270 SUPPORT, FR BUMPER RH	1.00	83.30	15.00	? 70.80
12	5	S52611-02310 ABSORBER, FR BUMPER	1.00	79.70	15.00	? 67.74
13	6	S52131-02190 REINFORCEMENT, FR	1.00	386.60	15.00	? 328.61
14	7	S53100-02760 GRILLE, RADIATOR	1.00	625.00	15.00	✓ 531.25

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Tan Jiah 97495744 Ex \$500 Revert. 21/2/18 @ 3:15pm. Not Authorised 5 days. *Returning before paint
			Amount Due Sur@lkanto.com

PLEASE TEAR ALONG PERFORATED LINE

3620504

3620504

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE
TIME 21/02/2018
08:51

VEHICLE NO

SKX7997X

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S10000004 / ICCUA1 Document No 0 Document Date 21/02/2018	Ms Tan Gek Hwa 682 Choa Chu Kang Crescent #10-516 Singapore 680682 Mobile: 98353396

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	C2	ZRE171R	29/12/2015	SKX7997X	0	29695 :60D/SKX7997X/20021:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

MRO53REH104540028 1ZRY218100 60 Shashitharan --/--/---- 0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	8	S53301-02310 HOOD SUB-ASSY	1.00	1213.10	15.00	bt 1031.13
16	9	T90467-09050 CLIP	6.00	2.30	15.00	11.70
17	0	S53510-02671 LOCK ASSY, HOOD	1.00	131.10	15.00	X 111.43
18	1	S53208-02210 SUPPORT SUB-ASSY, HO	1.00	145.20	15.00	Ry 123.42
19	2	S53201-02370 SUPPORT SUB-ASSY	1.00	1097.10	15.00	Ry 932.53
20	3	S75311-02190 RADIATOR GRILLE EMBLEM,	1.00	46.30	15.00	39.35
21	4	S75444-02700 PLATE, LUGGAGE COMPT	1.00	34.40	15.00	X 29.24
22	5	S75444-02A20 PLATE, LUGGAGE COMPT	1.00	34.40	15.00	X 29.24
23	6	S81110-02F31 HEADLAMP ASSY, RH	1.00	897.60	15.00	? 762.96
24	7	S81150-02F31 HEADLAMP ASSY, LH	1.00	897.60	15.00	762.96
25	8	S88450-02350 A/C CONDENSER ASSY,	1.00	1507.40	15.00	X 1281.29

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modifications is allowed

Supplementary item(s) must be resurveyed and is subject to insurance company

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Change Summary	Total	11,865.21
Acknowledged by Repairer	Parts: 6,655.21	GST 7.00%	830.56
Signature:	Labour: 5,130.00	Less	0.00
Date:	Materials: 80.00		
	Lubrication/Fluid: 0.00		
	Others: 0.00		
		Amount Due	12,695.77

PLEASE TEAR ALONG PERFORATED LINE

3620505

3620505

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE: 21/02/2018
TIME: 08:51

VEHICLE NO

SKX7997X

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1 Document No 0 Document Date 12/04/2018	Ms Tan Gek Hwa 682 Choa Chu Kang Crescent #10-516 Singapore 680682 Mobile: 98353396

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	C2	ZRE171R	29/12/2015	SKX7997X	37001	29695 :60D/SKX7997X/20021:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

MRO53REH104540028	1ZRY218100	60	Shashitharan	28/02/2018	8.00	28/02/2018	18.00
-------------------	------------	----	--------------	------------	------	------------	-------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	2	BP-SUNDRY SUNDRIES POLICY NO.:A29054644AT2 ACC DATE:04/02/18 DRIVE IN:20/02/18 EXCESS:\$500 DATE-IN:26/02/18 DATE SURVEY:21/02/18 NO OF REPAIR DAYS:5 days BY:toufikh AUTHORIZED ON:26/02/18	*			50.00
2	B	BP-LAB CHECK WIRING AND REFOCUS HEADLAMP	08			154.00
3	L	BP-LPO SUPPLY REGN PLATE (PO#)	E33			80.00
4	Z	BP-SLANT SUPPLY SEALANT (NETT)				80.00
5	B	BP-LAB REPL ACC AFF PARTS AND PANEL	08			1232.00
6	B	STRAIGHTEN AND REALIGN ACC AFF AREA	08			1012.00
7	V	BP-RES RESRPAY ACC AFF AREA	88			-500.00
8	1	EXC Excess element of insurance repair to be paidby the insured party	1.00	514.90	15.00	437.66
9	2	S52119-02955 COVER, FR BUMPER	10.00	3.90	15.00	33.10
10	3	S52161-OK040 PIECE, RR BUMPER	1.00	625.00	15.00	531.25
11	4	S53100-02760 GRILLE, RADIATOR	1.00	1213.10	15.00	1031.13
12	5	S53301-02310 HOOD SUB-ASSY	6.00	2.30	15.00	11.70
13	6	T90467-09050 CLIP	1.00	46.30	15.00	39.35
13	6	S75311-02190 EMBLEM, GRILLE				

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3622270

3622270

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES

DATE 12/04/2018
TIME 15:54



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel No.: 6631 1188

Account Detail				Account No		Customer Detail		
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept				S1000004 / ICCUA1		Ms Tan Gek Hwa 682 Choa Chu Kang Crescent #10-516 Singapore 680682 Mobile: 98353396		
				Document No				
				0				
				Document Date				
				12/04/2018				
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks	
15	GEXGKZ	C2	ZRE171R 29/12/2015	SKX7997X	37001	29695	60D/SKX7997X/200211	
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On		
MR053REH104540028	1ZRY218100	60	Shashitharan	28/02/2018 8.00	28/02/2018 18.00			
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
14	7	S81110-02F31 HEADLAMP ASSY, RH			1.00	897.60	15.00	762.96
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.								
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total 4,955.15		
		Please acknowledge receipt of vehicle		Parts	2,847.15	GST 7.00%		
				Labour	2,528.00	346.86		
				Materials	80.00	Less 0.00		
				Lubrication/Fluid	0.00			
				Others	0.00	Amount Due 5,302.01		
362227								

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 12/04/2018
TIME 15:54

362227

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18003291/T1RBN2

Date: 24/05/2018

REFERENCE

Insured/Claimant: TAN GEK HWA Policy No: 29054644AT2
Date of Loss: 04/02/2018 Nature of Claim: OD Claim No: 549040

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX7997X Engine No: 1ZRY218100
Make & Model: TOYOTA COROLLA ALTIS, 1.6 Classic (A) Chassis No: MR053REH104540028
Reg. Date: 29/12/2015 (Man. Year: 2015) Odometer: 39860 km
Colour: Silver
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$83,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,915.21	3,057.15	3,858.06	55.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,950.00	2,398.00	2,552.00	51.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,865.21	5,455.15	6,410.06	54.02
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	11,365.21	4,955.15	6,410.06	56.40
+ GST 7.00/7.00% (S\$)	795.56	346.86	448.70	56.40
Nett Amount (S\$)	12,160.77	5,302.01	6,858.76	56.40

INSPECTION

Date of Assignment: 21/02/2018
Date Inspected: 21/02/2018 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 May 2018)
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 Classic (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SKX7997X)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*COVER,FR BUMPER	Deformed	437.66 FS	*437.66 FS
3	10		*PIECE,RR BUMPER	Necessary	33.10 FS	*33.10 FS
4	1		*SUPPORT,FR BUMPER LH	Not Necessary	70.80 FS	*- FS
5	1		*SUPPORT,FR BUMPER RH	Not Necessary	70.80 FS	*- FS
6	1		*ABSORBER,FR BUMPER	Not Necessary	67.74 FS	*- FS
7	1		*REINFORCEMENT,FR	Not Necessary	328.61 FS	*- FS
8	1		*GRILLE,RADIATOR	Cracked	531.25 FS	*531.25 FS
9	1		*HOOD SUB-ASSY	Bent	1,031.13 FS	*1,031.13 FS
10	6		*CLIP	Necessary	11.70 FS	*11.70 FS
11	1		*LOCK ASSY,HOOD	Not Necessary	111.43 FS	*- FS
12	1		*SUPPORT SUB-ASSY,HO	Repair	123.42 FS	*- FS
13	1		*SUPPORT SUB-ASSY	Repair	932.53 FS	*- FS
14	1		*RADIATOR GRILLE EMBLEM	Necessary	39.35 FS	*39.35 FS
15	1		*PLATE,LUGGAGE COMPT	Not Necessary	29.24 FS	*- FS
16	1		*PLATE,LUGGAGE COMPT	Not Necessary	29.24 FS	*- FS
17	1		*HEADLAMP ASSY,RH	Not Necessary	762.96 FS	*- FS
18	1		*HEADLAMP ASSY,LH	Cracked	762.96 FS	*762.96 FS
19	1		*A/C CONDENSER ASSY	Not Necessary	1,281.29 FS	*- FS
20	1		*REGN PLATE	Bent	80.00 FS	*80.00 FS
21	1		*SEALANT	Necessary	80.00 FS	*80.00 FS
Total Parts (\$\$)					6,915.21	3,057.15

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND REFOCUS HEADLAMP	New	154.00	154.00
2	R/I AIRCOND PIPE VACCUM AND REGAS	New	308.00	0.00
3	REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA	New	2,464.00	1,232.00
4	RESPRAY ACC AFF AREA	New	2,024.00	1,012.00
Gross Labour Cost (S\$)			4,950.00	2,398.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >