

22/03/2002

ASS. REC. BY:

REF:

CS3 / FWD18003297 / Abe2

Special Instruction:

Surveyor

Merimen

ASSIGNMENT (Office)

From (Person):

Belliana Lim

of

FWD

Date/Time:

21/02/2018 1.37pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 6850T

Insured:

SJL 8025U

at Workshop m/s

Sheng Li Lai

Tel:

91119222

of

Blk J Kaki Bukit Ave 2 #01-36

Policy No:

PNPY2017-00008672

Claim No:

1201800002443

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/02/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS w/p

H.O.D. Endorsement:

Date/Time:

21/02/2018 3:24pm

Person Contacted:

Mr. Low

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

Dismantle: 26/2/2018

Before paint: 28/2/2018

Simulation

REF:

Denise / PRS FWD

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GBF 6850T
 at Workshop mis: Sheng Li Lai
 of: Kaki Bukit #01-36
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: GBF 6850T Yr Regn: 2017 Feb
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Hiace C/C: 2982
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 40972 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KDH2010208524
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/80R15
 R: 195/80R15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 7 days Res: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS (PRS)
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 21/02/18
 Survey held at Sheng Li Lai
 Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or _____
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
TP FWD . Estimated repair range \$5,500 - \$7,000

RECEIVED 12 JUN 2018

[Signature]
 6/6/2018

Date/Time File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 7
 Resurvey No. of Trip: 2

Date/Time File Return to?

3)

Add Fee: Site Insp \$
 Interview \$
 Tech. Insp \$
 Weekend \$

Survey Fee:	
Transportation:	
\$ - RS \$:	
Photo:	
Other:	
TOTAL:	

Report Format: PRS

Lump Sum / I.B.I: \$

Nivitha (LKK Auto)

From: motorclaims.sg@fwd.com
Sent: Wednesday, 21 February 2018 1:37 PM
To: yvonne@ealc.com.sg
Cc: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com
Subject: FW: FWD Insured SJL8025U [EAL.2018.5483.MK.ya GBF6850T]; FWD Claim Ref: 1201800002443
Attachments: 180220 GIA.pdf

21/2/18 @ 3:24pm
vehicle in
sur @ Adnien

Without Prejudice

Dear Sir/ Madam

We refer to the above matter.

We will be appointing LKK Auto Consultants to conduct pre-repair survey of your client's vehicle GBF6850T.

Thanks.

Regards

Belliana Lim
Assistant Manager, Claims



FWD Singapore Pte Ltd

6 Temasek Boulevard, #18-01
Suntec Tower 4, Singapore 038986
T +65 6727 5721
E belliana@fwd.com

	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!		2.02% p.a. fwd.com.sg save now
--	---	--	---

From: Yvonne [<mailto:yvonne@ealc.com.sg>]
Sent: Tuesday, 20 February, 2018 6:13 PM
To: SG Corporate Contact
Subject: FWD Insured SJL8025U [EAL.2018.5483.MK.ya GBF6850T]

Our ref : 2018.5483.MK.ya **GBF6850T**
Your ref : **SJL8025U**

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

FWD Singapore Pte Ltd
6 Temasek Boulevard
#18-01 Suntec Tower Four
Singapore 038986
Attn: Motor Claims Department
NOTICE OF ACCIDENT

For your information only
Owner of **SJL8025U**
Lim Sou Hun
17 Yunnan Walk 1
Singapore 638148

Dear Sir/Madam,

CLAIMANT: DOUBLE I TRADING

ACCIDENT INVOLVING GBF6850T & SJL8025U ON 16 FEBRUARY 2018 ALONG SLIP ROAD PIE (CHANGI) TOWARDS BUKIT BATOK ROAD AT ABOUT 1500 HOURS

We are instructed by **DOUBLE I TRADING** to notify you (the insurer of **SJL8025U**) of a road traffic accident on **16 FEBRUARY 2018 ALONG SLIP ROAD PIE (CHANGI) TOWARDS BUKIT BATOK ROAD AT ABOUT 1500 HOURS** involving our client's vehicle registration number **GBF6850T** and vehicle registration number **SJL8025U** driven by your insured at the material time.

A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's vehicle **GBF6850T** has been damaged. Before our client proceed to repair the damaged vehicle:

1. Please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle; and
2. Please forward a copy of your insured's report.

Our client proposes to use one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

3. Dennis Yap Teck Wee - Pal's Appraiser Pte Ltd

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	0172D
Vehicle Details	
Vehicle No.:	GBF6850T
Vehicle to be Exported:	No
Intended De-registration Date:	12 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 3.0 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1KD2659146
Chassis No.:	KDH2010208524
Maximum Power Output:	-
Open Market Value:	\$33,616.00
Original Registration Date:	16 Feb 2017
First Registration Date:	16 Feb 2017
Transfer Count:	1
Actual ARF Paid:	\$1,681.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Feb 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$47,227.00
COE Rebate Amount:	\$40,972.00
Total Rebate Amount:	\$40,972.00

The information contained herein is correct as at 12 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for Investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	20/02/2018 12:17
Date Of Accident	16/02/2018 15:00
Exact Location Of Accident	SLIP RD PIE (CHANGI) TWDS BUKIT BATOK RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF6850T
Insured/Policyholder	
Name Of Registered Owner	DOUBLE I TRADING
Co Reg No	53120172D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90075354
Alternative Phone No	OFFICE-90075354
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE DX 3.0 MANUAL
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	MT20177781
Driver	
Name of Driver	SELLIAH PANDI SURESH
Passport No/FIN	G5248598W
Date Of Birth	31/03/1983
Occupation	INDOOR
Date Of Driving Pass	12/07/2016
Driving Experience	1 YEAR AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86174933
Fax Number	
Contact Number	OFFICE-86174933
EMail Address	NOEMAIL

Address 12 CHANDER ROAD
 Postcode 219529
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON STATED DATE AND TIME, MY VEHICLE WAS STATIONARY STOPPED AS INCOMING VEHICLE PASSING BY ALONG THE MAIN ROAD. SUDDENLY VEHICLE B HIT ONTO MY VEHICLE REAR PORTION.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJL8025U
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 1

DETAILS OF INJURED PERSON 1

Name SELLIAH PANDI SURESH

Approximate Age

Injuries Sustain

NECK & BACK

Injured person in which vehicle?

GBF6850T

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Feb 2018 Edit Reg		21 Feb 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	-, Co. Reg. No.: -		
Main Claimant:	DOUBLE I TRADING , Co. Reg. No.: 53120172D		
Vehicle Reg. No.:	GBF6850T	Date of Loss:	16/02/2018 15:00 - :59 [12 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201800002443	Policy/Cover Note No.:	PNPV2017-00008672
Vehicle Reg. No. (Insured):	SJL8025U	Policy No. (Claimant):	MT20177781
		Excess:	
Repairer:	Sheng Li Lai (KAKI BUKIT) NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT, 417921 Kaki Bukit - Tel: 91119222		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Belliana - 67275741]		
Claimant's Insurer:	Great American Insurance Company (HQ) - Tel: 6804 6047		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 02/03/2018]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

*GBF6850T (1201800002443)
 [SJL8025U]
 TP
DOUBLE I TRADING
 Feb 16 2018 3:00PM
 [-]
 Sheng Li Lai

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
2	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
3	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
4	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
5	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
6	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
7	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
8	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
9	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
10	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
11	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
12	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
13	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
14	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
15	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
16	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
17	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
18	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
19	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
20	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
21	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
22	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
23	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
24	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
25	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
26	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
27	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
28	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
29	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
30	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
31	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
32	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
33	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
34	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
35	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/06/18 12:19	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	12/06/18 12:19	General View	Load JPG	<input checked="" type="checkbox"/>
39	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
50	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
51	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
52	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
53	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
54	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
55	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
56	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
57	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
58	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
59	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
60	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
61	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
62	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
63	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
64	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
65	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
66	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
67	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
68	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
69	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
70	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
71	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
72	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
73	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
74	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
75	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
76	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
77	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
78	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
79	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
80	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
81	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
82	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
83	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
84	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
85	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
86	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
87	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
89	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
90	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
91	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
92	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
93	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
94	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
95	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
96	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
97	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
98	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
99	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
100	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
101	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
102	12/06/18 12:20	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
103	12/06/18 12:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
104	12/06/18 12:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
105	12/06/18 12:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
106	12/06/18 12:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
107	12/06/18 12:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
108	12/06/18 12:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
109	12/06/18 12:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
110	12/06/18 12:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
111	12/06/18 12:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
112	12/06/18 12:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
113	12/06/18 12:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
114	12/06/18 12:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
115	12/06/18 12:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
116	12/06/18 12:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
117	12/06/18 12:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
118	12/06/18 12:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
119	12/06/18 12:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
120	12/06/18 12:21	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD18003297/ABE2

Date: 18/06/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00008672
 Claimant Vehicle No: GBF6850T Insured Vehicle No: SJL8025U
 Date of Loss: 16/02/2018 Nature of Claim: TP Claim No: 1201800002443

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF6850T**
 Make & Model: TOYOTA HIACE, 3.0 D DX (M) Engine No: 1KD2659146
 Reg. Date: 16/02/2017 (Man. Year: 2016) Chassis No: KDH2010208524
 Colour: Silver Odometer: 40972 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/80 R15 Rear Tyre Size: 195/80 R15
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/02/2018
 Date Inspected: 21/02/2018 Inspected At: Sheng Li Lai (KAKI BUKIT)
 NO. 2 KAKI BUKIT AVE 2, # 01-36
 AUTOHUB KAKI BUKIT
 Singapore 417921
 Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,500.00 -\$7,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Jun 2018)

Parts: 213 TOYOTA HIACE 3.0 D DX (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBF6850T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >