



# COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

## ComfortDelGro Engineering Pte Ltd

215 Braddell Road, Singapore 570701  
 Mainline + 65 6393 8283 Facsimile + 65 6260 9793  
**Workshops**  
 29 Loyang Drive, Singapore 508528      24 Serangoon Loop, Singapore 756156  
 343 Sin Ming Drive, Singapore 575711      1 Sungei Kadut Way, Singapore 722751  
 45 Pandan Road, Singapore 209296      6 Ulu Alam Avenue 1, Singapore 539537

Date/Time: 20.02.2018 13:26 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO 305118211

CUSTOMER AS COMFORT TRANSPORTATION PTE LTD AS 7010045 CUSTOMER NO 383 SIN MING DRIVE ADDRESS Singapore SINGAPORE 575717 65508755 (R) (P) (O)	REGN NO: <b>SHB4154H</b>	MILEAGE
	MAKE: <b>HYUNDAI</b>	FUEL E.....1/2.....F
	MODEL <b>I-40</b>	DATE/TIME IN <b>20.02.2018 09:00</b>
	YR OF MANU <b>29.10.2015</b>	TARGET DATE
	CHASSIS CODE <b>KMHLB41UMGU080210</b>	COMPLETION DATE/TIME:

QUANTITY CARD NO.

JOB DESCRIPTION

Accident Date: 17.02.2018  
 NATURE: 3P 17.02.18

NO	LABOR CODE	DESCRIPTION
----	------------	-------------

RECEIVED & PASSED OUT BY: \_\_\_\_\_

\_\_\_\_\_  
 SERVICE ADVISOR

\_\_\_\_\_  
 CUSTOMER'S SIGNATURE

Identification Slip

Exit Pass

Vehicle No.: **SHB4154H**      **LIMITS**

Vehicle No.: **SHB4154H**

\_\_\_\_\_  
 Service Advisor

\_\_\_\_\_  
 Signature/Date

\_\_\_\_\_  
 Name of Service Advisor

\_\_\_\_\_  
 Date

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/02/2018 11:01
Date Of Accident	17/02/2018 19:50
Exact Location Of Accident	BUKIT BATOK RD > BRICKLAND RD NEAR BUS STOP 43781
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB4154H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

### Driver

Name of Driver	MOHAMED HANIFA S/O S.P.M.I
NRIC No	S1665102H
Date Of Birth	20/02/1964
Occupation	OUTDOOR
Date Of Driving Pass	21/03/1984
Driving Experience	33 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	BLACKMANIAC92@HOTMAIL.COM

Address	BLK 465 CHOA CHU KANG AVENUE 4 #07-03
Postcode	680465
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

REFER ATTACHED

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FZ4442Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	MUHAMMAD ZULFIKAR
NRIC/Passport Number	S9445154Z
Contact Number	96925913
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

4 - 8  
6 - 6

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


As attached

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

  
 Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time:

Lim Ee Soon  
CSO

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SHB 4154 H - ACCIDENT STATEMENT

I travelled on Bukit Batok Road on Saturday night (17/02/2018) after exiting PIE and heading towards Brickland Road.


While I slowed down the speed in tandem with a private car which reduced speed near bus stop No 43781, I suddenly felt an impact after a rider on m/cycle B( FZ 4442Z) hit into the rear bumper of my taxi.

The accident was captured in the video camera mounted on my taxi.

I took photos of the m/cycle B at the scene. Its rider was not injured.

The impact inflicted damage to the rear right portion of my taxi.

I affirmed the above-statement is true and correct.



Driver name : Mohd Hanifa  
NRIC NO : S 1665102H  
Date: 20/02/2018

Recorded by Alex Lim



**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

MSIG-CP(P)

TS

DATE 20/2/2018

VEHICLE NO : SHB 4154H

PP 1635

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 603.60
	Rear Bumper Reinforcement			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) <i>X su</i>	\$	180.00	\$ 360.00
	Rear Bumper Side Bracket <i>X su</i>	\$	49.00	\$ 98.00
	Rear Bumper Clips			\$ 22.00
	Rear Bumper Sponge <i>X su</i>			\$ 143.40
	Rear Bumper Under Cover <i>X su</i>			\$ 225.00
	Rear Bumper Reflector Lamp (RH)			\$ 32.00
	Rear Fender (RH) <i>X reg</i>			\$ 2,020.10
	Rear Windscreen Moulding <i>X "</i>			\$ 60.00
	Tail lamp (RH) <i>X "</i>			\$ 65.60
	<b>SUB TOTAL</b>			<b>\$ 4,068.45</b>
	<b>LESS 20%</b>			<b>\$ 813.69</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 3,254.76</b>
	Rear Bumper Reverse Sensor <i>sll</i>			\$ 135.70 <b>Nett</b>
	Rear Fender Advertisement Logo (RH) <i>na</i>			\$ 100.00 <b>Nett</b>
	Rear Windscreen Sealant <i>X "</i>			\$ 46.00 <b>Nett</b>
				<b>\$ 281.70</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>850.00</del> <i>400</i>
	Spray Painting Charge			\$ <del>400.00</del> <i>360</i>
	Wiring Charge			\$ <del>50.00</del> <i>20</i>
	Tuff Kote			\$ <del>50.00</del> <i>X "</i>
	Remove/Refix Cushion & Upholstery Rear			\$ <del>150.00</del> <i>50</i>
	Remove/Refix Rear Windscreen Glass			\$ <del>120.00</del> <i>X "</i>
	Remove/Refix Reverse Sensor			\$ <del>120.00</del> <i>20</i>
	<b>TOTAL LABOUR</b>			<b>\$ 1,740.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 5,276.46</b> <i>5728.94</i>

*Kalua (LKH)  
 2/2/18 15:10 hrs  
 2 Pgs  
 PIP  
 Before part photo.*

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



## REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305118211  
 REGN NO : SHB4154H  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : I-40  
 DATE OF REGN : 29.10.2015  
 DATE/TIME IN : 20.02.2018 09:00  
 ACCIDENT DATE : 17.02.2018

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
10	L	22.00	20.00	17.60
0001	04-01-0101-0111-G	REAR BUMPER CLIPS		
1		603.60	20.00	482.88
0002	04-01-0103-0579-G	REAR BUMPER		
1		135.70		135.70
0003	09-01-9999-0068-A	REVERSE SENSOR		
1		565.60	20.00	452.48
0004	04-01-0103-0585-A	TAILLAMP RH**		
1		32.00	20.00	25.60
0005	04-01-0103-0852-G	REAR BUMPER REFLECTOR RH		

SUB-TOTAL : 1,114.26

## JOB NATURE

0000	L	PANEL BEATING		400.00
0001	23-502	SPRAYPAINT ON AFFECTED AREA		360.00
0002	17-01	CHECK ALL LIGHTING		20.00
0003	L	R/I UPHOLSTERY ETC		50.00
0004	L	R/I REVERSE SENSOR		20.00
0005	20-05	Rear Fender Adv.Sticker RH		100.00

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305118211  
REGN NO : SHB4154H  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 29.10.2015  
DATE/TIME IN : 20.02.2018 09:00  
ACCIDENT DATE : 17.02.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 950.00

TOTAL : 2,064.26

  
MVA NAME & SIGNATURE  
DATE :

\_\_\_\_\_  
SURVEYOR NAME & SIGNATURE  
DATE : AUTHORIZED : YES / NO

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

Our Job Ref No : 305118211  
Date : 22/02/18

## FINALIZATION FORM

To : LKK  
Attn : KALVIN ANG  
Vehicle Reg No. : SHB4154H

Fax :

Date of Accident : 17-Feb-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: MSIG --- FZ4442Z
2. The finalized amount shall be:
 


(a) Spare Parts after List discount	<u>\$1,114.26</u>
(b) Labour Charges	<u>\$950.00</u>
<b>Total for Part-By-Part Repair Cost</b>	<b><u>\$2,064.26</u></b>
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	<u>                    </u>
<b>Final Lumpsum Repair cost</b>	<u>                    </u>

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : LIM T S  
Tel : 62148398  
Fax : 65468156

Signature :   
Name : KALVIN  
Date : 23/2/18

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees	-----			
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003301/K1RBN2  
Date: 27/02/2018

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/17-370675
Claimant:	SHB4154H	Insured Vehicle No:	FZ4442Z
Vehicle No:		Nature of Claim:	TP
Date of Loss:	17/02/2018		Claim No: N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB4154H	Engine No:	D4DFDU555314
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L AT ABS AIRBAG 4DR (M)	Chassis No:	KMHLB41UMGU080210
Reg. Date:	29/10/2015 (Man. Year: 2015)	Odometer:	363803 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,988.94	1,214.26	2,774.68	69.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,740.00	850.00	890.00	51.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,728.94</b>	<b>2,064.26</b>	<b>3,664.68</b>	<b>63.97</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>401.03</b>	<b>144.50</b>	<b>256.53</b>	<b>63.97</b>
<b>Nett Amount (S\$)</b>	<b>6,129.97</b>	<b>2,208.76</b>	<b>3,921.21</b>	<b>63.97</b>

### INSPECTION

Date of Assignment:	21/02/2018	
Date Inspected:	21/02/2018	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Feb 2018)  
 Parts: 143 HYUNDAI I40 1.7 D CRDI F/L AT ABS AIRBAG 4DR (M) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: (Unsubmitted, no print-code for SHB4154H)  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	603.60 FL	*603.60 FL
2	1		*REAR BUMPER REINFORCEMENT	Serviceable	504.35 FL	*- FL
3	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Serviceable	360.00 FL	*- FL
4	2		*REAR BUMPER SIDE BRACKET	Serviceable	98.00 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
6	1		*REAR BUMPER SPONGE	Serviceable	143.40 FL	*- FL
7	1		*REAR BUMPER UNDER COVER	Serviceable	225.00 FL	*- FL
8	1		*REAR BUMPER REFLECTOR LAMP (RH)	Cracked	32.00 FL	*32.00 FL
9	1		*REAR FENDER (RH)	Repair	2,020.10 FL	*- FL
10	1		*REAR WINDSCREEN MOULDING	Not Necessary	60.00 FL	*- FL
11	1		*TAILLAMP (RH)	Cracked	565.60 FL	*565.60 FL
12	1		*REAR BUMPER REVERSE SENSOR	Shorted	135.70 FS	*135.70 FS
13	1		*REAR FENDER ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
14	1		*REAR WINDSCREEN SEALANT	Not Necessary	46.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,915.75	1,458.90
- List Item Discount on L Items 20.00/20.00% (S\$)	926.81	244.64
<b>Total Parts (S\$)</b>	<b>3,988.94</b>	<b>1,214.26</b>

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	850.00	400.00
2	SPRAY PAINTING CHARGE	New	400.00	360.00
3	WIRING CHARGE	New	50.00	20.00
4	TUFF KOTE	New	50.00	-
5	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	50.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	-
7	REMOVE/REFIX REVERSE SENSOR	New	120.00	20.00
<b>Gross Labour Cost (S\$)</b>			<b>1,740.00</b>	<b>850.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >