



PEGASUS

ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Call on 20 02 2018 @ 1530hrs.

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
 C/O 51 DEFU LANE 10
 539216
 Officer in Charge : ALVIN LOW WAI LUN
 Tel :
 Email :

Customer : *Confirmed 5 mins*
GRAB RENTALS PTE LTD
 18 SIN MING LANE
 #01-08 MIDVIEW CITY
 SINGAPORE 573960
Maurus 21/02/18 @ 1700hrs
Not Actual
2/5 @ 1500/2
 Attn :
 Tel :
 Fax :

Quotation No : QO18/02-1131	Quotation Date : 20/02/2018	Terms : 30 DAYS
Vehicle No : SLN4278Z	Chassis No : JM6BN22A8H0151360	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AIG, TP VEHICLE NO: SLG1346S, DATE OF ACCIDENT: 19/02/2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	1	1,075.0000	1,075.00
2	REAR BUMPER REINFORCEMENT	1	558.0000	558.00
3	REAR BUMPER SIDE HOLDER	2	37.0000	74.00
4	REAR BUMPER SIDE RETAINER	2	74.0000	148.00
5	REAR BUMPER SIDE HOLDER RIVETS	2	9.1000	18.20
6	REAR BUMPER REFLECTOR	2	51.0000	102.00
7	N/S REAR BUMPER TOW COVER	1	18.0000	18.00
8	REAR BUMPER CLIPS	10	5.0000	50.00
9	REAR END PANEL	1	506.0000	506.00
10	REAR END PANEL INNER TRIM	1	86.0000	86.00
11	LESS 20% (ITEMS 1-10)	1	527.0400	527.04
12	REAR BUMPER PARKING SENSOR	1	450.0000	450.00
13	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	780.0000	780.00
14	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	750.0000	750.00
15	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	120.0000	120.00
16	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	40.0000	40.00
17	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	120.0000	120.00
18	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	100.0000	100.00

C/F 0.00

1143
914.40



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216
Officer in Charge : ALVIN LOW WAI LUN Tel : Email :

Customer :
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn : Tel : Fax :

Quotation No : QO18/02-1131	Quotation Date : 20/02/2018	Terms : 30 DAYS
Vehicle No : SLN4278Z	Chassis No : JM6BN22A8H0151360	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AIG, TP VEHICLE NO: SLG1346S, DATE OF ACCIDENT: 19/02/2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before later spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub Total	5,522.24
GST(7.00%)	386.56
Total (SGD)	5,908.80

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216