INS. CASE OWNE	Lynn	1 cc4, 8011800	3316, U	1663 9 LKK: IDAC:		12.
Surveyor:	MADUS	DOI: ASSIGNM		Date / Time: 21 2	1.8	
Pre-assign / CCU	1/FFF	n		Registered in Merimen:		
Treasagu / CCC	(1	12 6527 C				
Insured Vehicle N	io. :	A CALAMAN	Claim No.	:		
Name of Insured	1HESTAP	of CETMN UPLEADED	Policy No.	: omporta	900r FV	245
Insured Tel No.		HP: 40238782	Make / Model	C. CRUTE	-	31.00
Excess Sec II :SS	, ^\ <del></del>	D.O.A: 18 (V18	Place of Accide		4.	-
Is driver the owner			Place of Accide	ant. [swop. 5 s	1.	
	0	Nature of Accident :				
If NO, Driver Na Driver Tel		(V/L: YES / NO)	OI GIA REPOI Insured Liabilit	RT: YES / NO ; TP GIA REPO y: % Final ? Y		10
SLM 97	\$1J		7			
INSRS: WSP: Tel: Liability: RMKS:	INSR WSP: Tel: Liabil RMK	iity:	INSRS: WSP: Tel: Liability: RMKS:	INSR WSP Tel: Liabi RMK	lity :	
Date/ Time						
-Az	CIMPLANT X-	SHECHLX		STAGE	DATE /	PIC
Arthur	3 / /	200-214		Non-Reporting Itr (1st) Non-Reporting Itr (2nd):		
				Non-Reporting ltr (Final):		
Flate 4 in no		Name and the second sec		Notification ltr (if non-pickup)	-	
5/3/16 ( 11.94		ACCIONAL OF LINE BY INTO		Call OI: EMON 9/3) After call ltr to OI	18	
	AWARE AROUN NOO	IP. INTORN TP CUAIN AGERO TO	o selice mes	Documentation Check List: H	andler Tv	pist
	Timize Times Co	( John )		Notification ltr (if non-pickup)		
	EMAIL YOUR LIABILITY CI	JAR		After call ltr to OI:	~	
				Authorisation To Act:	-	
				Release Voucher: (J() NESS)		
				Final Repair Bill: Car Rental Invoice: UPTE	1	$\vdash$
			-	Towing Invoice: 1897/E	-	=
	Photo and and			LTA / GIA :		H
	RECEIV	ED 1 9 JUN 2018		Medical Bill		-
		2010		PIR:	Ħ	
				Mandate/Reject Instruction:		
				LOD		
				Payment Breakdown Form:		
PRELIMINARY ADVICE	Date/Time:	Sent By: -NNL		Post-Repair Photos:		$\vdash$
FINALIZATION	Date/Time: 5.6.18	Confirm with: Pl		Others: Confirm by: (Jc)		
Repair Cost: 45		7. days) Reduction: 50	%	Email	Call	
FINAL SETTLEMENT	Date/Time: 54-48	Confirm with P1		Email Call	4,700	The second
Final Liability:	The state of the s	1/ Assessed) BOLA S/N No. : 9d		If NO or B 28, Ass. Lia :		
Repair Cost: ୧୩୯୬			SHE OWN HE	MAIN RUAD		
Loss of Rental (LOR):		1.5 days) x +66.85		C VARIO	EM5F	
Loss of Use (LOU):		days)		P 19 6	18	
Loss of Income (LOI): LOR only LOU only		t days) LOR + LOI [Tick only one]		20170		
GIA/LTA Search	S\$7-149	[Tick only one]				-
Medical:	S\$ -			1) Claim status: Normal/Reject	/Private Sett	le
Disbursement:	SS -	(e.g. Tow/ Independent )		2) Report Format		
Legal Cost	SS -	7227770		3) Survey fee: \$\phi \psi 00		
Total:	SS 5.884.53	Global Sum SS:				
FINAL PAYMENT	Date/Time: 5 4/9	Confirm with: [7]		Email Call		
Payee 1:	S\$5,886.53	Name 1: PEGPENS ENGINEERING	B TRAISHA T	TE CID		
Payce 2: (Strike if N.A.)	S\$	Name 2				
Payee 3: (Strike if N.A.)	SS	Name 3:				

ASS. REC. BY: MOVIES	2 4/
Δ	ASSIGNMENT
From: Date:	Veh No: SZM 9787 Yr Regn: 417
Estimated Cost:	Type M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD TP WS TP RES OD RES EVA INV MV	Truck / Trailer or (A)
To Inspect Vehicle No: SLM 975/J	Make: mexbe ? c.c 1496
at Workshop m/s Persus	Colour (inc) A/C: Insured / Std / NI / NA
of Jan	Sp.Reading 705-37 T/Radio: Insured / Std / NI / NA
Insured: \$12, 8127C	Eng/No:
Policy No.	CNO: JM 6BN 27A.8HO(4986
Claims No.	Gen. Cond: Geod/Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt of
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nity S/Rim / STD A/Rim or
50-402 February 12-50 February 1	_
(Policy Condition)	/
A THE STATE OF THE	R:RS / DIIN / EXNOVA / GV / ES / L IZA / MIC / OUTSIL / BID / SI MIL /
repair at the time of inspection.	BOY BONT EXHOURT OF THE TELEX TIMIC TONT SUT PIR TOUNIT
Bal. or Market Value:	Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Balmm R/Balmm
GIA / PR Seen: Consistent?: Yes or No	L/Bal mm L/Bal mm
Est. Repairs: T days Res.: Yes or No	D.O.A. 18/1/18 D.O.I. 21/2/18
Lum Sum: >0 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages ; Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / C Date: Person Contacted:	7 17 17
ACCOMPANY AND	The UIC / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
010/ 18-1/ no	we vides. of Lold
US: 44,900 (AD: +4908.40 5	nt s
13 - 110 0 0 1 1848 10 0	v(+)
late/Time, File Pass to?	Davis Of Pagates
E. Freil, Report	Days Of Repair:
ate/Time, File Pass to? : Prell. Report : Final Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee:
: Final Report	Resurvey No. of Trip: Survey Fee: Transportation:
: Final Report	Resurvey No. of Trip:   Survey Fee:
: Final Report  Date/Time, File Return to?  Add F	Resurvey No. of Trip:   Survey Fee:
: Final Report	Resurvey No. of Trip:   Survey Fee:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Inte	rnationale Des Experts En Autor	nobile
EQ	INSURANCE COM	IPANY LTD	Ref : CC4/EQI18003	3316/Uea3
#17	AXWELL ROAD -00 TOWER BLOC D COMPLEXSING		Date : 21-02-2018	
1.		Policy Particu	lars :- THIRD PARTY CLA	IM
	Insured Veh.	SJZ 6527C	Veh. Inspected	SLM 9781J
	Policy No.	DMPPHQ17-006245	Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	21/02/2018
2.		Vehicle I	Particulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer		Steering	
	Brakes		Modification	
	General			
3.		Co	nditions of Tyres	
_		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
6.30	L/H Rear Tyre			mm
4.	B DV AN EAS	Desc	ription of Damages	A STATE OF THE STA
5.		Ge	neral Information	ALICE BUT CARE SELV
	Accident Date	18/02/2018	Inspection Date	21/02/2018
	Survey held at	PEGASUS ENGINEERING	& TRADING PTE LTD	
	.00	51 DEFU LANE 10 SINGAPORE 539216		
5a.	OLE BUILD &	Y STATE OF LANDING	Remarks	E PARTE NEW PROPERTY.

Company Registration No. 199607198R

#### 51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

TBA

Our ref:

CC4/EQI18003316/Uea3

Date:

22.02.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

#### PRELIMINARY ADVICE OF VEHICLE NO.

**SLM 9781J** 

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 21.02.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd (Loyang) and have the following to report:-

Workshop Estimate Amount	: S\$	9,828.40
Revised Estimate Amount	: S\$	4,302.16
"Check" Items Amount	: S\$	1,665.60
Market Value	: S\$	•
LTA Reimbursement Value	: S\$	
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the

N/S Front Portion & U/C



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs:

5.0 days

Yours faithfully,

MARCUS CHUA

Licensed Appraiser

# **PEGASUS**

Email sent EU 20/02/2018@ 1730

# ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO: 201101753C

# Quotation

From:

PEGASUS ENGINEERING & TRADING PTE LTD

C/O 51 DEFU LANE 10

539216

Officer in Charge: WEE TZE FAH

Tel:

Email:

Customer:

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Attn:

Tel:

Fax:

Quotation No : QO18/02-1128	Quotation Date: 19/02/2018	T	
Vehicle No : SLM9781J		Terms: 30 DAYS	
Model: MAZDA 3 Chassis No: JM6BN22A8H0149967		Third Party Insurer :	
	JRED'S VEH NO: SJZ6527C, DATE OF ACCID	Date of Accident :	

ITEM	DESCRIPTION	0	TY	LIMIT DELOT	I
1	FRONT FENDER N/S	_		UNIT PRICE	AMOUNT (SGD)
2	FRONT FENDER INNER LINER				2000
3	FRONT FENDER INNER LINER CLIPS	= 50			
4	FRONT FENDER INSULATOR FOAM		- 00		
5	FRONT BUMPER	(d	,		48.00
6	FRONT BUMPER INDICATION LIGHT N/S	1	りょり	826.0000	826.00
7	FRONT BUMPER INDICATION LIGHT GARNISH N/S	1	ca	c 140.0000	140.00
8	FRONT BUMPER INDICATION LIGHT GARNISH EXTENSION N/S	1	Cu	7 25.0000 -	25.00
9	FRONT BUMPER SIDE RETAINER	1	11		X 35.00
10	FRONT BUMPER REINFORCEMENT	2	Msca	19.0000	€C 38.00
11	FRONT BUMPER REINFORCEMENT COVER	1	1	478.8000 (	X 478.80
.2		1	17	98.0000	× 98.00
13	FRONT BUMPER AID CHIEF AND	3	17	4.0000	X 12.00
14	FRONT BUMPER AIR GUIDE N/S	1	17	25.0000 6	¥ 25.00
15	FRONT BUMPER AIR GUIDE CLIPS	2	11	4.0000	× 8.00
16	HEAD LAMP N/S	1	cre	1,020.0000	1,020.00
17	RADIATOR GRILLE	1	11	150.0000	150.00
7200	RADIATOR GRILLE CHROME GARNISH N/S	1	17	98.0000 U	
18	RADIATOR GRILLE CHROME GARNISH BASE	1	17	38.0000 X	and the second second
19	RADIATOR GRILLE INNER SIDE BRACKET N/S	1	11	11.0000 9	
20	RADIATOR GRILLE INNER SIDE BRACKET WHITE CLIPS N/S	1	17	5.0000 4	11.00
21	RADIATOR GRILLE INNER SIDE BRACKET WHITE CLIPS HOLDER N/S	1	11	5.0000	
	RADIATOR GRILLE OUTER GARNISH RIVETS	4	17	9.0000 🗸	20.00
23	RADIATOR GRILLE OUTER GARNISH CLIPS	2	11	4.0000	30.00
	1/5 for whole file - 5750			C/F	

1/s front whole type - \$250 co sty cur 47180 cm / 60/ 10fs. N

Page 1 of 3

# **PEGASUS**

# ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO: 201101753C

# Quotation

rom:

PEGASUS ENGINEERING & TRADING PTE LTD

C/O 51 DEFU LANE 10

539216

Officer in Charge : WEE TZE FAH

Tel:

Email:

Customer :	
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960	p-495f 3966-0
Attn : Tel :	2218
Fax:	6184-4
	4947

Quotation No : QO18/02-1128	Quotation Date: 19/02/2018	
Vehicle No : SLM9781J		Terms: 30 DAYS
Model: MAZDA 3 Chassis No: JM6BN22A8H0149967		Third Party Insurer :
	IRED'S VEH NO: SJZ6527C, DATE OF ACCID	Date of Accident :

ITEM	DESCRIPTION	Q	TY	JNIT PRICE	AMOUNT (SGD)
24	DC VOLTAGE CONVERTER N/S				B/F 0.00
25	The state of the s	3	CN	482.2000	482.20
	FRONT WHEEL HUB CAP N/S	3	20	120.0000	120.00
26	FRONT SHOCK ABSORBER N/S	3	31	287.0000	21
27	FRONT LOWER ARM	4			_
28	FRONT WHEEL KNUCKLE		34	485.0000	
29	FRONT WHEEL BEARING WITH HUB	1	34	384.0000	384.00
30	FRONT BUMPER LOWER SUPPORT GARNISH	1	ren	542.0000	542.00
31		1	17	96.0000 4	96.00
2	FRONT BUMPER LOWER SUPPORT GARNISH BRACKET N/S	1	11	20.0000	₹ 20.00
3	FRONT BUMPER LOWER UNDER SPLASHIELD COVER	- 1		84.0000 (	84.00
3517	FRONT BUMPER LOWER UNDER SPLASHIELD COVER CLIPS	6	re	4.0000	24.00
2	REAR WHEEL HUB CAP N/S	31	CMT	120.0000	120.00
5	LESS 20% (ITEM 1 - 34)	1	/	-1,246,6000	
6	FRONT WHEEL RIM N/S	(f) 243	200	70	0.2 c J 1,246.60
7	TOWING FEES	18		1,612.0000 /	1,612.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	3		80.0000 6	0 80.00
	TO RUST-PROOFING OF THE AFFECTED AREAS	1		60.0000 2	60.00
		1		180.0000 3	0 180.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	3		120.0000 6	D 120.00
V i	TO TRANSFER OF N/S FRONT WHEEL RIM, TYRE AND ON WHEEL BALANCING	1	11	~	( 60.00
320	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS, REMOVE AND RENEWAL OF THE NECESSARY PARTS, TO PERFORM FINAL CHECKING AND TESTING	1		350.0000	w.* 350.00

# **PEGASUS**

# ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO: 201101753C

## Quotation

PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
539216

Officer in Charge : WEE TZE FAH
Tel :
Email :

Customer:

GRAB RENTALS PTE LTD

18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn:
Tel:
Fax:

Quotation No : QO18/02-1128	Quotation Date: 19/02/2018	T-mark no p to be	
Vehicle No: SLM9781J		Terms: 30 DAYS	
Model : MAZDA 3	Chassis No : JM6BN22A8H0149967	Third Party Insurer :	
		Date of Accident :	
1 Arks: IP INSURER: EQ. INSU	RED'S VEH NO: SJZ6527C, DATE OF ACCID	ENT: 18.02.2018	

ITEM	DESCRIPTION			
	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
43	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	780.0000	B/F 0.00
44	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,600,0000	/200 1,600.00

2110

# CK MOTOR PTE LTD

# Ang Mo Kio Industrial Park 2A Singapore 568047

Fax Number:

6484-2555

Customer

Date

2/23/2018 10:24 AM

Company

TAN LIM

VIN

License NO

Technician

Doometer

Order NO:

# VEHICLE ALIGNMENT REPORT

MAZDA, 3, 03-07, 1,3/1,6L Benzin

Primary Angles		Initial	Specifi	ications	Final		
	ringico		THE COLUMN	Min	Max	L HIGH	
	Caster	Left	61251	2"04"	4.04.	6°18	
		Right	6 18	2 04	4 04	6 06	
127	Camber	Lett	1"42"	1.41	0"19"	-1-42	
Front		Right	0.06	-10417	0.1191	0.08	
	1.0E	Leli	0.08	-0.05	0.17	0.06	
		Pight	3'24'	-01051	0°17"	0°24'	
		1008	0.30	-0"1"	0.33.	0.30	
	Califolica.	Left	-0136	-2.19	-0"19	-0.36	
		EUG	-1:08	2 19	-0 19	-1.06	
Real	To-	Left	0.12	201051	40°57"	0'12'	
11,152,000		Regist	0.06	-0103	0.17	0.08,	
		Total	0.18	72753	0.23	0.18	
	Three Angle		0.034			0.03	
Secondary Angles			Inual Stellingenius		1-9111112	Final	
9000000	en Frankies			Mino	1580		
(SA)		Cen	314 555		04.02	17.55	
- Larry		Right	13 22	14:04	14.02	13:26	
literation of	1904	0.07	12			13:13	
		Section 1	13 22			13132	
the bird of	e inter	No.	-			550	
		Plobi				0.00	
Illian Turri		198		25-10	101101		
1000	110100	600000	34.44	367.46	42 46	****	
ride conve	northernise:	Lati					
		Front					
Chinan		Right		-25	1000	300000	
		TYCH	wyleti.			distrib.	
Service of the ser			15-(30)11			öam	
100000 535	on Diff		50mm			10mm	
From Tide	rsudh						
		(8440)	-	227	22.25	*****	
Res Polar	Feligibi	Lun					
		Right				-	
House All	jin						

HIPhone . 2747 2555





# CK MOTOR PTE LTD

# Ang Mo Kio Industrial Park 2A Singapore 568047

Fax Number:

6484-2555

Customer

Date

2/24/2018 1:38 PM

Company

TAN LIM SLM 9781 J VIN

License NO: Ddometer:

Technician:

Order NO:

# VEHICLE ALIGNMENT REPORT

MAZDA 3 03-97 1,3/1.6L Banzin

Primary Angles			tostar	Spenif	ications	Final
				hero:	Max	6 111146
	Caster	Lett	(4) (42)	2 84	40041	6:30
		Right	Par 15	2.64	4.04	0.00
	- Germen	- 41	1.00	-1.41	0119	0.24
Front		Hight	-(3.41)			A MARK
	4700	200	-0 l/g	43/6/3	0.37	0.03
		#20tal	55.63	N.Ve.	0.17	0.050
		714.00	0.05	441.11	(4, 13)	0.00
	Certica	201	10.36	3.14	-11 19	-0136
		P0414	4.3%	2.75	8 19	1708
Figure	70	1.001	9515	(917)5	200000	0 15
11.0000		89 4 41 41	15,126	Dr. 640		0.00
					2.33	5120
26	The stanting					300065
Samo	tary Angles		=111	4.2		Himal
	234 A (15112) 255				11.	
						0.00
			007 120		, III - U.Z.	보양
			34111-0111			57(15).5



email sent EQ 20/02/2018@ 1730

# **ENGINEERING & TRADING PTE LTD**

GST / ROC COMPANY NO: 201101753C

### Quotation

From:

PEGASUS ENGINEERING & TRADING PTE LTD

C/O 51 DEFU LANE 10

539216

Officer in Charge : WEE TZE FAH

Tel: Email: Customer:

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Tel:

Fax:

Quotation No : QO18/02-1128	Quotation Date: 19/02/2018	Terms: 30 DAYS	
Vehicle No : SLM9781J	Chassis No : JM6BN22A8H0149967	Third Party Insurer :	
Model: MAZDA 3	V.5.1	Date of Accident :	

ITEM	DESCRIPTION	QTY	UN	IT PRICE	AMOUN	NT (SGD)
1	FRONT FENDER N/S	1	Suc	334.00000		334.00
2	FRONT FENDER INNER LINER	1	ton	130.0000		130.00
3	FRONT FENDER INNER LINER CLIPS	5	un	4.0000		20.00
4	FRONT FENDER INSULATOR FOAM	1	11	48.0000	X	48.00
5	FRONT BUMPER	1	10-5	826.0000	_	826.00
6	FRONT BUMPER INDICATION LIGHT N/S	1	cre	140.0000	_	140.00
7	FRONT BUMPER INDICATION LIGHT GARNISH N/S	1	Cu	25.0000	_	25.00
8	FRONT BUMPER INDICATION LIGHT GARNISH EXTENSION N/S	1	11	35.0000	X	35.00
9	FRONT BUMPER SIDE RETAINER	2/	ulscre	19.0000	VC	38.00
10	FRONT BUMPER REINFORCEMENT	1	1	478.8000	X	478.80
11	FRONT BUMPER REINFORCEMENT COVER	1	17	98.0000	X	98.00
12	FRONT BUMPER REINFORCEMENT COVER CLIPS	3	17	4.0000	X	12.00
13	FRONT BUMPER AIR GUIDE N/S	1	17	25.0000	a	25.00
14	FRONT BUMPER AIR GUIDE CLIPS	2	11	4.0000	K	8.00
15	HEAD LAMP N/S	1	CM	1,020.0000	/	1,020.00
16	RADIATOR GRILLE	1		150.0000	?	150.00
17	RADIATOR GRILLE CHROME GARNISH N/S	1	17	98.0000	4	98.00
18	RADIATOR GRILLE CHROME GARNISH BASE	1	11	38.0000	d	38.00
19	RADIATOR GRILLE INNER SIDE BRACKET N/S	1	11	11.0000	or	11.00
20	RADIATOR GRILLE INNER SIDE BRACKET WHITE CLIPS N/S	1	17	5.0000	4	5.00
21	RADIATOR GRILLE INNER SIDE BRACKET WHITE CLIPS HOLDER N/S	1	11	5.0000	×	5.00
22	RADIATOR GRILLE OUTER GARNISH RIVETS	4	17	9.0000	X	36.00
23	RADIATOR GRILLE OUTER GARNISH CLIPS	2	11	4.0000	X	8.00



# **ENGINEERING & TRADING PTE LTD**

GST / ROC COMPANY NO: 201101753C

## Quotation

PEGASUS ENGINEERING & TRADING PTE LTD

C/O 51 DEFU LANE 10

539216

Officer in Charge : WEE TZE FAH

Tel: Email: Customer:

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960

Attn :

Fax:

Quotation No : QO18/02-1128	Quotation Date: 19/02/2018	Terms: 30 DAYS	
Vehicle No : SLM9781J	Chassis No : JM6BN22A8H0149967	Third Party Insurer :	
Model: MAZDA 3	11,1,1	Date of Accident :	

ITEM	DESCRIPTION	QTY	UN	IT PRICE	AMOU	NT (SGD)
	d .				B/F	0.00
24	DC VOLTAGE CONVERTER N/S	1	Cre	482.2000	/	482.20
25	FRONT WHEEL HUB CAP N/S	1	33	120,0000	_	120.00
26	FRONT SHOCK ABSORBER N/S	1		287.0000	?	287.00
27	FRONT LOWER ARM	1		485.0000	7	485.00
28	FRONT WHEEL KNUCKLE	1		384.0000	7	384.00
29	FRONT WHEEL BEARING WITH HUB	1		542.0000	フ	542.00
30	FRONT BUMPER LOWER SUPPORT GARNISH	1	17	96.0000	×	96.00
31	FRONT BUMPER LOWER SUPPORT GARNISH BRACKET N/S	1	11	20.0000	4	20.00
32	FRONT BUMPER LOWER UNDER SPLASHIELD COVER	1		84.0000	?	84.00
33	FRONT BUMPER LOWER UNDER SPLASHIELD COVER CLIPS	6	ner	4.0000	/	24.00
34	REAR WHEEL HUB CAP N/S	1/10	chi	120,0000	X	120.00
35	LESS 20% (ITEM 1 - 34)	1		1,246.6000		1,246.60
36	FRONT WHEEL RIM N/S	1	30	1,612.0000	1005	1,612.00
37	TOWING FEES	1		80.0000	60	80.00
38	TO CHECK ELECTRICAL LIGHTING CONCERNED	1		60.0000	20	60.00
39	TO RUST-PROOFING OF THE AFFECTED AREAS	1		180.0000	30	180.00
40	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	1		120.0000	60	120.00
41	TO TRANSFER OF N/S FRONT WHEEL RIM, TYRE AND ON WHEEL BALANCING	1	N	60.0000		60.00
42	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS, REMOVE AND RENEWAL OF THE NECESSARY PARTS, TO PERFORM FINAL CHECKING AND TESTING	1		350.0000	120.	350.00

Page 2 of 3

GST / ROC COMPANY NO: 201101753C

### Quotation

_	_	_		٠.	
			п		

PEGASUS ENGINEERING & TRADING PTE LTD

C/O 51 DEFU LANE 10

539216

Officer in Charge: WEE TZE FAH

Tel: Email: Customer:

**GRAB RENTALS PTE LTD** 

18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960

Attn Tel:

Fax:

Quotation No : QO18/02-1128	Quotation Date: 19/02/2018	Terms: 30 DAYS	
Vehicle No : SLM9781J	Chassis No : JM6BN22A8H0149967	Third Party Insurer :	
Model: MAZDA 3		Date of Accident :	

marks: TP INSURER: EQ, INSURED'S VEH NO: SJZ6527C, DATE OF ACCIDENT: 18.02.2018

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (	SGD)
43	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	780.0000	120 T	0.00 780.00
44	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,600.0000	1000 1,8	00.00

LKK Auto Consultants nence notify the Repairer of the following:

To resurvey before after spray painting.

- . To risplay damaged partist during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No idegal modification(s) is allowed
- Supplementary dem(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total GST(7.00%) Total (SGD)

9,828.40 687.99 10,516.39

# Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particular	5	
Owner ID Type:	Company	
Owner ID:	7200G	
Vehicle Details		
Vehicle No.:	SLM9781J	
Vehicle to be Exported:	No	
Intended De-registration Date:	22 Feb 2018	
Vehicle Make:	MAZDA	
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6	
Primary Colour:	Grey	
Manufacturing Year:	2017	
Engine No.:	P520441619	
Chassis No.:	JM6BN22A8H0149967	
Maximum Power Output:	88.0 kW (118 bhp)	
Open Market Value:	\$14,476.00	
Original Registration Date:	19 Apr 2017	
First Registration Date:	19 Apr 2017	
Transfer Count:	0	
Actual ARF Paid:	\$9,476.00	
Intended PARF Rebate De	etails	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	18 Apr 2027	
PARF Rebate Amount:	\$7,107.00	
Intended COE Rebate Det	tails	
COE Expiry Date:	18 Apr 2027	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$51,765.00	
COE Rebate Amount:	\$47,403.00	
Total Rebate Amount:	\$54,510.00	

The information contained herein is correct as at 22 Feb 2018

## Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) < Meikwan@lkkauto.com>

Sent: Wednesday, 21 February 2018 4:41 PM

To: Bazlin Ahmad; assignments

Cc: Admin A

Subject: RE: Third Party Survey - SLM9781J EQ Insured - SJZ6527C DOA: 18.02.2018 Attachments:

SLM9781J 18.02.2018.pdf; SJZ6527C 18.02.2018.pdf; 20022018173339.pdf

12.17pm@22/2/18 vihicle In Sur@mercus

Dear Lynn,

Thank you for your assignment.

By copy to assignment team.

Kindly assist to arrange TP survey.

Thank you. Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Bazlin Ahmad [mailto:bazlin.ahmad@eginsurance.com.sg]

Sent: Wednesday, 21 February, 2018 4:29 PM

To: Admin A <admin-a@lkkauto.com>

Subject: FW: Third Party Survey - SLM9781J EQ Insured - SJZ6527C DOA: 18.02.2018

Dear LKK

We refer to the above new assignment, please find below email and attachments for easy reference.

Thank You.

Regards, Lynn Ahmad

Executive | Claims



**EQ Insurance Company Limited** 

5 Maxwell Road #17-00 Tower Block, MND Complex, Singapore 069110 did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190 www.eqinsurance.com.sg



you've got a friend

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Pegasus Engineering [mailto:claims@pegasusengrq.com.sq]

Sent: Wednesday, February 21, 2018 3:05 PM

To: Bazlin Ahmad

Subject: Re: Third Party Survey - SLM9781J EQ Insured - SJZ6527C DOA: 18.02.2018

Dear Sir/Mdm.

We choose LKK to survey.

Please arrange.

Thanks & Regards,

Alvin Low -CO

Pegasus Engineering & Trading Pte Ltd 51 Defu Lane 10 Singapore 539216

Tel

: 6858 1846 : 6487 6070

Fax Email

: claims@pegasusengrg.com.sg

On Wed, Feb 21, 2018 at 11:19 AM, Bazlin Ahmad <a href="mailto:specification.com.sg">bazlin.ahmad@eqinsurance.com.sg</a> wrote:

#### Without Prejudice

Dear Sir,

We refer to your Notice of Accident of even date.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please <u>revert within 2 working days</u> if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

# 1) AJAX Inspection Services Pte Ltd

Tel: 6255 0808

Fax: 6849 9155

Contact person : Joey/Joseh

# 2) Automobile Inspection Services Pte Ltd

Tel: 6286 0155

Fax: 6284 1539

Contact Person: Sophia

3) LBS Automotive Appraisal Pte Ltd  L.B.S. Auto Consultants Pte Ltd  Tel: 6281 6690 / 62832866  Fax: 6281 8748  Contact Person: Amy/ Grace	4) Priority Services  Tel: 62934822  Fax: 62963283  Contact Person: Sharon Kho
5) RT Appraisal Pte Ltd	6) LKK Auto Consultants Pte
Tel: 67486076	Ltd
Fax: 67480361	Tel: 6256-3561
Contact Person: Ricky Teng	Fax: 6741-4108
7) Kelvin Automotive	8) Automotive Appraiser &
Appraising Services	Surveying Services
Tel: 81825263	Tel: 96623655
Fax: 67461148	Fax: 67655662
Contact Person: Kelvin	Contact Person: Mr Chee
9) JP Knights Pte Ltd	
Tel: 63450068	
Fax: 63445328	
Contact Person: Edna Lee	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Thank You.

### Regards,

#### Lynn Ahmad

Executive | Claims



#### EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190 www.eqinsurance.com.sg





Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Janet Tan

Sent: Wednesday, February 21, 2018 8:49 AM

To: Bazlin Ahmad

Cc: claims@pegasusengrg.com.sg

Subject: FW: Third Party Survey - SLM9781J Your Insured - SJZ6527C DOA: 18.02.2018

Lynn,

For your necessary action.

Thank you.

Regards,

Janet Tan

Senior Executive | Claims



#### **EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190 www.eginsurance.com.sg





From: Pegasus Engineering [mailto:claims@pegasusengrg.com.sg]

Sent: Tuesday, February 20, 2018 5:30 PM

To: Elaine Cheong <elaine.cheong@eqinsurance.com.sg>

Cc: Janet Tan < janet.tan@eqinsurance.com.sg>

Subject: Third Party Survey - SLM9781J Your Insured - SJZ6527C DOA: 18.02.2018

Your Ref: SJZ6527C

Our Ref:

SLM9781J

DOA: 18.02.2018

Without Prejudice

Dear All,

We refer to the above matter.

We enclose the following documents for your attention:

- a. Copy of our client's SAS report and damaged photos;
- b. Copy of the estimated cost of repair.

Pursuant to paragraph 6.2 of Pre-Action Protocol for NIMA Cases, please let us know within 2 working days whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please arrange survey as soon as possible, vehicle is grounded in our premises.

In addition, please confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

Thanks & Regards,

Alvin Low-

Pegasus Engineering & Trading Pte Ltd 51 Defu Lane 10 Singapore 539216

Tel : Fax :

: 6858 1846 : 6487 6070

Email

: claims@pegasusengrg.com.sg

# Mei Kwan (LKKAuto)

From:

Mei Kwan (LKKAuto)

Sent:

Monday, 26 February, 2018 10:52 AM

To:

'Bazlin Ahmad'

Cc:

Admin A; Asher Sng (LKKAuto); Vic (LKKAuto)

Subject:

RE: Third Party Survey - SLM9781J EQ Insured - SJZ6527C DOA: 18.02.2018

Attachments:

LKK SURVEY PHOTO.pdf; TP ESTIMATE - MARKED.pdf; Preliminary Advice.pdf

Categories:

HMK

Your ref: TBA

LKK ref: CC4/EQI18003316/Uea3

#### WITHOUT PREJUDICE

Dear Lynn,

We refer to the above matter.

This is a third party direct settlement case.

Enclosed revert of vehicle: SLM 9781]

Date of survey: 21.02.2018

We have not authorized repairs.

#### Enclosed for your perusal is:

- TP estimate (marked)
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Please take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

#### To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

#### LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 22 February, 2018 12:18 PM

To: 'Bazlin Ahmad' <bazlin.ahmad@eqinsurance.com.sg>; assignments <assignments@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Third Party Survey - SLM9781J EQ Insured - SJZ6527C DOA: 18.02.2018

Dear Sir/Mdm,

Thank you for the assignment.

·Tel

: 6858 1846 : 6487 6070

Fax Email

: claims@pegasusengrg.com.sg

On Wed, Feb 21, 2018 at 11:19 AM, Bazlin Ahmad <br/>
<a href="mailto:bazlin.ahmad@eqinsurance.com.sg">bazlin.ahmad@eqinsurance.com.sg</a> wrote:

### Without Prejudice

Dear Sir,

We refer to your Notice of Accident of even date.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please <u>revert within 2 working days</u> if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd	2) Automobile Inspection Services Pte Ltd
Tel: 6255 0808	Tel: 6286 0155
Fax: 6849 9155	Fax: 6284 1539
Contact person : Joey/Joseh	Contact Person: Sophia
3) LBS Automotive	4) Priority Services
Appraisal Pte Ltd	Tel: 62934822
L.B.S. Auto Consultants Pte	
Ltd	Fax: 62963283
Tel: 6281 6690 / 62832866	Contact Person: Sharon Kho
Fax: 6281 8748	
Contact Person: Amy/ Grace	
5) RT Appraisal Pte Ltd	6) LKK Auto Consultants Pte Ltd
Tel: 67486076	20000000 20000000 200000000000000000000
	Tel: 6256-3561
Fax: 67480361	Fax: 6741-4108
Contact Person: Ricky Teng	100.0712 1200

From: Janet Tan

Sent: Wednesday, February 21, 2018 8:49 AM

To: Bazlin Ahmad

Cc: daims@pegasusengrg.com.sq

Subject: FW: Third Party Survey - SLM9781J Your Insured - SJZ6527C DOA: 18.02.2018

Lynn,

For your necessary action.

Thank you.

Regards,

Janet Tan

Senior Executive | Claims



#### **EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190 www.eqinsurance.com.sg



**®** 

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the:

From: Pegasus Engineering [mailto:claims@pegasusengrg.com.sg]

Sent: Tuesday, February 20, 2018 5:30 PM

To: Elaine Cheong <elaine.cheong@eqinsurance.com.sg>

Cc: Janet Tan < janet.tan@eqinsurance.com.sg>

Subject: Third Party Survey - SLM9781J Your Insured - SJZ6527C DOA: 18.02.2018

Your Ref: SJZ6527C

Our Ref:

SLM9781J

## Asher Sng (LKKAuto)

From:

Asher Sng (LKKAuto)

Sent:

Monday, 5 March 2018 12:48 PM

To:

'Pegasus Engineering'

Cc:

Admin A; Vic (LKKAuto)

Subject:

RE: Third Party Survey - SLM9781J EQ Insured - SJZ6527C DOA: 18.02.2018

#### WTHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents for us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Pegasus Engineering [mailto:claims@pegasusengrg.com.sq]

Sent: Wednesday, February 21, 2018 3:05 PM

To: Bazlin Ahmad

Subject: Re: Third Party Survey - SLM9781J EQ Insured - SJZ6527C DOA: 18.02.2018

Dear Sir/Mdm.

We choose LKK to survey.

Please arrange.

Thanks & Regards,

Alvin Low -CO

4.4

Pegasus Engineering & Trading Pte Ltd 51 Defu Lane 10 Singapore 539216

Tel : 6858 1846 Fax : 6487 6070

Email : claims@pegasusengrg.com.sg

On Wed, Feb 21, 2018 at 11:19 AM, Bazlin Ahmad <a href="mailto:bazlin.ahmad@eqinsurance.com.sg">bazlin.ahmad@eqinsurance.com.sg</a> wrote:

## Without Prejudice

Dear Sir,

We refer to your Notice of Accident of even date.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please <u>revert within 2 working days</u> if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd	2) Automobile Inspection Services Pte Ltd
Tel: 6255 0808	Tel: 6286 0155
Fax: 6849 9155	Fax: 6284 1539
Contact person : Joey/Joseh	Contact Person: Sophia
3) LBS Automotive	4) Priority Services
Appraisal Pte Ltd	Tel: 62934822
L.B.S. Auto Consultants Pte Ltd	Fax: 62963283
Tel: 6281 6690 / 62832866	Contact Person: Sharon Kho

Fax: 6281 8748  Contact Person: Amy/ Grace  5) RT Appraisal Pte Ltd  Tel: 67486076  Fax: 67480361	6) LKK Auto Consultants Pte Ltd  Tel: 6256-3561  Fax: 6741-4108
7) Kelvin Automotive Appraising Services  Tel: 81825263  Fax: 67461148  Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services  Tel: 96623655  Fax: 67655662  Contact Person: Mr Chee
9) JP Knights Pte Ltd  Tel: 63450068  Fax: 63445328  Contact Person: Edna Lee	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Thank You.


Regards,

Lynn Ahmad Executive | Claims



## **EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190 www.eginsurance.com.sg





Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Janet Tan

Sent: Wednesday, February 21, 2018 8:49 AM

To: Bazlin Ahmad

Cc: claims@pegasusengrg.com.sq

Subject: FW: Third Party Survey - SLM9781J Your Insured - SJZ6527C DOA: 18.02.2018

Lynn,

For your necessary action.

Thank you.

Regards,


Janet Tan

Senior Executive | Claims



#### **EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190 www.eqinsurance.com.sg





Privileged/Confidential information me	ly be contained in this message.	If you are not the inte	ended recipient, please no	otify the
--	----------------------------------	-------------------------	----------------------------	-----------

From: Pegasus Engineering [mailto:claims@pegasusengrg.com.sg]

Sent: Tuesday, February 20, 2018 5:30 PM

To: Elaine Cheong <elaine.cheong@eqinsurance.com.sg>

Cc: Janet Tan < janet.tan@eginsurance.com.sg>

Subject: Third Party Survey - SLM9781J Your Insured - SJZ6527C DOA: 18.02.2018

Your Ref: SJZ6527C

Our Ref:

SLM9781J

DOA: 18.02.2018

Without Prejudice

Dear All.

We refer to the above matter.

We enclose the following documents for your attention:

- Copy of our client's SAS report and damaged photos;
- b. Copy of the estimated cost of repair.

Pursuant to paragraph 6.2 of Pre-Action Protocol for NIMA Cases, please let us know within 2 working days whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please arrange survey as soon as possible, vehicle is grounded in our premises.

In addition, please confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

Thanks & Regards,

Alvin Low-

WL

Pegasus Engineering & Trading Pte Ltd 51 Defu Lane 10 Singapore 539216

Tel : 6858 1846 Fax : 6487 6070

Email : claims@pegasusengrg.com.sg

Grab Rentals Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Your Ref: SJZ 6527C Our Ref: SLM 9781J

WITHOUT PREJUDICE

05/06/2017

Motor Claims Department

EQ Insurance Company Lotal.

Dear Sir/Madam

# ACCIDENT INVOLVING SLM9781J/SJZ6522C ON 18/02/2018

We refer to the above-mentioned accident.

We confirmed acceptance on your offer of 5\$ 5886-57 in full and final settlement of our property damaged claim.

We hereby authorize that the said payment is to be issued in favour of Messrs PEGASUS ENGINEERING & TRADING PTE LTD within fourteen (14) days or upon receipt of the duly signed discharge voucher.

Your attention and prompt action in this matter is greatly appreciated.

Yours sincerely



MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Wey, #21-01, SGX Centre 2, Singapore 058807 Tel +65 6827 7888, Fax +65 6827 7800 Co. Reg. No. 200412212G GST Reg. No. 20-041221G

# Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1958 (FEDERATION OF MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)

(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.Z.400 Cars for Hire

COMMERCIAL VEHICLE - FLEET Comprehensive

Certificate No. A 29069766 MKF

Excess: SGD2,000

1. Index Mark and Registration Number of Vehicle SLM9781J

2. Name of Policyholder

Grab Rentals Pte. Ltd.

Effective Date of the Commencement of Insurance for the purposes of the Act 01/02/2018

4. Date of Expiry of Insurance

31/01/2019

5. Persons or Classes of Persons entitled to drive\*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use'

Use for the carriage of passengers or goods in connection with the Policyholder's business.

Use for social domestic and pleasure purposes.

The Policy does not cover

Use for racing pace-making reliability trial or speed-testing.
 Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte, Ltd. Approved Insurers

Chief Executive Officer



Tel: 6858 1846 / HP 9628 6508

Fax: 6858 0877

9A Lok Yang Singapore 628628 c/o 51 Defu Lane 10 Singapore 539216

WITHOUT PREJUDICE Claims Department - Executive In Change.
BQ Insurance Company Ltd Dear Sir/Madam, ACCIDENT INVOLVING SLM 9781] / SJZ 6527c ON 18/02/2018
(P4e HITE). Refer to the above accident and please acknowledge receipt of this letter within 14 days. It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -O Original survey report/\_\_\_\_ copies of photographs \_ Original Tax-invoice number 18/64-1913. O police report / police result Wehicle search result O Certificate Of Insurance S Authorization To Act & Owner/Hirer \*Survey under insurance instruction / Independent surveyor / No survey. LKK Cost of repair (inclusive GST) a) Survey fees / Photographs as per request b) Vehicle Search fees / GIA fees / Police Report fees / Reporting fees c) Loss of rental 10 days @ \$ 66-95 d) Loss of earnings /rental fees \_\_\_\_days @ \$\_ (3 Administrative charges to negotiate settlement f) (Waive if 100% offer made within acknowledge timeframe) 9) Total

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Pegasus Engineering & Trading Pte Ltd" within 28 days.

Yours faithfully,

Sharon Ow

Email: claims@pegasusengrg.com.sg

<sup>\*</sup> Driver's injury and other losses exclude in this claim.

# Asher Sng (LKKAuto)

From:

Asher Sng (LKKAuto)

Sent:

Friday, 9 March 2018 2:33 PM

To:

'KTHESEIRA@IGROUPNET.COM'

Subject:

ACCIDENT INVOLVING SJZ 6527C AND SLM 9781J ON 18/02/2018



Auto Consultants Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 67414108 Our Ref: CC4/EOI18003316/Uea3

09 MAR 2018

#### THESEIRA KELVIN GERARD

Dear Sir/Madam,

#### ACCIDENT INVOLVING SJZ 6527C AND SLM 9781J ON 18/02/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher

Case Handler DID: 6841 6051 FAX: 6741 4108

Email: Ashersng@lkkauto.com

c.c. EQ INSURANCE COMPANY LIMITED

(Motor Claims Dept)

# AUTHORIZATION TO ACT

TO: PEGASUS ENGINEERING & TRADING PTE LTD
FROM: OWNER OF VEHICLE NUMBERSLM9781J
ACCIDENT INVOLVING
ALONG/AT Tampines Street 82 & Tampines Avenue 3 ON 18/05/18.
We hereby authorize you to act on our behalf in pursuance of our claim for all damages during the repair arising out of the above accident.
This letter serve as the 'AUTHORITY TO ACT'.
We also hereby authorize all agreed settlement payment be made in favour to PEGASUS ENGINEERING & TRADING PTE LTD.
Name : Grab Rentals Pte Ltd
Co Reg No : 201617200G
Address : 18 Sin Ming Lane #01-08 Midview City Singapore 573960
Contact : 6655 0005
Date : Mospies.
Signature  Signature
1 /

Owner



GST / ROC Company No: 201101753C

Third Party Insurer:

EQ

Insured's Veh No:

SJZ6527C

Date of accident :

18.02.2018

Grab Rentals Pte Ltd 18 Sin Ming Lane #01-08 Midview City

Tax Invoice No:

IV18/04-1213

Singapore 573960

Invoice Date:

30.04.2018

Vehicle Model:

Mazda 3 Sedan 1.5

Vehicle No:

SLM9781J

Chassis No:

JM68N22A8H0149967

	Pages :	1 of
DESCRIPTION		TANOMA
TO LUMP SUM REPAIR AS RECOMMENDED BY SURVEYOR	s	4,900.00
Sub Total	\$	4,900.00
GST (7.00%)	s	343.0
Total	\$	5,243.00

Cheques should be made payable to PEGASUS ENGINEERING & TRADING PTE LTD

#### PEGASUS ENGINEERING & TRADING PTE LTD



Authorised Signature (Company Stamp)

If you have enquiries concerning this invoice, please contact Mr. Alvin or Mr. Wee at Tel: (65) 6858 1846 Mailing Address : Pegasus Engineering@Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216 E-mail: claims@pegasusengrg.com.sg



Our Ref: GR-ACC-2017-02

01 June 2017

Pagasus Engineering & Trading Pte Ltd No. 51 Defu Lane 10 Singapore 539216

Mailing Address 18 Sin Ming Lane, #01-08 Midview City, Singapore 573960 Co. No. 201617200G

To whom it may concern,

Re: Vehicle Rental Rates for Loss of Rental Claims.

With regards to the above subject matter, we are pleased to inform you our Grab Rental rate for our various vehicles which are as follows:

S/No.	Make & Model	Daily Rental Rates (S\$)
01	Toyota Prius 1,798cc, 90kw, 120bhp, Automatic	\$ 79.95
02	Mazda 3 1.5 (A) Sedan	\$ 66,95
03	Nissan Qashqal 1.2L	\$78.95
04	Honda Vezel 1.5L	\$77,95
05	Honda Vezel 1.5L Hybrid	\$84.95
06	Toyota Vios 1.5L	\$66.95

Please note that the above stated rate is our daily rental rate to our drivers. For your necessary actions on third party accident claims on loss of rental.

Yours faithfully,

Tay Chee Wee Grab Rental Pte Ltd 2/19/2018 Vehicle Hub

### Enquire Vehicle & Owner Information (Vehicle No. SJZ6527C As At 18 Feb 2018 / 11:15:00)

#### Law Firm Search Details

Search Reason:

Insurance claim in relation to traffic accident

Law Firm Case No.:

SLM9781J

**Current Owner Details** 

Owner ID Type:

Singapore NRIC

Owner ID:

S1551224E

Owner Name:

THESEIRA KELVIN GERARD

Registered Address Type: HDB / HUDC Registered Block/House

940

Registered Street Name: TAMPINES AVENUE 5

Registered Unit No.:

#02-185

Registered Building Name: -

Registered Postal Code: 520940

**Current Vehicle Details** 

Vehicle No.:

SJZ6527C

Make Description/Model: CHEVROLET / CRUZE 1.6L AUTO ABS D/AB 2WD 4DR

Insurance Company Name: EQ INSURANCE COMPANY LTD

Print OK





Lee Ming Hui Kelvin has successfully logged out. Your last login date and time was 19 Feb 2018, 12:31:51. To return to ONE.MOTORING, please click here For security reasons, please CLEAR YOUR CACHE after each session.

#### Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	SJZ6527C	*	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	19 Feb 2018 / 12:33:23



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

### To: M/s EQ INSURANCE COMPANY LTD

Date: 26/06/2018

#### THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SJZ 6527C	(Insd Veh)	Your Ref. No.: DMPPHQ17-006245
venicle No.	SLM 9781J	(TP Veh)	Our Ref. No. : CC4/EQI18003316/Uea3q2
Date of Accident	18/2/2018		

Liability		100%	
Final Repair Cost	: \$	5,243.00	
Loss of Use	: \$		days
Rental (If any)	: \$	636.03	9.5 days
Others:	: \$	7.49	
	: \$		
		5,886.52	
Final Settlement Sum	: \$	5,886.52	
Remarks			

1)	PEGASUS ENGINEERING & TRADING PTE LTD	: \$	5,886.52
		: \$	

JOANNE LEE LKK Auto Consultants Pte Ltd



5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

		Affiliated to Federation Inter-	nationale Des Experts En Autor	nobile
EQ	INSURANCE COM	IPANY LTD	Ref : CC4/EQI18003	3316/Uea3q2
#17	AXWELL ROAD -00 TOWER BLOC D COMPLEXSING		Date: 26-06-2018  Code: EQI	
1.		Policy Particul	ars :- THIRD PARTY CLA	IM
	Insured Veh.	SJZ 6527C	Veh. Inspected	SLM 9781J
	Policy No.	DMPPHQ17-006245	Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	21/02/2018
2.		Vehicle P	articulars & Condition	U S O Z PULLED
	Make & Model	MAZDA 3 (A)	c.c	1496
П	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JM6BN22A8H0149967	Colour	GREY
	Odometer	70532	Steering	AFFECTED
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Cor	nditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	WEST LAKE	7 mm
	L/H Front Tyre	205/60 R16	WEST LAKE	7 mm
	R/H Rear Tyre	205/60 R16	WEST LAKE	7 mm
	L/H Rear Tyre	205/60 R16	WEST LAKE	7 mm
4.		Descr	iption of Damages	THE MEDICAL PROPERTY.
	THE VEHICLE SU DUE TO COLLISIO	STAINED DAMAGES AT THE DN.	N/S FRONT PORTION.THE	UNDERCARRIAGE AFFECT
	DAMAGES SEE D			
5.	Kan Cauching		eral Information	In the second second
	Accident Date	18/02/2018	Inspection Date	21/02/2018
	Survey held at	PEGASUS ENGINEERING	& TRADING PTE LTD	
		51 DEFU LANE 10 SINGAPORE 539216		
5a.	HITESAND PARTY OF		Remarks	

Estimate Days of Repair

7 Working Days



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 9781J

ty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER N/S	BUCKLED	334.00	334.00
1	FRONT FENDER INNER LINER	TORN	130.00	130.00
5	FRONT FENDER INNER LINER CLIPS @\$4.00	NECESSARY	20.00	20.00
1	FRONT FENDER INSULATOR FOAM	NOT NECESSARY	48.00	
1	FRONT BUMPER	DISTORTED	826.00	826.00
1	FRONT BUMPER INDICATION LIGHT N/S	CRACKED	140.00	140.00
1	FRONT BUMPER INDICATION LIGHT GARNISH N/S	CUT	25.00	25.00
1	FRONT BUMPER INDICATION LIGHT GARNISH EXTENSION N/S	NOT NECESSARY	35.00	
1	FRONT BUMPER SIDE RETAINER	N/S CRACKED	38.00	19.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	478.80	1
1	FRONT BUMPER REINFORCEMENT COVER	NOT NECESSARY	98.00	
3	FRONT BUMPER REINFORCEMENT COVER CLIPS @\$4.00	NOT NECESSARY	12.00	
1	FRONT BUMPER AIR GUIDE N/S	NOT NECESSARY	25.00	
2	FRONT BUMPER AIR GUIDE CLIPS @\$4.00	NOT NECESSARY	8.00	
1	HEAD LAMP N/S	CRACKED	1,020.00	1,020.00
1	RADIATOR GRILLE	NOT NECESSARY	150.00	
1	RADIATOR GRILLE CHROME GARNISH N/S	NOT NECESSARY	98.00	
1	RADIATOR GRILLE CHROME GARNISH BASE	NOT NECESSARY	38.00	
1	RADIATOR GRILLE INNER SIDE BRACKET N/S	NOT NECESSARY	11.00	
1	RADIATOR GRILLE INNER SIDE BRACKET WHITE CLIPS N/S	NOT NECESSARY	5.00	
1	RADIATOR GRILLE INNER SIDE BRACKET WHITE CLIPS HOLDER N/S	NOT NECESSARY	5.00	
4	RADIATOR GRILLE OUTER GARNISH RIVETS @\$9.00	NOT NECESSARY	36.00	
2	RADIATOR GRILLE OUTER GARNISH CLIPS @\$4.00	NOT NECESSARY	8.00	
1	DC VOLTAGE CONVERTER N/S	CRACKED	482.20	482.20
1	FRONT WHEEL HUB CAP N/S	DENTED	120.00	120.00
1	FRONT SHOCK ABSORBER N/S	BENT	287.00	287.00
1	FRONT LOWER ARM	BENT	485.00	485.00

Report Ref No. CC4/EQI18003316/Uea3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	FRONT WHEEL KNUCKLE	BENT	384.00	384.00
1	FRONT WHEEL BEARING WITH HUB	NECESSARY	542.00	542.00
1	FRONT BUMPER LOWER SUPPORT GARNISH	NOT NECESSARY	96.00	
1	FRONT BUMPER LOWER SUPPORT GARNISH BRACKET N/S	NOT NECESSARY	20.00	
1	FRONT BUMPER LOWER UNDER SPLASHIELD COVER	NOT NECESSARY	84.00	
6	FRONT BUMPER LOWER UNDER SPLASHIELD COVER CLIPS @\$4.00	NECESSARY	24.00	24.00
1	REAR WHEEL HUB CAP N/S	CUT	120.00	120.00
	LESS 20% DISCOUNT		-1,246.60	-991.64
			4,986.40	3,966.56
	SPECIAL NETT ITEMS			
1	N/S FRONT WHEEL TYRE (LOCAL PURCHASE) (60%) (\$180.00) (SN)	сит	250.00	108.00
1	FRONT WHEEL RIM N/S (SN)	DENTED	1,612.00	100.00
			1,862.00	208.00
	LABOUR			
	TOWING FEES.		80.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		180.00	30.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT		120.00	60.00
	TO TRANSFER OF N/S FRONT WHEEL RIM , TYRE AND ON WHEEL BALANCING .	NOT NECESSARY	60.00	-
	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS , REMOVE AND RENEWAL OF THE NECESSARY PARTS , TO PERFORM FINAL CHECKING AND TESTING.		350.00	120.00
	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT .		780.00	520.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,600.00	1,200.00
			3,230.00	2,010.00
	GRAND TOTAL		10,078.40	6,184.56

Report Ref No. CC4/EQI18003316/Uea3q2



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS	0.0010.000	HAVE SUITE	4,900.00
(TO ITS PRE-ACCIDENT CONDITION)	I Bernyin i wasin i	CONTRACTOR OF THE PARTY OF THE	

Report Ref No. CC4/EQI18003316/Uea3q2

CHUA KANG SENG

Licensed Appraiser