

Your ref: S8M0099J

Our ref: CC4/ASM18003327/K1hb3

Date: 22.02.2018

The Motor Claims Department
M/s AXA INSURANCE SINGAPORE PTE LTD


Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.**SHC626J**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21.02.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

| | | |
|-------------------------------|-------|----------|
| Workshop Estimate Amount | : S\$ | 2,058.80 |
| Revised Estimate Amount | : S\$ | 560.00 |
| "Check" Items Amount | : S\$ | - |
| Total (Including Check Items) | : S\$ | 560.00 |
| Market Value | : S\$ | - |
| LTA Reimbursement Value | : S\$ | - |
| Nett Value | : S\$ | - |

Description of Damage:
The vehicle sustained damages at the
Front N/S Portion

Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser