

ASS. REC. BY:

REF: CS/FCI18003340/Ugd39

Special Instruction

Survey of  
CWS

MARCUS

ASSIGNMENT (Office)

From (Person)

Serene Ler

of

FCI

Date/Time

21/2/18 @ 5:55pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

FBF 9293 G

Insured:

SHA 7859 T

at Workshop m/s

Bun Hock Hin

Tel:

62816520

of

No. 6 Defu Lane 4

Policy No:

Claim No:

D18001253MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/02/2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

22/02/18 @ 8am

Person Contacted:

Raymond

Vehicle  IN  OUT

Date/Time

Action/Instruction (✓) Estimate

FBF 9293 G - X

SHA 7859 T - NA / INCL 14015354 / d2

D.O.A: 12/8/14

23/2/18 @

3:55pm revised to Serene Ler by email.

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: F3F92936

at Workshop m/s SMH

of \_\_\_\_\_

Insured: SHA 7859T

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 5200

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: F3F92936 Yr Regn: 1, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha YBR125 c.c. 124

Colour: white A/C: Insured / Std / NI / NA

Sp.Reading: 44630 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: L13PKC128PA-0252758

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 2.75-18

R: 3.00-18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or metzeler

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm

D.O.A. 8/2/18 D.O.I. 21/2/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt - O/S 3.6

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 448 11.00

20/3/18 LTA 606 NETT 4594  
L/S # 2600 contact with Raymond.  
(had @ 264, 47%)

RECEIVED 12 MAR 2018

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: 5

: Final Report

Resurvey No. of Trip: 1

1) 17/13 11.00

2) \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS + SI

Photos

Others

TOTAL

135
50
50
715
350

Report Format: 7P

Lump Sum / I.B.I: (\$ 2600 )



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18003340/Uqd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 22-02-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7859T	Veh. Inspected	FBF 9293G
Policy No.		Coverage (\$)	0.00
Claim No.	D18001253MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	22/02/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	08/02/2018	Inspection Date	21/02/2018
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	09-02-2018	<b>Our Ref No.</b> D18001253MFSH
<b>Accident Date</b>	08-02-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA7859T	<b>Third Party Vehicle.</b> FBF9293G
<b>Survey Location</b>	NO. 6 DEFU LANE 4	
<b>Contact Person.</b>	RAYMOND	
<b>Contact No.</b>	62816520/ 0	<b>Fax No.</b> 62842969
<b>Survey Type</b>	DIRECT SETTLEMENT: EST. COR - \$5,204.48	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	BAN HOCK HIN CO. PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	SERENE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234886)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D18001253MFSH	<b>Policy No</b>	D-18088936MFSH	<b>Claimant S.No &amp; Name</b>	1 & BAN HOCI
<b>Workshop Name</b>	BAN HOCK HIN CO. PTE LTD (Contact Person : RAYMOND)	<b>Survey Location &amp; Contact Details</b>	NO. 6 DEFU LANE 4 <b>Mobile: 0 , Phone: 62816520 , Fax: 62842969</b> <b>EmailId: RAYMOND@BHH.COM.SG</b>		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	DIRECT SETTLEMENT: EST. COR - \$5,204.48		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SHA7859T	<b>TP Vehicle No</b>	FBF9293G
<b>PRI Recieved Date</b>	21-02-2018 02:37:35 PM	<b>Surveyor Appointed Date</b>	21-02-2018 05:54:04 PM	<b>Surveyor Accept Date</b>	22-02-2018 0

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	22-02-2018	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select Year"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Friday, 23 February 2018 3:35 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** SERENELER@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18001253MFSH/1  
**Attachments:** CSFCI18003340Uqd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of FBF 9293G.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Thursday, 22 February 2018 8:01 AM  
**To:** 'Claim Workflow System' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D18001253MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Wednesday, 21 February 2018 5:54 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [SERENELER@MSFIRSTCAPITAL.COM.SG](mailto:SERENELER@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18001253MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001253MFSH

Date: 23 February 2018

Our Ref: CS/FCI18003340/Uqd3

The Motor Claims Department  
First Capital Insurance Ltd


Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. FBF 9293G**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/02/2018 at the premises of M/s BAN HOCK HIN, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 4,864.00</u>
Revised Estimate Amount	: <u>S\$ 3,117.00</u>
"Check" Items Amount	: <u>S\$ 1,100.00</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:  
The vehicle sustained damages  
at the n/s front, o/s body.



Yours faithfully

CHUA KANG SENG  
Licensed Appraiser

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	20/02/2018 23:54
Date Of Accident	08/02/2018 11:45
Exact Location Of Accident	JUNCTION OF ADMIRALTY ROAD WEST & SEMBAWANG DRIVE
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBF9293G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KOLI EXPRESS PTE LTD
Co Reg No	201539703W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67456068

#### Vehicle Particulars

Manufacturer	YAMAHA
Model	YBR125
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

#### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	MSD/VMT/18-988613
Cover Note Number	N.A.

#### Driver

Name of Driver	SHAIK ABDUL KHABIR BIN MOHAMED YUSUF
NRIC No	S8915374C
Date Of Birth	12/05/1989
Occupation	OUTDOOR
Date Of Driving Pass	08/04/2010
Driving Experience	7 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93387616
Fax Number	
Contact Number	OFFICE-93387616
Email Address	KHABIRUN@GMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	YISHUN NORTH N P C
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Refer to Police Report No: T/20180208/2123 lodged at Yishun North N P C Brief Details On 08.02.2018 at about 11.45hrs, I was riding along Admiralty Road West towards Sembawang Drive. I was in the extreme right lane. I spotted a taxi in a bus stop. Suddenly, I saw the taxi turning into my lane from the bus stop. Before I could brake, I knocked onto the right front side of the taxi. I fell into the center divider. I believe that the taxi wanted to enter into the slip road into Sembawang Road. I was conveyed by ambulance to Khoo Teck Puat Hospital. I was given 4 days of MC. My shoulder were dislocated and abrasions on some parts of the left body.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA7859T
Vehicle Make/Model/Colour	HYUNDAI/i40 1.7L CRDI A
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	LOW CHIN KIAT
NRIC/Passport Number	S7325413B
Contact Number	97478908
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

1

**DETAILS OF INJURED PERSON 1**

Name	SHAIK ABDUL KHABIR BIN MOHAMED YUSUF
Approximate Age	28
Injuries Sustain	SHOULDER DISLOCATED AND ABRASIONS ON SOME PARTS OF THE LEFT BODY,
Injured person in which vehicle?	FBF9293G
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Sketch Plan

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
  2. This Form must be completed by the Policyholder and/or the Authorized Driver.
  3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
  4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
  5. Any false reporting may be referred to the Police for investigation.
  6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




**VERIFIED BY AJAX MARS  
REPORTING OFFICER  
VICTOR ANG**

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

**Sketch Plan**



Common Statement

*Describe Circumstances of the Accident*

Refer to police report No. T/20180208/2123.

**Declaration:**

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

 SR7421936

Witnessed by Reporting Centre  
Personnel

POLICE REPORT



SINGAPORE  
POLICE FORCE



T/20180208/2123

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1800-8529999

1 of 3  
Report No. T/20180208/2123

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/02/2018 17:32	Video Report No.:	Station Diary No.: 118
--	-------------------	---------------------------

Informant's Particulars

Name of Informant: SHAIK ABDUL KHABIR BIN MOHAMED YUSUF		Address: NO 1 JLN PERJIRANAN 11/6 BDR DATO ONN 81100 JB JOHOR, MALAYSIA	
ID Type / ID No.: NRIC NO / S8915374C		Contact No.: Home/Office: Mobile: 91808355	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 28	Date of Birth: 12/05/1989	Type of Informant: Rider
Race: Indian		Language:	Institution / School Name:
Occupation: Despatch worker		Driving Licence Information: Class: 2B Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 08/02/2018 11:45	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 ADMIRALTY ROAD WEST SEMBAWANG DRIVE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBF9293G	Motorcycle				Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: Nil	Use of Pedestrian Crossing: NA

POLICE REPORT

POLICE REPORT

Name	BAHRI ABON, PHAZIM BIN MOHAMMED	ID No	268153740
Vehicle No	YUJ27	Contact No	91500350
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	08/02/2018	Date Discharge	08/02/2018
No. of Days granted Medical Leave	04	Degree of Injury	Serious
Name	LOW CHEN KIAT	ID No	67225413B
Vehicle No	NIL	Contact No	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details:**  
 On 08.02.2018 at about 1145hrs, I was riding along airmail road West towards Sembawang Drive. I was in the extreme right lane. I spotted a taxi in a bus stop. Suddenly, I saw the taxi turning into my lane from the bus stop. Before I could brake, I knocked onto the right front side of the taxi. I fell into the center divider. I believe that the taxi wanted to enter into the slip road into Sembawang Road. I was conveyed by ambulance to Khoo Teck Puat Hospital. I was given 4 days of MC. My shoulders were dislocated and abrasions on some parts of the left body.

POLICE REPORT



SINGAPORE  
POLICE FORCE



T/20180208/2123

Police Station Of Origin:  
Yishun North N P C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1800-8529999

3 of 3  
Report No. T/20180208/2123

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: F / SI MOHAMED SAHIR		Signature Of Informant: 	
Signature Of Interpreter: Not applicable		Date/Time: 08/02/2018 17:32	
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt NOR FAJZAL BIN YAHYA Contact No.: 65476202		Classification Of Case:	
Authentication Stamp NP188		Signature:	SN 085
	Singapore Police Force		

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9703W
Vehicle Details	
Vehicle No.:	FBF9293G
Vehicle to be Exported:	No
Intended De-registration Date:	22 Feb 2018
Vehicle Make:	YAMAHA
Vehicle Model:	YBR125
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	E3D6E004441
Chassis No.:	LBPKE1288A0052758
Maximum Power Output:	-
Open Market Value:	\$1,123.00
Original Registration Date:	20 Jan 2012
First Registration Date:	20 Jan 2012
Transfer Count:	2
Actual ARF Paid:	\$169.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jan 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,552.00
COE Rebate Amount:	\$606.00
<b>Total Rebate Amount:</b>	<b>\$606.00</b>

The information contained herein is correct as at 22 Feb 2018

OK

## Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	FBF9293G
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	YAMAHA
Vehicle Model :	YBR125
Chassis No. :	LBPKE1288A0052758
Propellant :	Petrol
Engine No. :	E3D6E004441
Engine Capacity :	124 cc
Maximum Power Output :	-
Maximum Laden Weight :	-
Unladen Weight :	106 kg
Year Of Manufacture :	2011
Original Registration Date :	20 Jan 2012
Lifespan Expiry Date :	-
COE Category :	D - Motorcycle
Quota Premium :	\$1,552.00
COE Expiry Date :	19 Jan 2022





REPORT ERROR [▶ \(/LISTING/LISTING/ERROR/USEDBIKE/3323/\)](#) [➕ ADD TO SHORTLIST](#)

SHARE (WHATSAPP://SEND?TEXT+HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/YAMAHA-YAMAHA-YBR125/3323/)

## Yamaha YBR125

Listing Type	Paid Ad
Brand	Yamaha ( <a href="/listing/usedbike/brand/yamaha/">/listing/usedbike/brand/yamaha/</a> )
Model	Yamaha YBR125 ( <a href="/listing/usedbike/model/yamaha-ybr125/">/listing/usedbike/model/yamaha-ybr125/</a> )
Engine Capacity	124cc
Classification	2B
Registration Date	01/07/2013
COE Expiry Date	30/06/2023 (5 years 4 months left)
Mileage	50461km
No. of owners	-
Type of Vehicle	Street Bikes ( <a href="/listing/usedbikes/listing/?bike_type=7">/listing/usedbikes/listing/?bike_type=7</a> )

**Price: SGD\$5800**

### Details

Used Yamaha YBR125 available for sales. Bike available for viewing at 1 Kaki Bukit Ave 6 #02-54/55 Autobay S'pore 417883 Tel:68446378 Trade in welcome. Loan available. 0% interest credit card installment plans available.



### Similar Bikes

[View All \(/listing/usedbikes/listing/\)](/listing/usedbikes/listing/)



Yamaha YBR125

[\(/listing/usedbike/yamaha-yamaha-ybr125/5373/\)](/listing/usedbike/yamaha-yamaha-ybr125/5373/)



Yamaha YBR125

[\(/listing/usedbike/yamaha-yamaha-ybr125/3323/\)](/listing/usedbike/yamaha-yamaha-ybr125/3323/)



Yamaha YBR125

[\(/listing/usedbike/yamaha-yamaha-ybr125/5384/\)](/listing/usedbike/yamaha-yamaha-ybr125/5384/)



Yamaha YBR125

[\(/listing/usedbike/yamaha-yamaha-ybr125/5908/\)](/listing/usedbike/yamaha-yamaha-ybr125/5908/)



Yamaha YBR125

[\(/listing/usedbike/yamaha-yamaha-ybr125/3614/\)](/listing/usedbike/yamaha-yamaha-ybr125/3614/)



Yamaha YBR125

[\(/listing/usedbike/yamaha-yamaha-ybr125/3917/\)](/listing/usedbike/yamaha-yamaha-ybr125/3917/)



**QUOTATION**

Customer :

FIRST CAPITAL INSURANCE LTD  
06 RAFFLES QUAY #21-00  
SINGAPORE 048580

*not added  
haha  
L/S 2600  
21/2/18  
take photo after repair*

NO. : 32374

DATE : 10/02/2018  
CLAIM NO. : 11099  
POLICY NO. : MSD/VMT/18-988613-WT  
FROM : RAYMOND

VEHICLE NO. : FBF9293G  
MAKE/MODEL : YAM / YBR125

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561	<i>1cben</i> REPLACE	1.00	\$330.00	<i>300</i> 330.00
2	AXLE WHEEL FRONT P/N: 25363	REPLACE	1.00	\$17.00	<i>see</i> 17.00
3	BAR HANDLE P/N: 24856	REPLACE	1.00	\$28.00	<i>see</i> 28.00
4	BEARING 6202 (NACHI) P/N: 36694	REPLACE	2.00	\$14.00	<i>see</i> 28.00
5	BOX REAR FIBRE STD (23X18X18) TL-V2 P/N: 38504	REPLACE	1.00	\$310.00	<i>see R</i> 310.00
6	BRACKET (RAM) ADJUSTABLE SOCKET W/OCT P/N: 48686	REPLACE	1.00	\$52.00	<i>7.1</i> 52.00
7	BRACKET FOOTREST LH P/N: 25346	REPLACE	1.00	\$38.00	<i>see</i> 38.00
8	BRACKET IU METER (UNIVERSAL) S/STEEL P/N: 31712	REPLACE	1.00	\$30.00	<i>see</i> 30.00
9	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$180.00	<i>see</i> 180.00
10	CABLE CLUTCH P/N: 44111	REPLACE	1.00	\$19.00	<i>see</i> 19.00
11	COWLING FRONT (RED) P/N: 26138	REPLACE	1.00	\$134.00	<i>see</i> 134.00
12	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00	<i>see</i> 195.00
13	FOOTREST FRONT P/N: 26850	REPLACE	1.00	\$48.00	<i>see</i> 48.00
14	FORK FRONT ASSY LH P/N: 25338	REPLACE	1.00	\$358.00	<i>see</i> 358.00



S/N	Description	Action	Qty	Unit Price	Amount
15	FORK FRONT ASSY RH P/N: 25337	REPLACE	1.00	\$358.00	358.00
16	GRIP HANDLE SET (GPR) F2 P/N: 45347	REPLACE	1.00	\$14.00	14.00
17	GUIDE AIR LH P/N: 26495	REPLACE	1.00	\$9.00	9.00
18	HOLDER LEVER CLUTCH P/N: 26864	REPLACE	1.00	\$12.00	12.00
19	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	5.00	\$35.00	175.00
20	LAMP SIGNAL REAR LH P/N: 26504	REPLACE	1.00	\$28.00	28.00
21	LEVER BRAKE P/N: 26343	REPLACE	1.00	\$19.00	19.00
22	LEVER CLUTCH P/N: 52644	REPLACE	1.00	\$19.00	19.00
23	LOCK BOX REAR (3 INCH) P/N: 12369	REPLACE	1.00	\$16.00	16.00
24	METER IU (12V) NEW MODEL P/N: 34351	REPLACE	1.00	\$200.00	200.00
25	MID OIL SEAL P/N: 20911	REPLACE	1.00	\$5.00	5.00
26	MIRROR LH P/N: 52645	REPLACE	1.00	\$30.00	30.00
27	MIRROR RH P/N: 46219	REPLACE	1.00	\$30.00	30.00
28	MUDGUARD FRONT (RED) P/N: 24855	REPLACE	1.00	\$90.00	90.00
29	MUDGUARD REAR P/N: 24858	REPLACE	1.00	\$55.00	55.00
30	PLATE DISC BRAKE P/N: 26500	REPLACE	1.00	\$89.00	89.00
31	PROTECTOR MUFFLER (REAR) P/N: 27115	REPLACE	1.00	\$32.00	32.00
32	RIM SPORT FRONT (GOLD) P/N: 26501	REPLACE	1.00	\$395.00	395.00
33	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	2.00	\$14.00	28.00
34	SCOOP AIR LH (MAROON) P/N: 38817	REPLACE	1.00	\$30.00	30.00
35	SHIFT PEDAL ASSY P/N: 50002	REPLACE	1.00	\$20.00	20.00



S/N	Description	Action	Qty	Unit Price	Amount	Amount
36	SPRAY PAINTING (Fibre Box Rear)	Spray	1.00	\$220.00	200	220.00
37	SPRAY PAINTING (Front Cowling)	Spray	1.00	\$60.00		60.00 ✓
38	SPRAY PAINTING (Front Mudguard)	Spray	1.00	\$45.00	40	45.00
39	SPRAY PAINTING (Fuel Tank lower cover LH)	Spray	1.00	\$25.00		25.00 ✓
40	SPRAY PAINTING Fuel Tank	Spray	1.00	\$125.00	100	125.00
41	STAND MAIN P/N: 26847	REPLACE	1.00	\$40.00	1	40.00 ✓
42	STEERING CONE SET P/N: 41793	REPLACE	1.00	\$66.00	1	66.00 ✓
43	STICKER (KOLI EXPRESS) BOX REAR P/N: 44598	REPLACE	1.00	\$95.00	1	95.00 ✓
44	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$12.00	10	12.00 ✓
45	SWITCH CLUTCH P/N: 26865	REPLACE	1.00	\$10.00	1	10.00 ✓
46	SWITCH SIGNAL ASSY P/N: 26532	REPLACE	1.00	\$58.00	1	58.00 ✓
47	TANK FUEL (RED) P/N: 27784	REPLACE	1.00	\$580.00	1	580.00 ✓
48	TRANSPORT CHARGES P/N: 07169 - TOWED BACK BIKE FOR ACCIDENT REPAIR.		1.00	\$35.00		35.00 ✓
49	X-GRIP (RAM) UNIVERSAL (LARGE) P/N: 46451	REPLACE	1.00	\$72.00	1	72.00 ✓

SUB TOTAL \$4,864.00  
 GST @ 7 % \$340.48  
**GRAND TOTAL \$5,204.48**

Validity: 30 days

For & on Behalf of  
**BAN HOCK HIN CO PTE LTD**



**RAYMOND**

This quotation is sent via email / LAN-Fax and will bear a computer generated signature



S.N - 120

Acknowledge & Accepted By

P-2377  
 238-30

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Resurvey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:





**QUOTATION**

Customer :

NO. : 32374 - Rev. 2

FIRST CAPITAL INSURANCE LTD  
06 RAFFLES QUAY #21-00  
SINGAPORE 048580

DATE : 10/02/2018  
CLAIM NO. : 11099  
POLICY NO. : MSD/VMT/18-988613-WT  
FROM : RAYMOND

VEHICLE NO. : FBF9293G  
MAKE/MODEL : YAM / YBR125

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561	REPLACE	1.00	\$300.00	300.00
2	AXLE WHEEL FRONT P/N: 25363	REPLACE	1.00	\$17.00 Disc %: 10.00	15.30
3	BAR HANDLE P/N: 24856	REPLACE	1.00	\$28.00 Disc %: 10.00	25.20
4	BEARING 6202 (NACHI) P/N: 36694	REPLACE	2.00	\$14.00 Disc %: 10.00	25.20
5	BRACKET FOOTREST LH P/N: 25346	REPLACE	1.00	\$38.00 Disc %: 10.00	34.20
6	BRACKET IU METER (UNIVERSAL) S/STEEL P/N: 31712	REPLACE	1.00	\$30.00 Disc %: 10.00	27.00
7	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$180.00 Disc %: 10.00	162.00
8	CABLE CLUTCH P/N: 44111	REPLACE	1.00	\$19.00 Disc %: 10.00	17.10
9	COWLING FRONT (RED) P/N: 26138	REPLACE	1.00	\$134.00 Disc %: 10.00	120.60
10	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00 Disc %: 10.00	175.50
11	FOOTREST FRONT P/N: 26850	REPLACE	1.00	\$48.00 Disc %: 10.00	43.20
12	FORK FRONT ASSY LH P/N: 25338	REPLACE	1.00	\$358.00 Disc %: 10.00	322.20
13	GRIP HANDLE SET (GPR) F2 P/N: 45347	REPLACE	1.00	\$14.00 Disc %: 10.00	12.60
14	GUIDE AIR LH P/N: 26495	REPLACE	1.00	\$9.00 Disc %: 10.00	8.10



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
15	HOLDER LEVER CLUTCH P/N: 26854	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
16	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	5.00	\$30.00	150.00
17	LAMP SIGNAL REAR LH P/N: 26504	REPLACE	1.00	\$28.00 Disc %: 10.00	25.20
18	LEVER BRAKE P/N: 26343	REPLACE	1.00	\$19.00 Disc %: 10.00	17.10
19	LEVER CLUTCH P/N: 52644	REPLACE	1.00	\$19.00 Disc %: 10.00	17.10
20	METER IU (12V) NEW MODEL P/N: 34351	REPLACE	1.00	\$200.00	200.00
21	MID OIL SEAL P/N: 20911	REPLACE	1.00	\$5.00 Disc %: 10.00	4.50
22	MIRROR LH P/N: 52645	REPLACE	1.00	\$30.00 Disc %: 10.00	27.00
23	MIRROR RH P/N: 46219	REPLACE	1.00	\$30.00 Disc %: 10.00	27.00
24	MUDGUARD FRONT (RED) P/N: 24855	REPLACE	1.00	\$90.00 Disc %: 10.00	81.00
25	MUDGUARD REAR P/N: 24858	REPLACE	1.00	\$55.00 Disc %: 10.00	49.50
26	PROTECTOR MUFFLER (REAR) P/N: 27115	REPLACE	1.00	\$32.00 Disc %: 10.00	28.80
27	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	2.00	\$14.00 Disc %: 10.00	25.20
28	SCOOP AIR LH (MAROON) P/N: 38817	REPLACE	1.00	\$30.00 Disc %: 10.00	27.00
29	SHIFT PEDAL ASSY P/N: 50002	REPLACE	1.00	\$20.00 Disc %: 10.00	18.00
30	SPRAY PAINTING (Fibre Box Rear)	Spray	1.00	\$200.00	200.00
31	SPRAY PAINTING (Front Cowling)	Spray	1.00	\$60.00	60.00
32	SPRAY PAINTING (Front Mudguard)	Spray	1.00	\$40.00	40.00
33	SPRAY PAINTING (Fuel Tank lower cover LH)	Spray	1.00	\$25.00	25.00
34	SPRAY PAINTING Fuel Tank	Spray	1.00	\$100.00	100.00
35	STEERING CONE SET P/N: 41793	REPLACE	1.00	\$66.00 Disc %: 10.00	59.40
36	STICKER (KOLI EXPRESS) BOX REAR P/N: 44598	REPLACE	1.00	\$95.00	95.00



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
37	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$10.00	10.00
38	SWITCH CLUTCH P/N: 26865	REPLACE	1.00	\$10.00 Disc %: 10.00	9.00
39	SWITCH SIGNAL ASSY P/N: 26532	REPLACE	1.00	\$58.00 Disc %: 10.00	52.20
40	TANK FUEL (RED) P/N: 27784	REPLACE	1.00	\$580.00 Disc %: 10.00	522.00
41	TRANSPORT CHARGES P/N: 07169 - TOWED BACK BIKE FOR ACCIDENT REPAIR.		1.00	\$35.00	35.00
42	X-GRIP (RAM) UNIVERSAL (LARGE) P/N: 46451	REPLACE	1.00	\$72.00 Disc %: 10.00	64.80
<b>SUB TOTAL</b>					<b>\$3,268.80</b>
<b>GST @ 7 %</b>					<b>\$228.82</b>
<b>GRAND TOTAL</b>					<b>\$3,497.62</b>

Validity: 30 days

For & on Behalf of  
**BAN HOCK HIN CO PTE LTD**

Acknowledge & Accepted By



**RAYMOND**

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

3 831-55





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC1802988  
INV Date 22/03/2018  
Reference CS/FC118003340/Uqd3q2  
Code FCI2



#### PROFESSIONAL SERVICE FEE

Vehicle No. FBF 9293G  
Insured Veh. SHA 7859T  
Claim No. D18001253MFSH  
Policy No. D-18088936MFSH  
Accident Date 08/02/2018  
Inspection Date 21/02/2018

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003340/Uqd3q2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 22-03-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 7859T	Veh. Inspected	FBF 9293G
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18001253MFSH	Excess (\$)	0.00
Assign From	SERENE LER	Assign Date	21/02/2018
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA YBR125	c.c	124
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	LBPKE1288A0052758	Colour	WHITE
Odometer	44630	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	2.75-18	METZELER	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	3.00-18	METZELER	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/02/2018	Inspection Date	21/02/2018
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 9293G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	AXLE WHEEL FRONT	NECESSARY	17.00	17.00
1	BAR HANDLE	BENT	28.00	28.00
2	BEARING 6202 (NACHI) @\$14.00	NECESSARY	28.00	28.00
1	BOX REAR FIBRE STD (23X8X18) TL-V2	TO REPAIR SEE LABOUR	310.00	-
1	BRACKET (RAM) ADJUSTABLE SOCKET W/OCT	NOT NECESSARY	52.00	-
1	BRACKET FOOTREST LH	BENT	38.00	38.00
1	BRACKET IU METER (UNIVERSAL) S/STEEL	BENT	30.00	30.00
1	BRACKET UNDER FORK	BENT	180.00	180.00
1	CABLE CLUTCH	DAMAGED	19.00	19.00
1	COWLING FRONT (RED)	CUT	134.00	134.00
1	CRASH BAR	BENT	195.00	195.00
1	FOOTREST FRONT	TWISTED	48.00	48.00
1	FORK FRONT ASSY LH	BENT	358.00	358.00
1	FORK FRONT ASSY RH	TO REPAIR SEE LABOUR	358.00	-
1	GRIP HANDLE SET (GPR) F2	TORN	14.00	14.00
1	GUIDE AIR LH	CRACKED	9.00	9.00
1	HOLDER LEVER CLUTCH	CRACKED	12.00	12.00
1	LAMP SIGNAL REAR LH	CRACKED	28.00	28.00
1	LEVER BRAKE	SCRATCHED	19.00	19.00
1	LEVER CLUTCH	SCRATCHED	19.00	19.00
1	LOCK BOX REAR (3 INCH)	NOT NECESSARY	16.00	-
1	MID OIL SEAL	NECESSARY	5.00	5.00
1	MIRROR LH	CUT	30.00	30.00
1	MIRROR RH	CUT	30.00	30.00
1	MUDGUARD FRONT (RED)	BROKEN	90.00	90.00
1	MUDGUARD REAR	TORN	55.00	55.00
1	PLATE DISC BRAKE	NOT NECESSARY	89.00	-
1	PROTECTOR MUFFLER (REAR)	SCRATCHED	32.00	32.00
1	RIM SPORT FRONT (GOLD)	TO REPAIR SEE LABOUR	395.00	-

Report Ref No. CS/FCI18003340/Uqd3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	RUBBER FOOTREST FRONT @\$14.00	TORN	28.00	28.00
1	SCOOP AIR LH (MAROON)	CRACKED	30.00	30.00
1	SHIFT PEDAL ASSY	BENT	20.00	20.00
1	STAND MAIN	TO REPAIR SEE LABOUR	40.00	-
1	SET STEERING CONE	NECESSARY	66.00	66.00
1	STICKER (KOLI EXPRESS) BOX REAR	NECESSARY	95.00	95.00
1	SWITCH CLUTCH	TWISTED	10.00	10.00
1	SWITCH SIGNAL ASSY	CRACKED	58.00	58.00
1	TANK FUEL (RED)	DENTED	580.00	580.00
1	X-GRIP (RAM) UNIVERSAL (LARGE)	MISSING	72.00	72.00
	LESS 10% DISCOUNT		-	-237.70
			3,637.00	2,139.30
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	METER IU (12V) NEW MODEL (SN)	CUT	200.00	200.00
1	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT (SN)	NECESSARY	12.00	10.00
			212.00	210.00
	<b><u>LABOUR</u></b>			
	ALIGNMENT BODY .		330.00	300.00
	LABOUR-FOR DISMANTLE AND ASSEMBLING OF PARTS QUOTED.INCLUSIVE OF THE REPAIR OF BOX REAR FIBRE STD (23X8X18) TL-V2,FORK FRONT ASSY RH,RIM SPORT FRONT (GOLD) AND STAND MAIN.		175.00	150.00
	SPRAY PAINTING (FIBRE BOX REAR).		220.00	200.00
	SPRAY PAINTING (FRONT COWLING).		60.00	60.00
	SPRAY PAINTING (FRONT MUDGUARD).		45.00	40.00
	SRPAY PAINTING (FUEL TANK LOWER COVER LH).		25.00	25.00
	SPRAY PAINTING FUEL TANK.		125.00	100.00
	TRANSPORT CHARGES.		35.00	35.00
			1,015.00	910.00
	<b>GRAND TOTAL</b>		<b>4,864.00</b>	<b>3,259.30</b>

Report Ref No. CS/FC118003340/Uqd3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,600.00
---	--	--	----------

Report Ref No. CS/FCI18003340/Uqd3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.