

ASS. REC. BY:

REF: CS/MSG18003351/ Kvd3 ⁿ² Special Instructions:Surveyor
Merimen

Kenneth

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSG

Date/Time:

21/2/18 @ 2:30pm

Estimated Cost:

Bill to:

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 2855G

Insured:

GBE 7365B

at Workshop m/s

Alan's United

Tel:

64538686

of

Blk 7, Sin Ming Ind. Est #01-76

Policy No:

A28911326MKC

Claim No:

548417

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (w/p)

H.O.D. Endorsement:

Date/Time:

20/2/18 @ 4:41pm

Person Contacted:

Kenny

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBF 2855G-X

GBE 7365B-CS/MSG18002443/R/vd3

D.O.A: 29/1/18

21/2/18

Send preli revised by merimen

16/3/18

88822-96 Confirm (Red 934.95, 1290)

ASS. REC. BY:

REF: *msc1**Kenneth*

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

07 days

Res.: Yes or No

Lum Sum: _____

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

26/2 *At pass to Catherine*Veh No: *GBF 28556*Yr Regn: *08, 16*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *NIS NV350*c.c. *2400*Colour: *Black*

A/C: _____

Insured / Std / NI / NA

Sp. Reading: *24771*

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: *JNIMC 2E 288 000 7054*Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: *Nil* / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

195 R15 X8

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. *9* mmR/Bal. *9* mmL/Bal. *9* mmL/Bal. *9* mmD.O.A. *29/1/18*D.O.A. *23/2/18*

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

NIS Acc body

The U/C / Chassis frame / Body Structure affected due to collision.

16/3/2018

RECEIVED 16 MAR 2018

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

*16/3 - typist*Days Of Repair: *7*Resurvey No. of Trip: *1*Add Fee: ☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Survey Fee: *200*Transportation: *10*

Photos

Others

TOTAL

*210*Report Format: *menimen*Lump Sum / I.B.I. (\$) *6622.96*

Survey Department Check List (Case Handler)

Reference No.: CS | MS9 | 800 3351 | Kv03
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 16/3/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18003351/Kvd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 22-02-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 7365B		Veh. Inspected	GBF 2855G
Policy No.	A28911326MKC		Coverage (\$)	0.00
Claim No.	548417		Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)		Assign Date	22/02/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/01/2018		Inspection Date	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2018		20 Feb 2018 14:30 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SH FOODS LLP, Co. Reg. No.: T12LL0537F		
Main Claimant:	APRISIN SINGAPORE PTE LTD, Co. Reg. No.: 199102150W		
Vehicle Reg. No.:	GBF2855G	Date of Loss:	29/01/2018 13:00 - :59
Claim Type:	TP / 548417	Policy/Cover Note No.:	A28911326MKC (Comprehensive) Coverage: 14/03/2017 - 13/03/2018
Vehicle Reg. No. (Insured):	GBE7365B	Policy No. (Claimant):	
		Excess:	S\$600.00
Repairer:	Alans United Auto Pte Ltd (HQ) BLK 7 SIN MING INDUSTRIAL ESTATE #01-76, 575642 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/02/2018]		
Driver/Custodian (Insured):	ONG KIM SENG (), NRIC: S1255260B		
Adj Asg. Remarks:	W/s wld like Mr Kenneth Kong to survey the vehicle.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Christina Wong	Date:	27 Feb 2018
<u>Preliminary Advice</u>			

Insured Vehicle No	: GBE7365B	Accident Date	: 29/01/2018
TP Vehicle No	: GBF2855G	Assignment Date	: 20/02/2018
Make	: NISSAN NV350	Est. Duration of Repair	: 7.00
Date of Inspection	: 23/02/2018		
Inspection At	: ALANS UNITED AUTO PTE LTD (HQ) BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,397.91
Revised Amount	:S\$	5,347.86
Check Items (Estimated)	:S\$	1,115.10
Total	:S\$	
Lump Sum Repair	:S\$	
<u>Total Loss Consideration</u>		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

The owner and vehicle particulars for Vehicle No. GBF2855G as at 30 Aug 2016 are as follows:

1.	Name	: APRISIN SINGAPORE PTE LTD
2.	Identification No. Type	: Company
3.	Identification No.	: 199102150W
4.	Place Of Passport Issue	: -
5.	Registered Address	: 18 TAMPINES INDUSTRIAL CRESCENT #03-07 SPACE@TAMPINES SINGAPORE 528605
6.	Mailing Address	: -
7.	Vehicle No.	: GBF2855G
8.	Effective Date of Ownership	: 30 Aug 2016
9.	Original Registration Date	: 30 Aug 2016
10.	First Registration Date	: 30 Aug 2016
11.	Vehicle Type	: A50 - Goods (Closed) Van/Van Panel (Delivery)
12.	Vehicle Scheme	: Normal
13.	Attachment 1	: No Attachment
14.	Attachment 2	: -
15.	Attachment 3	: -
16.	Vehicle Make	: NISSAN
17.	Vehicle Model	: NV350 PANEL VAN 2.5 5MT 5DR EURO V
18.	Year of Manufacture	: 2016
19.	Primary Colour	: Black
20.	Secondary Colour	: -
21.	Passenger Capacity	: 2
22.	Chassis/Trailer Chassis No.	: JN1MC2E26Z0007054 / -
23.	Propellant/Emission Standard	: Diesel / Euro V
24.	Engine No./Motor No.	: YD25404922A / -
25.	Engine Capacity(cc)/Power Rating(kW)	: 2488 / -
26.	Maximum Power Output(kW/bhp)	: - / -
27.	Unladen Weight(kg)	: 1800
28.	Maximum Laden Weight(kg)	: 3300
29.	Open Market Value	: \$23,668.00
30.	PARF Eligibility	: No
31.	PARF Eligibility Expiry Date	: -
32.	Minimum PARF Benefit	: \$0.00
33.	IU Label No.	: -
34.	COE No.	: 2016083005001339N
35.	COE Expiry Date	: 29 Aug 2026
36.	COE Category	: -
37.	Quota Premium/Prevailing Quota Premium	: \$46,254.00
38.	Actual Quota Premium/PQP Paid	: \$43,303.00
39.	Actual ARF Paid	: \$1,184.00
40.	CO2 Emission(g/km)	: 232.00
41.	Actual CEVS Rebate Utilised	: -
42.	CEVS Surcharge Paid	: -
43.	Actual Green Vehicle Rebate Utilised	: -
44.	Vehicle Lifespan Expiry Date	: 29 Aug 2036
45.	Road Tax Amount	: \$213.00
46.	Road Tax Start Date	: 30 Aug 2016
47.	Road Tax End Date	: 28 Feb 2017
48.	Remarks	: This vehicle requires side marking. The vehicle is registered under Early Turnover Scheme.

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBE 7365B
Accident Date : 29-Jan-2018

Our Ref : 218030 (MSIG) / CHAN

APRISIN SINGAPORE PTE LTD
18 TAMPINES INDUSTRIAL CRESCENT
#03-07, SPACE@TAMPINES
Singapore 528605

No. : 05726

Date : 20-Feb-2018

PAGE : 1

Not Authorized
1.B.1
Resurvey B4 panel
Foley

ESTIMATED COST OF REPAIR FOR NISSAN NV350 GBF2855G

=====

1 pc	N/s sliding door
1 pc	N/s rear panel
1 pc	N/s rear panel inner panel
1 pc	N/s taillamp
1 pc	Rear bumper fascia
1 pc	Rear n/s bumper side bracket
1 pc	Rear n/s mudflap

28/2/18

<i>By</i>	1,255.70	<i>✓</i>
<i>By</i>	1,793.40	<i>✓</i>
	1,239.00	<i>7</i>
<i>Sub</i>	209.80	<i>✓</i>
<i>Brake</i>	600.50	<i>✓</i>
<i>Oil</i>	16.00	<i>✓</i>
<i>in</i>	105.50	<i>X</i>

5,219.90

Less 10% : 521.99

4,697.91

To apply undersealing

601 100.00

To putty and spray replaced parts

8006 1,200.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1000 1,400.00

Total : S\$ 7,397.91

=====

7557.91

Singapore Dollars Seven Thousand Three Hundred
and Ninety Seven and Cents Ninety One Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBE 7365B
Accident Date : 29-Jan-2018

Our Ref : 218030 (MSIG) / CHAN

APRISIN SINGAPORE PTE LTD
18 TAMPINES INDUSTRIAL CRESCENT
#03-07, SPACE@TAMPINES
Singapore 528605

No. : 05726

Date : 20-Feb-2018

PAGE : 1

Not Authorized
1-B.1
Recovery B4 parts
7 days

ESTIMATED COST OF REPAIR FOR NISSAN NV350 GBF2855G

- 1 pc N/s sliding door
- 1 pc N/s rear panel
- 1 pc N/s rear panel inner panel
- 1 pc N/s taillamp
- 1 pc Rear bumper fascia
- 1 pc Rear n/s bumper side bracket
- 1 pc Rear n/s mudflap

<i>R1</i>	1,255.70	✓
<i>R2</i>	1,793.40	✓
<i>R1/R2</i>	1,239.00	✓
<i>Sub</i>	209.80	✓
<i>Brake</i>	600.50	✓
<i>Oil</i>	16.00	✓
<i>Sub</i>	105.50	X
	5,219.90	
Less 10% :	521.99	
	4,697.91	

5114.40
511.44
4602.96
4,697.91

To apply undersealing

60l 100.00

To putty and spray replaced parts

800l 1,200.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1000l 1,400.00

Total : S\$ 7,397.91

Singapore Dollars Seven Thousand Three Hundred
and Ninety Seven and Cents Ninety One Only

Pay By Pay
4602.96
7 days
Kenrick Plus Graham
THS

P 4602.96
S.P.SN 60
S.P.L 100
L 1860.00
6602.96 ✓ OK

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBE7365B (MSIG)

Date : 23-02-2018

Accident Date : 29-01-2018

Our Ref : 218030 / CHAN

APRINSIN SINGAPORE PTE LTD

C/O ALAN'S UNITED AUTO PTEE LTD

SUPPLEMENTARY ADDITIONAL LABOUR FOR NISSAN NV350 GBF2855G

1 PC REAR N/S PANEL UPPER WINDOW PANEL COVER SEALANT *Mr* \$60.00 SN ✓

LABOUR TO CUT OUT SEALANT FOR UPPER WINDOW PANEL COVER ,
REFIX AND CONDUCT WATER LEAK TEST

\$100.00 ✓

\$160.00

Singapore Dollars One Hundred Sixty Only

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003351/KVD3N2

Date: 19/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28911326MKC
Claimant Vehicle No :	GBF2855G	Insured Vehicle No :	GBE7365B
Date of Loss:	29/01/2018	Nature of Claim:	TP
		Claim No:	548417

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF2855G	Engine No:	YD25404922A
Make & Model:	NISSAN NV350, 2.5 5MT 5DR EURO V (A)	Chassis No:	JN1MC2E26Z0007054
Reg. Date:	30/08/2016 (Man. Year: 2016)	Odometer:	24771 km
Colour:	Metallic Black		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,757.91	4,662.96	94.95	2.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,960.00	840.00	30.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,557.91	6,622.96	934.95	12.37
+ GST 7.00/7.00% (S\$)	529.05	463.61	65.44	12.37
Nett Amount (S\$)	8,086.96	7,086.57	1,000.39	12.37

INSPECTION

Date of Assignment:	20/02/2018	
Date Inspected:	23/02/2018 Inspected At:	Alans United Auto Pte Ltd (HQ) BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 Singapore 575642

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Mar 2018)	
Parts:	N/A	NISSAN NV350 2.5 5MT 5DR EURO V (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF2855G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S SLIDING DOOR	Bent	1,255.70 FL	*1,255.70 FL
2	1		*N/S REAR PANEL	Bent	1,793.40 FL	*1,793.40 FL
3	1		*N/S REAR PANEL INNER PANEL	Buckled/Bent	1,239.00 FL	*1,239.00 FL
4	1		*N/S TAILLAMP	Scratched	209.80 FL	*209.80 FL
5	1		*REAR BUMPER FASCIA	Buckled/Dented	600.50 FL	*600.50 FL
6	1		*REAR N/S BUMPER SIDE BRACKET	Distorted	16.00 FL	*16.00 FL
7	1		*REAR N/S MUDFLAP	Serviceable	105.50 FL	*- FL
8	1		*REAR N/S PANEL UPPER WINDOW PANEL COVER SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,279.90	5,174.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	521.99	511.44
Total Parts (\$\$)	4,757.91	4,662.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO APPLY UNDERSEALING	New	100.00	60.00
2	TO PUTTY AND SPRAY REPLACED PARTS	New	1,200.00	800.00
3	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	1,400.00	1,000.00
4	LABOUR TO CUT OUT SEALANT FOR UPPER WINDOW PANEL COVER,REFIX AND CONDUCT WATER LEAK TEST	New	100.00	100.00
Gross Labour Cost (\$\$)			2,800.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >