

15/5/2010

CC 3 /AIG1800

37264, Fwb3

LKK:

IDAC:

INS. CASE OWNER:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

2/7/18

Date / Time :

2/7/18

Registered in Merimen:

2/7/18

Pre-assign / CCU / FTE



Insured Vehicle No. :

SLE 7909K

Name of Insured :

Insured Tel No. :

HP:

Excess Sec II : \$\$

D.O.A :

Is driver the owner?

(YES / NO)

Nature of Accident :

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SNC 55283



INSRS:

WSP:

Tel :

Liability :

RMKS:

Trans
CMB

INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time	STAGE	DATE / PIC
SNC 55283 - 43/01/2018/5/18/18 Fwb3 2/7/18 SLE 7909K - X	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐ ☐
	After call ltr to OI:	☐ ☐
	Authorisation To Act:	☐ ☐
	Release Voucher:	☐ ☐
	Final Repair Bill:	☐ ☐
	Car Rental Invoice:	☐ ☐
	Towing Invoice	☐ ☐
	LTA / GIA :	☐ ☐
Medical Bill:	☐ ☐	
PIR:	☐ ☐	
Mandate/Reject Instruction:	☐ ☐	
LOD	☐ ☐	
Payment Breakdown Form:	☐ ☐	
Post-Repair Photos:	☐ ☐	
Others:	☐ ☐	
PRELIMINARY ADVICE Date/Time:	Sent By:	
FINALIZATION Date/Time:	Confirm with:	
Repair Cost: \$\$	(days) Reduction: %	Confirm by: Email ☐ Call ☐
FINAL SETTLEMENT Date/Time:	Confirm with	
Final Liability: %	(Agreed / Assessed) BOLA S/N No. :	Email ☐ Call ☐
Repair Cost: \$\$		If NO or B 28, Ass. Lia :
Loss of Rental (LOR): \$\$	(days)	
Loss of Use (LOU): \$\$	(\$ x days)	
Loss of Income (LOI): \$\$	(\$ x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]		
GIA/LTA Search	\$\$	1) Claim status: Normal/Reject/Private Settle
Medical:	\$\$	2) Report Format:
Disbursement:	\$\$	3) Survey fee:
Legal Cost	\$\$	
Total: \$\$	Global Sum \$:	Email ☐ Call ☐
FINAL PAYMENT Date/Time:	Confirm with:	
Payee 1: \$\$	Name 1:	
Payee 2: (Strike if N.A.) \$\$	Name 2:	
Payee 3: (Strike if N.A.) \$\$	Name 3:	

ASS. REC. BY:

REF:

AIG

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SITC 3528B

Yr Regn:

08, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1995

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

378913

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VI-1ABL15AUC 278869

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S / Rim / STD A / Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

Rear

R/Bal.

7

mm

R/Bal.

9

mm

L/Bal.

7

mm

L/Bal.

9

mm

D.O.A.

18/2/18

D.O.I.

21/2/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/2

File post to Customer NITE
LI En 880501

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$