

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI Date/Time: 20 Feb 2018

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XD 1067 X Insured: SAG 18 R

at Workshop m/s Pro Plus Automobile Engineer (HQ) Tel: _____

of 221 Balestier Road #10-01 Rocca Balestier

Policy No: DMHCSN1619171701 Claim No: TP/SNM18D00930C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 10/2/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 20/2 Person Contacted: _____ Vehicle: IN/OUT

[illegible][illegible]



REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **X17 1067X**Yr Regn: **2006 Sep 29**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

☒ Truck ☐ Trailer orMake: **ISUZU CXZ50K**C.C: **17068**Colour: **White**

A/C: Insured / Std / NI / NA

Sp Reading: **-**

T/Radio: Insured / Std / NI / NA

Eng/No: **6WA1U00370**C/No: **JALCXZ50K67000082**Gen. Cond: **Good** / Fair / Poor / BurntSteering: **Good** / Jammed / Leaked / Burnt orBrake: **Good** / Jammed / Leaked / Burnt orModi: **NO** / S/Rim / STD A/Rim orTyre Size: F: **295/80 R22.5**R: **- " - (double)**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wastkice

Front

Rear

R/Bal: **5** mmR/Bal: **5/5** mmL/Bal: **5** mmL/Bal: **5/5** mmD.O.A: **10/02/2018**D.O.I: **21/02/2018 @ 1045am**Survey held at **SI Page ubi**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The vehicle TMA was reported

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Change Tarping.**Estimated repair range 28K - 35K. 5 days.****At the time of survey, no key was available.****No TP GIA provided.****Unable to check vehicle details.**

RECEIVED 6 APR 2018

Date/Time: File Pass to?

☐

Preli. Report

1) **05042018**☐

Final Report

Date/Time: File Return to?

2) _____

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + B5 - SI

) Photos

) Others:

TOTAL

Report Format: **PRS**

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI18003396/Db

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 22-02-2018



Code : CTI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SGG 181R	Veh. Inspected	XD 1067X
Policy No.	DMHCSN1619171701	Coverage (\$)	0.00
Claim No.	SNM18D00930C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	20/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/02/2018	Inspection Date	21/02/2018
Survey held at	-		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Feb 2018		20 Feb 2018 17:53 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	M/S M & L CAFETERIA		
Main Claimant:	FIT TRANSPORT SYSTEMS PTE LTD		
Vehicle Reg. No.:	XD1067X	Date of Loss:	10/02/2018 02:00 - :59
Claim Type:	TP / SNM18D00930C02	Policy/Cover Note No.:	DMHCSN1619171701
Vehicle Reg. No. (Insured):	SGG181R	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Pro Plus Automobile Engineers (HQ) 221 BALESTIER ROAD #10-01 ROCCA BALESTIER, 329928 Balestier - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/03/2018]		
Adj Asg. Remarks:	PLEASE SURVEY THIRD PARTY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Angie Foo

From: Angie Foo
Sent: Tuesday, 20 February, 2018 5:39 PM
To: 'Sow-ye Wong'
Cc: Claims Dept of CTI; Errol Tan; Agnes Teo; Chong Boon Sen; Admin A; SUR; Denise Tay
Subject: RE: OUR REF: PRS/SNM18D00930C02/1 & YR REF: FCY/470/18 -TO CONDUCT PRE REPAIR SURVEY TMA XD1067X

Without Prejudice
Save As To Costs

Dear Sow Yee,

We refer to your email on even date.

We are objecting to your list of surveyors and shall be appointing M/S LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Please ensure that your client's vehicle is available for survey within 2 working days.

REMARKS:

Dear Calvin / Marcus,

Please arrange to conduct survey, checking consistency of the damages on without prejudice.

Kindly take note, the claim handler on this case is Chong Boon Sen 63896171

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Sow-ye Wong [mailto:wongsylaw@gmail.com]
Sent: Tuesday, 20 February, 2018 5:27 PM
To: Angie Foo
Cc: Claims Dept of CTI; Errol Tan; Agnes Teo; Chong Boon Sen

Subject: Re: OUR REF: PRS/SNM18D00930C02/1 & YR REF: FCY/470/18 -TO CONDUCT PRE REPAIR SURVEY TMA XD1067X

Dear Angie

Kong Hee Fatt Choy!

We thank you for your proposed list of Surveyors below

However we regret to inform you that our Client is unable to agree to your said proposal

We are pleased to have instructions to propose

MR ERROL TAN

M/s Pro Plus Automobile Engineers

221 Balestier Rd

10 - 01 Rocca Balestier

S 329928

Tel : 6707 8932

Fax : 6352 6802

Email : ethtan88@singnet.com.sg

Mobile : 9673 0595 / 9788 9809

Please contact **MS AGNES TEO**

Address :

M/s Tai Wah Motor

1 Kaki Bukit Ave 6 Block A

01 - 06/07 AutoBay@ Kaki Bukit

S (417883)

Tel : 6284 3376 / 6284 3375

Fax : 6285 6292

Email : taiwahmotorrepair@gmail.com

Mobile : 9738 2668

Appreciate your kind understanding

Yours Sincerely

Sow yee

M/s Fong & Fong LLC

On Tue, Feb 20, 2018 at 3:48 PM, Angie Foo <angie.foo@sg.entaiping.com> wrote:

WITHOUT PREJUDICE

SAVE AS TO COSTS

Dear Sow Yee,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
SAMUEL PHUN
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
DEREK OH SIONG WEE
KALVIN ANG
MARCUS CHUA
SIMON HO
LOW SAR HUEI
HONG FOOK CHOY

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Kindly let us hear from you.

REMARKS:

Kindly take note, the claim handler on this case is Chong Boon Sen 6389 6171

Thank you.

Regards,

Angie Foo

Executive

Motor Division

Claims Department

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Co.Reg.No.200208384E

DID: 6389 6186

Fax: 6224 7478 /6224 7175

Email: angie.foo@sg.cntaiping.com

Email: claimsdept@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Sow-ye Wong [mailto:wongsylaw@gmail.com]

Sent: Monday, 19 February, 2018 6:27 PM

To: Claims Dept of CTI; Errol Tan; Agnes Teo

Subject: NOTICE OF ACCIDENT - TMA XD 1067X & SGG 181R ON 10.02.18 ALONG 2ND LANE KPE NORTHBOUND 3.6 KM MARK ABOUT 02:00AM

Our Ref : FCY / 470 / 18

Your Ref : SGG 181R - M & L CAFETERIA - 53227050M

M/s China Taiping Insurance (S) P L

Email: claimsdept@sg.cntaiping.com

3 Anson Rd

16 – 00 Springleaf Tower

S (079909)

Attn: The Manager - Motor Claims

Dear Sirs

NOTICE OF ACCIDENT

CLAIMANTS: FIT TRANSPORT SYSTEMS PTE LTD

ACCIDENT INVOLVING TMA XD 1067X & SGG 181R ON 10.02.18 ALONG 2ND LANE KPE NORTHBOUND (3.6 KM MARK) @ ABOUT 02:00 AM

Happy New Year!

We act for **FIT TRANSPORT SYSTEMS PTE LTD** owners

Our Clients' Vehicle : **TMA XD 1067X**

Your / Your Insured's Car : **SGG 181R**

Date & Time of Accident : **10 FEBRUARY 2018 / 02:00 AM**

Place of Accident : **2ND LANE KPE NORTHBOUND (3.6 KM MARK)**

Before our Clients proceeds to repair the damaged TMA, we are requesting a Pre-Repair Survey

Kindly let us know within **2 working days** of this Notice whether you or your Insurers would like to conduct a PRS of the TMA

If we do not receive any reply from you/your Insurers within the stipulated timeline, our Clients shall proceed to repair the 'TMA without further reference to you & our Clients will be compensated for the loss of use of the TMA for this period of time

Our Clients' Appointed Workshop :

MS AGNES TEO

Address :

M/s Tai Wah Motor

1 Kaki Bukit Ave 6 Block A

01 – 06/07 AutoBay@ Kaki Bukit

S (417883)

Tel : 6284 3376 / 6284 3375

Fax : 6285 6292

Email : taiwahmotorrepair@gmail.com

Mobile : 9738 2668

Our Clients' Appointed Surveyor :

MR ERROL TAN

Address

M/s Pro Plus Automobile Engineers

221 Balestier Rd

10 - 01 Rocca Balestier

S (329928)

Tel : 6707 8932

Fax : 6352 6802

Email : ethtan88@singnet.com.sg

Mobile: 9673 0595 / 9788 9809

Copies of our Clients' Driver's Police Report, Incident Reports, Sketch Plan of accident, LTA Search of SGG 181R & COI are enclosed for your kind attention

Deeply appreciate your prompt action

Yours Faithfully

Cc: Clients

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	XD1067X		
Vehicle Type :	B33 - Goods (Open) Tipper/Dumper Truck		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	ISUZU		
Vehicle Model :	CXZ50K		
Chassis No. :	JALCXZ50K67000082		
Propellant :	Diesel		
Engine No. :	6WA1400370		
Engine Capacity :	12068 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	27500 kg		
Unladen Weight :	10360 kg		
Year Of Manufacture :	2006		
Original Registration Date :	29 Sep 2006		
Lifespan Expiry Date :	28 Sep 2026		
COE Category :	C - Goods Vehicle & Bus		
PQP Paid :	\$24,044.00		
COE Expiry Date :	28 Sep 2021		
Road Tax Expiry Date :	28 Sep 2018		
Inspection Due Date :	28 Sep 2018		
Intended Transfer Date :	05 Apr 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
This vehicle has a road tax Over Payment of \$192.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.			
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.			

You may print this page for reference.

OK

Print

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Feb 2018		20 Feb 2018 17:53 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	M/S M & L CAFETERIA, Co. Reg. No.: -		
Main Claimant:	FIT TRANSPORT SYSTEMS PTE LTD		
Vehicle Reg. No.:	XD1067X	Date of Loss:	10/02/2018 02:00 - :59 [136 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D00930C02	Policy/Cover Note No.:	DMHCSN1619171701
Vehicle Reg. No. (Insured):	SGG181R	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Pro Plus Automobile Engineers (HQ) 221 BALESTIER ROAD #10-01 ROCCA BALESTIER, 329928 Balestier - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 01/03/2018]		
Adj Asg. Remarks:	PLEASE SURVEY THIRD PARTY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***XD1067X (SNM18D00930C02)**
[SGG181R]

TP

FIT TRANSPORT SYSTEMS PTE LTD

Feb 10 2018 2:00AM

[M/S M & L CAFETERIA]

Pro Plus Automobile Engineers


Upload Documents Upload Photos Compose New Letter

View View in Browser

Photos/Images

			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/04/18 17:24	Rear View Left	 Load JPG	<input checked="" type="checkbox"/>
2	05/04/18 17:24	Rear View	 Load JPG	<input checked="" type="checkbox"/>
3	05/04/18 17:24	Rear View Right	 Load JPG	<input checked="" type="checkbox"/>
4	05/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
5	05/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
6	05/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
7	05/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
8	05/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
9	05/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
10	05/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
11	05/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
12	05/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
13	05/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
14	05/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
15	05/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
16	05/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
17	05/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
18	05/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
19	05/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
20	05/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
21	05/04/18 17:24	General View	 Load JPG	<input checked="" type="checkbox"/>
22	05/04/18 17:25	General View	 Load JPG	<input checked="" type="checkbox"/>

Documentation

			1 per page	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/02/18 17:54	THIRD PARTY XD1067X -PRS EMAIL BTW CIC AND FONG & FONG LLC	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118003396/DBS2

Date: 09/04/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSN1619171701

Claimant Vehicle No: XD1067X Insured Vehicle No: SGG181R

Date of Loss: 10/02/2018 Nature of Claim: TP Claim No: SNM18D00930C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD1067X

Make & Model: ISUZU TFS69H-29(T), 3.1 D (M) Engine No: 6WA1400370

Reg. Date: 29/09/2006 (Man. Year: 2006) Chassis No: JALCXZ50K67000082

Colour: White Odometer: 0 km

Engine Capacity: 12068 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5/5 mm

Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/02/2018

Date Inspected: 21/02/2018 Inspected At: Pro Plus Automobile Engineers (HQ)
221 BALESTIER ROAD #10-01 ROCCA BALESTIER
Singapore 329928

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/9/2018.

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$28,000.00 - \$35,000.00

REPAIR DETAILS

Reference

Part Source:

(Last Synchronised: 09 Apr 2018)

Parts:

N/A

ISUZU TFS69H-29(T) 3.1 D (M) (Model not available in database)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code:

(Unsubmitted, no print-code for XD1067X)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
END OF ESTIMATES marker on the last estimate page

Further Info:

Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >