

ASS. REC. BY:

REF: CS3/AIG18003405/Gd3er DAR 3 DAYS

Surveyor: menmen

GO
Chin Lee Ying

ASSIGNMENT (Office)

of AIG

Date/Time: 21/2/18 @ 3:57pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJR 8045E

Insured: SJN 4593L

at Workshop m/s: Siang Hui Motor

Tel: 67444605

of Blk 3006, ubi Rd 1 # 01-338

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A: 15/2/18

CA / REV / REP. / REV 24 HRS / up

23/2/18

H.O.D. Endorsement:

Date/Time: 12:04pm @ 22/2/18

Person Contacted: Mr. Teh

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate	
	SJR 8045E - NA / INK 18003180/24	D.O.A: 15/2/18
	SJN 4593L - NA / INK 18003180/24	D.O.A: 15/2/18

PRS XML

AIG

23/2/18

SIR 8045E

15 Jul 2009

0

~~SJN 4593~~

Siang Hui

Blk 3006, Ubi Rd 1 #01-338

9630 9032


Hyundai Avante

1591

Silver

166236

KMH0U41BR9U768890



195/60 R15

11

\$16k.

6

6

6

6

4

w/s

26-02-18
11AM

RECEIVED 13 APR 2018



Pres. Report

Date of Report 4.

Final Report

Resurvey No. of Trk

180

DAR

20

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18003405/Gd3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 22-02-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJN 4593L	Veh. Inspected	SJR 8045E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	22/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/02/2018	Inspection Date	
Survey held at	SIANG HUI MOTOR WORKS BLK 3006 UBI ROAD 1 #01-338 SINGAPORE 408700		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SJN4593L AND SJR8045E ON 15/2/2018**

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: 21/2/2018 3:57:44 PM
Attachments:  FaxDCB3.tif

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

BONNIE KWOK LLC
Advocates & Solicitors

101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358

Tel: (65) 6536 6026
Fax: (65) 6536 2279
INOT FOR SERVICE OF COURT DOCUMENTS!
CST REG. NO. 2012035472

Your Vehicle: SJN 4593 L (3rd Party Vehicle)

Our Vehicle: SJR 8045 E

Date: 19 February 2018

M/s AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way AIG Building
#08-16
Singapore 079120

By Fax 6835 7416 Only

Dear Sir,

ACCIDENT INVOLVING SJR 8045 E & SJN 4593 L ON 15/2/18

We refer to the above matter.

I hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle SJR 8045 E
M/s Siang Hui Motor Works, Block 3006 Ubi Road 1 #01-338 Singapore 568047. Contact number
67444605.

Your faithfully



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2717A
Vehicle Details	
Vehicle No.:	SJR8045E
Vehicle to be Exported:	No
Intended De-registration Date:	27 Feb 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	G4FC9U659962
Chassis No.:	KMHDU41BR9U768890
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,278.00
Original Registration Date:	15 Jul 2009
First Registration Date:	15 Jul 2009
Transfer Count:	1
Actual ARF Paid:	\$11,278.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jul 2019
PARF Rebate Amount:	\$6,202.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jul 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$7,789.00
COE Rebate Amount:	\$1,046.00
Total Rebate Amount:	\$7,248.00

The information contained herein is correct as at 27 Feb 2018.

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/02/2018 10:25
Date Of Accident	15/02/2018 23:30
Exact Location Of Accident	ALONG LORONG 15 GEYLANG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR8045E
Insured/Policyholder	
Name Of Registered Owner	TAY TIONG BENG
NRIC No	S0092717A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-86135703
Alternative Phone No	OFFICE-86135703
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	HD AVANTE 1.6 A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092559133
Cover Note Number	
Driver	
Name of Driver	TAY TIONG BENG
NRIC No	S0092717A
Date Of Birth	22/04/1952
Occupation	OUTDOOR
Date Of Driving Pass	15/04/1971
Driving Experience	46 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86135703
Fax Number	
Contact Number	OFFICE-86135703
EMail Address	NOEMAIL

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consents under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under [d] above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Condition (CON)
 (0) Best (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
 (07) Deformed (08) Shilled (09) Buckled (10) Broken (11) Necessary (12) Missing
 (13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (LH)

ACTION (AC)
 (1) Replace (✓) (2) Repair (X) (3) Check (?)
 (4) Not Consistent (NC)

Aug 21

Left Portion

Vehicle No: **STR 8045 E**

NAC	INC	Item	CON	AC	Qty
1255	995326	Frnt LH Door			
1256	995140	Frnt LH Door Protector			
1257	995104	Frnt LH Door Hinge			
1258	995142	Frnt LH Door Wing Mirror			
1259	995102	Frnt LH Door Garnish	DM	✓	
1260	991593	Frnt LH Door Glass Outer Moulding			
1261	991588	Frnt LH Door Glass Inner Moulding			
1262	995103	Frnt LH Door Glass			
1263	991595	Frnt LH Door Glass Regulator			
1264	991596	Frnt LH Door Glass Regulator Motor			
1265	991662	Frnt LH Door Rubber	X	DM	
1266	991636	Frnt LH Door Outer Handle			
1267	991607	Frnt LH Door Inner Handle			
1268	991625	Frnt LH Door Lock w/Key			
1269	991624	Frnt LH Door Lock			
1270	991562	Frnt LH Door Central Lock			
1271	991675	Frnt LH Door Switch			
1272	991617	Frnt LH Door Inner Trim Board			
1273	991568	Frnt LH Door Checker			
1274	991575	Frnt LH Door Felt			
1275	991688	Frnt LH Door Wire Harness			
1276	991683	Frnt LH Door Window Glass Pillar			
1277	991640	Frnt LH Door Outer Pillar			
1278	991613	Frnt LH Door Inner Pillar			
1279	991646	Frnt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frnt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frnt Bumper			
1006	991325	Frnt Bumper Bracket	CUT	✓	
1007	991462	Frnt Bumper Side Retainer			
1008	991433	Frnt Bumper Reinforcement	Nec	2 pks	
1009	991468	Frnt Bumper Sponge			
1010	991427	Frnt Bumper Protector			
1011	991301	Frnt Bumper Moulding			
1012	991407	Frnt Bumper Lower Spoiler			
1013	995153	Frnt LH Headlamp Assy			
1014	995088	Frnt LH Side Lamp			
1015	995070	Frnt LH Fender			
1016	995147	Frnt LH Fender Lamp	DM	✓	
1017	995148	Frnt LH Fender Protector	X	DM	

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door			
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1041	992958	Rear Bumper			
1047	992976	Rear Bumper Bracket			
1048	993068	Rear Bumper Side Retainer			
1049	993045	Rear Bumper Reinforcement			
1050	993077	Rear Bumper Sponge			
1051	993040	Rear Bumper Protector			
1052	993026	Rear Bumper Moulding			
1053	993023	Rear Bumper Lower Spoiler			
1063	993851	Rear LH Taillamp			
1018	993436	Rear LH Fender			
1019	993449	Rear LH Fender Protector			
1036	990247	Sticker			

4
 * 7 days

No of Items:

Assessor:

LHF headlamp x 1 crack mounting.
 LHF Fender inner garnish x 1 deformed.
 LHF door outer moulding x 1. cut
 LHF door window x 1 scratches.
 LHF Fender inner panel deformed repair.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Mar 2018 Edit Reg		21 Feb 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS			[Created by adjuster]
Insured:	Saifudin Anshari Bin Buang, ID: S8029027F		
Main Claimant:	TAY TIONG BENG, ID: S0092717A		
Vehicle Reg. No.:	SJR8045E	Date of Loss:	15/02/2018 23:00 - :59 [103 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8868709421SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SJN4593L	Policy No. (Claimant):	
		Excess:	
Repairer:	Siang Hui Motor Works (HQ) 3006 Ubi Road 1, #01-338, 408700 Ubi - Tel: 67444605		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/03/2018]		
Claimant's Solicitor:	BONNIE KWOK LLC - Tel: 65366026		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (12/03/2018): Request To Upload TP GIA Report 		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SJR8045E (8868709421SG)
[SJN4593L]
TP
TAY TIONG BENG
Feb 15 2018 11:00PM
[Saifudin Anshari Bin Buang]
Siang Hui Motor Works

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser	
Photos/Images											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
2	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
3	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
4	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
5	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
6	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
7	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
8	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
9	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
10	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
11	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
12	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
13	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
14	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
15	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
16	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
17	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
18	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
19	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
20	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
21	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
22	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
23	22/03/18 17:50	Chassis Number							Load JPG	<input checked="" type="checkbox"/>		
24	22/03/18 17:50	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>		
25	22/03/18 17:50	General View							Load JPG	<input checked="" type="checkbox"/>		
26	22/03/18 17:50	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
27	22/03/18 17:50	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
28	22/03/18 17:50	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
29	22/03/18 17:50	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
30	22/03/18 17:50	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
31	22/03/18 17:50	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
32	22/03/18 17:50	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		
33	22/03/18 17:52	Photo After Spray							Load JPG	<input checked="" type="checkbox"/>		
34	22/03/18 17:52	Photo After Spray							Load JPG	<input checked="" type="checkbox"/>		
35	22/03/18 17:52	Photo After Spray							Load JPG	<input checked="" type="checkbox"/>		
36	22/03/18 17:52	Photo After Spray							Load JPG	<input checked="" type="checkbox"/>		
37	22/03/18 17:52	Photo After Spray							Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
38	22/03/18 17:52	Photo After Spray		Thumbnail <input checked="" type="checkbox"/>
				Print <input checked="" type="checkbox"/>
39	22/03/18 17:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
40	22/03/18 17:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
41	22/03/18 17:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
42	22/03/18 17:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
43	22/03/18 17:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
44	22/03/18 17:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
45	22/03/18 17:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
46	22/03/18 17:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
47	22/03/18 17:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
48	22/03/18 17:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
49	22/03/18 17:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
50	22/03/18 17:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
51	22/03/18 17:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
52	22/03/18 17:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		
1	12/03/18 09:46	OI GIA report		Thumbnail <input checked="" type="checkbox"/>
				Print <input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18003405/GD3E2

Date: 13/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJR8045E

Insured Vehicle No : SJN4593L

Date of Loss: 15/02/2018

Nature of Claim: TP

Claim No: 8868709421SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR8045E**

Make & Model: HYUNDAI HD AVANTE 1.6 A (BI-FUEL), 1.6 (A)

Engine No: G4FC9U659962

Reg. Date: 15/07/2009 (Man. Year: 2009)

Chassis No: KMHDU41BR9U768890

Colour: Silver

Odometer: 166236 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/02/2018

Date Inspected: 26/02/2018

Inspected At:

Siang Hui Motor Works (HQ)
3006 Ubi Road 1, #01-338
Singapore 408700

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRT LH DOOR WING MIRROR	Damaged	0.00 F	*- F	
2	1		*FRT BUMPER	Cut	0.00 F	*- F	
3	2		*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*- F	
4	1		*FRT LH FENDER	Damaged	0.00 F	*- F	
5	1		*LHF HEADLAMP	MTG Cracked	0.00 F	*- F	
6	1		*LHF FENDER INNER GARNISH	Deformed	0.00 F	*- F	
7	1		*LHF DOOR OUTER MOULDING	Cut	0.00 F	*- F	
8	1		*LHF DOOR WINDOW	Scratched	0.00 F	*- F	
9	1		*LHF FENDER INNER PANEL	Repair	0.00 F	*- F	
					Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >