ASS. REC. BY: Rasul	ASSIGNMENT (Office)	1d3 Special instruction:	
From (Person): YvonW Arv	ASM	Date/Time 20/2/18	
Estimated Cost	Bill to:		
OD TP+WS+TP RES / OD RE	S/EVA/INV/MV7CS		
To Inspect Vehicle No: at Workshop m/s	SDF 2626C Prestige Auto,	Insured: Tel: 67426787	
of lat 70	Inima kutona Road	101 044 20141	
Policy No:	Claim No:	1 (800 MBS	
Sum Insured:	Excess:	\$ 600-00	
Make of Veh:	-	D.O.A. 6/2/18	
(Client's Record)	77530D	2	
CA) REV / REP. / REV 24 H	RS	H.O.D. Endorsement:	
1341111000	Person Contacted:	Vehicle IN JOUT	
Date/Time Action/Instruction			
	vised to growne they		-11
18 9 18 80 570 pm 2m	I nevert to yvonne me	p was Smart Claim. Coupplement	101
[8/9/186 W. Man 90	once the intermed can	proceed supplementary of Smar	of C
NO 10 207	, a days. Gert ?	[017-17, 77/0]	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

AXA	INSURANCE PTE	LTD	Ref : CS/ASM18003	3417/R1qd3
	HENTON WAY #24			
	TOWERSINGAPO		Date: 22-02-2018	
			Code: ASM	
1.		Policy Particula	ars :- OWN DAMAGE	
	Insured Veh.		Veh. Inspected	SDF 2626C
	Policy No.		Coverage (\$)	0.00
	Claim No.	S8M008J1	Excess (\$)	600.00
	Assign From	SMARTCLAIM (YVONNE ANG)	Assign Date	22/02/2018
2.		Vehicle Partic	culars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	P.	Steering	
	Brakes		Modification	
	General			
3.		Conditi	ons of Tyres	
	4	Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm -
	L/H Rear Tyre			mm
4.		Description	on of Damages	harry will and the
5.	Lington No. 2		Information	
	Accident Date		Inspection Date	
	Survey held at	PRESTIGE AUTO	8	
_		191 TANJONG KATONG ROAD		
5a.	Gongal Andrew	Re	emarks	

Menu



Service Request Details

Claim

IL800M85

Reference

None 🧳

Loss Date

February 6, 2018

Request Date

February 20, 2018

Due Date

February 27, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions Next Step Agree to perform service Decline Work Accept Work

Vehicle Information

Incident Vehicle Registration # SDF2626C

Make

MERCEDES

Menu

Service Address

111

Primary Contact/Insured

KOH SIOW CHUANG ALBINA 27 CLAYMORE ROAD, #13-01 THE CLAYMORE, 229544, Singapore 96710575

Claim Handler

ANG Yvonne 6568804461 yvonne.ang@axa.com.sg

Additional Instructions

EXCESS 600

Messages Invoices History Documents Assessment Metrics Notes

New Message

Shiau Chan (LKKAuto)

From	**
LLOI	н.

Shiau Chan (LKKAuto)

Sent:

Wednesday, 19 September 2018 1:48 PM

To:

'Prestige Chong'

Subject:

RE: SDF2626C

Dear June,

WITHOUT PREJUDISE

As spoken with you last Friday (14/09/2018).

The repair cost should be at Lump Sum \$8,850.00 instead of \$11,109.90 before excess \$600.00.

Kindly amend your discharge voucher and tax invoice to repair cost at Lump Sum \$8,850.00 and send it back to us.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,

#02-25 | S(408933)

-----Original Message-----

Sent: Tuesday, 27 March 2018 5:29 PM

To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Subject: Re: SDF2626C

Hi Shiau,

Please find attached invoice for your persual.

Thanks and regards

June

On 2/28/18, Shiau Chan (LKKAuto) <siewsc@lkkauto.com> wrote:

- > Dear June,
- >
- > Received with thanks.
- >
- > Best Regards,
- > Shiau Chan (Ms) | Case Handler
- > LKK Auto Consultants Pte Ltd
- > Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51,
- > Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)
- > -----Original Message-----
- > From: Prestige Chong [mailto:prestige.chong@gmail.com]
- > Sent: Wednesday, 28 February 2018 3:16 PM
- > To: SUR <sur@lkkauto.com>
- > Subject: SDF2626C
- >

> Hi,

Menu



Re:2ND IA OF VEHICLE SDF 2626C UPLOADED

Type

Question

Message

LUMP SUM REVISE TO \$8850 BEFORE EXCESS. PLEASE PROCEED

Reply

Menu



2ND IA OF VEHICLE SDF 2626C UPLOADED

Type

Q Question

Message

Dear Yvonne, please be informed that 2nd IA of vehicle SDF 2626C uploaded. Damages consistent. repair cost economical. kindly approve on supplementary, we will re-finalise repair cost with repairer. - Shiau Chan

Reply

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd

Date: 14/09/18

Survey Details:

Date of loss	6-Feb-18	
Date of appointment	20-Feb-18	_
Date of survey	21-Feb-18	
Location of survey	PRESTIGE AUTO	

Vehicle Details:

Claim Type:	Own Dama	ige
Vehicle number	SDF 2626C	
Make and Model	MERCEDES CLK200ML	
Date of registration	5/10/2000	N .
Excess	\$	600.00
Market Value	\$	22,000.00
Parf Rebate	\$	10,633.00
Nett Loss	\$	11,367.00

Repair details:

Initial Estimate	Ś	18,677.79	(EST \$16,677.79 +
Initial Estimate	, , , , , , , , , , , , , , , , , , ,		SUPP \$2,000.00)

Proposed/Revised repair cost:

Parts	\$ 8,429.90
Check items (estimate)	\$
Labour	\$ 2,680.00
Total	\$ 11,109.90
Lump Sum(if applicable)	\$ 8,850.00

Number of days for repair	9
Number of days for repair	-

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.	
KINDLY APPROVE ON SUPPLEMENTARY.	

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	



Alice 67379928. ×102

LETTER OF UNDERTAKING! AUTHORIZATION FOR LUMP SUM REPAIR

- 1. I, [Name] [NRIC] KOH STOW CHUANG, ALBINA the owner/ authorized driver of vehicle [Registration No.] SDF 2626C ("Vehicle") do hereby authorize the [Workshop/Insurer] to repair the Vehicle on a lump sum basis instead of part by part.
- The [Workshop/Insurer] has explained to me the difference between lump sum repair and part by part repair and the consequences of my authorization for lump sum repair for the Vehicle.
- 3. I understand that with lump sum repair, the Workshop may use a mixture of genuine parts, original equipment manufacturer (OEM) parts, reconditioned and second hand parts to carry out the repair and I note that the [Workshop/Insurer] will not be furnishing a detailed breakdown of parts or price for such lump sum repair.
- 4. I am aware that AXA Insurance Pte Ltd ("AXA Insurance") does not encourage lump sum repair as AXA Insurance strongly recommends repairs for vehicles on a part by part basis for transparency reasons. I confirm that I will hold AXA Insurance harmless from any claims arising from the lump sum repair of the Vehicle which I have authorized.
- 5 * To be applicable where person authorizing is the authorized driver.
 I confirm that I have the authority from the owner of the Vehicle to authorize the lump sum repairs and that I have duly notified the owner of the Vehicle of the contents of this Letter of Authorization.

Signed and acknowledged by:

Signature of policyholder/ authorized driver* and company stamp (where applicable)

Date: 23 Tels 2018

Name and signature of workshop personnel including workshop stamp

*authorized driver to either the named drivers as per motor insurance policy or in the case of commercial vehicles, permitted drivers who are permitted to drive the insured Vehicle.



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S8M008JI

Date: 23rd February 2018

Our Ref: CS/ASM18003417/R1qd3

The Motor Claims Department AXA Insurance Singapore Pte L td

Attn: Yvonne

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SDF 2626C .

We thank you for the instruction on _20/02/2018.


Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/02/2018 (4.20pm) at the premises of M/s PRESTIGA AUTO and have the following to report:-

Workshop Estimate Amount	: S\$	16,677.79	
Revised Estimate Amount	: S\$	8,553.79	_
"Check" Items Amount	: S\$	6,363.76	
Total	: S\$	14,917.55	
Market Value	: S\$	22,000.00	_
LTA Reimbursement Value	: S\$	10,633.00	33
Nett Value	: S\$	11,367.00	

Description of Damage:

The vehicle sustained damages at the

o/s front portion.



Comments/ Present Status:

<u>Damages consistent.</u>

<u>Pending for Lump Sum repair letter from repairer Recommend days of repair: 9 days</u>

We have authorised the repairs.

Yours faithfully

Rasul

Automobile Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Agreement on the second		
Owner ID Type:	Singapore NRIC	
Owner ID:	0971Z	
Vehicle Details		
Vehicle No.:	SDF2626C	
Vehicle to be Exported:	No	
Intended De-registration Date:	22 Feb 2018	
Vehicle Make:	MERCEDES BENZ	
Vehicle Model:	CLK200ML AT	
Primary Colour:	Black	
Manufacturing Year:	2000	
Engine No.:	11195632019021	
Chassis No.:	WDB2083442F169646	
Maximum Power Output:	2	
Open Market Value:	\$49,140.00	
Original Registration Date:	05 Oct 2000	
First Registration Date:	05 Oct 2000	
Transfer Count:	0	
Actual ARF Paid:	\$68,796.00	
ntended PARF Rebate Details		
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:	*	
PARF Rebate Amount:	\$0.00	
ntended COE Rebate Details		

COE Expiry Date:	30 Sep 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$40,810.00
COE Rebate Amount:	\$10,633.00
Total Rebate Amount:	\$10,633.00

The information contained herein is correct as at 22 Feb 2018

OK 22,000 10,633 11,367 MCC418018569-01 / Cycle & Carriage Industries Pts Ltd - Pandan Loop ENTRY DATE & TIME: 06/02/2018 16:08 SUBMITTED BY: Lim Xin Yi

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

HELD SHOP IN A SHOP	ACCIDENT STATEMENT
Date Of Report	06/02/2018 16:08
Date Of Accident	06/02/2018 11:45
Exact Location Of Accident	ALONG BUKIT TIMAH RD TOWARDS KHEAM HOCK RD
Country/State of Loss	SINGAPORE
有可能的证明是实现	DETAILS OF OWN VEHICLE

	DETAILS OF OWN VEHICLE	ASSESSMENT OF STREET
Vehicle Registration Number	SDF2626C	

Insured/Policyholder

Name Of Registered Owner KOH SIOW CHUANG ALBINA

NRIC No S0120971Z Email Address NOEMAIL

 Mobile Phone No
 (LOCAL) +65-96710575

 Alternative Phone No
 OFFICE-96710575

Vehicle Particulars

 Manufacturer
 MERCEDES-BENZ

 Model
 CLK 200 ML

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number GA065977/1

Cover Note Number

Driver

Name of Driver KOH SIOW CHUANG ALBINA

 NRIC No
 S0120971Z

 Date Of Birth
 26/03/1954

 Occupation
 INDOOR

 Date Of Driving Pass
 23/04/1992

Driving Experience 25 YEARS AND 9 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-96710575

Fax Number

Contact Number OFFICE-96710575

EMail Address NOEMAIL

Address

18 TREVOSE CRESCENT

Postcode

298032

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD ON COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

NO

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS DRIVING STRAIGHT, CROSSING BUKIT TIMAH TOWARDS KHEAM HOCK ROAD. AT THE POINT OF CROSSING BUKIT TIMAH, THE TRAFFIC LIGHT WAS GREEN. VEHICLE B (SKV5249X) WAS DRIVING THE OPPOSITE WAY TOWARDS MY CAR AND TURNED RIGHT AT THE JUNCTION INTO BUKIT TIMAH INTO MY PATH. AT THAT POINT, OUR CARS COLLIDED.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKV5249X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

MPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process
- This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wiful misrepresentation or withholding of material facts may allow
- 6 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being
- 8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- [4] My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may are permitted to collect, use, disclose and/or my insurer collectively the "Personal Information set out in this [form] and any other personal information provided by me or possessed by insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured website(s) involved in this accident (all insurers) who have insured website(s) involved in this accident shall be collectively. thy insurer (corectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to
 - (ii) investigating the accident and/or my claims.
 - $\left(\mathrm{iii}\right)$ carrying out and/or dealing with my instructions or responding to any enquiries by me.
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers law firms, may/are permitted to collect, use. disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers andler GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and
- (e) the information so collected under (d) above may be shared / disclosed.
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - $\langle \hat{n} \rangle$ for complying with requirements under any regulations, laws or court orders.

Eric Lee Ming Hui DID: 6771 4336 HP: 9181 7717 Email : eric.lee@cyclecarriage.com.sg Cycle & Carriage Industries Pte Ltd Customer Service Centre - Pandan Loop

Policyholder's Signature Date & Time 6/Teb/2018

Driver's Signature

(If driver is not the policyholder)


Date & Time

Reporting Centre Personnel's

Name

NRIC/FIN NO.

Sketch Plan #2



I WAS DRIVING STRAIGHT, CROSSING BUKIT TIMAH TOWARDS KHEAM HOCK ROAD, AT THE POINT OF CROSSING BUKIT TIMAH, THE TRAFFIC LIGHT WAS GREEN. VEH B(SKV5249X) WAS DRIVING THE OPPOSITE WAY TOWARDS MY VEHICLE & TURNED RIGHT AT THE JUNCTION INTO BUKIT TIMAH INTO MY PATH, AT THAT POINT, OUR CARS COLLIDED.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Shull

Policyholder's Signature Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time

DID: 6771 4336 HP: 9181 7717 Email: eric.lee@cyclecarriage.com.ag Cycle & Carriage Industries Pte Ltd Customer Service Centre - Pandan Loop

Eric Lee Ming Hui

Reporting Centre Personnel's

Name.

NRIC/FIN No.

Sketch Plan #3





AXA Insurance Pte Ltd. 2 1800 580 4858 (Within Singapore) (65) 6880 4888 (International) ≦ (65) 6880 4740 E custamer.care@asa.com.sg men.aua.com.ug

account number

Certificate of Insurance

14080 Fully, 1967-4-ad harmonia, 1987 Waters

Policy details

Policybolder name Plan name NCD applicable Vehicle registration number Period of Insurance

KOH STOW CHUANG ALBINA Comprehensive Private Sen. 5DF2626C from 05/10/2017 to 04/10/2018 more distre viplusive

Certificate number Engine number

GA065977 / 1 WD82083441*189646 11195632019021

Persons or classes of persons entitled to drive*

Finance team company

(b) Any person who is driving on the Policyholder's lader or with their parts

Provided that the person driving is permitted in accordance with the logisting or other basis or regulations to drive the Motor Vehical or has been at pernisted and is not disqualified by order of a Court of Litw or by reason of any executivent or negotiation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Limitation as to use*

Use only for social, domestic and pleasure surposes and for the Pouryholder's business.

The policy does not cover ruse for here or reward, racing pace-making, reliability trial, speed festing, the servage of goods other than samples in connection with motor trade or business or use for any purpose in connection with motor trade, or when the Motor Car, whether abstrongly, in use in otherwise, guestion or according track, cross, route, course or any other roads by whatever rights called that are typically used for racing, procentaking or such similar purposes.

 Unotations rendered inoperative by Section 6 or the Amous venicles (Third Early Robo and Oldaneys) are not to be included under these readings. are the respect to the first authorized are stated to the second of the

EXCESS

Basic Own Darriage Excess Windscreen Excess

980 500,00 880 500,00

An Addressial Excess is applicable as follows:

- 1. \$\$500 for unrismed Authorised Emier
- 2. \$\$500 for declared roung and Inexpenenced Driver
- 3. \$\$5,000 for undeclared mong and menpemented Drivers. This additional express is reduced to \$\$2,500 if you have chosen AVA Phyriaum

Additional clauses & endorsements to your policy

No

(We hereby certify that the policy to which the Curtificate relates is inspect in accordance Compensation Act, (Chaster 189) and Part IV of the Ruser Transport Act, 1987 (Malayera). in the provision of the Motor Venkings (Trind Party Risks and AXA Insurance Pto Ltd

Authorised signature

Important note

Prospections are served that on the saw of a motor venice, they must sumenour the Certificate of insurance and the fine of insurance company, if the Certificate of insurance and the Place to the insurance company, if the Certificate of insurance that because the theorems of the certificate of insurance that the

AXA Insurance Pte Ltd (199903512M) 8 Sheeton Way, #24-01, AVA Tower,

Sketch Plan #4



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

23 Apr 1992




NP 428A

Licence No. S0120971Z













Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE 6 Raffles Quay #18-00 Singapore D46580
Tel (65) 6224 D010 Pax (65) 6224 0030
Decrating Hours: Monday to Friday, 09:00 – 17:00
UN: S668S00200 / G87 Ng. Ne.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

		ADDENDON
A	PARTICULARS OF PERS	ON MAKING THE AMENDMENTS:
	Original Report No :	UCCAISO 18569 Vehicle Agristration No: SDF2626 C 601 SIOU Chuayaric/FIN/Passport No: SO120971Z
	Name(as shown in NRIC) : _	60 Sion Chuayaric/FIN/PassportNo: SO120971Z
	(*Vehicle Driver / Vehi	cle Owner) (*) Please delete as appropriate
	Address :_	_Singapore()
	Contact (Tel)	Mobile No.:
	Email Address :_	
	Date of Accident :_	6 0 18
	Place of Accident :_	Bt. Timan Rd turb Kheam HOCK Rd
	Insurance Company: _	AXA
B	ADDITIONAL INFORM	ATION / AMENDMENTS:
-		n the above mentioned accident and would like to include additional information or
	make the following am	
	P	ment to 'OD' Clariu.
		Del 10 00 Clotos
		I .
	(
	1	
	11/	1100
	Athin o. W	Wik Chan Hoe he Lad
	e marca 3	& Carringe Industrial Const.
	Policyholder / Driver's	Signature Reporting Control Resonance
	Date: 15/Feb/20	Names of The Names
		Anual Date: 15/2/18
		4

PRESTIGE AUTO AIR CON ACCESSORIES

191 TANJONG KATONG ROAD SINGAPORE 436993 TEL:6742 6787 FAX:6842 3217

Quality Check and Estimated Quotation For Repairs

Customer: KOH SIOW CHUANG ALBINA

Address

18 TREVOSE CRESCENT S (298032)

Attn:

Fax

Tel:

Hp: 96710575

Veh No: SDF2626C

and are pleased to submit our quotation cost of repair for your vehicle as follows: -

LKK Auto Consultants hence-otify the Repairer of the following:

- . To resurvey before after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis.
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Date: 14-Feb-2018 From JEE HON CHONC Hp 90210057

Make: MERCEDES

Model: CLK 200ML

Hp 90010068

()	No. of the last of	Qty	Total (\$)	I day
lo:	Description	1	414.00	sca /
1	FRONT FOG LIGHT RIGHT	1		CR47 010
2	HEADLAMP UNIT RIGHT. LEFT SIDE TRAFFIC	1	/ 214.24	64
3	STIFFENING HEAD LAMP PANEL RIGHT FRONT LIGHTING UNIT	1	143 52	i Xzec
4	COVERING FRONT CROSS MEMBER OUTER	1	810.56	1. xxx 21/02/18 01/2
5	BEAM FRONT CROSS MEMBER INNER		140.08	Xxx 21/04/8 6/97
8	STRUT BRACE PANEL BETWEEN STIFFENING AND CROSS MEMBER		274.05	15vc
7	STIFFENING FRONT CENTRAL	1	646.18	
8	PROTECTIVE GRILLE RAD-GRILLE	+ 3 +	- 1,758.02	[[K X]] . U
9	HOOD BONNET	1	56.81	
10	RAIL RIGHT BUMPER MOUNTING	1	63.67	
11	IMPACT ABSORBER INSIDE RIGHT	1	108 16	mus Resy 54 po
12	IMPACT ABSORBER INSIDE CENTRAL	1	26.69	mu = 0 - 6400
13	COVER BUMPERPANELLING, RIGHT COVER	1	55.78	DE Keny ST
14	COVER BUMPERPANELLING, CENTRAL TRIM	1	255.70	sor.
15	BUMPER BOTTOM	1	256.11	XV a Ato
16	LICENSE PLATE MOULDING	1-	발생 (1925년대 - 1927년대) [1]	I SIND
17	RAIL RIGHT PROTECTOR	1	243.57	The second second
18	BUMPER TOP GEPRIMERT	1	/ 1,430.33	h . / 1
19	FRONT FENDER	1	882.06	170 1 V 1.0
20	CAPACITOR A/C CONDENSER	-1	1,176.85	
385	RADIATOR (CHARGING AIR INTERCOOLER)	1	1,331.70	121
21		01	1,498.84	4 .
22	RADIATOR	Sub-Total (A)	\$ 13,207.79	9

B)	Total (\$)	- 120
23 LABOUR TO REPAIR AND REPLACE FRONT 24 SPRAY PAINTING ON FRONT AFFECTED AR 25 REMOVE, REFIX AIR CON SYSTEM AND REF 26 CHECK WIRING SYSTEM AND REFORCES H 27 TO DIAGNOSE AND RESET SYSTEM AFTER	1,20ed IS 1594 MP 80.1	00 200 -
28 CHECK WHEEL ALIGHMENT 29 TOWING CHARGES Validity of quote will be 14	1981	60 60

\$ 16,677.79 Total (A + B) 18677.79.

If the above estimate is acceptable kindly let us have

Your authorisation to proceed with the repair

Please comfirm.sign,and revert this fax,as soon as possible

Your sincerely

PRESTIGE AUTO AIR CON ACCESSORIES

Prestige Auto Air-Con Accessories

Signature Of Customer

Date:

Company Stamp

191 Tanjong Katong Road Singapore 436993 Tel: (65) 6742 6787 Fax: (65) 6842 3217

PRESTIGE AUTO AIR CON ACCESSORIES

191 TANJONG KATONG ROAD SINGAPORE 436993 TEL:6742 6787 FAX:6842 3217

Customer: AXA INSURANCE PTE LTD

Date: 27-Mar-2018

Address: 8 SHENTON WAY #24-01 AXA TOWER S068811

Invoice No: PA0001

Attn:

Make; MERCEDES

Fax: 68804740

Model: CLK 200ML

Tel: 1800 8804888

Veh No: SDF2626C

1	ľ.	μ	٩	d	١	
_	Ľ	_	_	2	L	

No.	Description	Qty	Total (\$)
1	FRONT FOG LIGHT RIGHT	1	414.00
2	HEADLAMP UNIT RIGHT, LEFT SIDE TRAFFIC	1	1,028.62
3	STIFFENING HEAD LAMP PANEL RIGHT FRONT LIGHTING UNIT	1	214.24
4	HOOD BONNET	1	1,758.02
700	RAIL RIGHT BUMPER MOUNTING	1	56.81
5	IMPACT ABSORBER INSIDE RIGHT	1	63.67
7	COVER BUMPERPANELLING, RIGHT COVER	1	26.69
8	COVER BUMPERPANELLING, CENTRAL TRIM	1	55.78
-	LICENSE PLATE MOULDING	1	256.11
10	RAIL RIGHT PROTECTOR	1	243.57
	BUMPER TOP GEPRIMERT	1	1,430.33
11		1	882.06
12	FRONT FENDER	-1	1,800.00
13	FRONT WINDSHIELD FRONT RIGHT WHEEL COVERING X2 (TOP)	2	200.00
14	LABOUR TO REPAIR AND REPLACE FRONT DAMAGED PARTS		1,200.0
15	SPRAY PAINTING ON FRONT AFFECTED AREA		1,000.0
16	REMOVE, REFIX AIR CON SYSTEM AND REFILL GAS		120.00
17	CHECK WIRING SYSTEM AND REFORCES HEADLAMP		40.00
18	TO DIAGNOSE AND RESET SYSTEM AFTER REPAIR		200.0
-			60.0
20	CHECK WHEEL ALIGHMENT		60.0
21	TOWING CHARGES		
_	Sub-Tota	I (A)	\$ 11,109.90

(B)		
No.		Total (\$)
	LESS BASIC OWN DAMAGE EXCESS - KOH SIOW CHUANG ALBINA	600.00
	WINDSCREEN EXCESS	100.00

Total

\$10,409.90

PRESTIGE AUTO AIR-CON ACCESSORIES

191 Tanjong Katong Road Shell Service Station Singapore 436993

27 MARCH 2018

DISCHARGE VOUCHER

I/We, KOH SIEW CHUANG ALBINA

Hereby acknowledge that my vehicle no. SDF2626C Mercedes CLK 200ML has been repaired to my satisfaction and collect on 24 Harrh

I/We agree the sum of SGD \$10,409.90 to be paid to repairer PRESTIGE AUTO AIR CON ACCESSORIES for such repairs shall be in full discharge of all claims against the insurance company AXA INSURANCE COMPANY

In respect of all claim against the insurance sustained to my said motor vehicle in the accident which occurred.

Signature of Owner

Name: Koh Siew Chuang Albina

NRIC: S0120971Z

Signature of Witness

Name:

NRIC: (72 208748

PRESTIGE AUTO AIR CON ACCESSORIES

191 TANJONG KATONG ROAD SINGAPORE 436993 TEL:8742 6787 FAX:6842 3217

Customer: AXA INSURANCE PTE LTD

Address 8 SHENTON WAY #24-01 AXA TOWER S068B11

Date; 27-Mar-2018

Invoice No: PA0001

Altn: Steam Chain

Fax: 68804740 Tel:1800 8804888 Make: MERCEDES Model: CLK 200ML

Veh No: SDF2626C

No.	Description	Qty	Total (S)
1 LUMP SUM REPAIR CO			8.850.0
			J-,
1			
+			
-+			<u> </u>
		Sub-Total (A)	S 8,850.00
3)			
10.			Total (S)
LESS BASIC OWN DAM	AGE EXCESS - KOH SIOW CHUANG ALBINA	(600.0
1			1

PRESTIGE AUTO AIR CON ACCESSORIES

Prestige Auto Air-Enn Accessories

191 Tanjong Katong Road Singapore 436993 Tel: (65) 6742 6787 Fax: (65) 6842 3717

PRESTIGE AUTO AIR-CON ACCESSORIES

191 Tanjong Katong Road Shell Service Station Singapore 436993

27 MARCH 2018

DISCHARGE VOUCHER

I/We, KOH SIEW CHUANG ALBINA

Hereby acknowledge that my vehicle no. SDF2626C Mercedes CLK 200ML has been repaired to my satisfaction and collect on 29 MARCH 2018

I/We agree the sum of SGD \$8250.00 to be paid to repairer PRESTIGE AUTO AIR CON ACCESSORIES for such repairs shall be in full discharge of all claims against the insurance company AXA INSURANCE COMPANY

In respect of all claim against the insurance sustained to my said motor vehicle in the accident which occurred.

Signature of Owner

Name: Koh Siew Chuang Albina

NRIC: S0120971Z

Signature of Witness

Name:

372 205 74 2

NRIC:



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internation		
AXA INSURANCE PTE	LTD	Ref : CS/ASM180034	17/R1qd3s2
8 SHENTON WAY #24 AXA TOWERSINGAPO		Date: 10-10-2018	
ATTN: YVONNE ANG	Dallay Bartlay	ars :- OWN DAMAGE	
Insured Veh.	Policy Particul	Veh. Inspected	SDF 2626C
Policy No.	GA065977/1	Coverage (\$)	0.00
Claim No.	S8M008J1	Excess (\$)	600.00
Assign From	YVONNE ANG	Assign Date	20/02/2018
2.	Vehicle Parti	culars & Condition	
Make & Model	MERCEDES BENZ CLK200ML	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2000
Chassis No.	WDB2083442F169646	Colour	BLACK
Odometer	054977	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3.	Condit	ions of Tyres	
	Size	Make	Balance
R/H Front Tyre	205/55R16	MICHELIN	6 mm
L/H Front Tyre	205/55R16	MICHELIN	6 mm
R/H Rear Tyre	205/55R16	MICHELIN	6 mm
L/H Rear Tyre	205/55R16	MICHELIN	6 mm
4.	Descript	ion of Damages	
THE VEHICLE SU	ISTAINED DAMAGES AT THE O/S	S FRONT PORTION.	
DAMAGES SEE D	DETAILS.		
5.	Genera	al Information	
Accident Date	06/02/2018	Inspection Date	21/02/2018
Survey held at	PRESTIGE AUTO	HEZITAR-PENANCARIM MATERIALISM	
	191 TANJONG KATONG ROAL	SINGAPORE 436993	
5a.	F	Remarks	
A)THE MARKET N B)IN ACCORDAN	VALUE IS \$\$22,000.00(EST. AVER CE TO YOUR INSTRUCTIONS, V	RAGE) VE HAVE AUTHORISED R	EPAIRS.
5b.		Days of Repair	
ESTIMATED NOF	RMAL PERIOD FOR REPAIR:	9 Working Day	s



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDF 2626C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FOG LIGHT RIGHT (CONSISTENT)	SCRATCHED	414.00	414.00
1	HEADLAMP UNIT RIGHT, LEFT SIDE TRAFFIC (CONSISTENT)	CRACKED	1,028.62	1,028.62
1	STIFFENED HEAD LAMP PANEL RIGHT FRONT LIGHTING UNIT (CONSISTENT)	BENT	214.24	214.24
1	COVERING FRONT CROSS MEMBER OUTER (CONSISTENT)	SERVICEABLE	143.52	-
1	BEAM FRONT CROSS MEMBER INNER (CONSISTENT)	SERVICEABLE	810.56	-
1	STRUT BRACE PANEL BETWEEN STIFFENING AND CROSS MEMBER (CONSISTENT)	SERVICEABLE	140.08	7
1	STIFFENING FRONT CENTRAL (CONSISTENT)	SERVICEABLE	274.05	-
1	PROTECTIVE GRILLE RAD-GRILLE (CONSISTENT)	SERVICEABLE	646.18	-
1	HOOD BONNET (CONSISTENT)	BENT	1,758.02	1,758.02
1	RAIL RIGHT BUMPER MOUNTING (CONSISTENT)	BENT	56.81	56.81
1	IMPACT ABSORBER INSIDE RIGHT (CONSISTENT)	MISSING	63.67	63.67
1	IMPACT ABSORBER INSIDE CENTRAL (CONSISTENT)	SERVICEABLE	108.16	
1	COVER BUMPERPANELLING, RIGHT COVER (CONSISTENT)	MISSING	26.69	26.69
1	COVER BUMPERPANNELLING, CENTRAL TRIM (CONSISTENT)	DEFORMED	55.78	55.78
1	BUMPER BOTTOM (CONSISTENT)	SERVICEABLE	647.95	-
1	LICENSE PLATE MOULDING (CONSISTENT)	CUT	256.11	256.11
1	RAIL RIGHT PROTECTOR (CONSISTENT)	MISSING	243.57	243.57
1	BUMPER TOP GEPRIMERT (CONSISTENT)	DEFORMED	1,430.33	1,430.33
1	FRONT FENDER (CONSISTENT)	BUCKLED	882.06	882.06
1	CAPACITOR A/C CONDENSER (CONSISTENT)	SERVICEABLE	1,176.85	
1	RADIATOR (CHARGING AIR INTERCOOLER) (CONSISTENT)	SERVICEABLE	1,331.70	
1	RADIATOR (CONSISTENT)	SERVICEABLE	1,498.84	
1	FRONT WINDSHIELD (CONSISTENT) (ADDITIONAL)	CRACKED	1,800.00	1,800.00
2	FRONT RIGHT WHEEL COVERING (TOP) (CONSISTENT) (ADDITIONAL)	DEFORMED	200.00	200.00
			15,207.79	8,429.90

Report Ref No. CS/ASM18003417/R1qd3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	LABOUR TO REPAIR AND REPLACE FRONT DAMAGED PARTS.		1,400.00	1,200.00
	SPRAY PAINTING ON FRONT AFFECTED AREA.		1,200.00	1,000.00
	REMOVE, REFIX AIR CON SYSTEM AND REFILL GAS.		150.00	120,00
	CHECK WIRING SYSTEM AND REFOCUS HEADLAMP.		80.00	40.00
	TO DIAGNOSE AND RESET SYSTEM AFTER REPAIR.		420.00	200.00
	CHECK WHEEL ALIGNMENT.		120.00	60.00
	TOWING CHARGES.		100.00	60.00
			3,470.00	2,680.00
	GRAND TOTAL		18,677.79	11,109.90

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	8,850.00
LESS EXCESS	-600.00
NETT LIABILITY	8,250.00

Report Ref No. CS/ASM18003417/R1qd3s2

MKB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

H.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.