

MLHM18009913 / Lai Huat (Meng Kee) Motor Pte Ltd - Sin Ming
 ENTRY DATE & TIME: 20/01/2018 11:10
 SUBMITTED BY: Jenny Lim Lai Poong

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 20/01/2018 11:10
 Date Of Accident 18/01/2018 17:00
 Exact Location Of Accident BLK 10 JALAN BATU OPEN CAR PARK
 Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number PC1553J
 Insured/Policyholder
 Name Of Registered Owner ST. HILDA'S COMMUNITY SERVICES CENTRE
 Co Reg No 0
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No Office-63450054

Vehicle Particulars

Manufacturer TOYOTA
 Model HIACE
 Exact Purpose for which vehicle was being used at time of accident COMPANY USE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken REPORTING ONLY
 Vehicle Category COMMERCIAL VEHICLE
 Insurance Company
 Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number A 28613390 MKC
 Cover Note Number

Driver

Name of Driver TANG KIM HOCK
 NRIC No S1367208C
 Date Of Birth 14/04/1959
 Occupation OUTDOOR
 Date Of Driving Pass 16/02/1979
 Driving Experience 38 YEARS AND 11 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-90408755
 Fax Number
 Contact Number
 Email Address KHTANG111888@GMAIL.COM
 Address BLK 574 PASIR RIS STREET 53 #15-22
 Postcode 510574
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLIDED INTO PARKED VEHICLE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident

Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV858X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firm, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

10, SINGAPORE SERVICE CENTRE
10, JALAN BATU #01-06
SINGAPORE 431010
TEL: 6242 0094 FAX: 6242 0093

Policyholder's Signature
Date & Time:

19 JAN 2018

Driver's Signature
(If driver is not the policyholder)

Date & Time: 19 JAN 2018

Reporting Centre Personnel's Signature

Name: Jenny Lim
NRIC/FIN No.: S6927273H

SKETCH PLAN



A - PC 1553J

B - SKV 858X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

parking in lot, move out accidentally
knocked existing car parked next to my left

DECLARATION

I/We declare the foregoing particulars are true in every respect.

10, BLOK 10 JALAN BATU, #01-05
SINGAPORE 431010
TEL: 6345 0054 FAX: 6345 0052

Policyholder's Signature

Date & Time:

19 JAN 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time: 19 JAN 2018

Reporting Centre Personnel's Signature

Name:

Jenny Lim

NRIC/FIN No.:

S5927273H

Sketch Plan #2



Sketch Plan #3

**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, # 21-01, SGC Centre 2, Singapore 068807
 Tel: +65 6527 7000 Fax: +65 6827 7800
 Co-Reg No: 200412212G GST Reg No: 20-0412212G

iCover Services

4 SHENTON WAY #21-01 SGC CENTRE 2
 SINGAPORE 068807 TEL: 6527 7000 FAX: 6528 0900

COMMERCIAL VEHICLE			RENEWAL INVITATION
Policy Number	Renewal Period of Insurance	Expiry Date	Place of Issue
A 28613390 MKC	04/10/2017 to 03/10/2018	03/10/2017	SINGAPORE
Name and Address of Insured			Date of Issue
St. Hilda's Community Services Centre 10 Jalan Batu #01-06 Singapore 431010			03/08/2017
			Client Number
			10142318
			Account Number
			155521
Premium	GST	Premium Payable	
SGD2,617.60	SGD183.23	SGD2,800.83	

RISK NUMBER 1		COMMERCIAL VEHICLE	
BUSINESS			
Community Service			
SCOPE OF COVER Comprehensive			
INTEREST INSURED			
ITEM	0001	SUM INSURED	MARKET VALUE
REGISTRATION NO.	PC1551J	NO CLAIM DISCOUNT	30.00% (or P/D)
MAKE/MODEL	Toyota Hiace	EXCESS	SGD1,000
ENGINE NUMBER	1KD2200221	WINDSCREEN	UNLIMITED
CHASSIS NUMBER	JTFST22FX00014050	ANNUAL PREMIUM	SGD2,617.60
YEAR OF MFG	2013		
CAPACITY	2982 C.C.		
SEATING CAPACITY	11 (INCL. DRIVER)		
AUTHORISED DRIVERS			
Any other person provided he is driving on the Insured's order or with the Insured's permission.			
LIMITATION AS TO USE			
Use only for the carriage of passengers or goods in connection with the Insured's business. The Policy does not cover			

DA201708032207

M/C1506 109

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



CHASSIS NO. : 2K2-1740011012

UNLOADED WT. : 7200 KG

MAX. LOADED WT. : 8500 KG

PASSENGER CAP. : 1 DRIVER OTHER

TYRE SIZE : (F)

(R)



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
 GST Reg No: MX 0869103 NO Business Reg No: 394773/00D
 E-mail: nphauto@pacific.net.sg



TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

CHING TUAN YEE
 BLK 10 JALAN BATU
 #08-10
 Singapore 431010

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP017/02/18
Policy No:		Date of Loss:	18/02/2018
Vehicle Reg. No.:	SKV858X	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHING TUAN YEE	Driver (Insured):	CHING TUAN YEE
Make/Model:	HONDA MOBILIO, 1.5 V CVT (A)	Vehicle Reg. Date:	28/08/2015
Vehicle Colour:	SILVER		
Engine No:	L15Z12101075	Chassis No:	MRHDD487OFP000251
Odometer:	49808 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	SEE ATTACHED		
Present Location:	NPH AUTO SERVICE (HQ)		

COST OF CLAIMS

	Amount
Parts	356.50
Miscellaneous Items	0.00
Labour	825.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	1,181.50
+ GST 7.00% (\$\$)	82.71
Nett Amount (\$\$)	1,264.21

This claim is handled by: PEGGY FOO

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Feb 2018)

Parts: M1-MPV HONDA MOBILIO 1.5 V CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKV858X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER ✓ SR / DD	0.00	0.00	*180.00 F ✓
2	1		*FRONT BUMPER FOG LAMP GRILLE RH ✓ SR / CRA	0.00	0.00	*55.00 F ✓
3	1		*FRONT BUMPER LOWER CENTER GRILLE ✓ CRA	0.00	0.00	*55.00 F ✓
4	1		*FRONT BUMPER SIDE RETAINER L&R (2) @10 ✓ NEC	0.00	0.00	*20.00 F ✓

F=Franchise part.

Sub Total (S\$) 310.00

+ Margin on L,N Items 15.00% (S\$) 46.50

Total Parts (S\$) 356.50

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts (cost.)
margin

\$310.00
\$46.50

\$356.50

Labour

\$725.00

\$1081.50

=

2 Days Repair

(Remark = Reduction → 806)

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REMOVE & INSTALL F/HEADLAMP, F/GRILLE, F/BUMPER, KNOCK F/FENDER AND RESTRAIGHTEN BODY.	New	350.00 ³⁰⁰
2	SPRAY PAINTING.	New	450.00 ⁴⁰⁰
3	CHECK WIRING SYSTEM.	New	25.00 ✓
Gross Labour Cost (\$\$)			825.00 ⁷²⁵

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Without Prejudice
Resurvey Before Paint
Parts By Parts
Parts Price Subject
To Confirmation

2 Days Repair

W. Loh, LKK

26/2/2018

12/3/18

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Wilson (LKKAUTO)

From: Mark <mark@nphauto.com>
Sent: Tuesday, 13 March, 2018 4:09 PM
To: Wilson (LKKAUTO)
Subject: Finalised: Honda Mobilio

Dear Wilson,

As spoken, confirm COR: \$1081.50.

Regards,
Roy

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jan 2018 Sendback Est	23 Feb 2018 13:37 S\$1,181.50	23 Feb 2018 14:29 Edit Adj Rpt	S\$1,081.50 Edit Estimates	S\$1,081.50 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	ST. HILDA'S COMMUNITY SERVICES CENTRE , ID: S7538468H, Tel: +6598213468		
Main Claimant:	CHING TUAN YEE , ID: S7538468H		
Vehicle Reg. No.:	SKV858X	Date of Loss:	18/01/2018 17:00 - :59 [28 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 546789	Policy/Cover Note No.:	28613390MKC (Comprehensive) Coverage: 04/10/2017 - 03/10/2018
Vehicle Reg. No. (Insured):	PC1553J	Policy No. (Claimant):	
		Excess:	
Repairer:	NPH Auto Service (HQ) Blk 9005 Tampines Steet 93, #01-246/254, 528839 Tampines - Tel: 6784 0663		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 25/03/2018]		
Driver/Custodian (Insured):	TANG KIM HOCK (42 / Male), NRIC: S1367208C, Tel: +6598213468		
Adj Asg. Remarks:	Please reassign case to Marcus Chua. To Survey NPH Auto on 23/02/2018 at 10.30 am. Thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKV858X (546789)
[PC1553J]
TP
CHING TUAN YEE
Jan 18 2018 5:00PM
[ST. HILDA'S COMMUNITY SERVICES CENTRE]
NPH Auto Service

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports

No	Finalized On	NPH Auto Service (HQ)	1 per page	Thumbnail	Print
1	23/02/18 13:37	Repairer Estimates	1	Load HTM	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	23/02/18 14:30	Accident Statement From: TP - Reg. No: SKV858X, Claimant: Ching Tuan Yee (Zhuang Duanyi)	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	31/03/18 09:55	Adjuster Immediate Advice	1	Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page	Thumbnail	Print
1	27/02/18 11:36	General View	1	Load JPG	✓
2	27/02/18 11:36	General View	1	Load JPG	✓
3	27/02/18 11:36	General View	1	Load JPG	✓
4	27/02/18 11:36	General View	1	Load JPG	✓
5	27/02/18 11:36	General View	1	Load JPG	✓
6	27/02/18 11:36	General View	1	Load JPG	✓
7	27/02/18 11:36	General View	1	Load JPG	✓
8	27/02/18 11:36	General View	1	Load JPG	✓
9	27/02/18 11:36	General View	1	Load JPG	✓
10	27/02/18 11:36	General View	1	Load JPG	✓
11	27/02/18 11:36	General View	1	Load JPG	✓
12	27/02/18 11:36	General View	1	Load JPG	✓
13	27/02/18 11:36	General View	1	Load JPG	✓
14	27/02/18 11:36	General View	1	Load JPG	✓
15	27/02/18 11:36	General View	1	Load JPG	✓
16	27/02/18 11:36	General View	1	Load JPG	✓
17	27/02/18 11:36	General View	1	Load JPG	✓
18	27/02/18 11:36	General View	1	Load JPG	✓
19	27/02/18 11:36	General View	1	Load JPG	✓
20	27/02/18 11:36	General View	1	Load JPG	✓
21	27/02/18 11:36	General View	1	Load JPG	✓
22	27/02/18 11:36	General View	1	Load JPG	✓
23	27/02/18 11:36	General View	1	Load JPG	✓
24	27/02/18 11:36	General View	1	Load JPG	✓
25	27/02/18 11:36	General View	1	Load JPG	✓
26	27/02/18 11:36	General View	1	Load JPG	✓
27	27/02/18 11:36	General View	1	Load JPG	✓
28	27/02/18 11:36	General View	1	Load JPG	✓

Assessment Reports			1 per page	☒
No	Finalized On	NPH Auto Service (HQ)	Thumbnail	Print
29	27/02/18 11:36	General View	 Load JPG	☒
30	27/02/18 11:36	General View	 Load JPG	☒
31	27/02/18 11:36	General View	 Load JPG	☒
32	27/02/18 11:36	General View	 Load JPG	☒
33	27/02/18 11:36	General View	 Load JPG	☒
34	27/02/18 11:36	General View	 Load JPG	☒
35	27/02/18 11:36	General View	 Load JPG	☒
36	27/02/18 11:36	General View	 Load JPG	☒
37	27/02/18 11:36	General View	 Load JPG	☒
38	27/02/18 11:36	General View	 Load JPG	☒
39	27/02/18 11:36	General View	 Load JPG	☒
40	27/02/18 11:36	General View	 Load JPG	☒
41	27/02/18 11:36	General View	 Load JPG	☒
42	27/02/18 11:36	General View	 Load JPG	☒
43	27/02/18 11:36	General View	 Load JPG	☒
44	27/02/18 11:36	General View	 Load JPG	☒
45	27/02/18 11:36	General View	 Load JPG	☒
46	27/02/18 11:36	General View	 Load JPG	☒
47	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
48	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
49	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
50	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
51	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
52	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
53	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
54	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
55	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
56	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
57	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
58	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
59	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
60	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
61	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
62	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
63	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
64	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
65	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
66	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
67	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
68	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
69	27/02/18 11:44	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	NPH Auto Service (HQ)	Thumbnail	Print
1	23/02/18 13:36	E-filed GIA report	 Load PDF	
2	23/02/18 13:36	Driver's Driving License	 Load PDF	
3	23/02/18 13:36	Certificate of Insurance	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/02/18 14:30	Survey arrangement with owner of SKV858X From: TP - Reg. No: SKV858X, Claimant: Ching Tuan Yee (Zhuang Duanyi)	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003448/WVBS2
Date: 04/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 28613390MKC
Claimant Vehicle No: SKV858X Insured Vehicle No: PC1553J
Date of Loss: 18/01/2018 Nature of Claim: TP Claim No: 546789

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKV858X Engine No: L15Z12101075
Make & Model: HONDA MOBILIO, 1.5 V CVT (A) Chassis No: MRHDD4870FP000251
Reg. Date: 28/08/2015 (Man. Year: 2015) Odometer: 49808 km
Colour: Silver
Engine Capacity: 1497 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15 Rear Tyre Size: 185/65R15
Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm
Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	356.50	356.50	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	825.00	725.00	100.00	12.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,181.50	1,081.50	100.00	8.46
+ GST 7.00/7.00% (S\$)	82.71	75.71	7.00	8.46
Nett Amount (S\$)	1,264.21	1,157.21	107.00	8.46

INSPECTION

Date of Assignment: 23/02/2018
Date Inspected: 23/02/2018 Inspected At: NPH Auto Service (HQ)
Singapore 528839
Estimated Period of Repair: 2.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Apr 2018)

Parts: M1-MPV HONDA MOBILIO 1.5 V CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKV858X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Scratched / Dented	180.00 F	*180.00 F
2	1		*FRONT BUMPER FOG LAMP GRILLE RH (WCP)	Scratched / Cracked	55.00 F	*55.00 F
3	1		*FRONT BUMPER LOWER CENTER GRILLE (WCP)	Cracked	55.00 F	*55.00 F
4	1		*FRONT BUMPER SIDE RETAINER L&R (2) @10 (WCP)	O/s Necessary	20.00 F	*20.00 F

F=Franchise part.

Sub Total (S\$)	310.00	310.00
+ Margin on L,N Items 15.00/15.00% (S\$)	46.50	46.50
Total Parts (S\$)	356.50	356.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & INSTALL F/HEADLAMP, F/GRILLE, F/BUMPER, KNOCK F/FENDER AND RESTRAIGHTEN BODY.	New	350.00	300.00
2	SPRAY PAINTING.	New	450.00	400.00
3	CHECK WIRING SYSTEM.	New	25.00	25.00
Gross Labour Cost (S\$)			825.00	725.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >