

22/03/2001

ASS. REC. BY:

REF:

CS/MG618003452/TLVb.52

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Joslin Lim

of

MSIG.

Date/Time:

22/3/2018

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

YP 2875 Z

Insured:

Tel:

68676918

at Workshop m/s

Comfort Delgro

of

45 Pandan Rd

Policy No:

B29067387 MKF

Claim No:

549197

Excess:

750

Sum Insured:

D.O.A.

7/3/18

Make of Veh:

(Client's Record)

CA / REV / REP / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

28/3

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	YP 2875 Z - CVI VAL 18002659 DV MV \$90K (Est)
26/3/18	Revert vehicle T/L by merimen
5/3/18	Submit unrecnomical T/L - MV: \$90K (Est) LTA: \$34,990 NV: \$55,010

Signature: *Tanjin*

REF: MSG

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **YP 2875 Z**
 at Workshop m/s: **Comfort Delgro**
 of: **H5 Pandan Rd.**
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: **750**
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

X	X
N/S	O/S
X	X

Bal. or Market Value: **989K 90K**
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **YP 2875 Z** Yr Regn: **2016 June**
 Type: M/Car / M/Cycle / Bus / Van / ☒ Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Mitsubishi Canter** cc **2998**
 Colour: **white** A/C: _____ Insured / Std / NI / NA
 Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **FEB21CA 20036**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **Inorder** / Jammed / Leaked / Burnt or
 Brake: **Inorder** / Jammed / Leaked / Burnt or
 Mod: **Nil** / S/Rim / STD A/Rim or
 Tyre Size: F: **145/85R15**
 R: **- - (D)**
☒ BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear
R/Bal. 6 mm		R/Bal. 6/L mm
L/Bal. 6 mm		L/Bal. 6/L mm
D.O.A. 7/2/18		D.O.I. 23/2/18 @ 1430
Survey held at: CDGE Pandan		
Des. of Damages: <input checked="" type="radio"/> Fr / <input checked="" type="radio"/> Rear / <input checked="" type="radio"/> O/S / <input checked="" type="radio"/> N/S / <input checked="" type="radio"/> U/C / <input checked="" type="radio"/> Rooftop or		

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction **Battery weak**

26/2 Spoken to William from Goldbell, LOR roughly and \$70K+

RECEIVED 05 MAR 2018

Date/Time File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1) S + RS: \$

2) Photo

3) Others

Date/Time File Return to?

1) **5/3- typist**

Add Fee: ☐ : Site Insp \$

☐ : Interview \$

☐ : Tech. Insp \$

☐ : Weekend \$

Report Format: **merimen- TL**

Lump Sum / I.B.I. \$

450
10

TOTAL

Survey Department Check List (Case Handler)

Reference No. : CS/MSG/1803452/Tivb
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 5/3/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18003452/T1vb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 23-02-2018		
		Code : MSG		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		YP 2875Z	
Policy No. B29067387MKF	Coverage (\$)		0.00	
Claim No. 549197	Excess (\$)		750.00	
Assign From JOSLIN LIM (MERIMEN)	Assign Date		22/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No. HIDDEN	Year of Reg.			
Chassis No.	Colour			
Odometer -	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 07/02/2018	Inspection Date		23/02/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 45 PANDAN ROAD SINGAPORE 609286			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Feb 2018 Sendback Est	22 Feb 2018 08:37 S\$84,000.00	22 Feb 2018 11:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	TOPSELLER PTE LTD, Co. Reg. No.: 197701362R, Tel: +6586861130		
Vehicle Reg. No.:	YP2875Z	Date of Loss:	07/02/2018 16:00 - :59
Claim Type:	OD / 549197	Policy/Cover Note No.:	B29067387MKF (Comprehensive) Coverage: 01/01/2018 - 31/12/2018
		Excess:	S\$750.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Pandan) 45 Pandan Road, 609286 Eunos - Tel: 6338 8778		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/02/2018]		
Driver/Custodian:	EEE SIONG SOON (29 / Male), NRIC: G8324940X, Tel: +6598108292		
Adj Asg. Remarks:	URGENT.Please survey and revert.		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

☐ **ALL ASSOCIATED TASKS**
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

View Received Message

This mail is associated with :

YP2875Z (549197)

OD

Feb 7 2018 4:00PM

[TOPSELLER PTE LTD]

ComfortDelGro Engineering Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on **02/03/2018 12:13 PM.**

To LKK_HQ

Subject Alert - Adj Mandate Revoked - YP2875Z - Claim Handler: Joslin Lim

Revoked:Veh is not economical to be repaired. Case will be settled on Constructive total loss basis

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Joslin Lim	Date: 26 Feb 2018
<u>Preliminary Advice</u>	

Vehicle No	: YP2875Z	Accident Date	: 07/02/2018
Make	: MITSUBISHI FEB21CR4SDEB	Policy No.	: B29067387MKF
Assignment Date	: 22/02/2018	Excess	: S\$750.00
Date of Inspection	: 23/02/2018	Est. Duration of Repair	: 0.00
Inspection At	COMFORTDELGRO ENGINEERING PTE LTD (PANDAN) 45 PANDAN ROAD SINGAPORE 609286		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, n/s body, undercarriage and rooftop. The chassis frame and body structure affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	84,000.00
Revised Amount	:S\$	79,500.00
Check Items (Estimated)	:S\$	1,000.00
Total	:S\$	80,500.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	90,000.00
COE / PARF Rebate	:S\$	34,990.00
Salvage Value	:S\$	
Margin for Repair	:S\$	55,010.00

Remarks

(X) The vehicle is not economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Surveyor Copy

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/02/2018 12:40
Date Of Accident	07/02/2018 16:45
Exact Location Of Accident	ALONG BUKIT MERAH VIEW TOWARDS LOWER DELTA ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP2875Z
Insured/Policyholder	
Name Of Registered Owner	TOPSELLER PTE LTD
Co Reg No	197701362R
Email Address	VICTORYEO@HAMWELL.COM.SG
Mobile Phone No	(LOCAL) +65-86861130
Alternative Phone No	OFFICE-68778687

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FEB21CR4SDEB-3.0 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	B29067387MKF
Cover Note Number	

Driver

Name of Driver	EEE SIONG SOON
NRIC No	G8324940X
Date Of Birth	29/01/1989
Occupation	OUTDOOR
Date Of Driving Pass	06/02/2014
Driving Experience	4 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98108292
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	348 JALAN BOON LAY SINGAPORE
Postcode	619529
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	JURONG WEST N.P.C
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED POLICE REPORT NO.T/20180208/2042

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	UNABLE UPLOAD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	ROAD RIVIDER/KERB/RAILINGS
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	EEE SIONG SOON
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	YP2875Z
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If Driver is not the policyholder)
Date & Time:

12:40pm
8/2/18

COMFORTDELGRO ENGINEERING PTE LTD
EXTERNAL BUSINESS DIV. SINGAPORE BRANCH
NAME & SIGNATURE: 
DESIGNATION: _____ DATE: 8/2/18

Reporting Centre Personnel's Signature
Name: WONG CHEE WEI
NRIC/FIN No: 672180994

SKETCH PLAN



Refer to Attachment Report No - T/20180208/2042

I/We declare the foregoing particulars are true in every respect.



Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

IMPORT/EXPORT ENGINEERING PTE LTD
EXTERNAL BUSINESS DIV. PANDAN BRANCH
NAME & SIGNATURE: [Signature]
DESIGNATION: _____ DATE: 8/2

Reporting Centre Personnel's Signature
Name: WONG CHEE WEI
NRIC/FIN No.: 672180994



SINGAPORE
POLICE FORCE



T/20180208/2042

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

1 of 3
Report No. T/20180208/2042

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/02/2018 11:44		Vide Report No.: D/20180207/0072		Station Diary No.: 112	
Informant's Particulars					
Name of Informant: EEE SIONG SOON			Address: APT BLK 120 HO CHING ROAD #07-99 SINGAPORE 610120		
ID Type / ID No.: FIN NO / G8324940X			Contact No.: Home/Office: Mobile: 88261678		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 29	Date of Birth: 29/01/1989	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Sales Representative			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 07/02/2018 16:45	Type of Location:
Location: Along Road 1 BUKIT MERAH VIEW TOWARDS LOWER DELTA ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Moving Vehicle Against - Road Divider/Kerb/Railings				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
YP2875Z	Lorry				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



SINGAPORE
POLICE FORCE



T/20180208/2042

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

3 of 3

Report No. T/20180208/2042

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
J /
Sgt 1 NURAQILAH BINTE ABDUL HAMID

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
08/02/2018 11:44

Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt YUS MASTARI H KHAZALI
Contact No.: 65476214

Classification Of Case:

Authentication Stamp
NP168



SINGAPORE
POLICE FORCE



T/20180208/2042

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2688999

2 of 3

Report No: T/20180208/2042

CONTINUATION OF REPORT

Driver			
Name	EEE SIONG SOON	ID No.	G8324940X
Related Vehicle	YP2875Z (Lorry)	Contact No.	88261678
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	07/02/2018	Date Discharge	07/02/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On 7/2/2018 at about 4.45pm, I (YP2875Z) was along Bukit Merah View towards Lower Delta Road and was looking at the Google Maps as I was not familiar with the area. The next moment, I mounted a kerb on the road and went into the canal near the road. I then managed to get myself out of the lorry and subsequently the ambulance conveyed me to Singapore General Hospital where I received 5 days MC.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1362R
Vehicle Details	
Vehicle No.:	YP2875Z
Vehicle to be Exported:	No
Intended De-registration Date:	23 Feb 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21CR3SDEB
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4P10C06064
Chassis No.:	FEB21CA20036
Maximum Power Output:	-
Open Market Value:	\$45,344.00
Original Registration Date:	01 Jun 2016
First Registration Date:	01 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$2,268.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2026
COE Category:	C - Goods Vehicle & Bus

COE Period(Years):	10
QP Paid:	\$42,302.00
COE Rebate Amount:	\$34,990.00
Total Rebate Amount:	\$34,990.00

The information contained herein is correct as at 23 Feb 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	1362R

Vehicle Details

Vehicle No.:	YP2875Z
Vehicle to be Exported:	Yes
Intended De-registration Date:	10 Feb 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21CR3SDEB
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4P10C06064
Chassis No.:	FEB21CA20036
Maximum Power Output:	-
Open Market Value:	\$45,344.00
Original Registration Date:	01 Jun 2016
First Registration Date:	01 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$2,268.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 May 2026
------------------	-------------

COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,302.00
COE Rebate Amount:	\$33,841.00
Total Rebate Amount:	\$33,841.00

The information contained herein is correct as at 10 Feb 2018

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Mitsubishi Canter FEB21

Price Range

Depreciation

2016

Vehicle Type

Home » Used Cars » Victory Automotives Pte Ltd » Mitsubishi Fuso Canter FEB21

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Mitsubishi Fuso Canter FEB21

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD

Singapore Vehicle Traders Association
新加坡車業公會

bizSAFE

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$89,800
Depreciation	\$10,990 /yr View models with similar depreciation
Reg Date	12-Apr-2016 (8yrs 2mths 1day COE left)
Manufactured	2015
Mileage	11,900 km (6.5k /yr)
Transmission	Manual
Engine Cap	2,998 cc
Curb Weight	2,480 kg
Fuel type	Diesel
Features	Freezer Box -25 Degree From HweeJan
Accessories	With Remote Control/ 2 Spare Key & Freezer Box With Key Lock.
Description	Best Of The Best [HweeJan] Freezer Box -25 Degree! From Day 1 Seldom Drive Till Now With A Superb Low Mileage At 11,900km, Orig Paintwork Well Kept With A Smell Of Brand New Unit, Box Comes With Overnight Charging And Still In Excellent Condition, Class 3 Without Vpc And 100% Loan With High Trade In Avail, Hurry Grab Now While Is Still Hot In Oven.
COE	\$4,597
OMV	\$29,940
ARF	\$1,497
Dereg Value	\$3,756 as of today (change)
No. of Owners	1
Type of Veh	Truck
Category	Premium Ad Car, Low Mileage Car
Availability	Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 09-Feb-2018 | Last Updated on: 09-Feb-2018

Tags: Mitsubishi Fuso, 2016 Mitsubishi Fuso, Mitsubishi, Fuso, Used Mitsubishi



Location Map



Price Analysis

Seller Information

Company	Victory Automotives Pte Ltd • dealer's pricelist • 3 vehs sold 11 vehs available
Address	25 Kaki Bukit Road 4 #01-67 Search cars nearby this location
Location	Synergy @ KB
Website	www.victoryautomotives.com
Office No	64698806
Contact Person(s)	Victor Tan 90699696

Upfront Payment

• High Finance Rate

Transfer Fee	\$25	
Down Payment	\$8,980 (change)	Maximum 90% Loan

Car Tyres



SAMSUNG

One machine.
Two washers.Multiple loads at the
same time.

LEARN MORE

FlexWash™



MSIG

MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, #1 21-01, SGX Centre 2, Singapore 068807
 Tel: +65 6827 7888, Fax: +65 6827 7800
 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1969 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1986 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.2.300
 Goods Carrying Vehicle - Sch I

COMMERCIAL VEHICLE - FLEET
 Comprehensive

Certificate No. B 29067387 MKF

Excess: 300750

1. Index Mark and Registration Number of Vehicle
 YP28752

2. Name of Policyholder
 Topseller Pte Ltd

3. Effective Date of the Commencement of Insurance for the purposes of the Act
 01/01/2018

4. Date of Expiry of Insurance
 31/12/2018

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*


Use in connection with the Policyholder's business.
 Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
 Use for social domestic and pleasure purposes.
 The Policy does not cover
 (1) Use for hire or reward or for racing pace-making reliability trial or speed-testing.
 (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
 Approved Insurers


 for Chief Executive Officer

Sketch Plan Pg. 7

WORK PERMIT
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer:
TOPSELLER PTE LTD

Photo: SERVICE

Name:
EEE SIONG SOON

Occupation:
SALES REPRESENTATIVE

Work Permit No:
4 02021501

Date of Application:
06-05-2015

Date of Issue:
18-04-2017

Date of Expiry:
29-04-2018



L7840315

VISIT PASS
Immigration Regulations

Name:
EEE SIONG SOON



Date of Birth: **29-01-1980** Sex: **M** Nationality: **MALAYSIAN**

FIN: **G632494DX** Date of Issue: **18-04-2017** Date of Expiry: **29-04-2018**

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.





ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

45 Pandan Road

Singapore 609286

Tel: 6338 8778 Email: denisteo@cdge.com.sg

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	B29067387MKF	Date of Loss:	07/02/2018
Vehicle Reg. No.:	YP2875Z	Driveable?	
Driver Age/Info:	29 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	TOPSELLER PTE LTD	Contact No:	+6586861130
Driver:	EEE SIONG SOON		

Make/Model:	mitsubishi feb21cr4sdeb, 3.0 D (M)	Vehicle Reg. Date:	01/06/2016
Vehicle Colour:	WHITE		
Engine No:	4P10C06064	Chassis No:	FEB21CA20036
Odometer:	0 KM		

Paint Type:
Total Loss?
Est. Duration of Repair (day)

YES

50

* Total Loss
Not Economical To Repair.

Taylkh 9747549

Ex \$750

24/2/18 R 1430

Revent

sure/kkauto-wm.

[Signature]
24/2/18

Description of Accident/Loss: REFER TO ATTACHED POLICE REPORT NO.T/20180208/2042

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (PANDAN)

COST OF CLAIMS

Parts
Miscellaneous Items
Labour
Paintwork Labour
Towing

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting.
 - To display damaged part(s) during resurvey.
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed.
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Calculated Gross Total (\$\$)

Amount

71,500.00

1,000.00

11,500.00

0.00

0.00

84,000.00

- Excess (\$\$)

750.00

(\$\$)

83,250.00

+ GST 7.00% (\$\$)

5,827.50

Nett Amount (\$\$)

89,077.50

This claim is handled by: **WONG CHEE WEI**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 22 Feb 2018)

Parts: N/A MITSUBISHI FEB21CR4SDEB 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/YP2875Z/22/02/2018 08:37

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*ESTIMATE PARTS COST	0.00	0.00	*65,000.00 F
F=Franchise part.						
Sub Total (\$\$)						65,000.00
+ Margin on L,N Items 10.00% (\$\$)						6,500.00
Total Parts (\$\$)						71,500.00

ComfortDelGro Engineering Pte Ltd/YP2875Z/22/02/2018 08:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars		Amount
<u>Miscellaneous Items</u>				
1	1	ESTIMATE COST	? 700	1,000.00
Sub Total (S\$)				1,000.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	ESTIMATE LABOUR CHARGES	New 6000	8,000.00
2	TO PUTTY, SPRAY PAINT : FRONT CABIN AND REAR REAR BOX	New 2000	3,500.00
Gross Labour Cost (S\$)			11,500.00

ComfortDelGro Engineering Pte Ltd/YP2875Z/22/02/2018 08:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	08 Feb 2018	22 Feb 2018 08:37 S\$84,000.00	22 Feb 2018 11:33 Edit Adj Rpt	S\$79,500.00 Edit Estimates	S\$79,500.00 View Rpt	Pending for Survey Report

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	TOPSELLER PTE LTD, Co. Reg. No.: 197701362R, Tel: +6586861130		
Vehicle Reg. No.:	YP2875Z	Date of Loss:	07/02/2018 16:00 - :59
Claim Type:	OD / 549197	Policy/Cover Note No.:	B29067387MKF (Comprehensive) Coverage: 01/01/2018 - 31/12/2018
		Excess:	S\$750.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Pandan) 45 Pandan Road, 609286 Eunos - Tel: 6338 8778		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 24/03/2018]		
Driver/Custodian:	EEE SIONG SOON (29 / Male), NRIC: G8324940X, Tel: +6598108292		
Adj Asg. Remarks:	URGENT.Please survey and revert.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (02/03/2018): Alert - Adj Mandate Revoked - YP2875Z - Claim Handler: Joslin Lim

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

















































YP2875Z (549197)
OD
Feb 7 2018 4:00PM
[TOPSELLER PTE LTD]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
1	08/02/18 15:06	Video - Accident [Linked Accident Report Documents]	Load MP4	
Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
1	22/02/18 08:37	Repairer Estimates	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/02/18 15:15	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
2	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
3	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
4	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
5	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
6	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
7	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
8	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
9	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
10	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
11	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
12	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
13	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
14	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
15	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
16	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
17	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
18	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
19	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
20	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
21	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
22	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
23	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
24	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
25	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>
26	26/02/18 09:47	General View	Load JPG	<input checked="" type="checkbox"/>

27	26/02/18 09:47	General View	1	Load JPG	✓
28	26/02/18 09:47	General View	1	Load JPG	✓
29	26/02/18 09:47	General View	1	Load JPG	✓
30	26/02/18 09:47	General View	1	Load JPG	✓
31	26/02/18 09:47	General View	1	Load JPG	✓
32	26/02/18 09:47	General View	1	Load JPG	✓
33	26/02/18 09:47	General View	1	Load JPG	✓
34	26/02/18 09:47	General View	1	Load JPG	✓
35	26/02/18 09:47	General View	1	Load JPG	✓
36	26/02/18 09:47	General View	1	Load JPG	✓
37	26/02/18 09:47	General View	1	Load JPG	✓
38	26/02/18 09:47	General View	1	Load JPG	✓
39	26/02/18 09:47	General View	1	Load JPG	✓
40	26/02/18 09:47	General View	1	Load JPG	✓
41	26/02/18 09:47	General View	1	Load JPG	✓
42	26/02/18 09:47	General View	1	Load JPG	✓
43	26/02/18 09:47	General View	1	Load JPG	✓
44	26/02/18 09:47	General View	1	Load JPG	✓
45	26/02/18 09:47	General View	1	Load JPG	✓
46	26/02/18 09:47	General View	1	Load JPG	✓
47	26/02/18 09:47	General View	1	Load JPG	✓
48	26/02/18 09:47	General View	1	Load JPG	✓
49	26/02/18 09:47	General View	1	Load JPG	✓
50	26/02/18 09:47	General View	1	Load JPG	✓
51	26/02/18 09:47	General View	1	Load JPG	✓
52	26/02/18 09:47	General View	1	Load JPG	✓
53	26/02/18 09:47	General View	1	Load JPG	✓
54	26/02/18 09:47	General View	1	Load JPG	✓
55	26/02/18 09:47	General View	1	Load JPG	✓
56	26/02/18 09:47	General View	1	Load JPG	✓
57	26/02/18 09:47	General View	1	Load JPG	✓
58	26/02/18 09:47	General View	1	Load JPG	✓
59	26/02/18 09:47	General View	1	Load JPG	✓
60	26/02/18 09:47	General View	1	Load JPG	✓
61	26/02/18 09:47	General View	1	Load JPG	✓
62	26/02/18 09:47	General View	1	Load JPG	✓
63	26/02/18 09:47	General View	1	Load JPG	✓
64	26/02/18 09:47	General View	1	Load JPG	✓
65	26/02/18 09:47	General View	1	Load JPG	✓
66	26/02/18 09:47	General View	1	Load JPG	✓
67	26/02/18 09:47	General View	1	Load JPG	✓
68	26/02/18 09:47	General View	1	Load JPG	✓
69	26/02/18 09:47	General View	1	Load JPG	✓
70	26/02/18 09:47	General View	1	Load JPG	✓
71	26/02/18 09:47	General View	1	Load JPG	✓
72	26/02/18 09:47	General View	1	Load JPG	✓
73	26/02/18 09:47	General View	1	Load JPG	✓
74	26/02/18 09:47	General View	1	Load JPG	✓

75	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
76	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
77	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
78	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
79	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
80	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
81	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
82	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
83	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
84	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
85	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
86	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
87	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
88	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
89	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
90	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
91	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
92	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
93	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
94	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
95	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
96	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
97	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
98	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
99	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
100	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
101	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
102	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
103	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
104	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
105	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
106	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
107	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
108	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
109	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
110	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
111	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
112	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
113	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
114	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
115	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
116	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
117	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
118	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
119	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
120	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
121	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>
122	26/02/18 09:47	General View		Load JPG	<input checked="" type="checkbox"/>

123	26/02/18 09:47	General View	1	Load JPG	✓
124	26/02/18 09:47	General View	1	Load JPG	✓
125	26/02/18 09:47	General View	1	Load JPG	✓
126	26/02/18 09:47	General View	1	Load JPG	✓
127	26/02/18 09:47	General View	1	Load JPG	✓
128	26/02/18 09:47	General View	1	Load JPG	✓
129	26/02/18 09:47	General View	1	Load JPG	✓
130	26/02/18 09:47	General View	1	Load JPG	✓
131	26/02/18 09:47	General View	1	Load JPG	✓
132	26/02/18 09:47	General View	1	Load JPG	✓
133	26/02/18 09:47	General View	1	Load JPG	✓
134	26/02/18 09:47	General View	1	Load JPG	✓
135	26/02/18 09:47	General View	1	Load JPG	✓
136	26/02/18 09:47	General View	1	Load JPG	✓
137	26/02/18 09:47	General View	1	Load JPG	✓
138	26/02/18 09:47	General View	1	Load JPG	✓
139	26/02/18 09:47	General View	1	Load JPG	✓
140	26/02/18 09:47	General View	1	Load JPG	✓
Documentation				1 per page	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	01/03/18 10:46	AJAX Immediate Advice	1	Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)		Thumbnail	Print
1	22/02/18 08:42	Singapore Accident Statement	1	Load PDF	
2	22/02/18 08:42	Work permit	1	Load PDF	
3	22/02/18 08:42	Drivers Driving License	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/02/18 11:09	ESTIMATE	1	Load PDF	
2	05/03/18 14:10	LTA REBATE 10 FEB 2018	1	Load PDF	
3	05/03/18 14:10	LTA REBATE 23 FEB 2018	1	Load PDF	

Linked Accident Report Documents

				View	View In Browser
Video				1 per page	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)		Thumbnail	Print
1	08/02/18 15:06	Video - Accident	1	Load MP4	
Assessment Reports				1 per page	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)		Thumbnail	Print
1	08/02/18 15:09	Accident Statement	1	Load HTM	
Photos/Images				3 per page	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)		Thumbnail	Print
1	08/02/18 12:54	Accident Photo	1	Load JPG	✓
2	08/02/18 12:54	Accident Photo	1	Load JPG	✓
3	08/02/18 12:54	Accident Photo	1	Load JPG	✓
4	08/02/18 12:54	Accident Photo	1	Load JPG	✓
5	08/02/18 14:59	Accident Photo	1	Load JPG	✓
6	08/02/18 14:59	Accident Photo	1	Load JPG	✓
7	08/02/18 14:59	Accident Photo	1	Load JPG	✓
8	08/02/18 14:59	Accident Photo	1	Load JPG	✓

9	08/02/18 14:59	Accident Photo	i	Load JPG	✓
10	08/02/18 14:59	Accident Photo	i	Load JPG	✓
11	08/02/18 14:59	Accident Photo	i	Load JPG	✓
12	08/02/18 14:59	Accident Photo	i	Load JPG	✓
13	08/02/18 14:59	Accident Photo	i	Load JPG	✓
14	08/02/18 14:59	Accident Photo	i	Load JPG	✓
15	08/02/18 14:59	Accident Photo	i	Load JPG	✓
16	08/02/18 14:59	Accident Photo	i	Load JPG	✓
17	08/02/18 14:59	Accident Photo	i	Load JPG	✓
18	08/02/18 14:59	Accident Photo	i	Load JPG	✓
19	08/02/18 14:59	Accident Photo	i	Load JPG	✓
20	08/02/18 14:59	Accident Photo	i	Load JPG	✓
21	08/02/18 14:59	Accident Photo	i	Load JPG	✓
22	08/02/18 14:59	Accident Photo	i	Load JPG	✓
23	08/02/18 14:59	Accident Photo	i	Load JPG	✓

Documentation

1 per page ▼



No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)		Thumbnail	Print
1	08/02/18 13:14	Sketch Plan	i	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18003452/TIVBS2

Date: 05/03/2018

REFERENCE

Insured/Claimant:	TOPSELLER PTE LTD	Policy No:	B29067387MKF	Claim No:	549197
Date of Loss:	07/02/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP2875Z	Engine No:	4P10C06064
Make & Model:	MAZDA3 CRDI 2.0 D (M)	Chassis No:	FEB21CA20036
Reg. Date:	01/06/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/85R15	Rear Tyre Size:	195/85R15 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	71,500.00	71,500.00	0.00	0.00
Miscellaneous Items	1,000.00	0.00	1,000.00	100.00
Labour	11,500.00	8,000.00	3,500.00	30.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	84,000.00	79,500.00	4,500.00	5.36
- Excess (S\$)	750.00	750.00	0.00	0.00
(S\$)	83,250.00	78,750.00	4,500.00	5.41
+ GST 7.00/7.00% (S\$)	5,827.50	5,512.50	315.00	5.41
Nett Amount (S\$)	89,077.50	84,262.50	4,815.00	5.41

INSPECTION

Date of Assignment:	22/02/2018	Present Location:	ComfortDelGro Engineering Pte Ltd (Pandan)
			ComfortDelGro Engineering Pte Ltd (Pandan)
Date Inspected:	23/02/2018	Inspected At:	45 Pandan Road
			Singapore 609286
Estimated Period of Repair:	0.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(EXCLUDE CHECK ITEMS S\$1,000.00 NETT)

TOTAL LOSS ASPECT

Market Value :	\$90,000.00
OMV :	\$45,344.00
PARF Rebate (1) :	\$0
Quota Premium Paid :	\$42,302.00
COE Rebate (2) :	\$34,990.00
Total Rebate (1) + (2) = :	\$34,990.00

The total amount incurred will be Market Value \$90,000.00 minus Total Rebate \$34,990.00 = \$55,010.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Reference

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ESTIMATE PARTS COST		65,000.00 F	*65,000.00 F
				Sub Total (\$)	65,000.00	65,000.00
			+ Margin on L,N Items 10.00/10.00% (\$)		6,500.00	6,500.00
				Total Parts (\$)	71,500.00	71,500.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	ESTIMATE COST (*Check)	1,000.00	0.00
Sub Total (\$\$)			1,000.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ESTIMATE LABOUR CHARGES	New	8,000.00	6,000.00
2	TO PUTTY,SPRAY PAINT : FRONT CABIN AMD REAR REAR BOX	New	3,500.00	2,000.00
Gross Labour Cost (\$\$)			11,500.00	8,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >