

ASS. REC. BY:

REF: CS/MSG18003456/T190302 Special Instruction:

SUNDAY

ASSIGNMENT (Office)

From (Person): Meinmen Irene Tan of MSIG Date/Time: 20/2/18 16:29

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKS 7722Z Insured: SLE 2482Kat Workshop m/s Cycle & carriage Automotive Tel: _____
of Pandan GardensPolicy No: 2879179QMY Claim No: 547377

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 24/11/2017
(Client's Record)CA / REV / REP. / REV 24 HRS ^{1wp} H.O.D. Endorsement: _____Date/Time: 21/2/18 Person Contacted: _____ Vehicle IN/OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/> Estimate
	SKS 7722Z -x
	SLE 2482K -x
06/3/18 @ 4.05pm	revised to Irene Tan via Meinmen.
	Final Hq @ 2885.13 (Red @ 1320, 31%)

CONCLUSION

From _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop No: _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured _____ Excess _____

(Client's Record)

Make of Vehl: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NS		OS	

Ball or Market Value:		
IDAC Accident Report:		Consistent? : Yes or No
GIA PR Seen:		Consistent? : Yes or No
Est. Repairs:	4 days	Res.: Yes or No
Sum Sur:	%	3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

en/12: SKS 7 7222 Date: 2015 Feb
 Type: ☒ Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover
 Truck / Trailer or
 Make: Mercedes Benz S400 :: 2996
 Colour: Maroon A/C Insured / Std / Nil / NA
 Self-Driving: 3221L - Pass Insured / Std / Nil / NA
 Eng No: WPD 221652 A139548
 C No: 8
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim
 Tyre Size: F: 245/45R19 R: 7 ~
 BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI
 TOYO / YOKO or

Front 6 mm R.Bal. 6 mm L.Bal. 6 mm D.O.A. 5/3/18 @ 1555

Survey held at: MS C&C Pardon Lungs

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date	Time	Action	Instruction
------	------	--------	-------------

SKV 181 P. Norway

RECEIVED 26 APR 2018

☐ Prelim. Report☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

100

1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 2674, 2675, 2676, 2677, 2678, 2679, 2680, 26

122

Add Fee:

[illegible]

— 22 —

1998, 1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 2674, 2675, 2676, 2677, 2678, 2679, 26

1998, 1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 2674, 2675, 2676, 2677, 2678, 2679, 26

Page 3 of 12

MER-TP

2885.13

200

10

210




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18003456/Sqd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 23-02-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLE 2482K	Veh. Inspected	SKS 7722Z	
Policy No.	28791796QMY	Coverage (\$)	0.00	
Claim No.	547377	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAN)	Assign Date	23/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/11/2017	Inspection Date		
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jan 2018		20 Feb 2018 16:29 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS [Created by insurer]				
Insured:	Hee Kim Simon, ID: S7770097H			
Main Claimant:	OUE LIMITED, Co. Reg. No.: 196400050E			
Vehicle Reg. No.:	SKS7722Z	Date of Loss:	24/11/2017 00:00 - :59	
Claim Type:	TP / 547377	Policy/Cover Note No.:	28791796QMY Coverage: 14/07/2017 - 13/07/2018	
Vehicle Reg. No. (Insured):	SLE2482K	Policy No. (Claimant):		
		Excess:		
Repairer:	Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ) 209 PANDAN GARDENS, 609339 West Coast - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/02/2018]			
ASSOCIATED MAIL RECEIVED View All Compose Case Mail				
There are no mail for this case.				
<div> <div> <div>ALL ASSOCIATED TASKS</div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div> </div> <div> <div>Due Date</div> <div>Priority</div> <div>Type</div> <div>Task Group</div> <div>Subject</div> <div>Handler</div> <div>Assigned By</div> <div>Completed On</div> <div>Created On</div> <div>Done?</div> </div> </div>				
No results.				

NO ANSWER

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 06 Mar 2018

Preliminary Advice

Insured Vehicle No	: SLE2482K	Accident Date	: 24/11/2017
TP Vehicle No	: SKS7722Z	Assignment Date	: 20/02/2018
Make	: MERCEDES-BENZ S400L	Est. Duration of Repair	: 4.00
Date of Inspection	: 05/03/2018		
Inspection At	: CYCLE & CARRIAGE FRANCE PTE LTD (PANDAN GARDENS) (HQ) 209 PANDAN GARDENS SINGAPORE 609339		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,205.13
Revised Amount	:S\$	2,885.13
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,885.13

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/12/2017 10:32
Date Of Accident	24/11/2017 00:40
Exact Location Of Accident	ORCHARD ROAD (MANDARIN HOTEL CP DECK 2 LOT A52)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS7722Z
Insured/Policyholder	
Name Of Registered Owner	OUE LIMITED
Co Reg No	196400050E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90686820

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	S400L

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100401509-02000
Cover Note Number	

Driver

Name of Driver	SEBASTIAN LIM HONG MENG
NRIC No	S7222482E
Date Of Birth	27/06/1972
Occupation	INDOOR
Date Of Driving Pass	24/07/1993
Driving Experience	24 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96623637
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 50 COLLYER QUAY #18-01/02
 OUE BAYFRONT
 Postcode 049321
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name ORCHARD NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 51 KILLINEY ROAD , POSTCODE: 239572 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-7359999 - FAX NO: 67331934
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REPORT NO: T/20171124/2144

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: REFER KO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLE2482K
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

A circular logo with the text "QUEENSLAND UNITED" around the top inner edge and "SINGAPORE" in the center.

Personnel KERLYN

[illegible]

Sketch Plan #2

Describe Circumstances of the Accident

REFER TO POLICE REPORT NO. T/20171124/2144

Declaration

I/We declare for foregoing particulars are true in every respect.

Please note that you have 14 calender days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.


(Please contact your insurance company for any further details)



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time 21/12/2017 1013

Kerlyn Ong Kai Li
DID : 6771 4420 HP : 9186 5113
Email : kerlyn.ong@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop
Witnessed by Reporting Centre
Personnel KERLYN



CERTIFICATE OF INSURANCE

MOTORVE TEL: (65) 6470 8000
FAX: (65) 6475 3723

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.4

MERCEDES-BENZ MOTOR INSURANCE

CERTIFICATE NO. 2100461509-02000

OWN DAMAGE EXCESS \$52000.00 (1)
WINDSCREEN EXCESS \$5100.00

(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PARF Yes

1) VEHICLE REGISTRATION NO.

SKS7722Z

2) NAME OF INSURED

OK B Limited

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

4 Feb 2017

4) DATE OF EXPIRY OF INSURANCE

7 Feb 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION : All Age Condition

Any person who is driving on the Insured's order or with their permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of \$51,000.00, in addition to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 21 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and not for the Insured's business. The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial, speed-testing the carriage or goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES - MERCEDES-BENZ AUTHORISED REPAIRERS

1. Cycle & Carriage Pandan Loop Service Center - 102 Pandan Loop (Tel: 6777 4388)

APPROVED REPORTING CENTRES - AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. Concorde Deloro Energy - 205 Braddell Rd (Tel: 63837118) 3. Jishou - 30 Bukit Batok Crestview 5477777

4. Glass Fix - 52 Loh Ave 2 (Tel: 62780847) - For windscreen only 5. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479566)

6. Lar Huet (Mong Kee) Motor - 21 Sun Mang Road (Tel: 64538174) 7. Nura Automotive - 1008 Bukit Merah Lane 1 (Tel: 62723892)

8. Progressive Automotive - 3622A Loh Rd 1 (Tel: 67455765) 9. SMI Motor - 1 Kaki Bukit Ave 6 Bld D (Tel: 67476100)

LOSS OF USE 15 Days Replacement Car only for repairs at C&C - Refer to policy wordings for details

NAMED DRIVER NA

HIRE PURCHASE COMPANY NA

EMPLOYER'S LOAN

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 17 Jan 2017

AIG Asia Pacific Insurance Pte. Ltd.

50660-454
CYCLE & CARRIAGE - KLEPP
2/9 ALEXANDRA ROAD
SINGAPORE 159936
ANSP-MOTOR

AUTHORISED REPRESENTATIVE

17 Jan 2017 15:00:00

Accident Sketch Plan

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S7222482E**

Name: **SEBASTIAN LIM HONG MENG**
(SEBASTIAN LIN HONGMING)

Date of Birth: **27 JUL 1972**

Valid Until: **22 JUL 2003**

100067573131

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE
IDENTITY CARD NO: **S7222482E**



SEBASTIAN LIM HONG MENG
(SEBASTIAN LIN HONGMING)

CHINESE

27-06-1972 M

SINGAPORE

FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

24 Jul 1993



S7222482E



O+

09-03-1996

NP 4204



License No: **S7222482E**

APT BLK 842 TAMPINES ST 82-002-163
SINGAPORE 520842

NRIC No: **S7222482E**

Date: 17-08-2000 (R) Age: 28 years

Sketch Plan #3



**SINGAPORE
POLICE FORCE**



T/20171124/2144

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

1 of 3

Report No: T/20171124/2144

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/11/2017 19:42		Vide Report No.:		Station Diary No.: 147	
Informant's Particulars					
Name of Informant: SEBASTIAN LIM HONG MENG			Address: APT BLK 842 TAMPINES ST 82 #02-163 SINGAPORE 520842		
ID Type / ID No.: NRIC NO / S7222482E			Contact No.: Home/Office: Mobile: 96623637		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 45	Date of Birth: 27/06/1972	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: CHAUFFEUR			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 24/11/2017 00:40	Type of Location: Car Park
Location: Along Road 1 ORCHARD ROAD MANDARIN HOTEL CARPARK, DECK 2, LOT NO. A52				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SKS7722Z	Car				Slightly Damaged	0
SLE2482K	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Sketch Plan #4



**SINGAPORE
POLICE FORCE**



T/20171124/2144

2 of 3

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

Report No: T/20171124/2144

CONTINUATION OF REPORT

Driver			
Name	SEBASTIAN LIM HONG MENG	ID No.	S7222482E
Related Vehicle	SKS7722Z (Car)	Contact No.	96623637
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 23/11/2017 at about 10.55p.m., I parked my company car SKS7722Z at Mandarin Hotel, Deck 2, Reserved Lot No. A52. On the 24/11/2017 at about 8.40a.m., I returned to the said car and discovered that there were scratches on the front grille, front car license plate number and front left bumper. There were no such damages on the car when I left it parked the night before.

I approached the security department of Mandarin Hotel and the Security Manager, Andy informed that CCTV focusing at the incident location captured that at about 12.40a.m., a vehicle SLE2482K had drove in front of my parked company car and as it was approaching the exit of the car park which was nearby, it hit my car with its left side. The driver male stopped his car momentarily and the front left female passenger opened her door to take a peek before driving off and leaving the car park.

The driver did not report the accident to Mandarin Hotel. I wish for Police to investigate into the matter.

Sketch Plan #5



SINGAPORE
POLICE FORCE

Police Station Of Origin
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999



T/20171124/2144

3 of 3

Report No. T/20171124/2144

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report
E /
Staff Sgt KAMISAH BINTE HANAFI

Signature Of Informant

Signature Of Interpreter:
Not applicable

Date/Time:
24/11/2017 19:42

Officer In Charge Of Case:
TP / HRT /
Sr Staff Sgt ESTHER CHONG
Contact No.: 65476368

Classification Of Case:

Authentication Stamp
NP168

214 172



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKS7722Z

Oue Limited

50 Collyer Quay
#18-01/02 Oue Bayfront
Singapore 049321

68096004Renne

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

Vehicle & Document Information

19092

SKS7722Z / 04/02/2015

/ 0

WDD2221652A139548

27682430147901

MB/S 400 L BlueEFFICIENCY SE

028 897 Ruby Black / 048 814 Leather Cap

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WCV18207	CRDVCH	24/01/2018/ 12:45	K0	301 / Kerlyn Ong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S BPNSUB								60.00
SUPPLY 1 SET NUMBER PLATE WITH HOUSING.NETT								960 1920.00
PURCHASE ORDER NO:								600 960.00
A BPILAB								480.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.								
A BPIRES								
RESPRAY FRONT BUMPER								
A BPILAB								
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO					1.00	718.60	00.00	718.60
IDENTIFICATION STANDARD. NETT					1.00	66.53	00.00	66.53
M RADIATOR GRILLE								
M RADIATOR GRILLE SEAL								

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kerlyn Ong Kai Li

DID: 6771 4420 HP: 9186 5113

Email: kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Taufik 97445749
5/3/18 @ 1555
4 days 'wp'
surv lkkauto.com
* Resurvey new part
Resurvey after repair

[Signature]
4/3/18

Confirmed & accepted by

	Nett	4,205.13
7% GST on	4205.13	294.36
Total Payable		4,499.49

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

TAX INVOICE

Invoice Name & Address		Owner Name & Vehicle Info	
MSIG INSURANCE (S'PORE) PTE LTD		Cust No/Name	WCV18207/0UE Limited
MOTOR CLAIM DEPARTMENT		Reg No/Reg Date	SKS7722Z / 04/02/2015
16 RAFFLES QUAY #24-01		Date In/Mileage	05/03/2018/ 36216
HONG LEONG BUILDING		Chassis No	WDD2221652A139548
SINGAPORE 048581		Engine No	27682430147901
Contact No 66431303		Make/Model	MB/S 400 L BlueEFFICIENCY SE
		Colour/Trim	028 897 Ruby Black / 048 814 Leather Cap



Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
WI000558	Credit	15/03/2018/ 16:09	YK	395 / Yik Chan Hoe	19092	28140437

Description of Goods / Services	Qty	Unit Price S\$	Amount S\$
M BPNSUN			F.O.C.
POLICY NO/ACC DATE : 2100401509-02000 // 24/12/2017			
DRIVE IN/TP VEH NO. : 24/12/2017 // SLE2482K - MSIG			
DATE IN/DATE SURVEY: 05/03/2018 @ 1600 // TAUFIKH LKK			
BY/AUTHORIZED ON : DIRECT SETTLEMENT // IRENE TAN MSIG			960.00
A BPILAB			
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.			600.00
A BPIRES			
RESpray FRONT BUMPER			480.00
A BPILAB			
USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			60.00
S BPNSUB			
SUPPLY 1 PC NO PLATE			
DN: 7019	1.00	718.60	718.60
X RADIATOR GRILLE	1.00	66.53	66.53
X RADIATOR GRILLE SEAL			

Finalization

Parts	785.13	Nett	2,885.13
Labour	2,040.00	7% GST on	2885.13
Standard Menu	0.00		
Specialist Job	60.00	Total Payable	3,087.09
Diagnostics Job	0.00	Paid	0.00
Sundry/Others	0.00	Total Due	3,087.09
Total(w/o GST)	2,885.13		

Payment should be made strictly by cash, NETS or credit cards. Thank you.
Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jan 2018		20 Feb 2018 16:29 Edit Adj Rpt	S\$2,885.13 Edit Estimates	S\$2,885.13 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Hee Kim Simon , ID: S7770097H								
Main Claimant:	QUE LIMITED , Co. Reg. No.: 196400050E								
Vehicle Reg. No.:	SKS7722Z	Date of Loss:	24/11/2017 00:00 - :59 [33 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 547377	Policy/Cover Note No.:	28791796QMY Coverage: 14/07/2017 - 13/07/2018						
Vehicle Reg. No. (Insured):	SLE2482K	Policy No. (Claimant):							
		Excess:							
Repairer:	Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ) 209 PANDAN GARDENS, 609339 West Coast - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 22/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKS7722Z (547377)**
[SLE2482K]
TP
QUE LIMITED
Nov 24 2017 12:00AM
[Hee Kim Simon]
Cycle & Carriage France Pte Ltd (Pandan Gardens)

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/03/18 16:05	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/04/18 09:52	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	26/04/18 09:52	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	26/04/18 09:52	General View	Load JPG	<input checked="" type="checkbox"/>
4	26/04/18 09:52	General View	Load JPG	<input checked="" type="checkbox"/>
5	26/04/18 09:52	General View	Load JPG	<input checked="" type="checkbox"/>
6	26/04/18 09:52	General View	Load JPG	<input checked="" type="checkbox"/>
7	26/04/18 09:52	General View	Load JPG	<input checked="" type="checkbox"/>
8	26/04/18 09:52	General View	Load JPG	<input checked="" type="checkbox"/>
9	26/04/18 09:52	General View	Load JPG	<input checked="" type="checkbox"/>
10	26/04/18 09:52	General View	Load JPG	<input checked="" type="checkbox"/>
11	26/04/18 09:52	General View	Load JPG	<input checked="" type="checkbox"/>
12	26/04/18 09:52	General View	Load JPG	<input checked="" type="checkbox"/>
13	26/04/18 09:52	General View	Load JPG	<input checked="" type="checkbox"/>
14	26/04/18 09:52	General View	Load JPG	<input checked="" type="checkbox"/>
15	26/04/18 09:52	General View	Load JPG	<input checked="" type="checkbox"/>
16	26/04/18 09:52	General View	Load JPG	<input checked="" type="checkbox"/>
17	26/04/18 09:52	General View	Load JPG	<input checked="" type="checkbox"/>
18	26/04/18 09:52	General View	Load JPG	<input checked="" type="checkbox"/>
19	26/04/18 09:52	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/01/18 15:59	TP PRI with Estimates and GIA report	Load PDF	
2	25/01/18 11:42	TP PRI Request	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003456/T1QD3E2
Date: 26/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 28791796QMY
Claimant Vehicle No: SKS7722Z Insured Vehicle No: SLE2482K
Date of Loss: 24/11/2017 Nature of Claim: TP Claim No: 547377

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKS7722Z Engine No: 27682430147901
Make & Model: MERCEDES-BENZ S400L, 3.0 R19 LED (A) Chassis No: WDD2221652A139548
Reg. Date: 04/02/2015 (Man. Year: 2014) Odometer: 36216 km
Colour: Maroon
Engine Capacity: 2996 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R19 Rear Tyre Size: 245/45 R19
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	845.13	845.13	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,360.00	2,040.00	1,320.00	39.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,205.13	2,885.13	1,320.00	31.39
+ GST 7.00/7.00% (S\$)	294.36	201.96	92.40	31.39
Nett Amount (S\$)	4,499.49	3,087.09	1,412.40	31.39

INSPECTION

Date of Assignment: 20/02/2018
Date Inspected: 05/03/2018 Inspected At: Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ)
209 PANDAN GARDENS
Singapore 609339

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Apr 2018)
Parts: 143 MERCEDES-BENZ S400L 3.0 R19 LED (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKS7722Z)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET NUMBER PLATE WITH HOUSING	Bent	60.00 FS	*60.00 FS
2	1		*RADIATOR GRILLE	Cut	718.60 FS	*718.60 FS
3	1		*RADIATOR GRILLE SEAL	Necessary	66.53 FS	*66.53 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					845.13	845.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	1,920.00	960.00
2	RESPRAY FRONT BUMPER	New	960.00	600.00
3	USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	480.00	480.00
Gross Labour Cost (S\$)			3,360.00	2,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >