

A.S. REC. BY:

REF: (83) CT118003457 M1622

Special Instruction:

Surveyor MA ASSIGNMENT (Office)From (Person): Joel Goh of CTI Date/Time: 20/2/18

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLN 5429Z Insured: 86Y4275Mat Workshop m/s Edwin Garage Tel: 97856612of BK5032 AMK # 01-295Policy No: DMPCSN3071151700 Claim No: SNM18D00863202

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 10/2/18
(Client's Record)**CA / REV / REP. / REV 24 HRS**

H.O.D. Endorsement: _____

Date/Time: 21/2 Person Contacted: _____ Vehicle IN / OUT

Date/Time	Action/Instruction (x) Estimate
	<u>SLN 5429Z-X</u>
	<u>86Y4275M-X.</u>
	<u>Dismantle: 26/2/2018</u>

REF:

CTL

ASSIGNMENT

From _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s

EDWIN GARAGE.

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SN5492 Vn Regn: 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA VEEZELC/O: 11496Colour: white

A/O: Insured / Std / NI / NA

Sp. Reading: 17728

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2431236738Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim or

Tyre Size

F: 225/45/18R: 2BS / DUN / EXNOVA / GY / FS / LIZA / MG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 7 mmR/Bal: 7 mmL/Bal: 7 mmL/Bal: 7 mm

D.O.A: _____

D.O.I: 26/2/2018

Survey held at: _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

No document upon survey.

* Repair Estimate : S\$ 7000 - 8000

* 4 days

RECEIVED 21 JUN 2018

Date/Time File Pass to?

☐

Preli. Report

To

☐

Final Report

Date/Time File Return to?

By

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee

Transcription

S - R - S

Photo

Diary

TOTAL

150

Add Fee:

☐

Site Insp IS

☐

Interview IS

☐

Tech Insp IS

☐

Weekend IS

Report Format /

Lump Sum / I.B.I: IS

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Feb 2018		20 Feb 2018 16:59 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TANG DEHAI, ID: S2734873D		
Main Claimant:	SKIES, Co. Reg. No.: 53335416A		
Vehicle Reg. No.:	SLN5429Z	Date of Loss:	10/02/2018 00:00 - :59
Claim Type:	TP / SNM18D00863C02	Policy/Cover Note No.:	DMPCSN3071151700
Vehicle Reg. No. (Insured):	SGY4275H	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Edwin Garage Automotive Pte Ltd (HQ) 5032 #01-295, Ang Mo Kio Industrial Park 2, 569535 Ang Mo Kio - Tel: 9785 6612		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/03/2018]		
Adj Asg. Remarks:	PLEASE SURVEY THIRD PARTY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR.		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

☐ **ALL ASSOCIATED TASKS** View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire Transfer Fee

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLN5429Z		
Vehicle Type :	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	VEZEL 1.5X HYBRID A		
Chassis No. :	RU31236738		
Propellant :	Petrol-Electric		
Engine No. :	LEB5936750		
Motor No. :	H12343843		
Engine Capacity :	1496 cc		
Power Rating :	22.0 kW		
Maximum Power Output :	112.0 kW (150 bhp)		
Maximum Laden Weight :	1555 kg		
Unladen Weight :	1280 kg		
Year Of Manufacture :	2017		
Original Registration Date :	08 May 2017		
Lifespan Expiry Date :	-		
COE Category :	B - Car above 1600cc or 97kW (130bhp)		
Quota Premium :	\$54,406.00		
COE Expiry Date :	07 May 2027		
Road Tax Expiry Date :	07 May 2018		
PARF Eligibility Expiry Date :	07 May 2027		
Inspection Due Date :	07 May 2020		
Intended Transfer Date :	02 May 2018		
CO2 Emission :	94.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$24,282.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 07 May 2018. You may renew the road tax from 08 Feb 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 07 May 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 08 May 2018 to 07 Nov 2018)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	5416A
Vehicle Details	
Vehicle No.:	SLN5429Z
Vehicle to be Exported:	No
Intended De-registration Date:	02 May 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X HYBRID A
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	LEB5936750
Chassis No.:	RU31236738
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$26,630.00
Original Registration Date:	08 May 2017
First Registration Date:	08 May 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 May 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	07 May 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,406.00
COE Rebate Amount:	\$49,038.00
Total Rebate Amount:	\$52,788.00

The information contained herein is correct as at 02 May 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/02/2018 12:21
Date Of Accident	09/02/2018 00:00
Exact Location Of Accident	TOA PAYOH LORONG 1/ TOA PAYOH NORTH JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN5429Z
Insured/Policyholder	
Name Of Registered Owner	SKIES
Co Reg No	53335416A
Email Address	MARCTANY@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92727752
Alternative Phone No	OFFICE-92727752

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL HYBRID
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5090620620
Cover Note Number	

Driver

Name of Driver	TAN YE YING (CHEN YIXING)
NRIC No	S8631682Z
Date Of Birth	17/10/1986
Occupation	INDOOR
Date Of Driving Pass	22/12/2011
Driving Experience	6 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-92727752
Fax Number	
Contact Number	
Email Address	MARCTANY@GMAIL.COM

Address	BLK 537 SERANGOON NORTH AVE 4 #08-145
Postcode	550537
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	HOUGANG N.P.C
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO : POLICE REPORT NO : T/20180210/2036

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGY4275H
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TANG DEHAI
NRIC/Passport Number	S2734873D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have Insured vehicle(s) involved in this accident (all Insurer(s) who have Insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have Insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report: J120180210/2036

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:




...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Feb 2018		20 Feb 2018 16:59 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TANG DEHAI , ID: S2734873D									
Main Claimant: SKIES , Co. Reg. No.: 53335416A									
Vehicle Reg. No.: SLN5429Z		Date of Loss: 10/02/2018 00:00 - :59 [9 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D00863C02		Policy/Cover Note No.: DMPCSN3071151700							
Vehicle Reg. No. (Insured): SGY4275H		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Edwin Garage Automotive Pte Ltd (HQ) 5032 #01-295, Ang Mo Kio Industrial Park 2, 569535 Ang Mo Kio - Tel: 9785 6612									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 01/03/2018]									
Adj Asg. Remarks: PLEASE SURVEY THIRD PARTY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLN5429Z (SNM18D00863C02)**
[SGY4275H]
TP
SKIES
Feb 10 2018 12:00AM
[TANG DEHAI]
Edwin Garage Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser <input type="button" value="v"/>	
Photos/Images			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/05/18 12:51	General View	 Load PDF	
2	02/05/18 12:51	Photographs of Damaged Parts	 Load PDF	
Documentation			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/02/18 17:01	THIRD PARTY SLN5429Z -FROM CHIA S ARUL -PRS LTR	 Load PDF	
2	20/02/18 17:01	THIRD PARTY SAS REPORT SLN5429Z	 Load PDF	
3	20/02/18 17:11	INSURED SAS REPORT SGY4275H	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div><div></div><div>^</div><div>v</div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118003457/M1BE2

Date: 27/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3071151700

Claimant Vehicle
No : SLN5429ZInsured Vehicle
No : SGY4275H

Date of Loss: 10/02/2018

Nature of Claim: TP

Claim
No: SNM18D00863C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLN5429Z

Make & Model: HONDA VEZEL, 1.5 HYBRID (A)

Engine No: LEB5936750

Reg. Date: 08/05/2017 (Man. Year: 2017)

Chassis No: RU31236738

Colour: White

Odometer: 17728 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/02/2018

Date Inspected: 26/02/2018 Inspected At:

Edwin Garage Automotive Pte Ltd (HQ)
5032 #01-295, Ang Mo Kio Industrial Park
2
Singapore 569535

Estimated Period of Repair: 4.0 days

Adjuster: MA CHIN FOOK

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 -\$8,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Jun 2018)

Parts: M1-SUV HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLN5429Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >