

ASS. REC. BY:

REF:

CS/MS618003464/Uqb72

Special Instruction:

Surveyor

**ASSIGNMENT (Office)**

From (Person): Katherine Wong of MSIA Date/Time: 22/2/2018

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No: XB 8506K Insured: RJN 3393D

at Workshop m/s V8ix Auto Tel: 96890102 / 6855 2957

of 60 Kaki Bukit Ave 6 #

Policy No: 399559400MA Claim No: 550768

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 21/2/18  
(Client's Record)

26/2/2018 10am

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 23/2 Person Contacted: Irene Vehicle IN/OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	<u>XB 8506K - X</u>
	<u>RJN 3393D - X</u>
	<u>79/7/18 @ 9pm revised to Katherine Wong via Meinman.</u>

REF MS19

ASSIGNMENT

Date 26/2/18

Vehicle XB806K #12

Vehicle No: XB 8506 K  
Licence: Vfix Auto  
Address: 60 Kaki Bkt Ave 6  
Time: 10am

Make: VOLVO  
Color: white  
Registration: 537557  
VIN: YV2J1E1D0CA732634  
Tyre Size: 315/80R22.5

NS	CS

BS/DUN/EXNOVA/GR/RS LZA/MID/O-TS/PR/SUM  
TOYO/YOKO: Sunfull  
Front: 6  
Rear: 6  
L-Br: 6  
D-Br: 21/2/18  
Spare: 26/2/18

Estimate: 2 days  
Cost: 20  
24hrs work

MS 19

22/3/18 4/5 #1500 conf. and with her.  
(Used 6 5356, 78%)

Signature  
27/3/2018

RECEIVED 20 MAR 2018

Final Report  
1500

Days of Repair: 2  
Spare Fee: 200  
10  
210



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD Ref : CS/MSG18003464/Uqb

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 23-02-2018



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJN 3393D	Veh. Inspected	XB 8506K
Policy No.	39955940DMA	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	KATHERINE WONG (MERIMEN)	Assign Date	22/02/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c
Engine No.	Year of Reg.
Chassis No.	Colour
Odometer	Steering
Brakes	Modification
General	

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	21/02/2018	Inspection Date
Survey held at		

## 5a. Remarks

--

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Feb 2018		22 Feb 2018 10:55 <a href="#">Assign</a>				<a href="#">New Assignment</a> <a href="#">Cancel Case</a>

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

<b>Insured:</b>	DESMOND CHEW CHEE HAN, ID: S7677548F		
<b>Main Claimant:</b>	Express Transport Services & Construction Pte Ltd, Co. Reg. No.: 199506970Z		
<b>Vehicle Reg. No.:</b>	XB8506K	<b>Date of Loss:</b>	21/02/2018 08:00 - :59
<b>Claim Type:</b>	TP	<b>Policy/Cover Note No.:</b>	39955940DMA Coverage: 12/02/2018 - 11/02/2019
<b>Vehicle Reg. No. (Insured):</b>	SJN3393D	<b>Policy No. (Claimant):</b>	
		<b>Excess:</b>	
<b>Repairer:</b>	Vfix Auto Service Pte Ltd (HQ) 60 Kaki Bukit Ave 6, ARK@KB, 417892 Kaki Bukit - Tel: 96890102		
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/02/2018]		
<b>Driver/Custodian (Insured):</b>	LEE HUI HUANG (), NRIC: S7281741I		
<b>Adj Asg. Remarks:</b>	Please assign to Mr Marcus Chua. Thank you.		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 27 Feb 2018

**Preliminary Advice**

Insured Vehicle No	: SJN3393D	Accident Date	: 21/02/2018
TP Vehicle No	: XB8506K	Assignment Date	: 22/02/2018
Make	: VOLVO FMX37064R	Est. Duration of Repair	: 2.00
Date of Inspection	: 26/02/2018		
Inspection At	: VFIX AUTO SERVICE PTE LTD (HQ) 60 KAKI BUKIT AVE 6, ARK@KB SINGAPORE 417892		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:SS	6,856.00
Revised Amount	:SS	1,903.20
Check Items (Estimated)	:SS	0.00
Total	:SS	1,903.20
Lump Sum Repair	:SS	

**Total Loss Consideration**

New for Old Value	:SS
Pre-Accident Value	:SS
COE / PARF Rebate	:SS
Salvage Value	:SS
Margin for Repair	:SS

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6970Z
Vehicle Details	
Vehicle No.:	XB8506K
Vehicle to be Exported:	No
Intended De-registration Date:	26 Feb 2018
Vehicle Make:	VOLVO
Vehicle Model:	FMX370 64R SLEEPER CAB
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	D11261664
Chassis No.:	YV2J1E1D0CA732634
Maximum Power Output:	-
Open Market Value:	\$107,326.00
Original Registration Date:	24 Aug 2012
First Registration Date:	24 Aug 2012
Transfer Count:	0
Actual ARF Paid:	\$5,367.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Aug 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$55,805.00
COE Rebate Amount:	\$25,067.00
<b>Total Rebate Amount:</b>	<b>\$25,067.00</b>

The information contained herein is correct as at 26 Feb 2018.

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/02/2018 12:20
Date Of Accident	21/02/2018 08:35
Exact Location Of Accident	AIRPORT ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XB8506K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	EXPRESS TRANSPORT SERVICES & CONSTRUCTION PTE LTD
Co Reg No	199506970Z
Email Address	KINHOE.NG@KTCGROUP.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64874646
<b>Vehicle Particulars</b>	
Manufacturer	VOLVO
Model	FMX37064R-10.8 D SLEEPER CAB (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
<b>Insurance Company</b>	
Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2017-V0089141-VCV-R005
Cover Note Number	24/08/2017 TO 23/08/2018
<b>Driver</b>	
Name of Driver	TAN NAM HUAT
NRIC No	S1162501J
Date Of Birth	18/07/1956
Occupation	OUTDOOR
Date Of Driving Pass	20/05/1980
Driving Experience	37 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91870032
Fax Number	
Contact Number	OFFICE-64874646
EEmail Address	NOEMAIL

Address APT BLK 312 SEMBAWANG DRIVE #05-490 (S) 750312  
 Postcode  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - CHANGE/CROSS LANE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes,Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes,against whom?

**Circumstances of Accident**

on 21/02/2018 at about 0835am,i was driving along airport road. While I was travelling on my lane, vehicle B (SJN3393D) suddenly cut into my lane and collided on to my truck.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SJN3393D  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

# Accident Sketch Plan Pg. 1

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:




Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

21/2/2018

Accident Sketch Plan Pg. 1

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 21/02/2018 at about 0835am, I was driving along Airport Road. While I was travelling on my lane, vehicle B (SJN 3393D) suddenly cut into my lane and collided on to my truck.


Insurance Co.	Grant Eastern General
Vehicle No.	XB8506K of Accident 21/2/2018
<input type="checkbox"/>	Reporting Only
<input type="checkbox"/>	Own Damage Claims
<input checked="" type="checkbox"/>	Third Party Claims
<input checked="" type="checkbox"/>	Other Workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect.


  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:


  
 Reporting Centre Person's Signature  
 Name:  
 NRIC/FIN No:

GEORGE S. D. P. S. and Co., M

MSIG INS S'PORE PTE LTD  
 16 RAFFLES QUAY  
 #24-01 HONG LEONG BUILDING  
 SINGAPORE 048581

**Attention: Motor Claim Department**  
**RE : VEHICLE NO XB8506K VOLVO FMX370**

*rest of repair  
 all  
 2/5 \$1500/2  
 2 pty.  
 26/2/18  
 to height. After repair*

**ESTIMATE**  
 DATE : 21/02/2018  
 ACC DATE : 21/02/2018  
 REF NO. : VFIX-TP20180432  
 POLICY NO :

DESCRIPTION	AMOUNT S\$
1 1 HEADLAMP HOUSING LH	17 385.00 ✓
2 1 FRONT BUMPER LH	gamb 470.00 ✓
3 1 FRONT BUMPER END GARNISH NO1	tu, 128.00 ✓
4 1 FRONT BUMPER END GARNISH NO2	17 128.00 ✓
5 1 STEP BOARD GARNISH LH	17 480.00 ✓
6 1 STEP BOARD LH	17 680.00 ✓
7 1 MUDGUARD REAR LH	to. 850.00 ✓
8 1 MUDGUARD BRACKET REAR LH	17 285.00 ✓
	\$ 3,406.00

*102*

DESCRIPTION	SPECIAL NETT	AMOUNT S\$
1 1 TYRE 315/80/22.5		17 285.00 ✓
2 1 SIDE GUARD LH		17 850.00 ✓
3 3 WHEEL STUB BOLT	55.00	17 165.00 ✓
		\$ 1,300.00

LABOUR & MISCELLANEOUS:	AMOUNT S\$
1 To remove damaged parts with all necessary components/attachments apply hot-works where necessary replace new parts refit align into position with all necessary components attachments <b>attachmets</b>	300 1,000.00
2 To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	300 1,000.00
3 To remove,replace front wheel stub bolt	17 \$ 150.00
	\$ 2,150.00

**GRAND TOTAL : \$ 6,856.00**

SINGAPORE DOLLARS : SIX THOUSAND EIGHT HUNDRED & FIFTY SIX ONLY

Vfix Auto Service Pte Ltd



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003464/UQBN2

Date: 29/03/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: P39955940DMA  
 Claimant: XB8506K Insured Vehicle No: SJN3393D  
 Vehicle No: XB8506K Nature of Claim: TP Claim No: 550268  
 Date of Loss: 21/02/2018

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XB8506K Engine No: D11261664  
 Make & Model: VOLVO FMX37064R, 10.8 D SLEEPER CAB (M) Chassis No: YV2J1E1D0CA732634  
 Reg. Date: 24/08/2012 (Man. Year: 2012) Odometer: 537557 km  
 Colour: White  
 Engine Capacity: 10837 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 315/80 R22.5 Rear Tyre Size: 315/80 R22.5 (D/D)  
 Front Left Side: SUNFULL 6 mm Rear Left Side: SUNFULL 6/6/6 mm  
 Front Right Side: SUNFULL 6 mm Rear Right Side: SUNFULL 6/6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,706.00	1,303.20	3,402.80	72.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	600.00	1,550.00	72.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,856.00</b>	<b>1,903.20</b>	<b>4,952.80</b>	<b>72.24</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,500.00</b>		
(S\$)	6,856.00	1,500.00	5,356.00	78.12
+ GST 7.00/7.00% (S\$)	479.92	105.00	374.92	78.12
<b>Nett Amount (S\$)</b>	<b>7,335.92</b>	<b>1,605.00</b>	<b>5,730.92</b>	<b>78.12</b>

INSPECTION

Date of Assignment: 22/02/2018  
 Date Inspected: 26/02/2018 Inspected At: Vfix Auto Service Pte Ltd (HQ)  
 60 Kaki Bukit Ave 6, ARK@KB  
 Singapore 417892

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 29 Mar 2018)	
<b>Parts:</b>	N/A	VOLVO FMX37064R 10.8 D SLEEPER CAB (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for XB8506K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP HOUSING LH	Not Necessary	385.00 F	*- FL
2	1		*FRONT BUMPER LH	Grazed	470.00 F	*470.00 FL
3	1		*FRONT BUMPER END GARNISH NO1	Twisted	128.00 F	*128.00 FL
4	1		*FRONT BUMPER END GARNISH NO2	Not Necessary	128.00 F	*- FL
5	1		*STEP BOARD GARNISH LH	Not Necessary	480.00 F	*- FL
6	1		*STEP BOARD LH	Not Necessary	680.00 F	*- FL
7	1		*MUDGUARD REAR LH	Torn	850.00 F	*850.00 FL
8	1		*MUDGUARD BRACKET REAR LH	Not Necessary	285.00 F	*- FL
9	1		*TYRE 315/80/22.5	Not Necessary	285.00 FS	*- FS
10	1		*SIDE GUARD LH	Not Necessary	850.00 FS	*- FS
11	3		*WHEEL STUB BOLT	Not Necessary	165.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,706.00</b>	<b>1,448.00</b>
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	144.80
<b>Total Parts (\$\$)</b>	<b>4,706.00</b>	<b>1,303.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE DAMAGED PARTS WITH ALL NECESSARY COMPONENTS/ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY REPLACE NEW PARTS REFIT ALIGN INTO POSITION WITH ALL NECESSARY COMPONENTS ATTACHMENTS	New	1,000.00	300.00
2	TO SPRAY PAINT REPLACED/REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	1,000.00	300.00
3	TO REMOVE,REPLACE FRONT WHEEL STUD BOLT	New	150.00	-
<b>Gross Labour Cost (\$\$)</b>			<b>2,150.00</b>	<b>600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >