

22/03/2018

ASS. REC. BY:

REF: CS3 / AIG 18003476 / SD3/02

DAR & days

Original Instruction:

Surveyor: Sebastian

ASSIGNMENT (Office)

From (Person): Chin lee Ying

of

AIG

Date/Time: 22/2/18 @ 1.54pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKC 5224S

Insured:

SLH 1558S

at Workshop m/s

Hendon Automotive

Tel:

9459 2885

of 280 woodlands Ind. Prk E5 # 01-19

Policy No:

Claim No:

264641582586

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 21/02/2018

CA / REV / REP. / REV 24 HRS

1wp

H.O.D. Endorsement:

Date/Time: 11:02am 23/2/18

Person Contacted:

Lynn

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	SKC 5224S - X
	SLH 1558S - X

REF: RIG

Ismaail

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Est. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time | Action / Instruction

20/10 Submit DAR report.

Veh No: SKCS2245

Yr Regn: 6/9/2011

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: BMW 318i

CC 1715

Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 154125

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAPI 2050F970294

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Order / Jammed / Leaked / Burnt orBrake: ☒ Order / Jammed / Leaked / Burnt orMod: ☒ NJ / S/Rim / STD A/Rim or

Tyre Size: F: 235/35 ZR19

R: 265/30 ZR19

BS / DUN / EXNOVA / GY / FS / LZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 21/1/18

D.O.A. 25/2/18

Survey held at Hendon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 20 APR 2013

Date/Time File Pass to?

☐ : Prel. Report

Days Of Repair: 3

Date/Time File Return to?

☐ : Final Report

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Report Format: DAR

Lump Sum / I.B.I.: (\$

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

S + RS: \$

Phone

Others


TOTAL

180

20

200

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SLH1558S AND SKC5224S ON 21/02/2018**

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: 22/2/2018 1:54:49 PM
Attachments:  SLH1558S.TIF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

HENDON AUTOMOTIVE PTE LTD
 280 Woodlands Industrial Park ES #01-19, Harvest@Woodlands S(757322)
 TEL : 94592885 FAX : 63345178

Pre-repair inspection

Date:

By Fax 6415 3727 Only

M/s AIG Asia Pacific Insurance Pte. Ltd
 AIG Building
 78 Shenton Way
 #08-16
 Singapore 079120

Dear Sir,

ACCIDENT INVOLVING S'K C 5224 S AND S'K 1558 S - ON 21/02/18 @ 07:55

We refer to the above matter.

We are the appointed repair workshop of vehicle no. S'K C 5224 S

We understand that you are the insurer of vehicle no. S'K 1558 S

The owner of vehicle no. S'K C 5224 S has authorised us to carry out the repairs to his vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insurer and/or insured's authorised driver for the accident which is caused wholly and/or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damaged to the vehicle prior to the commencement of the repairs.

Kindly take note that we hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. S'K C 5224 S at my premises.



Your faithfully



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9960C
Vehicle Details	
Vehicle No.:	SKC5224S
Vehicle to be Exported:	No
Intended De-registration Date:	20 Apr 2018
Vehicle Make:	B.M.W.
Vehicle Model:	318i 2.0 AT D/AB 2WD 4DR GAS/D SR DRL
Primary Colour:	Grey
Manufacturing Year:	2011
Engine No.:	A248I950N46B20BZ
Chassis No.:	WBAPF72050FG90294
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$30,141.00
Original Registration Date:	06 Sep 2011
First Registration Date:	06 Sep 2011
Transfer Count:	0
Actual ARF Paid:	\$30,141.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Sep 2021
PARF Rebate Amount:	\$19,591.00
Intended COE Rebate Details	
COE Expiry Date:	05 Sep 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$70,117.00
COE Rebate Amount:	\$23,677.00
Total Rebate Amount:	\$43,268.00

The information contained herein is correct as at 20 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/02/2018 15:33
Date Of Accident	21/02/2018 07:55
Exact Location Of Accident	PIE (TUAS) SLIP ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC5224S
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	KAMAL BIN YACOB
NRIC No	S7709960C
Email Address	KAMALBY@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98753330
Alternative Phone No	OFFICE-98753330

Vehicle Particulars

Manufacturer	BMW
Model	318I 2.0 AT D/AB 2WD 4DR GAS/D SR DRL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5073064315-02
Cover Note Number	

Driver

Name of Driver	KAMAL BIN YACOB
NRIC No	S7709960C
Date Of Birth	19/03/1977
Occupation	INDOOR
Date Of Driving Pass	30/04/1997
Driving Experience	20 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98753330
Fax Number	
Contact Number	
EEmail Address	KAMALBY@GMAIL.COM

Address	612 TELOK BLANGAH ROAD #24-12
Postcode	109026
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH1558S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM HWEE MIAN
NRIC/Passport Number	S7814838A
Contact Number	90268921
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I, Kamal Bin Jacob, (S7709960C), was stationary in my car (SKC 5224S) at the slip road from PIE to Jalan Bahar, as the traffic light was red. The car behind (SLH 1558S), driven by Lim Hwee Mian (S7814838A) suddenly moved forward and hit the rear portion of my car. This is.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	CRK	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Scr Retainer	DM	✓	
1149	993045	Rear Bumper Reinforcement	DD	✓	
1150	992970	Rear Bumper Beam	DD	✓	
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler	DD	✓	
1158	994023	Reverse Sensor	SC	✓	
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	SCR	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD	R	
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	DD	✓	
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			

Vehicle No: SKC 5224 S

[illegible]

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Apr 2018 Edit Reg		22 Feb 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

LIM KAH GUAN, ID: S7704652F

Main Claimant:

KAMAL BIN YACOB

Vehicle Reg. No.:

SKC5224S

Claim Type:

TP / 2646415825SG

Vehicle Reg. No. (Insured):

SLH1558S

Repairer:

Hendon Automotive (HQ) 280 WOODLANDS INDUSTRIAL PARK E5, #01-19 HARVEST @ WOODLANDS, 757322 Woodlands - Tel:

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 12/04/2018]

Date of Loss:

21/02/2018 00:00 - :59

Policy/Cover Note No.:

[77 Months and 15 Days From LTA Reg Date (Man Yr)]

Policy No. (Claimant):

(Comprehensive)

Excess:

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG (04/04/2018): TP GIA REPORT






































ALL ASSOCIATED TASKS















































[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)


Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKC5224S (2646415825SG)
[SLH1558S]
TP
KAMAL BIN YACOB
Feb 21 2018 12:00AM
[LIM KAH GUAN]
Hendon Automotive

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)															Thumbnail	Print		
1	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
2	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
3	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
4	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
5	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
6	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
7	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
8	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
9	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
10	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
11	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
12	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
13	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
14	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
15	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
16	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
17	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
18	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
19	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
20	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
21	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
22	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
23	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
24	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
25	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
26	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
27	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
28	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
29	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
30	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
31	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
32	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
33	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
34	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
35	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
36	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			
37	03/04/18 17:49	General View														Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	03/04/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
39	03/04/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
40	03/04/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
41	03/04/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/04/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/04/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/04/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/04/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/04/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
47	03/04/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
48	03/04/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
49	03/04/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
50	03/04/18 17:49	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
51	03/04/18 17:49	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
52	03/04/18 17:49	General View	 Load JPG	<input checked="" type="checkbox"/>
53	03/04/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	03/04/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	03/04/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	03/04/18 17:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	03/04/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	03/04/18 17:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
85	03/04/18 17:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
86	03/04/18 17:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
87	03/04/18 17:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
			Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		
1	04/04/18 12:10	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18003476/SD3E2

Date: 23/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKC5224S

Insured Vehicle No : SLH1558S

Date of Loss: 21/02/2018

Nature of Claim: TP

Claim No: 2646415825SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKC5224S

Make & Model: BMW 318I, 2.0 (A)

Engine No: A248I950N46B20BZ

Reg. Date: 06/09/2011 (Man. Year: 2011)

Chassis No: WBAPF72050FG90294

Colour: Grey

Odometer: 154125 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35Z R19

Rear Tyre Size: 265/30Z R19

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/02/2018

Date Inspected: 23/02/2018 Inspected At:

Hendon Automotive (HQ)
280 WOODLANDS INDUSTRIAL PARK
E5, #01-19 HARVEST @ WOODLANDS
Singapore 757322

Estimated Period of Repair: 3.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER RETAINER	Damaged	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
5	1		*REAR BUMPER BEAM	Dented	0.00 F	*- F
6	1		*REAR BUMPER LOWER SPOILER	Dented	0.00 F	*- F
7	1		*REVERSE SENSOR	Shorted	0.00 F	*- F
8	1		*REAR LH TAILLAMP	Scratched	0.00 F	*- F
9	1		*BOOTLID	Repair	0.00 F	*- F
10	1		*BOOTLID LOCK	Dented	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >