

REF: ASM

ASSIGNMENT

Date 02/03/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

GBF 4397Z

at Worksite plus

Mova Automotive

of

15 Fan Yang Rd

Insured

Policy No

Claims No

Sum Insured

Excess

(Client's Record)

Moming

Make of Van

(Policy Condition)

Remark: The van had commenced its repair at the time of inspection.

NS	O/S

Bal. or Market Value

\$63K

IDAO Accident Report

Consistent? : Yes or No

GIA / PP Seen

Consistent? : Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

OA / REV / REP. / 24 HRS

Lup

Date

Person Contacted

Vehicle IN / OUT

Date / Time Action / Instruction

Van No

GBF 4397Z

Reg: 2016 Oct.

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make

Nissan NV 200

CC: 1461

Colour

B/gch.

A/C Insured / Std / Nil / NA

Sp. Reading

40827

T. Radio Insured / Std / Nil / NA

Eng No

C No

VSKY BAM 2020129604

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: (NS) / S/Rim / STD A/Rim or

Tyre Size:

F:

175/70 R14

R:

BS / DUN / EXNOVA / SV / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front

Rear

R. Bal.

C

mm

R. Bal.

C

L. Bal.

C

mm

L. Bal.

C

D.O.A

D.O.A

2/3/18

Survey held at

Mara Fan Yang

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roofed or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 02 NOV 2018

Date/Time File Pass to:

typist



Preli. Report



Final Report

Date/Time File Return to:

Days Of Repair

6

Resurvey No. of Trip

Survey Fee

250

Transportation

Lubrication

Paint

Other

Add Fee:



Steered

\$



Inter

\$



Tether

\$



Access

\$

Record Format:

Lum Sum / L.B. / S.

250