

12/03/2003

ASS. REC. BY:

REF CS3/MSG18003503/Gd3er

Range  
Special Instructions

Surveyor:

Meimen

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSG

Date/Time

23/2/18 @ 1.26pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 1357S

Insured:

SGG 7362P

at Workshop m/s

N-SI Automotive

Tel:

68420051

of

2 Kelki Bkt # 01-17/18

Policy No:

A27710566QMX

Claim No:

550353

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/2/18

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

2.10pm @ 23/2/18

Person Contacted:

Amely

Vehicle IN/OUT

OUT

Date/Time	Action/Instruction (X) Estimate
	SLT 1357S-X
	SGG 7362P-X
	Dismantle: 9/3/2018
	After repair: 12/3/2018

PRS

REF: msh

Circulation

mesmen.

## ASSIGNMENT

From: Date: 01/03/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLT 1357S

at Workshop mis: N-51

of: 2 Kaki Bukit Ave 2 #01-17

Insured

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

10am - 10:30am

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bel. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLT1357S Vc Reg: 19 oct 2017

Type: M/Cas / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Colour

Sp. Reading

Eng No:

C No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M/R / S/Rim / STD A/Rim or

Tyre Size F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

R/Bal:

L/Bal:

D.O.A:

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

\* Repair Estimate : S\$ 7000-8000

RECEIVED 07 MAY 2018

Date/Time: File Pass to?

☐

Prel. Report

☐

Final Report

Date/Time: File Return to?

1

Report Format: PRS

Lump Sum / I.B.I. / S

Days Of Repair:

Resurvey No. of Trip: 3

Survey Fee

Transportation

13-4-85

Shops:

Contract

Add Fee:

☐

Site Insp: S

☐

Interlock: S

☐

Tech. Insp: S

☐

Weekend: S

120

50

10

180

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Feb 2018		23 Feb 2018 13:26 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	DR CAO WENJUN, ID: S6978889J		[Created by insurer]
Main Claimant:	TWINCAR LEASING PTE LTD, Co. Reg. No.: 201533046C		
Vehicle Reg. No.:	SLT1357S	Date of Loss:	21/02/2018 18:00 - :59
Claim Type:	TP / 550353	Policy/Cover Note No.:	A27710566QMX (Comprehensive)
Vehicle Reg. No. (Insured):	SGG7362P	Policy No. (Claimant):	Coverage: 22/05/2017 - 21/05/2018
		Excess:	S\$500.00
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/02/2018]		
Driver/Custodian (Insured):	LIN YU (), NRIC: S7076195E		

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

## Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SLT1357S
Vehicle Type :	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	HONDA
Vehicle Model :	SHUTTLE HYBRID 1.5 AUTO
Chassis No. :	GP71121020
Propellant :	Petrol-Electric
Engine No. :	LEB6325921
Motor No. :	H13626058
Engine Capacity :	1496 cc
Power Rating :	22.0 kW
Maximum Power Output :	101.0 kW ( 135 bhp )
Maximum Laden Weight :	1465 kg
Unladen Weight :	1190 kg
Year Of Manufacture :	2017
Original Registration Date :	19 Oct 2017
Lifespan Expiry Date :	-
COE Category :	B - Car above 1600cc or 97kW (130bhp)
Quota Premium :	\$48,109.00
COE Expiry Date :	18 Oct 2027
Road Tax Expiry Date :	18 Apr 2018
PARF Eligibility Expiry Date :	18 Oct 2027
Inspection Due Date :	18 Oct 2020
Intended Transfer Date :	12 Mar 2018
CO2 Emission :	87.00 (g/km)
CEV/VES Rebate Utilised Amount :	\$16,816.00
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-
The current road tax expiry is 18 Apr 2018. You may renew the road tax from 19 Jan 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 18 Apr 2018, late renewal fee(s) will be imposed. Please use <a href="#">Enquire Road Tax Payable</a> to check on the late fee(s) payable.	
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.	
Amount Payable (From 19 Apr 2018 to 18 Oct 2018)	

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/02/2018 16:44
Date Of Accident	21/02/2018 18:20
Exact Location Of Accident	PINE GROVE CONDO OPEN CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT1357S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TWINCAR LEASING PTE LTD
Co Reg No	201533046C
Email Address	SALES@N51.COM.SG
Mobile Phone No	(LOCAL) +65-83802233
Alternative Phone No	OFFICE-68420051

### Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE HYBRID-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SD17V11639/VPZ/R02
Cover Note Number	

### Driver

Name of Driver	PETER TAN SWEE HUAT
NRIC No	S1800876I
Date Of Birth	13/01/1967
Occupation	OUTDOOR
Date Of Driving Pass	13/01/1990
Driving Experience	28 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91911313
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 294A COMPASSVALE CRESCENT #15-13
Postcode	541294
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGG7362P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	PETER TAN SWEE HUAT
Approximate Age	

Injuries Sustain

Injured person in which vehicle?

SLT1357S

Were seat belts worn?

Was this injured conveyed to hospital by  
ambulance?

Address

Postcode

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## Sketch Plan #2

### SKETCH PLAN

VEHICLE A - SLT 13575  
VEHICLE B - SGA 7362P




### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MY VEHICLE CAME TO A STATIONARY POSITION TO ALIGHT
PASSENGER
AFTER MY PASSENGER ALIGHTED, I ABOUT TO MOVE OFF SUDDENLY
A VEHICLE REVERSE AND HIT UNTO THE RIGHT SIDE OF MY
VEHICLE.
ALIGHTED FROM MY VEHICLE AND REALIZED A VEHICLE AGAIN
(SGA 7362P) HAD COLLIDED TO THE RIGHT SIDE OF
MY VEHICLE WHILE I'M IN THE STATIONARY POSITION.
THE WHOLE ACCIDENT FOOTAGE WAS CAPTURED BY MY IN-CAR
CAMERA:
VEHICLE A - SLT 13575
VEHICLE B - SGA 7362P

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 

Reporting Centre Personnel's Signature  
Name:   
NRIC/FIN No: \_\_\_\_\_

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main:	22 Feb 2018		23 Feb 2018 13:26 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>













  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>DR CAO WENJUN</b> , ID: S6978889J									
Main Claimant: <b>TWINCAR LEASING PTE LTD</b> , Co. Reg. No.: 201533046C									
Vehicle Reg. No.: <b>SLT1357S</b>		Date of Loss: 21/02/2018 18:00 - :59 [4 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 550353</b>		Policy/Cover Note No.: A27710566QMX (Comprehensive) Coverage: 22/05/2017 - 21/05/2018							
Vehicle Reg. No. (Insured): <b>SGG7362P</b>		Policy No. (Claimant):							
		Excess: S\$500.00							
Repairer: <b>N-51 Automotive Pte Ltd (HQ)</b> BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Irene Tan Gek Ing</b> - 6594 2541]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Teo Cheng Ming Wilson</b> ] ... [Imm.Advice due 24/02/2018]									
Driver/Custodian (Insured): LIN YU (), NRIC: S7076195E									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SLT1357S (550353)  
[SGG7362P]  
TP  
TWINCAR LEASING PTE LTD  
Feb 21 2018 6:00PM  
[DR CAO WENJUN]  
N-51 Automotive Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	27/04/18 11:31	Video - Accident					1	Load MP4		
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	23/02/18 13:20	Accident Statement From: SC - Reg. No: SGG7362P, Claimant: CAO WENJUN					1	Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
2	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
3	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
4	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
5	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
6	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
7	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
8	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
9	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
10	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
11	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
12	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
13	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
14	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
15	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
16	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
17	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
18	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
19	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
20	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
21	07/05/18 10:38	General View					1	Load JPG	<input checked="" type="checkbox"/>	
22	07/05/18 10:39	Photographs of Damaged Parts					1	Load JPG	<input checked="" type="checkbox"/>	
23	07/05/18 10:39	Photographs of Damaged Parts					1	Load JPG	<input checked="" type="checkbox"/>	
24	07/05/18 10:39	Photographs of Damaged Parts					1	Load JPG	<input checked="" type="checkbox"/>	
25	07/05/18 10:39	Photographs of Damaged Parts					1	Load JPG	<input checked="" type="checkbox"/>	
26	07/05/18 10:39	Photographs of Damaged Parts					1	Load JPG	<input checked="" type="checkbox"/>	
27	07/05/18 10:39	Photographs of Damaged Parts					1	Load JPG	<input checked="" type="checkbox"/>	
28	07/05/18 10:39	Photographs of Damaged Parts					1	Load JPG	<input checked="" type="checkbox"/>	
29	07/05/18 10:39	Photographs of Damaged Parts					1	Load JPG	<input checked="" type="checkbox"/>	
30	07/05/18 10:39	Photographs of Damaged Parts					1	Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
31	07/05/18 10:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	07/05/18 10:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	07/05/18 10:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	07/05/18 10:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	07/05/18 10:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	07/05/18 10:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	07/05/18 10:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	07/05/18 10:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	07/05/18 10:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	07/05/18 10:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	07/05/18 10:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/02/18 13:26	PRI	 Load PDF	
2	23/02/18 13:26	TP GIA REPORT	 Load PDF	
3	23/02/18 13:26	List of 10 surveyor from TP	 Load PDF	
4	23/02/18 13:26	EMAIL to TP reject their list of SJE	 Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18003503/GD3E2

Date: 07/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A27710566QMX

Claimant Vehicle No: SLT1357S

Insured Vehicle No: SGG7362P

Date of Loss: 21/02/2018

Nature of Claim: TP

Claim No: 550353

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT1357S

Make &amp; Model: HONDA SHUTTLE HYBRID, 1.5 (A)

Engine No: LEB6325921

Reg. Date: 19/10/2017 (Man. Year: 2017)

Chassis No: GP71121020

Colour: Silver

Odometer: 35577 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Yokohama 7 mm

Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm

Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment: 23/02/2018

Date Inspected: 09/03/2018 Inspected At:

N-51 Automotive Pte Ltd (HQ)  
BLK 2 KAKI BUKIT, #01-17/18 KAKI  
BUKIT AUTOHUB  
Singapore 417921

Estimated Period of Repair: 2.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 07 May 2018)	
<b>Parts:</b>	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLT1357S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >