

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BT1%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	11	1			FRT FOGLAMP RH			Cracked	66				66
	12	1			FRT FOGLAMP OUTER COVER RH			Missing	94				94
	13	1			FRT FOGLAMP SENSOR RH			Missing	116				116
	14	1			FRT DAY RUNNING LIGHT RH			Cracked	180				180
	15	1			FRT GRILLE BASE			Cracked	110				110
	16	1			FRT GRILLE ASSY			Cut	155				155
	17	1			FRT BUMPER BRACKET RH			Necessary	220				220
	18	1			FRT HEADLAMP RH			Cracked	300				300
	19	1			FRT FENDER RH			Repair	0				0
	20	1			FRT FENDER INNER SHIELD RH			Serviceable	0				0
	21	8			FRT FENDER INNER SHIELD CLIP			Serviceable	0				0
	22	1			FRT SUPPORT PANEL COMPLETE			Serviceable	0				0
	23	1			AIRCON AIR GUIDE			Necessary	47				47
	24	1			FRONT FOGLAMP SENSOR OUTER RIM			Necessary	46				46

Labour

Detailed Assessment

Inspection Date *

02/26/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

500

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

195/65R15

Condition of Vehicle at time of survey

General condition

Fair

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Spare wheel

Rear Tyre Size

195/65R15

FNOL INFORMATI... BLK 279 TOH GUAN ROAD, #10-199,
600279, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S8823521E

CATEGORY

Make

POLICY INFORMAT... CITROEN

ASSESSMENT INFO...

CITROEN

CATEGORY

Model

POLICY INFORMAT... BERLINGO L2 1.6 BLUEHDI

ASSESSMENT INFO...

BERLINGO L2 1.6 BLUEHDI S&S ETG6

CATEGORY

Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Chassis No

POLICY INFORMAT... VF77FBHYMHJ767923

CATEGORY

Date of Birth

FNOL INFORMATI... June 28, 1988

POST SURVEY INF...

mm/dd/yyyy

CATEGORY

Age

FNOL INFORMATI... 30

POST SURVEY INF...

CATEGORY

Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY

Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY

Driving Experience

Accelerated
workshop survey

joycefoo@hiapheng.com.sg

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Additional Instructions

EXCESS \$500

- Messages
- Assessment
- Invoices
- Metrics
- History
- Notes
- Documents
- Add

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
--------------	--------------	------------------	-----------------	--------	-------	-------

TEO Kitty	2/23/18 10:36 AM	3590	3590	Open	Share	Clone
-----------	------------------	------	------	------	-------	-------

Accelerated
workshop survey

joycefoo@hiapheng.com.sg

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes
- Document Type

Additional Instructions

EXCESS \$500

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
RESURVEY PHOTOS.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	August 2, 2018
MARK ESTIMATE.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	March 1, 2018
SURVEY PHOTOS.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	February 28, 2018