

INS. CASE OWNER:

CC 4 / ASM1800

LKK:
IDAC:

31948

Surveyor:

DOI:

Date / Time:

Registered in Merimen

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A: 13/2/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

8/3

Poh

12/5/18 * 1105

SKL 1261M - X; X0892L - X

Ponding 10/5.

CALLED OUI CONFIRMED ACCIDENT - OUI ROLL BACK AND TIP
TP REP. INFROM TP CLAIM ADVISED TO SETTLE AND
ADVISE ABOUT NEW ISSUE.

EMAIL REP LIABILITY CLAIM.

RECEIVED 11 OCT 2018

RECEIVED 11 OCT 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$5,350

(3 days)

Reduction:

41

%

Email ☒Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia.:

Repair Cost:

S\$5,734.50

OUI ROLL BACK.

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ 900.00

(\$150 x 6 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 29.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 6,653.50

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒Call ☐

Payee 1:

S\$ 6,653.50

Name 1:

EM-1 AUTO PIE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18003533/M1ea3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 23-02-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh. XD 892L	Veh. Inspected	SKL 1261M
	Policy No.	Coverage (\$)	0.00
	Claim No. S8M0090V	Excess (\$)	0.00
	Assign From	Assign Date	23/02/2018
2. Vehicle Particulars & Condition			
	Make & Model	c.c	0
	Engine No. HIDDEN	Year of Reg.	
	Chassis No.	Colour	
	Odometer -	Steering	
	Brakes	Modification	
	General		
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre		Balance
	L/H Front Tyre		mm
	R/H Rear Tyre		mm
	L/H Rear Tyre		mm
4. Description of Damages			
5. General Information			
	Accident Date 13/02/2018	Inspection Date	01/03/2018
	Survey held at EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO.: 201316380R

Vehicle Number : SKL 1261M
Vehicle Model : MAZDA 5 CW10
Accident Date : 13.02.2018
Original Reg Date : 30.09.2013

Date : 26.02.2018
Chassis : JM6CW10F1E0116288
TP INS. : AXA

ESTIMATE

1	1 pc	Bonnet	✓	det	✓		\$ 1033
2	1 pc	Bonnet Rubber (Outer)	✓	det	✓		\$ 75
3	1 pc	Bonnet Rubber (Inner)	✓	det	✓		\$ 56
4	2 pcs	Bonnet Stopper	✗	det	✗	⑤ 22	\$ 94
5	1 pc	Bonnet Insulator	✗	det	✗		\$ 169
6	1 pc	Bonnet Insulator Clip	✓	det	✓		\$ 40
7	1 set	Bonnet Inner Lock	✗	det	✗		\$ 197
8	2 pcs	Bonnet Hinge	✗	det	✗	⑤ 65	\$ 130
9	2 pcs	Headlamp	✗	det	✗	⑤ 1620	\$ 3300
10	2 set	Headlamp Clip	✓	det	✓	⑤ 20	\$ 40
11	1 pc	Front Bumper	✓	det	✓		\$ 729
12	1 pc	Front Bumper Reinforcement	✗	det	✗		\$ 226
13	1 pc	Front Bumper Sponge	✗	det	✗		\$ 132
14	2 pcs	Front Bumper Side Retainers	✓	det	✓	⑤ 39	\$ 78
15	1 set	Front Bumper Clips	✓	det	✓		\$ 20
16	1 pc	Front Bumper Badge	✓	det	✓		\$ 28
17	1 pc	Front Grille Assy	✓	det	✓		\$ 692
18	1 set	Front Grille Assy Clip	✗	det	✗		\$ 30
19	1 pc	Front Lower Grille	✗	det	✗		\$ 116
20	1 pc	Support Panel	✓	det	✓		\$ 295
21	1 pc	Brace Panel	✗	det	✗		\$ 65

Labour charge

Panel Beating	600	1,200.00
Spray painting	200	4,000.00
Check Wiring	30	50.00
Anti rust	30	100.00
Remove and install air con	120	150.00

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 2,500.00

5 days

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6748G
Vehicle Details	
Vehicle No.:	SKL1261M
Vehicle to be Exported:	Yes
Intended De-registration Date:	23 Feb 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 2.0L SP SEAT ABS D/AB 2WD 5DR SR
Primary Colour:	Grey
Manufacturing Year:	2013
Engine No.:	LF11547686
Chassis No.:	JM6CW10F1E0116288
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$20,037.00
Original Registration Date:	30 Sep 2013
First Registration Date:	30 Sep 2013 ✓
Transfer Count:	0
Actual ARF Paid:	\$20,052.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2023
PARF Rebate Amount:	\$15,039.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2023 ✓
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$86,239.00
COE Rebate Amount:	\$48,293.00
Total Rebate Amount:	\$63,332.00 ✓

The information contained herein is correct as at 23 Feb 2018

SKL 1261M

LABOUR

S/N PARTS

PARTS

\$600.00 ✓
\$500.00 ✓
\$30.00 ✓
\$30.00 ✓
\$120.00 ✓

\$1,033.00 ✓
\$75.00 ✓
\$56.00 ✓
\$40.00 ✓
\$3,300.00 ✓
\$40.00 ✓
\$759.00 ✓
\$78.00 ✓
\$50.00 ✓
\$58.00 ✓
\$692.00 ✓
\$595.00 ✓

\$1,280.00

\$0.00

\$6,776.00
\$1,355.20
\$8,420.80

Total: \$8,700.80

Lump Sum: \$5,360.64

5350k



Mazda 5

Price Range

Depreciation

2013

Vehicle Type



Search

Advanced Search

Home » Used Cars » Village Credit » Mazda 5 SP

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Car Tyres



Mazda 5 SP

Overview

Financial

Accessories

Similar

Research

Photos

Map

VC VILLAGE CREDIT PTE LTD

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$77,800

Depreciation \$12,100 /yr
View models with similar depreciationReg Date 30-Sep-2013
(5yrs 7mths 6days COE left)

Manufactured 2013

Mileage 92,121 km (20.9k /yr)

Transmission Auto

Engine Cap 1,999 cc

Road Tax \$1,212 /yr

Power 106.0 kW (142 bhp)
View specs of the Mazda 5 (2012)

Curb Weight 1,527 kg

Features Powerful And Reliable, 2.0L 4 Cylinder Inline DOHC, Multi Function Steering, Twin Powered Sliding Doors, Sunroof.

Accessories Sport Rim, Leather Seats, Pioneer DVD Player With Reverse Camera, Electrical Retractable Side Mirrors, Rear Aircon, Solar Film.

Description Agent Maintained, Roadtax Till Sep 2018, Stylishly Designed 7 Seaters, Great Handling And Stability, Generous Cabin Space. 1 Owner, Grab Fast Before Its Gone.

COE \$77,989

ONV \$20,037

ARF \$20,052

Dereg Value \$58,713 as of today (change)

No. of Owners 1

Type of Veh MPV

Category PARF Car

Availability Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 06-Feb-2018 | Last Updated on: 12-Feb-2018

Tags: Mazda 5, 2013 Mazda 5, Mazda, Mazda 5, Used Mazda



Seller Information

Company	Village Credit	
	* dealer's pricelist	
	* 14 vehs sold 6 vehs available	
Address	61 Ubi Avenue 2 #03-12	
	Search cars nearby this location	
Location	Automobile Megamart	
Website	www.villagecredit.com.sg	
Office No	67482227	
Contact Person(s)	Mr Lim	90688985
	Mr Toh	81388352

Start With AdWords Today

Our Specialists Are Here To Answer Your Questions & Get You Started AdWords

Google Ad



Upfront Payment

» more Financial info

Compare [2]

1,033.00
75.00
56.00
40.00

600.00	Total List Price	\$	6,776.00
500.00	Discount	20%	
30.00	List Price	\$	5,420.80
30.00	Total Nett Price	\$	-
120.00	Discount	20%	
	Nett Price	\$	-
	Total Special Nett	\$	-
	Total Labour	\$	1,280.00
	Grand Total	\$	6,700.80
	Discount 20%	20%	
	Lump Sum	\$	5,360.64

3,300.00
40.00
759.00

78.00	Columns	List Price
50.00	A	Nett Price
58.00	C	Special Nett
692.00	D	Labour
	E	

595.00

File
No: 5217

Vehicle No.
SKL 1261M

Model
MAZDA 5

10w 11 days

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SKL 1261M
Vehicle Model : MAZDA 5 CW10
Accident Date : 13.02.2018
Original Reg Date : 30.09.2013

Date : 26.02.2018
Chassis : JM6CW10F1E0116288
TP INS. : AXA

ESTIMATE

1	1 pc	Bonnet	✓	det		
2	1 pc	Bonnet Rubber (Outer)	✓	det nec		
3	1 pc	Bonnet Rubber (Inner)	✓	nec		
4	2 pcs	Bonnet Stopper	x	svc		
5	1 pc	Bonnet Insulator	x	svc		
6	1 pc	Bonnet Insulator Clip	✓	nec		-
7	1 set	Bonnet Inner Lock	x	svc		
8	2 pcs	Bonnet Hinge	x	det		-
9	2 pcs	Headlamp	o> crg	det svc		-
10	2 set	Headlamp Clip	✓	nec		-
11	1 pc	Front Bumper	✓	det		
12	1 pc	Front Bumper Reinforcment	x			
13	1 pc	Front Bumper Sponge	x			
14	2 pcs	Front Bumper Side Retainers	✓	det		-
15	1 set	Front Bumper Clips	✓	nec		
16	1 pc	Front Bumper Badge	✓	nec		
17	1 pc	Front Grille Assy	✓	det		-
18	1 set	Front Grille Assy Clip	x	nec		-
19	1 pc	Front Lower Grille	x			
20	1 pc	Support Panel	✓	det		
21	1 pc	Brace Panel	x	svc		

Labour charge

Panel Beating		1,200.00	600
Spray painting		4,000.00	500
Check Wiring		50.00	30
Anti rust		100.00	30
Remove and install air con		150.00	120

\$ 2,500.00

SVY

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6748G
Vehicle Details	
Vehicle No.:	SKL1261M
Vehicle to be Exported:	Yes
Intended De-registration Date:	23 Feb 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 2.0L SP 5EAT ABS D/AB 2WD 5DR SR
Primary Colour:	Grey
Manufacturing Year:	2013
Engine No.:	LF11547686
Chassis No.:	JM6CW10F1E0116288
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$20,037.00
Original Registration Date:	30 Sep 2013
First Registration Date:	30 Sep 2013
Transfer Count:	0
Actual ARF Paid:	\$20,052.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2023
PARF Rebate Amount:	\$15,039.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$86,239.00
COE Rebate Amount:	\$48,293.00
Total Rebate Amount:	\$63,332.00

The information contained herein is correct as at 23 Feb 2018

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Monday, 12 March 2018 2:10 PM
To: 'Chia Sin Muk'
Cc: Vic (LKKAUTO)
Subject: Accident Involving SKL 1261M & XD 892L on 13/02/2018

WITHOUT PREJUDICE

Your Ref: SKL 1261M
Our Ref: CC4/ASM18003533/M1ea3

Dear Sir/Madam,

Accident Involving SKL 1261M & XD 892L on 13/02/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents for us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



MANDATE REQUEST FOR S8M0090V

EQUEST

Type

Question

Message

Liability: Insured roll back and hit third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$5,724.50 (w/GST) Loss of Use: \$900.00 (6days x \$150) GIA Search: \$29.00 Total: \$6,653.50 Immediate Advice with Mandate for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (13/08/2018)

[Reply](#)



Re:MANDATE REQUEST FOR S8M0090V

Type

 Information

Message

pls proceed

Reply

LETTER OF DEMAND

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY/GST REG. NO: 201316380R

M/S HAWK ASIA PACIFIC PTE LTD

Date : 03-Aug-2018

AXA Insurance Singapore Pte Ltd

Motor Claim Department

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Without Prejudice

Date of Accident : 13-Feb-2018
Our Client's Vehicle Number : SKL 1261M
Vehicle Make/ Model : MAZDA 5
Your Insurer : XD 892L

DESCRIPTION	SUB-AMOUNT	GST 7%	AMOUNT (SGD)
Lump Sum Repair Cost (Recommended by LKK Mr Ma)	5,350.00	374.50	5,724.50 SR
GIA Fee	27.10	1.90	29.00 SR
Loss of (Rental/Use) (6 days x \$ 150) (Car Leasing)	900.00		900.00 ES

SGD (Six Thousand Six Hundred Fifty-Three And Cents Fifty
only)

GRAND TOTAL

6,653.50

Subject to 7% GST

376.40



Authorised Signature and Company Stamp

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Friday, 23 March 2018 11:32 AM
To: TONGHENG MOTORWORK@GMAIL.COM
Subject: ACCIDENT INVOLVING XD 892L AND SKL 1261M ALONG GRANGE RD ON 13/02/2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

23 MAR 2018

TONG HENG MOTOR WORK

Dear Sir/ Mdm

OUR REF : CC4/ASM18003533/M1ea3
YOUR REF : XD 892L
ACCIDENT INVOLVING XD 892L AND SKL 1261M ALONG GRANGE RD ON 13/02/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s EM-1 AUTO PTE LTD acting on behalf of the owner of SKL 1261M against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had roll back and hit the Third Party vehicle SKL 1261M. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to ashersng@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at ashersng@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

LETTER OF AUTHORISATION

ACCIDENT INVOLVING (any vehicle) SKL1261M and X0892L
ON 13/2/18 ALONG Grafe Rd @ Patterson Hill Junction

I, Hawk Asia Pacific P/L NRIC No. / Company Reg. No.
2003067486 of (address) 10 BUKIT BAYOK CRESCENT #11-03

Postal Code 658079, the registered owner (or authorised agent) of motor vehicle registration number

SKL1261M hereby authorise your workshop EM-1 Auto P/L (Company/GST REG.No. :

201316380R) Blk 8 #01-68 Sector C Sin Ming Industrial Estate Singapore 575643 to :-

1. Begin or commence repairs to my/our motor vehicle;
2. Start or initiate third party claims for damages incurred by me against third party(ies) responsible for the accident.
3. To instruct EM-1 Auto P/L on my/our behalf to negotiate a settlement with the third party and/or his insurers as you deem fit.
4. To appoint vehicle surveyor on my/our behalf to determine reasonable costs of repair and period of repair.
5. To act on my/our behalf for any documents mailed to EM-1 Auto P/L by the third party and/or his insurers for the claim of my vehicle, if I am not contactable.

I am prepared to attend at my/our solicitors' office or to attend Court in connection with my/our claim, if necessary, I shall give my full co-operation and support for the claim for cost of repair and loss of use and shall keep you informed of any correspondences and/or summons that I may receive due to this action before agreeing to pay up or receive any monies due to this claim.

I authorise you to claim for the period of loss of use as specified by the motor surveyor or such shorter period due to accelerated work. I further authorise you to accelerate the repair period with overtime work and additional resource, I will pay you a reasonable amount to reflect the additional period of time to shorten.

I agree to keep you informed of any document(s), including cheques, mailed to me by third party and/or his insurers before taking any action. I also will not bank in any cheques issued by third party insurance and/or his insurers without the approval of EM-1 Auto P/L, and should I get approval from EM-1 Auto P/L to bank in the said cheques, I agree to pay EM-1 Auto P/L the full settlement amount as stated on the cheques within 5 working days.

Should my/our claim be partly successful or unsuccessful or cannot be proceeded with and/or if any judgement or settlement is not honoured or satisfied by third party, I/We:

1. Agree to pay you the sum of monies (as agreed) or as certified by the surveyor appointed, being the costs of repairs, survey fees and/or any other expenses reasonably incurred by you on my/our behalf. You may use the recovered amount from my claim for loss of us to partially offset the difference.
2. Agree to pay you such increased cost for additional resources and overtime work to shorten the period of repair.
3. Will pay for any shortfall that may result in the settlement amount.

In the event that EM-1 Auto P/L or the Repairer is compelled to enforce this undertaking, I/We agree that I/we shall pay on a full indemnity basis, the legal costs incurred by EM-1 Auto P/L or the Repairer.

Signature: _____

Company Stamp:
(if applicable)

Name: _____

NRIC No: _____

Contact No: _____

Date: _____

Hawk Asia Pacific P/L

2003067486

83324095

13/2/18



redefining / insurance

Provide always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect or preclude me from making a further claim for general and special damages for my personal injuries sustained in the same accident.

CLAIM REF : S8M0090V
INSURED : TONG HENG MOTOR WORK

DISCHARGE VOUCHER

We/I [HAWK ASIA PACIFIC PTE LTD, NRIC NO. 200306748G] hereby agree to accept the sum of dollars [SIX THOUSAND SIX HUNDRED FIFTY THREE AND CENTS FIFTY ONLY.] [S\$6,653.50] paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their Insured or the driver of motor vehicle no. [XD 892L] as a result of an accident along [GRANGE ROAD AND PATTERSON HILL JUNCTION] on [13/02/2018] of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. [SKL 1261M].

We/I hereby declare that the said insurer or owner and/or driver of Insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. [XD 892L] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [XD 892L].

Dated this 08 day of October 2018

Claimant's Signature

NRIC no./ Company Stamp

Occupation/ Business

Address

Telephone No.

Witness's Name

Witness's Signature

Witness's NRIC No.

[Signature]
S 8120081/2
op manager



10 RT SILENT CIRCLE
#11-03 The Spire S(658079)
Chia Sim Muk
[Signature]
S1306599C

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

TAX INVOICE

M/S HAWK ASIA PACIFIC PTE LTD

Invoice No : 18/00250/5217TP

Date : 08-Oct-2018

AXA Insurance Singapore Pte Ltd

Motor Claim Department

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Date of Accident : 13-Feb-2018

Our Client's Vehicle Number : SKL 1261M

Vehicle Make / Model : MAZDA 5

Your Insurer : XD 892L

DESCRIPTION	SUB-AMOUNT	GST 7%	AMOUNT (SGD)
Lump Sum Repair Cost (Recommended by LKK Mr Ma)	5,350.00	374.50	5,724.50 SR

SGD (Five Thousand Seven Hundred Twenty-Four And
Cents Fifty only)

GRAND TOTAL

5,724.50

Subject to 7% GST

374.50



Authorised Signature and Company Stamp



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-028322
Date of Request: 23/02/2018

Your Ref No: WALK IN KOA

EM1 AUTO PTE LTD
BLK 8 #01-68 SIN MING INDUSTRIAL ESTATE SECTOR C
SINGAPORE 575643

Dear Sir/Madam,

Your Vehicle No: SKL1261M
Date of Accident: 13/02/2018
Place of Accident: GRANGE RD
Involving Vehicle No: XD892L

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque

TAX INVOICE

Our Ref No: GR-18-028323
Date of Request: 23/02/2018

Your Ref No: WALK IN KDA

EM1 AUTO PTE LTD
BLK 8 #01-68 SIN MING INDUSTRIAL ESTATE SECTOR C
SINGAPORE 575643

Dear Sir/Madam,

Date of Accident: 13/02/2018
Vehicle No: SKL1261M
Place of Accident: GRANGE ROAD AND PATTERSON HILL JUNCTION
Involving Vehicle No: XD892L

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
XD892L	GRANGE ROAD AND PATTERSON HILL JUNCTION	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	XD 892L (Insd veh)	Model:	MAZDA 5
	SKL 1261M (TP veh)		
Date of Accident:	13/02/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	11,432.95
Final Repair Cost	:	\$	5,724.50
Loss of Use	:	\$	900.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	29.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	6,653.50

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	EM-1 AUTO PTE LTD	:	\$ 6,653.50

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

11/10/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18003533/M1ea3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:ERNEST TAY

Date : 11-10-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 892L	Veh. Inspected	SKL 1261M
Policy No.	VCB/P19114944	Coverage (\$)	0.00
Claim No.	S8M0090V	Excess (\$)	0.00
Assign From		Assign Date	23/02/2018

2. Vehicle Particulars & Condition

Make & Model	MAZDA 5	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JM6CW10F1E0116288	Colour	GREY
Odometer	43865	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	FALKEN	6 mm
L/H Front Tyre	205/55 R16	FALKEN	6 mm
R/H Rear Tyre	205/55 R16	FALKEN	6 mm
L/H Rear Tyre	205/55 R16	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/02/2018	Inspection Date	01/03/2018
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 1261M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET (CONSISTENT)	BENT	1,033.00	1,033.00
1	BONNET RUBBER (OUTER) (CONSISTENT)	NECESSARY	75.00	75.00
1	BONNET RUBBER (INNER) (CONSISTENT)	NECESSARY	56.00	56.00
2	BONNET STOPPER @\$22.00 (CONSISTENT)	SERVICEABLE	44.00	-
1	BONNET INSULATOR (CONSISTENT)	SERVICEABLE	169.00	-
1	BONNET INSULATOR CLIP (CONSISTENT)	NECESSARY	40.00	40.00
1	SET BONNET INNER LOCK (CONSISTENT)	SERVICEABLE	197.00	-
2	BONNET HINGE @\$65.00 (CONSISTENT)	TO REPAIR SEE LABOUR	130.00	-
2	HEADLAMP @\$1650.00 (CONSISTENT)	CRACKED	3,300.00	3,300.00
2	HEADLAMP CLIP @\$20.00 (CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT BUMPER (CONSISTENT)	DEFORMED	759.00	759.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	526.00	-
1	FRONT BUMPER SPONGE (CONSISTENT)	NOT NECESSARY	132.00	-
2	FRONT BUMPER SIDE RETAINERS @\$39.00 (CONSISTENT)	DISTORTED	78.00	78.00
1	SET FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	FRONT BUMPER BADGE (CONSISTENT)	NECESSARY	58.00	58.00
1	FRONT GRILEL ASSY (CONSISTENT)	DEFORMED	692.00	692.00
1	SET FRONT GRILLE ASSY CLIP (CONSISTENT)	NOT NECESSARY	30.00	-
1	FRONT LOWER GRILLE (CONSISTENT)	NOT NECESSARY	116.00	-
1	SUPPORT PANEL (CONSISTENT)	DISTORTED	595.00	595.00
1	BRACE PANEL (CONSISTENT)	SERVICEABLE	65.00	-
	LESS 20% DISCOUNT		-	-1,355.20
			8,185.00	5,420.80
LABOUR				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BONNET HINGE.		1,200.00	600.00
	SPRAY PAINTING .		1,000.00	500.00
	CHECK WIRING .		50.00	30.00
	ANTI RUST .		100.00	30.00

Report Ref No. CC4/ASM18003533/M1ea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND INSTALL AIR CON.		150.00	120.00
			2,500.00	1,280.00
GRAND TOTAL			10,685.00	6,700.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,350.00

Report Ref No. CC4/ASM18003533/M1ea3q2

MA CHIN FOOK

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.