

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SKL 1261M
Vehicle Model : MAZDA 5 CW10
Accident Date : 13.02.2018
Original Reg Date : 30.09.2013

Date : 26.02.2018
Chassis : JM6CW10F1E0116288
TP INS. AXA

ESTIMATE

1	1 pc	Bonnet	✓	bt		
2	1 pc	Bonnet Rubber (Outer)	✓	dec nec		
3	1 pc	Bonnet Rubber (Inner)	✓	nec.		
4	2 pcs	Bonnet Stopper	✗	svc		
5	1 pc	Bonnet Insulator	✗	svc		
6	1 pc	Bonnet Insulator Clip	✓	nec		-
7	1 set	Bonnet Inner Lock	✗	svc		
8	2 pcs	Bonnet Hinge	✗	n		-
9	2 pcs	Headlamp	✗	ora ois svc.		-
10	2 set	Headlamp Clip	✓	nec		-
11	1 pc	Front Bumper	✓	dec		
12	1 pc	Front Bumper Reinforcement	✗			
13	1 pc	Front Bumper Sponge	✗			
14	2 pcs	Front Bumper Side Retainers	✓	ois		-
15	1 set	Front Bumper Clips	✓	nec		
16	1 pc	Front Bumper Badge	✓	nec		
17	1 pc	Front Grille Assy	✓	dec		-
18	1 set	Front Grille Assy Clip	✗	nec		-
19	1 pc	Front Lower Grille	✗			
20	1 pc	Support Panel	✓	dis		
21	1 pc	Brace Panel	✗	svc		

Labour charge

Panel Beating		1,200.00	600
Spray painting		4,000.00	500
Check Wiring		50.00	30
Anti rust		100.00	30
Remove and install air con		150.00	120

\$ 2,500.00