

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

23 FEB 2018

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

#car in #

Estimate No. : b1 46021
Date Estimated : 23/02/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 3

- ESTIMATE REPAIR FOR -
Chin Lawrence @Tjhin Lawrence
34 White House Park

Singapore 257613

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGL321C	5E80973	04/11/2016	X1 sDrive20i	0

DESCRIPTIONVALUE

To tow accident vehicle to PML workshop.

195.00

To replace rear bumper & attachments including to knock out boot lid, tail panel and dent area caused by the accident

2125 2,975.00

To respray rear bumper, boot lid and tail panel

2474 2,749.00

To replace front exhaust silencer including align exhaust system and conduct checks for leak.

451? 531.00

To replace rear exhaust silencer including alignment system and conduct checks for leak.

451 531.00

To replace exhaust catalytic converter including alignment and conduct checks for leak.

564? 664.00

To replace engine mountings including re-alignment of engine block to body frame.

577? 679.00

To replace gearbox mountings including re-alignment of gearbox to cross member and propeller shaft system.

577? 679.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

231 271.00

To replace bootlid smart opener top and bottom sensor lines including program and conduct checks for proper function.

561? 661.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46021
Date Estimated : 23/02/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGL321C	5E80973	04/11/2016	X1 sDrive20i	0

DESCRIPTION

Sundries.

VALUE

180.00

Total Labour 1: 10,469.00

DESCRIPTION

CLAMPING BUSH
GASKET RING
CLAMP
RUBBER MOUNTING
FRONT MUFFLE
REAR SILENCER
MUFFLER CLAM
TAILPIPE TRIM CHROME
Exchange Catalytic converter
ENGINE MOUNT
STABILIZER LINK
GEARBOX MOUNT
REAR LH BUMPER MOUNT
RR BUMPER CARRIER
MOUNTING SMART OPENER
REAR TRIM UNDERRIDE PROTECTION (X L
RR BUMPER LH CORNER MOUNTING
RR BUMPER RH CORNER MOUNTING
REAR BUMPER PANEL PRIMED
REAR BUMPER MIDDLE TRIM PANEL (PDC)
REAR BUMPER BOTTOM TRIM PANEL (LINE
EMBLEM GROMMET
BMW PLAQUE WITH ADHESIVE FILM
LETTERING X1
REAR BUMPER HEAT INSULATION
CLIP
SENSOR WIRE FOR SMART OPENER TOP
SENSOR WIRE FOR SMART OPENER BOTTOM
ULTRASONIC SENSOR BLACK
DECOUPING RING PDC TORQUE CONVERTER

QTY

PRIC

VALUE

1	79.75	79.75
1	29.60	29.60
1	41.80	41.80
2	17.05	34.10
1	1,043.65	1,043.65
1	1,465.05	1,465.05
1	41.80	41.80
2	95.15	190.30
1	2,201.35	2,201.35
1	198.55	198.55
1	89.80	89.80
1	198.55	198.55
1	142.55	142.55
1	456.90	456.90
1	36.60	36.60
1	99.85	99.85
1	142.55	142.55
1	142.55	142.55
1	723.45	723.45
1	227.90	227.90
1	217.05	217.05
2	0.80	1.60
1	69.50	69.50
1	62.55	62.55
1	67.85	67.85
10	1.30	13.00
1	42.10	42.10
1	40.50	40.50
1	248.70	497.40
1	5.05	10.10

Total Parts : 8,608.30

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46021
Date Estimated : 23/02/2018
Prepared By : Han Kwan Yong

Page No. : 3 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGL321C	5E80973	04/11/2016	X1 sDrive20i	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 26/02/18 01500 Excess S\$ _____Surveyor's Name Rasul Sign _____Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 6 days

Labour 1	:	10,469.00
Parts	:	8,608.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,335.41
Grand Total	:	20,412.71

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **