

ASSIGNMENT

TOTAL

423

Ref. No :	CS/TP/8003560/Utton 2		Res. Date: 26/1/18	Date Received:
Veh. No :	SLD7205		SP:	WKSP: Bent
C/No :				
Action/Instruction:				
1. File	2. Submit Photo?	YES / NO		
3. Indicate Res. Date On Photo Page?	YES / NO		Message:	
If No, due to	a) No authorisation		b) Days of repair	
others:				
Final Re-inspection or Progress Photos				Inspected By:

13/02/2018 TUE 11:43 FAX

001/004

MGME18021839 / GME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 13/02/2018 10:25
 SUBMITTED BY: Faris Wen Ya Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available stored.

ACCIDENT STATEMENT

Date Of Report 13/02/2018 10:25
 Date Of Accident 12/02/2018 09:00
 Exact Location Of Accident KAKI BUKIT RD 2 TO KAKI BUKIT AVE 2.
 Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLD720S
 Insured/Policyholder
 Name Of Registered Owner YAP CHIN YEE
 NRIC No S8582235G
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-81333339
 Alternative Phone No OFFICE-81333339
 Vehicle Particulars
 Manufacturer AUDI
 Model A3
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR
 Insurance Company
 Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 2100502962
 Cover Note Number
 Driver
 Name of Driver KOO WEN CHUNG
 NRIC No S7873961D
 Date Of Birth 11/01/1978
 Occupation INDOOR
 Date Of Driving Pass 01/06/2017
 Driving Experience 0 YEAR AND 8 MONTH
 Gender MALE
 Mobile Number (LOCAL) +65-93898823
 Fax Number
 Contact Number
 Email Address NOEMAIL

13/02 2018 TUE 11:43 FAX

002/004

Address 398 CHANGI ROAD #03-10
 Postcode 419977
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

ON 12/02/2018 AT ABOUT 9AM, I WAS DRIVING ON KAKI BUKIT ROAD 2. I WAS ABOUT TO COME TO A STOP, WHEN THE TRAFFIC LIGHT IS STILL RED. SUDDENLY VEHICLE B CAME FROM BEHIND AND HIT THE REAR OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJX1612H
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver HOO YONG KWEE
 NRIC/Passport Number
 Contact Number 97978058
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 1

13/02 2018 TUE 11:43 FAX

003/004

Accident Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/email packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Yap
Policyholder's Signature

Date & Time: 13/2/18, 10am

Barry
Driver's Signature

(If driver is not the policyholder)

Date & Time: 13/2/18, 10am

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

GUARAC SketchPlanForm_V.3


Binnel

13/02 2018 TUE 11:44 FAX

004/004

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12/2/18 at about 9am, I was driving on Kaki Bukit Road 2. I was about to come to a stop when the traffic light is still red. Suddenly vehicle B came from behind and hit the rear of my vehicle.

DECLARATION

We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature

Date & Time: 13/2/18, 10am

GARMC SketchPlanForm_V3

[Signature]
Driver's Signature

(if driver is not the policyholder)

Date & Time: 13/2/18, 10am

Bmw

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

2

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2235G
Vehicle Details	
Vehicle No.:	SLD720S
Vehicle to be Exported:	No
Intended De-registration Date:	26 Feb 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.4 TFSI (ATTRACTION)
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	CZC520093
Chassis No.:	WAUZZZ8V7G1075572
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$25,124.00
Original Registration Date:	01 Jun 2016
First Registration Date:	01 Jun 2016
Transfer Count:	1
Actual ARF Paid:	\$17,174.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 May 2026
PARF Rebate Amount:	\$12,880.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$49,700.00
COE Rebate Amount:	\$38,854.00
Total Rebate Amount:	\$51,734.00

The information contained herein is correct as at 26 Feb 2018

OK



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
(Unit C) #01-51/53/55 Singapore 417883
Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088

Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg

Co. Reg. No.: 200704951N

GST Reg. No.: 200704951N

Not Affected
2/5 @ \$200
body.

Acknowledged by Repairer

Signature:

Date:

SCD7205

	Boottlid	R	1620.00	X
	Boottlid Rear logo	rel	91.00	✓
	Boottlid 'TFSI' emblem	rel	88.00	✓
	Boottlid weatherstrip	twl	148.00	✓
	Boottlid inner lock	in	166.00	X
	Rear bumper	2D	1213.00	✓
	Rear bumper lower skirting	de/cu	322.00	✓
2 pcs	Rear bumper side retainers @ 65.00	rel	130.00	✓
	Rear bumper reinforcement	2D	366.00	✓
	Rear bumper inner top retainer	cm	185.00	✓
1 set	Rear bumper clips	rel	60.00	✓
2 pcs	Rear bumper reverse sensors @ 165.00	shock	330.00	✓
	Rear bumper towing cover	in	38.00	X
2 pcs	Tail lamps @ 695	o/c one	1390.00	1 pc
	Rear end panel outer	2x500	525.00	✓
	Rear end panel lower	e	248.00	X
	Rear end panel top garnish	twl/cne	192.00	✓
	Rear end panel sealant	rel	50.00	✓
		5%	7162.00	4395
	To check wiring		50.00	30
	To dismantle & replace reverse sensor		80.00	50
	To transfer Boottlid mechanism		80.00	✓
	To dismantle & ref. x seat cushion upholstery		120.00	100
	To spray rust proofing		80.00	50
	labour for panel beating, cut, weld, straighten		1080.00	850
	replacing parts			
	To putty & spray painting		1500.00	1200
	TOTAL		\$10152.00	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP18003560/Utbn2

BLK 1 KAKI BUKIT AVE 6
#01-28/51/53/55(MAIN OFFICE)SINGAPORE
417883

Date : 27-03-2018



ON BEHALF OF YAP CHIN YEE

Code : TP149

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SLD 720S
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	21/02/2018

2. Vehicle Particulars & Condition

Make & Model	AUDI A3 (A)	c.c	1395
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WAUZZZ8V7G1075572	Colour	WHITE
Odometer	24430	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 ZR18	MICHELIN	7 mm
L/H Front Tyre	225/40 ZR18	MICHELIN	7 mm
R/H Rear Tyre	225/40 ZR18	MICHELIN	7 mm
L/H Rear Tyre	225/40 ZR18	MICHELIN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	12/02/2018	Inspection Date	21/02/2018
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 720S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	TO REPAIR SEE LABOUR	1,620.00	-
1	BOOTLID REAR LOGO	NECESSARY	91.00	91.00
1	BOOTLID "TFSI" EMBLEM	NECESSARY	88.00	88.00
1	BOOTLID WEATHERSTRIP	TWISTED	148.00	148.00
1	BOOTLID INNER LOCK	NOT NECESSARY	166.00	-
1	REAR BUMPER	DENTED	1,213.00	1,213.00
1	REAR BUMPER LOWER SKIRTING	DEFORMED / CUT	322.00	322.00
2	REAR BUMPER SIDE RETAINERS @\$65.00	NECESSARY	130.00	130.00
1	REAR BUMPER REINFORCEMENT	DENTED	366.00	366.00
1	REAR BUMPER INNER TOP RETAINER	CRACKED	185.00	185.00
1	SET REAR BUMPER CLIPS	NECESSARY	60.00	60.00
2	REAR BUMPER REVERSE SENSORS @\$165.00	SHORTED	330.00	330.00
1	REAR BUMPER TOWING COVER	NOT NECESSARY	38.00	-
2	TAILLAMPS @\$695.00	O/S CRACKED	1,390.00	695.00
1	REAR END PANEL OUTER	BADLY DENTED	525.00	525.00
1	REAR END PANEL LOWER	TO REPAIR SEE LABOUR	248.00	-
1	REAR END PANEL TOP GARNISH	TWISTED / CRACKED	192.00	192.00
1	REAR END PANEL SEALANT	NECESSARY	50.00	50.00
	LESS 5% DISCOUNT		-	-219.75
			7,162.00	4,175.25
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO TRANSFER BOOTLID MECHANISM.		80.00	80.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		120.00	100.00
	TO SPRAY RUST PROOFING.		80.00	50.00
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID AND REAR END PANEL LOWER.		1,080.00	850.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,200.00
			2,990.00	2,360.00
	GRAND TOTAL		10,152.00	6,535.25

Report Ref No. CS/TP18003560/Utn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,200.00
---	--	--	----------

Report Ref No. CS/TP18003560/Utn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.