

Surgeur

Tayfin

REF: 17h

ASSIGNMENT

From: _____ Date: 21/03/2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 914 8549Y
at Workshop m/s Performane
of 303 Alexandra Rd

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Gomy

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair:

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

____ \$ + RS ____ \$

Photos

Others

TOTAL

Veh No: 914 8549Y

Yr Regn: 2016, Nov.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 420i

c.c. 2198

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 16915

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

WR A4D3 20806 754126

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 0 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

D.O.I. 21/3/18 @ 4pm

Survey held at pml

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.