

SS. REC. BY:

REF: CS / SPF 18003599 / K 902

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Abdul Rahman of SPF Date/Time: 26/02/2018

Estimated Cost: Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLR 9963A Insured: GZ 3371P

at Workshop m/s: Sin Ming Autocare Tel: 6455 0600

of Blk 176 Sin Ming Drive #02-05

Policy No: Claim No: AEMD / 105 / 009 / 2018 / 016

Sum Insured: Excess:

Make of Veh: D.O.A. 22.02.2018 (Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi' 28.02.2018 @ after 10am H.O.D. Endorsement:

Date/Time: 26/02/2018 1:30pm Person Contacted: Nurul Ain Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate	not Analyse
	SLR 9963A - X	
	GZ 3371P - X	
	L1 Rep @ 1400 (Paid \$ 4132.76, 75%)	

ASSIGNMENT

From: _____ Date: **28/02/2018**

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SLR 9963A**

at Workshop no: **376 Sin Ming Autocare**

of: **176 Sin Ming Dr #02-05**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: **SLR 9963A** Tr Page: **09 09**

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____

Make: **Honda Airwave** cc: **1496**

Colour: **M. Grey** A/C: Insured / Std / NI / NA

Sp Reading: **138531** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **GJI 1305251**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Mod: Nil / S/Rim / ST2 A/Rim or _____

Remark: **after 10am** The veh had commenced its repair at the time of inspection.

N/S	O/S

Tyre Size: F: **185/60R14**
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR. Seen: _____ Consistent? : Yes or No

Est. Repairs: **02** days Res: Yes or No

Lum Sum: **20** % 3 Val: Yes or No

Front: _____ Rear: _____

R/Bal: **6** mm R/Bal: **8** mm

L/Bal: **6** mm L/Bal: **8** mm

D.O.A: **22/2/18** D.O.I: **28/2/18**

Survey held at:

CA / REV / REP. / 24 HRS **WP**

Date: _____ Person Contacted: _____ Vehicle IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

1/3 PM pass to Customer

RECEIVED 28 MAR 2018

Date/Time: File Pass to? : Preli. Report

28/3 10:15 AM : Final Report

Date/Time: File Return to? _____

Report Format: **TP**

Lump Sum / I.B. **1400**

Days Of Repair: **2**

Resurvey No. of Trip: **2**

Survey Fee: _____

Transportation: _____

Add Fee: Site Insp: \$ _____

Interview: \$ _____

Tech. Insp: \$ _____

Weekend: \$ _____

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref : CS/SPF18003599/Kqb

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)
1 MOUNT PLEASANT ROAD
BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 26-02-2018



Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 3371P	Veh. Inspected	SLR 9963A
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/016	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	26/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/02/2018	Inspection Date	28/02/2018
Survey held at	SIN MING AUTOCARE BFG PTE LTD 176, SIN MING DRIVE #02-05 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SLR9963A

Our Ref : AEMD/105/009/2018/016

Date : 26 February 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933
Dear Elaine,

Via Fax only: 62564315

ACCIDENT ON 22 FEBRUARY 2018 INVOLVING GOVT VEHICLE GZ3371P AND OTHER VEHICLE SLR9963A

Dear Sir/Madam,

We refer to the above matter.

- 2 Please assist to arrange for a PRI of Vehicle no. **SLR9963A** at **M/s Sin Ming Autocare BFG Pte Ltd** of **176 Sin Ming Drive, #02-05 Sin Ming Autocare, Singapore 575721.**
- 3 For appointment kindly contact **Nur Ain** at **Tel: 64550600.**
- 4 Estimates were not provided by the workshop.
- 5 Thank you.

Yours faithfully,

Abdul Rahman
Accident Claims Officer
for Assistant Director

A FORCE FOR THE NATION

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/02/2018 14:27
Date Of Accident	22/02/2018 12:30
Exact Location Of Accident	ALONG BUKIT PANJANG RING ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR9963A
Insured/Policyholder	
Name Of Registered Owner	KEITH CHIA ZHEN GUANG
NRIC No	S8833542B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81894361
Alternative Phone No	OFFICE-81894361

Vehicle Particulars

Manufacturer	HONDA
Model	AIRWAVE-1.5 M (A)
Exact Purpose for which vehicle was being used at time of accident	GOING TO WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT000833
Cover Note Number	

Driver

Name of Driver	KEITH CHIA ZHEN GUANG
NRIC No	S8833542B
Date Of Birth	11/09/1988
Occupation	OUTDOOR
Date Of Driving Pass	28/01/2010
Driving Experience	8 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81894361
Fax Number	
Contact Number	OFFICE-81894361
EMail Address	NOEMAIL

Address	BLK 161 BISHAN STREET 13 #17-148
Postcode	570161
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TAN ZHI XIN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ3371P
Vehicle Make/Model/Colour	POLICE CAR
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name: **TAN JENNY**
 NRIC/ID No:



Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At approx 1230pm, 23 Feb 2017, I, driver of SLR4963A came to a stop behind a police car, G23371P at a red light traffic junction

We are about 1/3 car length away from G23371P

The police car started reversing slowly. I honk at the police vehicle when the distance became too close but it was too late and the front vehicle had hit my car

I could not reverse as there were vehicles behind me as well.


DECLARATION

(We declare the foregoing particulars are true in every respect)

Policyholder's Signature:
Date & Time:

Driver's Signature
(If driver is not the policyholder):
Date & Time:

Reporting Centre/Personnel's Signature:
Name:
NRIC/PTN No:





Sin Ming Autocare BFG Pte Ltd

176, Sin Ming Drive #02-05
Sin Ming Autocare Complex
Singapore 575721
Tel : (65) 6455 0600
Fax : (65) 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

AUTOMOTIVE ENGINEERING & MANAGEMENT DIVISION
POLICE LOGISTICS DEPARTMENT
1 MOUNT PLEASANT ROAD 298333
BLOCK & OLD POLICE ACADEMY
Attention : Motor Claim Department

Estimate : E18/2419

Date : 28/02/2018

Vehicle Num. : SLR9963A

Make/Model : HONDA AIRWAVE 1.5A-2009

Chassis/Eng# : GJ11305251/L15A5206353

Accident Date : 22/02/2018

Claim No. : BFG

Reference : TP CLAIM

Policy No. : MT000833

*Not Authorized
L15A @ 1400
Resurvey After Paint
2 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1PC	FRONT BUMPER <i>1050</i>		<i>Ru</i> 1,202.00 ✓
2.	1PC	TOWING COVER		<i>Su</i> 32.00 X
3.	1PC	FRONT BUMPER LOWER GRILLE GARNISH		<i>Su</i> 136.00 X
4.	2PCS	FRONT BUMPER SIDE GARNISH COVER	55.00	<i>Su</i> 110.00 X
5.	1PC	FRONT GRILLE		<i>CM</i> 204.00 ✓
6.	1PC	FRONT GRILLE MOULDING		<i>Su</i> 335.00 X
7.	1PC	EMBLEM		<i>Su</i> 29.80 ✓
8.	1PC	HEADLAMP LH		<i>Su</i> 655.40 X
9.	1PC	HEADLAMP RH		<i>Su</i> 655.40 X
10.	2PCS	BUMPER BRACKET	35.70	<i>R</i> 71.40 X
11.	1PC	BUMPER REINFORCEMENT		<i>R</i> 238.30 ✓
12.	2PCS	FRT BUMPER RETAINER	18.90 <i>dispi</i>	37.80 ✓
13.	1PC	FRT SUPPORT PANEL		<i>R</i> 506.40 X
14.	1PC	FRT FENDER RH		<i>R</i> 536.20 X
List Total S\$:				4,749.70
20.00% Discount S\$:				949.94
				3,799.76
SPECIAL NETT ITEMS :				
1.	6PCS	BUMPER CLIPS	3.00	<i>Me</i> 18.00 ✓
2.	1PC	FRT NUMBER PLATE		<i>Su</i> 30.00 X
3.	1PC	FRT NUMBER PLATE GARNISH		<i>Su</i> 25.00 X
Special Nett Total S\$:				73.00
LABOUR :				<i>32d</i>
TO SPRAY PAINT DAMAGED ON AFFECTED AREAS				800.00

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Sin Ming Autocare BFG Pte Ltd

176, Sin Ming Drive #02-05
 Sin Ming Autocare Complex
 Singapore 575721
 Tel : (65) 6455 0600
 Fax : (65) 6455 6192
 Website: www.autocare.com.sg
 GST Reg. No: 20-0210033-N

AUTOMOTIVE ENGINEERING & MANAGEMENT DIVISION
 POLICE LOGISTICS DEPARTMENT
 1 MOUNT PLEASANT ROAD 298333
 BLOCK & OLD POLICE ACADEMY
 Attention : Motor Claim Department

Estimate : E18/2419

Date : 28/02/2018
 Vehicle Num. : SLR9963A
 Make/Model : HONDA AIRWAVE 1.5A-2009
 Chassis/Eng# : GJ11305251/L15A5206353
 Accident Date : 22/02/2018
 Claim No. : BFG
 Reference : TP CLAIM
 Policy No. : MT000833

S/N	Quantity	Particular	Unit Price	Amount S\$
		RUST PROOFING TREATMENT		60.00 X
		TO REMOVE & REINSTALL FRONT BUMPER AND CHANGE ALL THE PARTS AS ABOVE.		200 } 300.00
		TO PANEL BEATING & REALIGNMENT ON FRONT SUPPORT PANEL AND ALL AFFECTED AREAS		200 } 400.00
		TO FOCUS HEADLAMP		151.5 } 50.00
		TO CHECK WIRING FOR PROPER FUNCTION		50.00
		Labour Total S\$:		1,660.00

E. & O.E.

Total S\$: 5,532.76
 =====


 for Sin Ming Autocare BFG Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18003599/Kqbn2

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)
1 MOUNT PLEASANT ROAD
BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 28-03-2018



Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 3371P	Veh. Inspected	SLR 9963A
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/016	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	26/02/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA AIRWAVE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	GJ11305251	Colour	METALLIC GREY
Odometer	138531	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R14	YOKOHAMA	6 mm
L/H Front Tyre	185/60 R14	YOKOHAMA	6 mm
R/H Rear Tyre	185/60 R14	YOKOHAMA	8 mm
L/H Rear Tyre	185/60 R14	YOKOHAMA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/02/2018	Inspection Date	28/02/2018
Survey held at	SIN MING AUTOCARE BFG PTE LTD 176, SIN MING DRIVE #02-05 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 9963A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	BUCKLED	1,202.00	1,050.00
1	TOWING COVER	SERVICEABLE	32.00	-
1	FRONT BUMPER LOWER GRILLE GARNISH	SERVICEABLE	136.00	-
2	FRONT BUMPER SIDE GARNISH COVER @\$55.00	SERVICEABLE	110.00	-
1	FRONT GRILLE	CRACKED	204.00	204.00
1	FRONT GRILLE MOULDING	SERVICEABLE	335.00	-
1	EMBLEM	NECESSARY	29.80	29.80
1	HEADLAMP LH	SERVICEABLE	655.40	-
1	HEADLAMP RH	SERVICEABLE	655.40	-
2	BUMPER BRACKET @\$35.70	TO REPAIR SEE LABOUR	71.40	-
1	BUMPER REINFORCEMENT	BENT	238.30	238.30
2	FRT BUMPER RETAINER @\$18.90	O/S DISTORTED	37.80	18.90
1	FRT SUPPORT PANEL	TO REPAIR SEE LABOUR	506.40	-
1	FRT FENDER RH	TO REPAIR SEE LABOUR	536.20	-
	LESS 20% DISCOUNT		-949.94	-308.20
			3,799.76	1,232.80
<u>SPECIAL NETT ITEMS</u>				
6	BUMPER CLIPS @\$3.00 (SN)	NECESSARY	18.00	18.00
1	FRT NUMBER PLATE (SN)	SERVICEABLE	30.00	-
1	FRT NUMBER PLATE GARNISH (SN)	SERVICEABLE	25.00	-
			73.00	18.00
<u>LABOUR</u>				
	TO SPRAY PAINT DAMAGED ON AFFECTED AREAS. RUST PROOFING TREATMENT.	NOT NECESSARY	800.00	320.00
	TO PANEL BEATING & REALIGNMENT ON FRONT SUPPORT PANEL AND ALL AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF BUMPER BRACKET,FRT SUPPORT PANEL AND FRT FENDER RH. }		400.00	200.00
	TO REMOVE & REINSTALL FRONT BUMPER AND CHANGE ALL THE PARTS AS ABOVE. }		300.00	-
	TO FOCUS HEADLAMP. }		50.00	15.00

Report Ref No. CS/SPF18003599/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING FOR PROPER FUNCTION. }		50.00	-
			1,660.00	535.00
GRAND TOTAL			5,532.76	1,785.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,400.00

Report Ref No. CS/SPF18003599/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.