

Your ref: CMTD1800787/GPL

Our ref: CS/SMO18003612/Uvd3

DATE: 1/3/2018

The Motor Claims Department

M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam

**PRELIMINARY ADVICE OF VEHICLE NO. SKS 989S**


We thank for your instruction on 23/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/2/2018 at the premises of M/s M-TECH MOTOR SERVICES and have the following to report:-

Workshop Estimate Amount	:S\$4,936.00
Revised Estimate Amount	:S\$2,565.70
"Check" Items Amount	:S\$1,631.70
Market Value	:S\$
LTA Reimbursement Value	:S\$
Nett Value	:S\$

**Description of Damage:**

The vehicle sustained damages at the rear portion



**Comments/Present Status:**

Damages Consistent

Yours faithfully,

MARCUS CHUA

**Licensed Appraiser**