

22/03/2003

ASS. REC BY:

REF: CS / SMO180036/2 / Urd3 / Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person) Grace Teo of SMO Date/Time: 23/2/18 3:12pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: Sks989S Insured: SJU 41582at Workshop m/s M-Tech Motor Tel: 97354567of Blk 900S, Tampines St. 93 # 01-252Policy No: _____ Claim No: CMTD1806787 / GPL

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 20/02/2018
(Client's Record)CA / REV / REP. / REV 24 HRS lwp 27/2/18 9am-12pm
Date/Time: 4:12pm 26/2/18 Person Contacted: Mr. Chen H.O.D. Endorsement: _____Vehicle IN OUT

Date/Time	Action/Instruction
	(<u>✓</u>) Estimate
	<u>Sks989S-CVI / VAL1701606E / TIV D.O.A: 11/8/17</u>
	<u>SJU 41582-x</u>
<u>1/3/18</u>	<u>Email preli revised to Grace</u>

SMD

Date 27/2/18

SKS 989S

Reg 12 11

① WS/TP RES/OD RES/EVA/INV/MV

To inspect vehicle No SKS 989S
at Workshop No M-Tech Motor

Blk 9005 tempines tempines st 93 #01-252

Insured

Policy No

Claims No

Sum Insured

Excess

Onsite Report

9am-12pm

Make of Van

(Policy Condition)

Remark: The van had commenced its repair at the time of inspection.

NS	OS

Sal. or Market Value

IDAO Accident Report

Consistent? Yes or No

Gr. or Seen

Consistent? Yes or No

Est. Repairs

3

days

Res

Yes or No

Est. Sum

20

to

3 Val

Yes or No

CA / REV / REP / 24 HRS / up

Date

Person Contacted

Vehicle IN / OUT

Make

BMW 730L

2996

Colour

white

Registration

128779

Engine

WBAKB 22080 C 951 375

Chassis

Gen. Cond. Good Fair Poor Burnt

Steering Ind. Jammed Locked Burnt

Brake Ind. Jammed Locked Burnt

Mod. Nil STD A/R

Tyre Size

245/50 R18

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/SUMI

TOYO/YOKO

Front

8

Rear

8

Rise

8

Rise

8

Loss

8

Loss

8

DOA

20/2/18

DOA

27/2/18

Surveyed at

See of Damages Fr. Rear OS NS LC / Referred to

Reer

The UIC / Chassis frame / Body Structure affected due to collision

26/3/18 2/5 @ 2800 confirmed with MR Chan. (Red 136, 439)

RECEIVED 4 APR 2018

Date Time File Passed

☐ Prel. Report
☐ Final Report

Prel. Report

Final Report

Days Of Repair

3

Resurvey No. of Trip

1

Date Time File Return

4/4 - typist

Add Fee

☐ Site Fee
☐ Trip Fee
☐ Rep. Fee
☐ Other Fee

Site Fee

Trip Fee

Rep. Fee

Other Fee

Report Form

TP

Auto Sum

LS 2800p

Survey Department Check List (Case Handler)

Reference No. : CS | SM018003612 | Urd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 4/4/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18003612/Uvd3		
50 RAFFLES PLACE		Date : 26-02-2018		
#05-01/06		Code : SMO		
SINGAPORE LAND TOWERS SINGAPORE 048623				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJU 4158Z	Veh. Inspected	SKS 989S	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1800787/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	26/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/02/2018	Inspection Date		
Survey held at	M-TECH MOTOR SERVICES BLK 9005 TAMPINES STREET 93 #01-252, TAMPINES INDUSTRIAL PARK A SINGAPORE 528839			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 19960719

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 625643

Your ref: CMTD1800787/GPL

Our ref: CS/SMO18003612/Uvd3

DATE: 1/3/2018

The Motor Claims Department
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam

PRELIMINARY ADVICE OF VEHICLE NO. SKS 989S


We thank for your instruction on 23/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/2/2018 at the premises of M/s M-TECH MOTOR SERVICES and have the following to report:-

Workshop Estimate Amount	:S\$4,936.00
Revised Estimate Amount	:S\$2,565.70
"Check" Items Amount	:S\$1,631.70
Market Value	:S\$
LTA Reimbursement Value	:S\$
Nett Value	:S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 1 March 2018 11:33 AM
To: 'Teo, Grace'
Cc: 'Gnoh, Pau Loong'; SUR
Subject: RE: CMTD1800787/GPL - ACCIDENT INVOLVING SJU4158Z & SKS989S on 20.02.2018
Attachments: SKS 989S PRELI ADVISED.pdf

Dear Grace,

Enclosed preliminary revised of vehicle SKS 989S
Date of survey: 27/2/2018
Number of days:3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 26 February 2018 4:26 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Gnoh, Pau Loong' <PauLoong.Gnoh@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1800787/GPL - ACCIDENT INVOLVING SJU4158Z & SKS989S on 20.02.2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Friday, 23 February 2018 3:12 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Kuru & Co <kurulegal@yahoo.com.sg>; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>
Subject: CMTD1800787/GPL - ACCIDENT INVOLVING SJU4158Z & SKS989S on 20.02.2018

^ Our Reference : CMTD1800787/GPL

* Dear LKK AUTO/ MARCUS,

Please make arrangement to conduct the survey for SKS989S.

Please be informed that Gnoh Pau Loong the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Kuru & Co [<mailto:kurulegal@yahoo.com.sg>]

Sent: Friday, February 23, 2018 3:02 PM

To: Teo, Grace

Cc: Gnoh, Pau Loong

Subject: Re: CMTD1800787/GPL - ACCIDENT INVOLVING SJU4158Z & SKS989S on 20.02.2018

Hi Grace

We refer to your letter of 22.02.2018.

Our client is agreeable to the following surveyor(s) as the SJE: LKK : Marcus Chua

Please arrange for your surveyor to survey our client's vehicle at the following address:

M-TECH MOTOR SERVICES

Blk 9005 Tampines St 93 #01-252

Singapore 528839

Tel: 97354567 Mr Chan

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey(s).

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Regards
Irene
Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

From: "Teo, Grace" <grace.teo@sompo.com.sg>
To: "kurulegal@yahoo.com.sg" <kurulegal@yahoo.com.sg>
Cc: "Gnoh, Pau Loong" <PauLoong.Gnoh@sompo.com.sg>
Sent: Thursday, 22 February 2018, 11:58
Subject: CMTD1800787/GPL - ACCIDENT INVOLVING SJU4158Z & SKS989S on 20.02.2018

Our Reference : CMTD1800787/GPL
Your Reference: L.18.0289.AT.cj

Without Prejudice

EMAIL ONLY

Date: 22nd February 2018

**Attention:
M/S KURU & CO**

Dear Sirs,

ACCIDENT INVOLVING SJU4158Z & SKS989S on 20.02.2018

We refer to your Notice of Accident dated 22/02/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	

		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Yours faithfully,

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Friday, 23 February 2018 3:12 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Kuru & Co; Gnoh, Pau Loong
Subject: CMTD1800787/GPL - ACCIDENT INVOLVING SJU4158Z & SKS989S on 20.02.2018

Our Reference : CMTD1800787/GPL

Dear LKK AUTO/ MARCUS,

Please make arrangement to conduct the survey for SKS989S.

Please be informed that Gnoh Pau Loong the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]

Sent: Friday, February 23, 2018 3:02 PM

To: Teo, Grace

Cc: Gnoh, Pau Loong

Subject: Re: CMTD1800787/GPL - ACCIDENT INVOLVING SJU4158Z & SKS989S on 20.02.2018

Hi Grace

We refer to your letter of 22.02.2018.

Our client is agreeable to the following surveyor(s) as the SJE: LKK : Marcus Chua

Please arrange for your surveyor to survey our client's vehicle at the following address:

M-TECH MOTOR SERVICES
Blk 9005 Tampines St 93 #01-252
Singapore 528839
Tel: 97354567 Mr Chan

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey(s).

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Regards
Irene
Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

From: "Teo, Grace" <grace.teo@sompo.com.sg>
To: "kurulegal@yahoo.com.sg" <kurulegal@yahoo.com.sg>
Cc: "Gnoh, Pau Loong" <PauLoong.Gnoh@sompo.com.sg>
Sent: Thursday, 22 February 2018, 11:58
Subject: CMTD1800787/GPL - ACCIDENT INVOLVING SJU4158Z & SKS989S on 20.02.2018

Our Reference : CMTD1800787/GPL
Your Reference: L.18.0289.AT.cj

Date: 22nd February 2018

Without Prejudice

EMAIL ONLY

Attention:
M/S KURU & CO

Dear Sirs,

ACCIDENT INVOLVING SJU4158Z & SKS989S on 20.02.2018

We refer to your Notice of Accident dated 22/02/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

- We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Yours faithfully,

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential

and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/02/2018 11:39
Date Of Accident	20/02/2018 08:00
Exact Location Of Accident	JUNCTION OF UPPER CHANGI ROAD NORTH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS989S
Insured/Policyholder	
Name Of Registered Owner	TAN AI LIAN
NRIC No	S1713968A
Email Address	MTECH-SERVICES@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96601010
Alternative Phone No	OFFICE-96601010

Vehicle Particulars

Manufacturer	BMW
Model	730LI AT ABS D/AB 2WD 4DR NAV HID SR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA300159
Cover Note Number	09/12/2017-08/12/2018

Driver

Name of Driver	TAI MOK YAM
NRIC No	S2560203Z
Date Of Birth	15/12/1963
Occupation	INDOOR
Date Of Driving Pass	18/01/1983
Driving Experience	35 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91087170
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	164 MARIAM WAY 07-01
Postcode	507086
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJU4158Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	BOON CHOON HIONG
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A S/KS 989 S
B SJU 4158 J.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving on 20-2-18 around 7:55am along upp changi Rd north going turn. & I stop my car for traffic to clear. Suddenly ~~knock~~ Vehicle B knocked. to rear bumper of my Car A

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Date: 21/2/18

To: Owner of Vehicle Number: SKS989S

The following has been advised to you via your workshop, staff, Enkelmi through their _____



Please tick the applicable box if you had been advice on the content as seen below:

- (1) You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- (1) You had been advised by the workshop on the liability and merits of the case accordingly.
- (1) You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- (X) There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- (X) There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- (X) The estimated waiting time for the spare parts to arrive is _____. The estimated arrival time does not include the repair period.
- (X) You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.
- (X) For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.
- For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using **any combination** of genuine original parts and/or original equipment manufacturer (OEM) parts.
- (X) You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- (X) For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- (1) Others Claim @ other workshop

Signed and acknowledge by:

Name and signature of policyholder/authorised driver

Name and signature of workshop personnel including company stamp

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3968A
Vehicle Details	
Vehicle No.:	SKS989S
Vehicle to be Exported:	No
Intended De-registration Date:	14 Mar 2018
Vehicle Make:	B.M.W.
Vehicle Model:	730LI AT ABS D/AB 2WD 4DR NAV HID SR
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	12997953N52B30AF
Chassis No.:	WBAKB22080C951375
Maximum Power Output:	190.0 kW (254 bhp)
Open Market Value:	\$73,608.00
Original Registration Date:	09 Dec 2011
First Registration Date:	09 Dec 2011
Transfer Count:	1
Actual ARF Paid:	\$73,608.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Dec 2021
PARF Rebate Amount:	\$47,845.00
Intended COE Rebate Details	
COE Expiry Date:	08 Dec 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$77,340.00
COE Rebate Amount:	\$28,868.00
Total Rebate Amount:	\$76,713.00

The information contained herein is correct as at 14 Mar 2018

OK

M-TECH MOTOR SERVICES

Blk 9005 Tampines St. 93, #01-252 Tampines Industrial Park A, Singapore 528839
Tel: 6784 0077 Fax: 6788 3025

(Registration No. 269252/00B)

Tan Ai Lian

164 Mariam Way #07-01

Singapore 507056

Attention : Motor Claim Department

Estimate : TI030168

Date : 27/02/2018

Vehicle Num. : SKS 989 S

Make/Model : BMW 730i

Chassis/Eng# : WDD221 156 2A 206507

Accident Date : 20/02/2018

Claim No. :

Reference : MT/989/2018

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	Rear bumper	DO/OE	1,738.00
2.	1	Rear bumper reinforcement	1532-81	880.00
3.	2	Rear parking sensor	781.30	810.00
4.	1	Rear bumper trim	235x2-470	250.00
5.	1	Rear bumper adapter	219	88.00
6.	1	Rear bumper centre guide	11	35.00
7.	1	Tailpipe chrome	ms	85.00
List Total S\$:			405.00	3,886.00

LABOUR :

To respray accident affected parts

Renew rear bumper, rear bumper reinforcement, realign necessary parts

Labour Total S\$:

400 600.00
300 450.00
1,050.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

No illegal modification(s) is allowed

- Supplementary repair must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

for M-TECH MOTOR SERVICES

E. & O.E.

Total S\$: 4,936.00

Noted
LKK
LKK photo after repair
2/5 #2800
327
27/2/18

P-3176.15
10%
2858.53
1060 + 700
3558.53



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18003612/Uvd3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERS SINGAPORE 048623		Date : 06-04-2018		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJU 4158Z	Veh. Inspected	SKS 989S	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1800787/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	23/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	BMW 730LI (A)	c.c	2996	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WBAKB22080C951375	Colour	WHITE	
Odometer	128779	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/50 R18	PIRELLI	8 mm	
L/H Front Tyre	245/50 R18	PIRELLI	8 mm	
R/H Rear Tyre	245/50 R18	PIRELLI	8 mm	
L/H Rear Tyre	245/50 R18	PIRELLI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/02/2018	Inspection Date	27/02/2018	
Survey held at	M-TECH MOTOR SERVICES BLK 9005 TAMPINES STREET 93 #01-252, TAMPINES INDUSTRIAL PARK A SINGAPORE 528839			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 989S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED / DEFORMED	1,738.00	1,532.85
1	REAR BUMPER REINFORCEMENT	DENTED	880.00	781.30
2	REAR PARKING SENSOR @\$405.00	SHORTED	810.00	470.00
1	REAR BUMPER TRIM	DENTED / DEFORMED	250.00	219.00
1	REAR BUMPER ADAPTER	TORN	88.00	88.00
1	REAR BUMPER CENTRE GUIDE	NOT NECESSARY	35.00	-
1	TAILPIPE CHROME	MISSING	85.00	85.00
	LESS 10% DISCOUNT		-	-317.62
			3,886.00	2,858.53
	<u>LABOUR</u>			
	TO RESPRAY ACCIDENT AFFECTED PARTS.		600.00	400.00
	RENEW REAR BUMPER, REAR BUMPER REINFORCEMENT, REALIGN NECESSARY PARTS.		450.00	300.00
			1,050.00	700.00
	GRAND TOTAL		4,936.00	3,558.53
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,800.00

Report Ref No. CS/SMO18003612/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.