

ASS. REC. BY:

REF: C03/MSH18003629/WB57

Special Instructions: *Range*

Surveyor: *Wilson*

ASSIGNMENT (Office)

Melimen

From (Person): *Catherine Tina* of *MSIG* Date/Time: *26/02/2018 10:50am*

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: *SJX 8688T* Insured: *CGN 6565R*

at Workshop m/s *N-BI Automotive* Tel: _____

of *2 Kaki Bukit Ave 2 #01-17*

Policy No: *B27495275 SMP* Claim No: *549328*

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. *08/02/2018*
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP' *27.02.2018* H.O.D. Endorsement: _____

Date/Time: *26/02/2018 2:17pm* Person Contacted: *Elynn* Vehicle *IN* / *OUT*

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	<i>SJX 8688T - C03/MSH18003629/WB57 D.O.A. = 29/02/2018</i>
	<i>CGN 6565R - X</i>
	<i>Dismantle Part: 01.03.2018</i>
	<i>After repair: 05.03.2018</i>

3/1/18

PRS
Wilson

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SIX 8688 T

at Workshop in: Twin Car

of _____

Insured _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record) _____

Make of Veh: _____

(Policy Condition) _____

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

JDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No


Est. Repairs: _____ days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS _____

Date: _____ Person Contacted: _____

Vehicle: IN / OUT _____



Veh No: SIX 8688 T (Vr Regn) S/1/2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Jeep cc 2967

Colour: Green A.C. Insured / Std / NI / NA

Sp. Reading: 11558 T. Radio: Insured / Std / NI / NA

Eng No: _____

C.No: SATA C06 D99 F27066

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modif: Nil / S/Rim / STD A/Rim or _____

Tyre Size F: 245 / 45ZR18

R: 245 / 45ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front R. Bal: 4 mm

Rear R. Bal: 3 mm

L. Bal: 4 mm

L. Bal: 3 mm

D.O.A: 2/2/2018 D.O.I: 27/2/2018

Survey held at: As Above

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Range \$4900 - \$5900

4/4/2018

RECEIVED 06 APR 2018

Date/Time File Pass to: 06/04/2018

Date/Time File Return to: _____

Report Format: PRS

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: Site Insp (\$ _____)

Interview (\$ _____)

Techn. Insp (\$ _____)

Weekend (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Feb 2018		26 Feb 2018 10:50 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHIA KIM HUI KENNETH, ID: S7927399F, Tel: +6596979354, Email: KENNETH_CHIA79@HOTMAIL.COM								
Main Claimant:	Yeo Seng Chong Simon, ID: S1659261G								
Vehicle Reg. No.:	SJX8688T	Date of Loss:	08/02/2018 18:00 - :59						
Claim Type:	TP / 549328	Policy/Cover Note No.:	B27495275SMP (Comprehensive) Coverage: 28/03/2017 - 27/03/2018						
Vehicle Reg. No. (Insured):	SGN6565R	Policy No. (Claimant):							
		Excess:	S\$750.00						
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/02/2018]								
Driver/Custodian (Insured):	CHIA KIM HUI KENNETH (38 / Male), NRIC: S7927399F, Tel: +6596979354								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MSME18020268 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 09/02/2018 16:52
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/02/2018 16:52
Date Of Accident	08/02/2018 18:25
Exact Location Of Accident	PIE INTO CTE/WOODLANDS BEFORE BRADDELL RD EXIT (PI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX8688T
Insured/Policyholder	
Name Of Registered Owner	YEO SENG CHONG SIMON
NRIC No	S1659261G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96922170
Alternative Phone No	OFFICE-96922170
Vehicle Particulars	
Manufacturer	JAGUAR
Model	XF-3.0 V6 PREMIUM LUXURY (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA086575
Cover Note Number	
Driver	
Name of Driver	YEO WEI LIN @YEO WEI YING
NRIC No	S7141727A
Date Of Birth	20/11/1971
Occupation	INDOOR
Date Of Driving Pass	17/09/1994
Driving Experience	23 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98266525
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	1A MARGATE ROAD
Postcode	438040
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG THE PIE SERVICE ROAD INTO CTE/SLE BEFORE BRADDELL ROAD EXIT. WHILE DRIVING STRAIGHT AHEAD, SUDDENLY A VEHICLE BEARING (SLN5517C) STOPPED IT'S VEHICLE. SO, I TOO APPLIED BRAKE TO COMPLETE STOP. SUDDENLY, I FELT A GREAT IMPACT FROM THE REAR OF MY VEHICLE WHILE I CAME TO A COMPLETE STOP. I ALIGHTED FROM MY VEHICLE AND REALISED A VEHICLE (SGN6565R) THAT COLLIDED ONTO THE REAR OF MY VEHICLE. IT WAS A CHAIN COLLISION INVOLVING 3 VEHICLES.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGN6565R
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJF8187S
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE C
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1


SKETCH PLAN**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

PIE SERVICE ROAD INTO CTE/SLE BEFORE BRADDELL ROAD EXIT.

- VEHICLE A - SJX 8688T
- VEHICLE B - SQN 6565R
- VEHICLE C - SJF 8187S



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ALONG THE PIE SERVICE ROAD INTO CTE/SLE BEFORE BRADDELL ROAD EXIT.

WHILE DRIVING STRAIGHT AHEAD, SUDDENLY A VEHICLE BEARING (SQN 5517C) STOPPED ITS VEHICLE. AND SO I TOO APPLIED BRAKE TO COMPLETE STOP. SUDDENLY I FELT A GREAT IMPACT FROM THE REAR OF MY VEHICLE, WHILE I CAME TO A COMPLETE STOP.

I ALIGHTED FROM MY VEHICLE AND REALIZED A VEHICLE, AND REALIZED IT WAS A VEHICLE BEARING (SQN 6565R) THAT COLLIDED TO THE REAR OF MY VEHICLE. AND IT WAS A CHAIN COLLISION INVOLVING 3 VEHICLES.

VEHICLE A - SJX 8688T
 VEHICLE B - SQN 6565R
 VEHICLE C - SJF 8187S

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan #3 Pg. 1


LETTER OF UNDERTAKING

I/We, SEO SENA CHONG SIMON, the owner of vehicle no. SSX 76877

My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltd, I/we shall decide whether to claim under ~~my/our Policy~~ against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, N-SI AUTOMOTIVE PTE LTD

Signed and Acknowledge by:


.....
Name no. and signature of policyholder

.....
Company Stamp

09/02/2018
.....
Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Feb 2018		26 Feb 2018 10:50 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHIA KIM HUI KENNETH , ID: S7927399F, Tel: +6596979354, Email: KENNETH_CHIA79@HOTMAIL.COM		
Main Claimant:	Yeo Seng Chong Simon , ID: S1659261G		
Vehicle Reg. No.:	SJX8688T	Date of Loss:	08/02/2018 18:00 - :59 [109 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 549328	Policy/Cover Note No.:	B27495275SMP (Comprehensive) Coverage: 28/03/2017 - 27/03/2018
Vehicle Reg. No. (Insured):	SGN6565R	Policy No. (Claimant):	
		Excess:	S\$750.00
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 27/02/2018]		
Driver/Custodian (Insured):	CHIA KIM HUI KENNETH (38 / Male), NRIC: S7927399F, Tel: +6596979354		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJX8688T (549328)**
[SGN6565R]
TP

Yeo Seng Chong Simon
Feb 8 2018 6:00PM
[CHIA KIM HUI KENNETH]
N-51 Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser ▾
Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/02/18 09:39	Accident Statement From:OD - Reg. No: SGN6565R, Claimant: CHIA KIM HUI KENNETH	Load HTM	
Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
2	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
3	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
4	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
5	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
6	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
7	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
8	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
9	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
10	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
11	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
12	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
13	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
14	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
15	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
16	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
17	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
18	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
19	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
20	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
21	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
22	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
23	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
24	05/04/18 18:42	General View	Load JPG	<input checked="" type="checkbox"/>
25	05/04/18 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
26	05/04/18 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
27	05/04/18 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
28	05/04/18 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
29	05/04/18 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
30	05/04/18 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
31	05/04/18 18:43	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	05/04/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
33	05/04/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
34	05/04/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
35	05/04/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
36	05/04/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
37	05/04/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
38	05/04/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
39	05/04/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
40	05/04/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
41	05/04/18 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
42	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	06/04/18 15:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
71	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
72	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
73	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
74	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
75	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
76	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
77	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
78	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
79	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
80	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
81	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
82	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
83	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
84	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
85	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
86	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
87	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
88	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
89	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
90	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
91	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
92	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
93	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
94	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
95	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
96	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
97	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
98	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
99	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
100	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
101	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>
102	06/04/18 15:14	General View	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/02/18 09:39	(1/3) SJX8688T E FILE REPORT From:OD - Reg. No: SGN6565R, Claimant: CHIA KIM HUI KENNETH	 Load PDF	
2	26/02/18 09:39	PRI Request - TP GIA Report.	 Load PDF	
3	26/02/18 10:52	PRI Details	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18003629/WBS2
Date: 09/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B27495275SMP
Claimant Vehicle No: SJX8688T Insured Vehicle No: SGN6565R
Date of Loss: 08/02/2018 Nature of Claim: TP Claim No: 549328

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJX8688T**
Make & Model: JAGUAR XF, 3.0 V6 PREMIUM LUXURY (A) Engine No: 576836367FC
Reg. Date: 05/01/2009 (Man. Year: 2008) Chassis No: SAJAC06D49FR27066
Colour: Green Odometer: 111588 km
Engine Capacity: 2967 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/45ZR18 Rear Tyre Size: 245/45ZR18
Front Left Side: Michelin 4 mm Rear Left Side: Michelin 3 mm
Front Right Side: Michelin 4 mm Rear Right Side: Michelin 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 26/02/2018
Date Inspected: 27/02/2018 Inspected At: N-51 Automotive Pte Ltd (HQ)
Singapore 417921
Estimated Period of Repair: 0.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/9/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,900.00 - \$5,900.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Apr 2018)

Parts: 143 JAGUAR XF 3.0 V6 PREMIUM LUXURY (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJX8688T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >