

22/03/2002

ASS. REC. BY:

REF:

CS/MS618003632/Tlr/bnz

Special Instruction:

ASSIGNMENT (Office)

Signature:

From (Person):

Catherine Trig

of

M866

Date/Time: 26/02/2018 11:11am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJV 830111

Insured:

SJN 6936T

at Workshop m/s

Cheng Auto

Tel:

6631 0707

of

5 Soan Lee St #01-62

Policy No:

S28880740SMF

Claim No:

5491189

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13/02/2018

(Client's Record)

28.02.2018 @ after 3pm

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

26/02/2018 2:10pm

Person Contacted:

Michael

Vehicle-IN/COUT

Date/Time	Action/Instruction (✓) Estimate
	SJV 830111 - X
	SJN 6936T - X
	Sent preli thru email

Singapore Taylors

REF: mscn

ASSIGNMENT

From: Date: 28/02/2018

Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJV 8304L

at Workshop m/s: Cheng Auto

of: 5 Soon Lee St #01-62

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

after spm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJV 8304L Yr Regn: 2020 Feb.

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hundai Avante cc: 1591

Colour: Maroon A/C: _____ Insured / Std / NI / NA

Sp. Reading: 156 929 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH04413 MAY 98/67

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R15 R: _____

PS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.A. <u>28/2/2015 pm</u>

Survey held at: Cheng Auto

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision: _____

Date / Time Action / Instruction

Confirm L/S \$1600 @ 4 days
red. 5603.04, 781.

RECEIVED 18 MAY 2018

Date/Time File Pass to? ☐ : Preli. Report ☒ : Final Report

by: typut

Date/Time File Return to? _____

Report Format: TP

Lump Sum / 12m: 1600

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp \$ ☐ Interview \$ ☐ Tech Insp \$ ☐ Weekend \$

Survey Fee: _____

Transporter: _____

Photos: _____

Notes: _____

200
10
210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18003632/T1rb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 26-02-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 6936T	Veh. Inspected	SVJ 8304L	
Policy No.	S28880740SMF	Coverage (\$)	0.00	
Claim No.	549489	Excess (\$)	0.00	
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	26/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/02/2018	Inspection Date		
Survey held at	CHENG AUTO BODYWORKS 1 SOON LEE STREET #06-41 PIONEER CENTRE SINGAPORE 627605			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Feb 2018 17:05 Sendback Est	22 Feb 2018 12:53 \$47,130.68	26 Feb 2018 11:11 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	VEMPU SANKARAN, ID: S77608071		
Main Claimant:	NG KIAN BOON, ID: S8009370E		
Vehicle Reg. No.:	SJV8304L	Date of Loss:	13/02/2018 09:00 - :59
Claim Type:	TP / 549489	Policy/Cover Note No.:	S28880740SMF (Comprehensive) Coverage: 25/02/2017 - 24/02/2018
Vehicle Reg. No. (Insured):	SJN6936T	Policy No. (Claimant):	18-MW008691-R02
		Excess:	S\$500.00
Repairer:	Cheng Auto Bodyworks (HQ) 5 Soon Lee Street #01-62 Pioneer Point, 627607 Pioneer - Tel: 6631 0707		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/02/2018]		
Driver/Custodian (Insured):	VEMPU SANKARAN (), NRIC: S77608071		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 08 Mar 2018

Preliminary Advice

Insured Vehicle No	: SJN6936T	Accident Date	: 13/02/2018
TP Vehicle No	: SJV8304L	Assignment Date	: 26/02/2018
Make	: HYUNDAI AVANTE	Est. Duration of Repair	: 4.00
Date of Inspection	: 28/02/2018		
Inspection At	: CHENG AUTO BODYWORKS (HQ) 5 SOON LEE STREET #01-62 PIONEER POINT SINGAPORE 627607		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,203.04
Revised Amount	:S\$	2,013.96
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,013.96
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SJV8304L / TP: msig wsg
✓ Ruled

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/02/2018 12:42
Date Of Accident	13/02/2018 08:45
Exact Location Of Accident	PIE BEFORE EXIT 28
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV8304L
Insured/Policyholder	
Name Of Registered Owner	NG KIAN BOON
NRIC No	S8009370E
Email Address	THEWISHINGSTAR@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96866883
Alternative Phone No	OFFICE-96866883

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE 1.6L AUTO ABS AIRBAG SR 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	18-MW008691-R02
Cover Note Number	

Driver

Name of Driver	NG KIAN BOON
NRIC No	S8009370E
Date Of Birth	26/03/1980
Occupation	INDOOR
Date Of Driving Pass	10/12/2003
Driving Experience	14 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96866883
Fax Number	
Contact Number	OFFICE-96866883
EMail Address	THEWISHINGSTAR@GMAIL.COM

Address	SINGAPORE
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED S & C REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJN6936T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	VEMPU SANKARAN
NRIC/Passport Number	S7760807I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJF7056T
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

ZAINI BIN MOHD ABDOH

NRIC/Passport Number

S7830969E

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 13/2/18

Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Accident Sketch Plan

Date of Accident: 13/02/18

SKETCH PLAN



A: S J V 8 3 6 4 L
B: S J M 6 9 3 6 T
C: S J F 7 0 5 6 T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 13/02/18 at 0845hrs I was travelling on the right most lane along PIE. Just before Exit 28, the car in front of my car, Vehicle C(SJF7056T) applied brakes and slowed down. I too braked and slowed down and came to a complete stop and avoided bumping into vehicle C. 1 - 2 seconds later, vehicle B(SJM6936T) collided into the rear of my car. All three drivers came out of our cars to inspect damages and exchange particulars. I did not feel any impact with vehicle C but including the details of vehicle C for reporting only. When inspecting the cars I also noted that there were no noticeable damages on the rear of vehicle C. There are no visible damages on the front of my car too.

- ☐ Open Damage Claim
☒ Third Party Claim
☐ OD/TP Claim at another workshop:
☐ Reporting Only

DECLARATION

(/We declare the foregoing particulars are true in every respect.

Policyholder's Signature:
Date & Time: 13/2/18

Driver's Signature:
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature:
Name:
NRIC/FIN No.:



CERT OF INS

Tokio Marine Insurance Singapore Ltd

20 Collyer Quay, Singapore 049315 (Tel: 65 6339 1888) Fax: 65 6339 1889

20 Collyer Quay, #20-01 Tokyo Marine Centre Singapore 068046

Tel: 65 6221 6111 / 65 6221 4355 / 65 6224 0895 / Email: TokioMarine@tmis.com.sg / www.tokiomarine.com.sg

Company No. 1192
Date of Incorporation: 1992



TOKIO MARINE
INSURANCE GROUP

FORM MX1

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1989 (MALAYSIA)

Policy No.: 18-MW008691-R02 (Private Motor Car)

- | | | |
|--|--|---------------------------------|
| 1. Index Mark and Registration Number of Vehicle | 5JVR304L | Chassis No.: KMHTD111BMA198K167 |
| 2. Name of Policyholder | MR NG KIAN BOON | |
| 3. Effective date of the Commencement of Insurance for the purposes of the Act | 10/02/2018 | |
| 4. Date of Expiry of Insurance | 09/02/2019 | |
| 5. Persons or Class of Persons entitled to drive* | (a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his permission. | |

* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations considered inoperative by Section 9 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 17 of the Road Transport Act, 1987 (Malaysia), are not to be included under these limitations.

We hereby verify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost or destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

ADDITIONAL INFORMATION

Account: 1457DDA

Insurance Plan:	Comprehensive Approved Workshop Plan	
Limit for total loss or theft:	Prevailing Market Value	
Policy Excess:	Own Damage Claims	SGD 1,000
	Windscreen Excess	SGD 100
Financial Interest:	DBS BANK LTD	

Tokio Marine Insurance Singapore Ltd.

Authorized Signature

User Name: Intermediaries from TMG

Printed: 05/02/2018

INSURED IC & DL FRONT



TP4 MSIG
Kendall

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 21 Feb 2018)

Parts: 143 **HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: Cheng Auto Bodyworks/SJV8304L/22/02/2018 12:53

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

4/5
LICK

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOT	20.00	0.00	Ry *780.00 FL
2	1		*BOOT HINGE RH	20.00	0.00	Ry *152.00 FL
3	1		*BOOT HINGE LH	20.00	0.00	Ry *152.00 FL
4	1		*BOOT RUBBER	20.00	0.00	X nq *83.00 FL
5	1		*BOOT LOCK CATCH	20.00	0.00	X nq *25.30 FL
6	1		*BOOT LOCK ASSY	20.00	0.00	X nq *127.30 FL
7	1		*EMBLEM LOGO	20.00	0.00	na *25.20 FL
8	1		*TAILAMP RH	20.00	0.00	X *298.90 FL
9	1		*TAILAMP LH	20.00	0.00	X *298.90 FL
10	1		*ENDPANEL	20.00	0.00	Ry *326.70 FL
11	1		*REAR BUMPER	20.00	0.00	de *547.30 FL
12	1		*BUMPER RETAINER RH	20.00	0.00	X *38.50 FL
13	1		*BUMPER RETAINER LH	20.00	0.00	na *38.50 FL
14	1		*REINFORCEMENT REAR	20.00	0.00	de *235.00 FL
15	1		*REAR FENDER RH	20.00	0.00	X *1,360.00 FL
16	10		*BUMPER CLIPS	20.00	0.00	na *56.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) **4,544.60**

- List Item Discount on L Items (\$\$) **908.92**

Total Parts (\$\$) **3,635.68**

Cheng Auto Bodyworks/SJV8304L/22/02/2018 12:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Supplement

① Rear Bumper - \$90.45. de ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

[Signature]
9/3/18

Tarhin 97495744
WP
28/2/18
4 days
Lumpsum
Resurvey after repair
Sure thank you

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	NO. PLATE W/ COVER	NN 45.00
2	1	PARKING SENSOR	NN 200.00
Sub Total (S\$)			245.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	PAINTWORK LABOUR	New 500	1,400.00
2	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New 30	100.00
3	ANTI-RUST COATING	New 20	100.00
4	REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	New 40	150.00
5	REMOVE AND REPLACE BUMPER SENSORS	New 30	100.00
<u>Labour Items</u>			
6	LABOUR	New 400	1,400.00
Gross Labour Cost (S\$)			3,250.00

Cheng Auto Bodyworks/SJV8304L/22/02/2018 12:53. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Cheng Auto Bodyworks (Co.Reg.No:53315238X)

5 Soon Lee Street #01-62 Pioneer Point

Singapore 627607

Tel: 6631 0707 Fax: 6316 2431 Email: cab@chengauto.com

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)**VEMPU SANKARAN**

SINGAPORE

Singapore

Claimant Insurer: Tokio Marine Insurance Singapore Ltd**PARTICULARS OF CLAIM**

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	13/02/2018
Vehicle Reg. No.:	SJV8304L	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	NG KIAN BOON	Driver (Insured):	VEMPU SANKARAN
Make/Model:	HYUNDAI AVANTE, 1.6 (A)	Vehicle Reg. Date:	10/02/2010
Vehicle Colour:	Red		
Engine No:	G4FCAU824089	Chassis No:	KMH DU41BMAU988167
Odometer:	100000 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	PLEASE REFER TO ATTACHED S & C REPORT		
Present Location:	CHENG AUTO BODYWORKS (HQ)		

COST OF CLAIMS	Amount
Parts	3,635.68
Miscellaneous Items	245.00
Labour	1,400.00
Paintwork Labour	1,850.00
Towing	0.00
Nett Amount (S\$)	7,130.68

This claim is handled by: LAI WAN SUN

7203.04

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Cheng Auto Bodyworks (Co.Reg.No:53315238X)

5 Soon Lee Street #01-62 Pioneer Point

Singapore 627607

Tel: 6631 0707 Fax: 6316 2431 Email: cab@chengauto.com

(SUPPLEMENTARY)

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

VEMPU SANKARAN

SINGAPORE

BLK 274 CHOA CHU KANG AVENUE2 #11-235

Singapore 680274

Claimant Insurer: Tokio Marine Insurance Singapore Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	S28880740SMF	Date of Loss:	13/02/2018
Vehicle Reg. No.:	SJV8304L	Driveable?	
Party At Fault:	UNKNOWN	Driver (Insured):	VEMPU SANKARAN
Driver (TP):	NG KIAN BOON		
Make/Model:	HYUNDAI AVANTE, 1.6 (A)	Vehicle Reg. Date:	10/02/2010
Vehicle Colour:	RED	Chassis No:	KMH DU41BMAU988167
Engine No:	G4FCAU824089		
Odometer:	100000 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	SJN6936T COLLIDED WITH SJV8304L		
Present Location:	CHENG AUTO BODYWORKS (HQ)		

COST OF CLAIMS	Amount
Parts	72.36
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Nett Amount (S\$)	72.36
+ Previous Estimates (S\$)	7,130.68
Claim Total (S\$)	7,203.04

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 02 Mar 2018)

Parts: 143 **HYUNDAI AVANTE 1.6 (A)** (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: **Cheng Auto Bodyworks/SJV8304L/02/03/2018 12:01**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR SPONGE	20.00	0.00	*90.45 FL / de /
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)						90.45
- List Item Discount on L Items (S\$)						18.09
Total Parts (S\$)						72.36

Cheng Auto Bodyworks/SJV8304L/02/03/2018 12:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Cheng Auto Bodyworks/SJV8304L/02/03/2018 12:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS
REFERENCE

Vehicle Reg No. : SJV8304L
 Make & Model : HYUNDAI AVANTE 1.6L AUTO ABS AIRBAG SR 2WD 4DR
 Chassis No. : KMHU41BMAU988167
 Engine No. : G4FCAU824089
 Year of Manufacture : 2010
 Labour : REPAIRER'S
 TP Vehicle Reg No. : SJN6936T SJF7056T
 DOA & Location : 13/02/2018 PIE BEFORE EXIT 28
 Our Ref : SJV8304L / NG KIAN BOON

ESTIMATES OF PARTS

No.	Qty	Description	Part No.	Price
1	1	BOOT		
2	1	BOOT HINGE RH		
3	1	BOOT HINGE LH		
4	1	BOOT RUBBER		
5	1	BOOT LOCK CATCH		
6	1	BOOT LOCK ASSY		
7	1	EMBLEM LOGO		\$ 25.20
8	1	TAILAMP RH		
9	1	TAILAMP LH		
10	1	ENDPANEL		
11	1	REAR BUMPER		\$ 547.30
12	1	BUMPER RETAINER RH		
13	1	BUMPER RETAINER LH		\$ 38.50
14	1	REINFORCEMENT REAR		\$ 235.00
15	1	REAR FENDER RH		
16	10	BUMPER CLIPS		\$ 56.00
Sub-Total (\$\$)				\$ 902.00
SAAA List Item Discount 20% (\$\$)				\$ 180.40
Sub-Total (\$\$)				\$ 721.60

LABOUR

No.	Description	Price
1	LABOUR	\$ 400.00
2	SPRAYPAINTING	\$ 500.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	\$ 30.00
4	ANTI-RUST COATING	\$ 20.00
5	REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	\$ 40.00
6	REMOVE AND REPLACE BUMPER SENSORS	\$ 30.00
Total Labour (\$\$)		\$ 1,020.00

MISCELLANEOUS ITEMS

No.	Description	Price
1	NO. PLATE W/ COVER	
2	PARKING SENSOR	\$ 200.00
Total Miscellaneous Items (\$\$)		\$ 200.00

SUPPLEMENTARY PARTS

No.	Qty	Description	Part No.	Price
1		REAR SPONGE		\$ 90.45
Sub-Total (\$\$)				\$ 90.45
SAAA List Item Discount 20% (\$\$)				\$ 18.09
Sub-Total (\$\$)				\$ 72.36

Total Parts (\$\$)	\$ 721.60
Total Labour (\$\$)	\$ 1,020.00
Total Miscellaneous (\$\$)	\$ 200.00
Total Supplementary (\$\$)	\$ 72.36
Total (\$\$)	\$ 2,013.96
Lumpsum 20% (\$\$)	\$ 402.79
Total (\$\$)	\$ 1,611.17

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003632/T1RBN2

Date: 23/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	S28880740SMF
Claimant Vehicle No :	SJV8304L	Insured Vehicle No :	SJN6936T
Date of Loss:	13/02/2018	Nature of Claim:	TP
		Claim No:	549489

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV8304L	Engine No:	G4FCAU824089
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMHU41BMAU988167
Reg. Date:	10/02/2010 (Man. Year: 2010)	Odometer:	156929 km
Colour:	Maroon		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60R15	Rear Tyre Size:	195/60R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,708.04	793.96	2,914.08	78.59
Miscellaneous Items	245.00	200.00	45.00	18.37
Labour	1,400.00	400.00	1,000.00	71.43
Paintwork Labour	1,850.00	620.00	1,230.00	66.49
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,203.04	2,013.96	5,189.08	72.04
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	7,203.04	1,600.00	5,603.04	77.79
+ GST 0.00/7.00% (S\$)	0.00	112.00	-112.00	
Nett Amount (S\$)	7,203.04	1,712.00	5,491.04	76.23

INSPECTION

Date of Assignment:	26/02/2018	Present Location:	Cheng Auto Bodyworks (HQ)
Date Inspected:	28/02/2018	Inspected At:	Cheng Auto Bodyworks (HQ)
			5 Soon Lee Street #01-62 Pioneer Point
			Singapore 627607

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2018)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV8304L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT	Repair	780.00 FL	*- FL
2	1		*BOOT HINGE RH	Repair	152.00 FL	*- FL
3	1		*BOOT HINGE LH	Repair	152.00 FL	*- FL
4	1		*BOOT RUBBER	Not Necessary	83.00 FL	*- FL
5	1		*BOOT LOCK CATCH	Not Necessary	25.30 FL	*- FL
6	1		*BOOT LOCK ASSY	Not Necessary	127.30 FL	*- FL
7	1		*EMBLEM LOGO	Necessary	25.20 FL	*25.20 FL
8	1		*TAILAMP RH	Not Necessary	298.90 FL	*- FL
9	1		*TAILAMP LH	Not Necessary	298.90 FL	*- FL
10	1		*ENDPANEL	Repair	326.70 FL	*- FL
11	1		*REAR BUMPER	Deformed	547.30 FL	*547.30 FL
12	1		*BUMPER RETAINER RH	Not Necessary	38.50 FL	*- FL
13	1		*BUMPER RETAINER LH	Necessary	38.50 FL	*38.50 FL
14	1		*REINFORCEMENT REAR	Deformed	235.00 FL	*235.00 FL
15	1		*REAR FENDER RH	Not Necessary	1,360.00 FL	*- FL
16	10		*BUMPER CLIPS	Necessary	56.00 FL	*56.00 FL
Supplementary #1						
17	1		*REAR SPONGE	Deformed	90.45 FL	*90.45 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,635.05	992.45
- List Item Discount on L Items 20.00/20.00% (\$\$)	927.01	198.49
Total Parts (\$\$)	3,708.04	793.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	NO. PLATE W/ COVER (Not Necessary)	45.00	0.00
2	1	PARKING SENSOR (Not Working)	200.00	200.00
Sub Total (\$\$)			245.00	200.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	PAINTWORK LABOUR	New	1,400.00	500.00
2	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New	100.00	30.00
3	ANTI-RUST COATING	New	100.00	20.00
4	REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	New	150.00	40.00
5	REMOVE AND REPLACE BUMPER SENSORS	New	100.00	30.00
Labour Items				
6	LABOUR	New	1,400.00	400.00
Gross Labour Cost (\$\$)			3,250.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >