

ASS. REC. BY:

REF: CS/MS618009635/Sqbez

Special Instruction:

Surveyor: Sebastian
McLimeh

ASSIGNMENT (Office)

From (Person): Irene Tan of MS6 Date/Time: 26/02/2018 1:14pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SL6 5532U Insured: ER 295L

at Workshop m/s World Auto Tel: 6362 1776

of 1 Kranji Loop

Policy No: A27519769TMP Claim No: 550296

Sum Insured: Excess:

Make of Veh: D.O.A. 19/02/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi' H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SL6 5532U - 003 / LCR17007803 / 5/1/18/3/2 ER 295L - x
01/3/18 @	9.27am visited to Irene Tan via Brecken.
16/3/18 @	3.07pm confirmed with Sophia final fig B1371, 13 days. L22d \$ 280.10, 17%.

MS19

File No: 27/2/18

SLG 55324

5/10/16

Engine No:

0

12 MONTHS COPIES COPIES

SLG 55324
World Auto
1 Krunji loop

Toyota Prius 4 1799

Color: Silver

Engine No: 115229

Engine:

Chassis No: JTDK133F4703534997

Gen. Cond. Good Poor Burnt

Steering Jammed Leaked Burnt


Brake Jammed Leaked Burnt

Tire SPT STD WRT

Tire Size = 195/65R15 Pirelli

= 11 Giti

Policy Condition



Remarks: The veh had commenced its repair at the time of inspection

NS OS

BS DUN ERNOVA GR PS UJA MO D-TSL PP SUT

FOR KYRHO

Body/Panel/Valve

Front

Rear

DIAG Accident Report Consistent? Yes or No

F Be 6

R Be 6

3-4 PP Seen Consistent? Yes or No

L Be 6

R Be 6

Est. Repairs 3 days Yes Yes or No

DD - 19/2/18

DD - 27/2/18

Est. Sum Yes Yes or No

Surveyed at

World Auto

CA REP REP 24 HRS 1wp

Des of Damages Fr. Rear OS NS UD Photos

Rear of S

Date Person Contacted

The UD Chassis frame Body Structure affected due to ...

Date Time Action Inspector

[Signature]
16/3/2018

RECEIVED

Days of Repair Prel. Report

Days of Repair 3

19/3 by post Final Report

Reserve No of Tnc

200

Days of Repair

App. Fee

Ins. Fee

10

1100-70

1371.1

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003635/Sqb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 26-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	ER 295L	Veh. Inspected	SLG 5532U
Policy No.	A27519769TMP	Coverage (\$)	0.00
Claim No.	550296	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	26/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	19/02/2018	Inspection Date	26/02/2018
Survey held at	1 KRANJI LOOP		
Repairer	WORLD AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Feb 2018		26 Feb 2018 13:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	KAMLESH PATEL HARMANBHAI, ID: S2714204D		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201604597K		
Vehicle Reg. No.:	SLG5532U	Date of Loss:	19/02/2018 13:00 - :59
Claim Type:	TP / 550296	Policy/Cover Note No.:	A27519769TMP (Comprehensive) Coverage: 01/07/2017 - 30/06/2018
Vehicle Reg. No. (Insured):	ER295L	Policy No. (Claimant):	
	Excess:		
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 63621776		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/02/2018]		
Driver/Custodian (Insured):	KAMLESH PATEL HARMANBHAI (), NRIC: S2714204D		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 16 March 2018 3:02 PM
To: ainee31@worldauto.com.sg
Cc: SUR
Subject: RE: Request for Finalized SLG5532U // ER295L DOA: 19/02/2018 TP/1862/18

Dear Sophia,

Confirm final fig \$1,371.10 and 3 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Friday, 16 March 2018 11:04 AM
To: 'Ainee31' <aine31@worldauto.com.sg>; Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>
Subject: RE: Request for Finalized SLG5532U // ER295L DOA: 19/02/2018 TP/1862/18

Thanks

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ainee31 [<mailto:aine31@worldauto.com.sg>]
Sent: Friday, 16 March 2018 10:13 AM
To: Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>; Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: Re: Request for Finalized SLG5532U // ER295L DOA: 19/02/2018 TP/1862/18

DEAR ALL,

Any updates for this???

Thanks and Rgds,

World Auto Pte Ltd

Tel HQ: 64513933

Kranji: 63621776

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 01 Mar 2018

Preliminary Advice

Insured Vehicle No	: ER295L	Accident Date	: 19/02/2018
TP Vehicle No	: SLG5532U	Assignment Date	: 26/02/2018
Make	: TOYOTA PRIUS C	Est. Duration of Repair	: 3.00
Date of Inspection	: 27/02/2018		
Inspection At	: WORLD AUTO PTE LTD - KRANJI (HQ) NO 1 KRANJI LOOP SINGAPORE 739535		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,651.10
Revised Amount	:S\$	1,371.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,371.10

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/02/2018 10:36
Date Of Accident	19/02/2018 13:35
Exact Location Of Accident	VERDUM RD TOWARDS KITCHENER RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG5532U
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201604597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995174
Cover Note Number	

Driver

Name of Driver	CHUA HOCK BOO
NRIC No	S1270817C
Date Of Birth	20/01/1957
Occupation	OUTDOOR
Date Of Driving Pass	18/05/1978
Driving Experience	39 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address NOADDRESS
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured PAID DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1 NAME: : NONAME
 GENDER: : MALE
 Passenger 2 NAME: : NONAME
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number ER295L
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name

Sketch Plan

SKEICH PLAN

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3 Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



WORLD AUTO PTE LTD

47 Jalan Remimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD

Estimate : ES005762

Attention : Motor Claim Department

Date : 21/02/2018
 Vehicle Num. : SLG 5532U (LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 19/02/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS : REAR BUMPER ✓ TN		423.90
2.	1	REAR BUMPER RIGHT PAD ✓ CMC		118.60
3.	1	REAR LOWER BUMPER ✓ Defor.		552.30

List TotalS\$:	1,094.80
25.00% Discount S\$:	273.70

	821.10

LABOUR :	
LABOUR TO RENEW REAR BUMPER,R/R/S BUMPER PAD,REAR LOWER BUMPER ETC.	380.00 250
SPRAY PAINT TO ABOVE AFFECTED AREAS	250.00 300

Labour Total S\$:	830.00

E. & O.E.	Total S\$:	1,651.10
		=====

for WORLD AUTO PTE LTD

Sebastian
 27/2/18
 - Part by part repair
 - Photo Before Paint
 90036121
 sebastianyeap@lkkauto.com

3 days -

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

WORLD AUTO PTE LTD

47 Jalan Remimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD

Estimate : ES005762

Attention : Motor Claim Department

Date : 21/02/2018
 Vehicle Num. : SLG 5532U (LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 19/02/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS : ✓ TN		
2.	1	REAR BUMPER		
3.	1	REAR BUMPER RIGHT PAD ✓ CAX		
		✓ REAR LOWER BUMPER ✓ Defor.		
List Total S\$:				1,094.80
25.00% Discount S\$:				273.70
				821.10

LABOUR :
 LABOUR TO RENEW REAR BUMPER, R/R/S BUMPER PAD, REAR LOWER BUMPER ETC.

SPRAY PAINT TO ABOVE AFFECTED AREAS

Labour Total S\$:

parts - 1094.80
 (25%) - 273.70

 821.10
 labour - 550.00

 nets 1371.10
 3 days

830.00

E. & O.E.

Total S\$: 1,651.10

for WORLD AUTO PTE LTD

Sebastian.
 27/2/18.
 - Part by part repair.
 - Photo Before Paint
 90036121
 sebastianyeang@lkkauto.com

3 days -

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Feb 2018		26 Feb 2018 13:14 Edit Adj Rpt	S\$1,371.10 Edit Estimates	S\$1,371.10 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	KAMLESH PATEL HARMANBHAI , ID: S2714204D								
Main Claimant:	LCRF PTE LTD , Co. Reg. No.: 201604597K								
Vehicle Reg. No.:	SLG5532U	Date of Loss:	19/02/2018 13:00 - :59						
Claim Type:	TP / 550296	Policy/Cover Note No.:	A27519769TMP (Comprehensive) Coverage: 01/07/2017 - 30/06/2018						
Vehicle Reg. No. (Insured):	ER295L	Policy No. (Claimant):							
		Excess:							
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 63621776								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 28/03/2018]								
Driver/Custodian (Insured):	KAMLESH PATEL HARMANBHAI (), NRIC: S2714204D								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLG5532U (550296)**
[ER295L]
TP
LCRF PTE LTD
Feb 19 2018 1:00PM
[KAMLESH PATEL HARMANBHAI]
World Auto Pte Ltd - Kranji

Upload Documents		Upload Photos	Compose New Letter	View View in Browser <input type="button" value="v"/>
Assessment Reports				1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	26/02/18 10:02	Accident Statement Adm. #1 <small>From:SC - Reg. No: ER295L, Claimant: PATEL KAMLESH HARMANBHAI</small>	<input checked="" type="checkbox"/>	Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	01/03/18 09:27	Adjuster Immediate Advice	<input checked="" type="checkbox"/>	Load HTM
Photos/Images				3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
2	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
3	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
4	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
5	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
6	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
7	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
8	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
9	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
10	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
11	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
12	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
13	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
14	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
15	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
16	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
17	16/03/18 15:38	Odometer Reading	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
18	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
19	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
20	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
21	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
22	16/03/18 15:38	General View	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
23	16/03/18 15:38	Chassis Number	<input checked="" type="checkbox"/>	Load JPG <input checked="" type="checkbox"/>
Documentation				1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	26/02/18 10:02	TP GIA REPORT <small>From:SC - Reg. No: ER295L, Claimant: PATEL KAMLESH HARMANBHAI</small>	<input checked="" type="checkbox"/>	Load PDF
2	26/02/18 13:14	Email from TP agree SJE	<input checked="" type="checkbox"/>	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003635/SQBE2

Date: 20/03/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A27519769TMP
Claimant Vehicle No : SLG5532U	Insured Vehicle No :	ER295L
Date of Loss: 19/02/2018	Nature of Claim:	TP
		Claim No: 550296

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG5532U	Engine No:	2ZRR949893
Make & Model:	TOYOTA PRIUS C, 1.5 HYBRID CVT (A)	Chassis No:	JTDKB3FU903534997
Reg. Date:	05/10/2016 (Man. Year: 2016)	Odometer:	115229 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	821.10	821.10	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	830.00	550.00	280.00	33.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,651.10	1,371.10	280.00	16.96
+ GST 7.00/7.00% (\$\$)	115.58	95.98	19.60	16.96
Nett Amount (\$\$)	1,766.68	1,467.08	299.60	16.96

INSPECTION

Date of Assignment:	26/02/2018		
Date Inspected:	27/02/2018	Inspected At:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop Singapore 739535

Estimated Period of Repair: 3.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Mar 2018)
Parts: 144 TOYOTA PRIUS C 1.5 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLG5532U)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Torn	423.90 FL	*423.90 FL	
2	1		*REAR BUMPER RIGHT PAD	Cracked	118.60 FL	*118.60 FL	
3	1		*REAR LOWER BUMPER	Deformed	552.30 FL	*552.30 FL	
					Sub Total (\$\$)	1,094.80	1,094.80
					- List Item Discount on L Items 25.00/25.00% (\$\$)	273.70	273.70
					Total Parts (\$\$)	821.10	821.10

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO RENEW REAR BUMPER, R/R/S BUMPER PAD, REAR LOWER BUMPER ETC	New	380.00	250.00
2	SPRAY PAINT TO ABOVE AFFECTED AREA	New	450.00	300.00
Gross Labour Cost (S\$)			830.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >