

22/03/2002

ASS. REC. BY:

REF: CS/ C7L18003636 / Wvhe

Special Instruction:

Surveyor: Wilson

ASSIGNMENT (Office)

From (Person): Angie Foo

of CIL

Date/Time: 23022018 2.45pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGX 718D

Insured:

YN 2376H

at Workshop m/s

V-70C Asia Automotive

Tel:

8823 1688

of

8 Kaki Bukit Ave 4 #07-08

Policy No:

Claim No:

SNM18D01001C03/6

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 21022018

CA / REV / REP. / REV 24 HRS 'WP'

benjamin@vtoauto.com.sg

H.O.D. Endorsement:

Date/Time: 23022018 204pm

Person Contacted:

Perry

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction (✓) Estimate
	SGX 718D - 216 / 12511001632 / 202100
7/3/18	Rec file
	Dismantle: 6/3/18
	After paint 9/3/18 (G)

SWISS

PKS

Wilson

ASSIGNMENT

COE Expired: 26/1/2027

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / NV: _____
 To inspect Vehicle No: SGX 718 D
 at Workshop: V-Tech
 of: Premier Okaka Bukit
 Insured: # 07-08
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record): _____
 Make of Ver: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 JDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lump Sum: _____ \$ 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGX 718 D or Regn: 27/7/2007
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Toyota Estima cc: 2362
 Colour: Blue Insured / Std / NI / NA
 Sp Reading: 99806 T Rad: Insured / Std / NI / NA
 Eng No: _____
 C No: ACR50-003785
 Gen Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or

Tyre Size F: 215 / 65 R17
 R: 215 / 65 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental

Front: _____ Rear: _____
 R/Bal: 4 mm R/Bal: 4 mm
 L/Bal: 4 mm L/Bal: 4 mm
 D.O.A: 21/2/2018 DO: 26/2/2018
 Survey held at: As Above

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date/Time: 29/3/2018 Action/ Instruction: Finalised Amount with workshop
at the amount \$3050 / 4 Day
(Red 4000, 5770)

RECEIVED 02 APR 2018

Date/Time File Passed: ☐ Preli. Report
☐ Final Report

Days Of Repair: 4
 Resurvey No. of Trip: 2

Survey Fee: 220
 Transducer: _____
 S-AB: _____

220

19/3 - typist
 Report Format: merimen
 Lump Sum / I.B. / S: 3050/2

Add Fee: ☐ Site Insp: _____ S
☐ Interview: _____ S
☐ Tech Insp: _____ S
☐ Weekend: _____ S



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18003636/Wvb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 26-02-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 2376H	Veh. Inspected	SGX 718D	
Policy No.		Coverage (\$)	0.00	
Claim No.	SNM18D01001C02/6	Excess (\$)	0.00	
Assign From	ANGIE FOO	Assign Date	23/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/02/2018	Inspection Date	26/02/2018	
Survey held at	V-TEC ASIA AUTOMOBILE - 8 KAKI BUKIT AVE 4 #07-08			
Repairer	-			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Catherine Chong (LKK Auto)

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Friday, 23 February, 2018 2:46 PM
To: assignments
Subject: FW: OUR REF: PRS/SNM18D01001C02/6 & YR REF: SGX718D -TO CONDUCT PRE REPAIR SURVEY -SGX718D

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Angie Foo [mailto:angie.foo@sg.cntaiping.com]
Sent: Friday, 23 February 2018 2:45 PM
To: Perry - V-tec <perry@vtecauto.com.sg>
Cc: benjamin@vtecauto.com.sg; wayne@vtecauto.com.sg; Irene Tay <irene.tay@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: RE: OUR REF: PRS/SNM18D01001C02/6 & YR REF: SGX718D -TO CONDUCT PRE REPAIR SURVEY -SGX718D

WITHOUT PREJUDICE

Dear Perry,

We refer to your email on even date.

We had appointed M/S LKK Auto Consultants Pte Ltd to conduct survey on your client's vehicle.

Please ensure that your client's vehicle is available for survey within 2 working days.

REMARKS:

Dear kalvin/Marcus/Simon,

Please conduct survey and check consistency of the damages on without prejudice.

Kindly take note, the claim handler is Irene Tay 63896192

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower

Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

-----Original Message-----

From: Perry - V-tec [mailto:perry@vtecauto.com.sg]
Sent: Friday, 23 February, 2018 2:25 PM
To: Angie Foo
Cc: benjamin@vtecauto.com.sg; wayne@vtecauto.com.sg; Irene Tay; Claims Dept of CTI
Subject: Re: OUR REF: PRS/SNM18D01001C02/6 & YR REF: SGX718D -TO CONDUCT PRE REPAIR SURVEY -SGX718D

Dear Angie,

We agreed to your list of surveyor, please arrange today, let me know what time they are coming.

Please do not hesitate to contact me @ 9610 9610 should you require further clarification.

Thank you.

Warmest Regards,
Perry Yeo
Business Development Manager

V-Tec Asia Automotive Pte Ltd
(Co Reg: 201534887R)
8 Kaki Bukit Avenue 4, #07-08/09
Premier@KB
Singapore 415875
Tel : +65 9610 9610
Website : www.vtecauto.com.sg
Email : perry@vtecauto.com.sg

On 2018-02-23 13:32, Angie Foo wrote:

> WITHOUT PREJUDICE

>

> Dear Perry,

>

> We intend to conduct a pre-repair survey of the damage to your
> client's vehicle jointly with your client/your motor workshop.

>

> We propose to use one of the following motor surveyors to conduct the
> joint pre-repair survey as a single joint expert.

>

> TAY BENG HEE
 > SAMUEL PHUN
 > SEE CHEW SENG
 > MOHD FADHILAH BIN OSMAN
 > DEREK OH SIONG WEE
 > KALVIN ANG
 > MARCUS CHUA
 > SIMON HO
 > LOW SAR HUEI
 > HONG FOOK CHOY
 >
 > Please let us know within two(2) working days whether you agree to
 > the appointment of any of these motor surveyors as a single joint
 > expert.
 >
 > You may select one of the listed motor surveyors and we will bear the
 > cost of the pre-repair survey carried out by the single joint expert.
 >
 > Kindly let us hear from you.
 >
 > REMARKS:
 > Kindly take note, the claim handler on this case is Irene Tay 6389
 > 6192
 >
 > Thank you.
 >
 > Regards,
 > Angie Foo
 > Executive
 > Motor Division
 > Claims Department
 > China Taiping Insurance (Singapore) Pte Ltd
 > 3 Anson Road #16-00
 > Springleaf Tower
 > Singapore 079909
 > Co.Reg.No.200208384E
 > DID: 6389 6186
 > Fax: 6224 7478 /6224 7175
 > Email: angie.foo@sg.cntaiping.com
 > Email: claimsdept@sg.cntaiping.com
 > Website: www.sg.cntaiping.com
 >
 > Disclaimer:
 > This message is confidential; its contents do not constitute a
 > commitment by China Taiping Insurance (Singapore) Pte. Ltd. except
 > where provided for in a written agreement between you and China
 > Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure,
 > use or dissemination, either in whole or partial, is prohibited. If
 > you are not the intended recipient of the message, please notify the
 > sender immediately.
 >
 > -----Original Message-----
 > From: Perry - V-tec [mailto:perry@vtecauto.com.sg]
 > Sent: Friday, 23 February, 2018 11:47 AM
 > To: Claims Dept of CTI
 > Cc: benjamin@vtecauto.com.sg; wayne@vtecauto.com.sg

> Subject: Yref : YN 2376 H
>
> Dear CN Taiping,
>
> Happy New year to you.
>
> Our client's vehicle SGX 718 D was hit by your insured vehicle YN 2376
> H
>
> Please find the attached for the GIA Report.
>
> We will be arranging a Direct Claim against China Taiping.
>
> Kindly arrange and inform us which surveyor and when will he be coming
> for the PRI.
>
> --
> Please do not hesitate to contact me @ 9610 9610 should you require
> further clarification.
>
> Thank you.
>
> Warmest Regards,
> Perry Yeo
> Business Development Manager
>
> V-Tec Asia Automotive Pte Ltd
> (Co Reg: 201534887R)
> 8 Kaki Bukit Avenue 4, #07-08/09
> Premier@KB
> Singapore 415875
> Tel : +65 9610 9610
> Website : www.vtecauto.com.sg
> Email : perry@vtcauto.com.sg
>
>
>
>
> _____
> This email has been scanned by the Symantec Email Security.cloud
> service.
> For more information please visit <http://www.symanteccloud.com>
> _____

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	0475J

Vehicle Details

Vehicle No.:	SGX718D
Vehicle to be Exported:	No
Intended De-registration Date:	07 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA 2.4 A
Primary Colour:	Blue
Manufacturing Year:	2007
Engine No.:	2AZF037843
Chassis No.:	ACR500037885
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$27,698.00
Original Registration Date:	27 Jul 2007
First Registration Date:	27 Jul 2007
Transfer Count:	0
Actual ARF Paid:	\$30,468.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	26 Jul 2027
COE Category:	B - Car (1601cc & above)

3/7/2018

PARF/COE Rebate Enquiry

10

COE Period(Years):

\$52,473.00

PQP Paid:

\$49,242.00

COE Rebate Amount:

\$49,242.00

Total Rebate Amount:

The information contained herein is correct as at 07 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/02/2018 17:43
Date Of Accident	21/02/2018 14:30
Exact Location Of Accident	ALONG HAIG AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGX718D
Insured/Policyholder	
Name Of Registered Owner	VIVIENA CHIN
NRIC No	S7170475J
Email Address	VIVIENA@ETERNAL-FA.COM
Mobile Phone No	(LOCAL) +65-96921775
Alternative Phone No	OFFICE-96921775

Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA-2.4 (A)
Exact Purpose for which vehicle was being used at time of accident	PARKED VEHICLE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA111493/1
Cover Note Number	27/07/2017 - 26/07/2018

Driver

Name of Driver	SIM KWAN SOON FREDDY
NRIC No	S1603807E
Date Of Birth	15/07/1963
Occupation	INDOOR
Date Of Driving Pass	07/12/1981
Driving Experience	36 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97437370
Fax Number	
Contact Number	
EEmail Address	FREDSIM@ETERNAL-FA.COM

Address	1G HAIG AVENUE
Postcode	438871
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD (6741 5336)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN2376H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	
Name of Driver	HU JUN
NRIC/Passport Number	G3402633K
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE



1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records/Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or expressed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claim and any necessary investigations relating to the claims;
 - (ii) investigating if I am at fault and/or my conduct;
 - (iii) carrying out and/or dealing with my instructions in my claim and this statement by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to third party delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) responding with applicable law in administering, processing, handling and/or dealing with my claims collectively the "Purposes".
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes and
- (c) my Personal Information may/are be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be located outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared /disclosed:
 - (i) to all insurers and for any other third parties that assist in evaluating, investigating, controlling or managing fraud;
 - (ii) regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (iii) for complying with requirements under any regulatory laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: 
NRIC/FIN No: 

Accident Sketch Plan

SKETCH PLAN

		Vehicle No A - B -
		Legend

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/2/18 at 230pm I received a call from my maid that a bus driver hit onto my wife car on the back. Bus driver rang my house door bell and apologised I rushed back to take photo of his bus plate no & his work permit. He keeps on apologising & said he just came to Spore and not with us. He is from BT & Tan Co. I called & spoke to a female staff. She said they will pay for the damaged.

I make this report on my wife Viviana Chin, NRIC 7170475 / I hereby

DECLARATION

I/We declare the foregoing particulars are true in every respect. Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Common Statement

ACCIDENT STATEMENT (Part I)

Reporting Centre: Progressive Automotive Pte Ltd

This is NOT an admission of blame / liability, but a summary of identities and facts which will speed up the settlement of claims

1 Date of accident 21/7/2018		2 Exact location of accident ALONG HAIG AVE		3 Insured by BOTH drivers Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
4 Injuries to vehicles A and B No <input type="checkbox"/> Yes <input checked="" type="checkbox"/>		5 To object other than vehicles No <input checked="" type="checkbox"/> Yes <input type="checkbox"/>		6 Witness' name, address and tel no. (to be underlined if he/she is passenger in vehicle A or vehicle B) 	
7 Injuries to vehicles A and B No <input type="checkbox"/> Yes <input checked="" type="checkbox"/>		8 To object other than vehicles No <input checked="" type="checkbox"/> Yes <input type="checkbox"/>		9 Vehicle Video Camera Available No <input type="checkbox"/> Yes <input checked="" type="checkbox"/>	

Registration No. (VEHICLE A)		SGX 718D	
<input checked="" type="checkbox"/> Insured / policyholder (see insurance cert)			
Name (capital letters) VIVIANA CHIN			
Address 			
NRIC / Passport no. <u>S71704757</u>			
Tel no. (home/mobile/fax) <u>76921775</u>			
<input checked="" type="checkbox"/> Vehicle			
Make / type 			
<input checked="" type="checkbox"/> Insurance company AXA <input checked="" type="checkbox"/> IC <input type="checkbox"/> DTA <input type="checkbox"/> DFO			
Total insurable value (in S\$) <u>100,000</u> (in S\$) <u>100,000</u>			
Policy No. <u>GA111493/1</u>			
<input checked="" type="checkbox"/> Driver		<input type="checkbox"/> Full-time Driver	
Name <u>SIM KUAN SON</u>			
(capital letters) FREDDY			
NRIC / Corresponding <u>S1603807F</u>			
Current Tel. No. <u>97438370</u>			
Driver with <input checked="" type="checkbox"/> License <input type="checkbox"/>			

12 CIRCUMSTANCES	
Put a check (X) in each of the relevant boxes applicable to <u>your</u> vehicle	
A	Is the engine
B	Is the engine manual
C	Is the engine diesel
D	Is the engine turbo diesel
E	Is the fuel injection
F	Is the fuel property
G	Is the engine oil and
H	Is the engine oil
I	Is the engine oil
J	Is the engine oil
K	Is the engine oil
L	Is the engine oil
M	Is the engine oil
N	Is the engine oil
O	Is the engine oil
P	Is the engine oil
Q	Is the engine oil
R	Is the engine oil
S	Is the engine oil
T	Is the engine oil
U	Is the engine oil
V	Is the engine oil
W	Is the engine oil
X	Is the engine oil
Y	Is the engine oil
Z	Is the engine oil
AA	Is the engine oil
AB	Is the engine oil
AC	Is the engine oil
AD	Is the engine oil
AE	Is the engine oil
AF	Is the engine oil
AG	Is the engine oil
AH	Is the engine oil
AI	Is the engine oil
AJ	Is the engine oil
AK	Is the engine oil
AL	Is the engine oil
AM	Is the engine oil
AN	Is the engine oil
AO	Is the engine oil
AP	Is the engine oil
AQ	Is the engine oil
AR	Is the engine oil
AS	Is the engine oil
AT	Is the engine oil
AU	Is the engine oil
AV	Is the engine oil
AW	Is the engine oil
AX	Is the engine oil
AY	Is the engine oil
AZ	Is the engine oil
BA	Is the engine oil
BB	Is the engine oil
BC	Is the engine oil
BD	Is the engine oil
BE	Is the engine oil
BF	Is the engine oil
BG	Is the engine oil
BH	Is the engine oil
BI	Is the engine oil
BJ	Is the engine oil
BK	Is the engine oil
BL	Is the engine oil
BM	Is the engine oil
BN	Is the engine oil
BO	Is the engine oil
BP	Is the engine oil
BQ	Is the engine oil
BR	Is the engine oil
BS	Is the engine oil
BT	Is the engine oil
BU	Is the engine oil
BV	Is the engine oil
BW	Is the engine oil
BX	Is the engine oil
BY	Is the engine oil
BZ	Is the engine oil
CA	Is the engine oil
CB	Is the engine oil
CC	Is the engine oil
CD	Is the engine oil
CE	Is the engine oil
CF	Is the engine oil
CG	Is the engine oil
CH	Is the engine oil
CI	Is the engine oil
CJ	Is the engine oil
CK	Is the engine oil
CL	Is the engine oil
CM	Is the engine oil
CN	Is the engine oil
CO	Is the engine oil
CP	Is the engine oil
CQ	Is the engine oil
CR	Is the engine oil
CS	Is the engine oil
CT	Is the engine oil
CU	Is the engine oil
CV	Is the engine oil
CW	Is the engine oil
CX	Is the engine oil
CY	Is the engine oil
CZ	Is the engine oil
DA	Is the engine oil
DB	Is the engine oil
DC	Is the engine oil
DD	Is the engine oil
DE	Is the engine oil
DF	Is the engine oil
DG	Is the engine oil
DH	Is the engine oil
DI	Is the engine oil
DJ	Is the engine oil
DK	Is the engine oil
DL	Is the engine oil
DM	Is the engine oil
DN	Is the engine oil
DO	Is the engine oil
DP	Is the engine oil
DQ	Is the engine oil
DR	Is the engine oil
DS	Is the engine oil
DT	Is the engine oil
DU	Is the engine oil
DV	Is the engine oil
DW	Is the engine oil
DX	Is the engine oil
DY	Is the engine oil
DZ	Is the engine oil
EA	Is the engine oil
EB	Is the engine oil
EC	Is the engine oil
ED	Is the engine oil
EE	Is the engine oil
EF	Is the engine oil
EG	Is the engine oil
EH	Is the engine oil
EI	Is the engine oil
EJ	Is the engine oil
EK	Is the engine oil
EL	Is the engine oil
EM	Is the engine oil
EN	Is the engine oil
EO	Is the engine oil
EP	Is the engine oil
EQ	Is the engine oil
ER	Is the engine oil
ES	Is the engine oil
ET	Is the engine oil
EU	Is the engine oil
EV	Is the engine oil
EW	Is the engine oil
EX	Is the engine oil
EY	Is the engine oil
EZ	Is the engine oil
FA	Is the engine oil
FB	Is the engine oil
FC	Is the engine oil
FD	Is the engine oil
FE	Is the engine oil
FF	Is the engine oil
FG	Is the engine oil
FH	Is the engine oil
FI	Is the engine oil
FJ	Is the engine oil
FK	Is the engine oil

[illegible][illegible]

REFER TO ATTACHED

602 **Make the most**
of what you can do
to contribute.

[illegible]

11-11-61, 10:00PM

Signature of Plaintiff

[illegible]

* The level of interest in the event of the 1966 election was not high
in 1966. It was not high in 1966.

CONFIDENTIAL - SECURITY INFORMATION - 2014 RELEASE UNDER E.O. 13526

FOR THE PRESIDENT ELECTION
1960

Individual Statement

Reporting Centre: Progressive Automotive Pte Ltd

INDIVIDUAL STATEMENT (Part II)		Own Workshop Email / Fax (if any)	
To be completed and submitted within 24 hours to your insurer or Tpac or appointed workshop (Use a separate sheet of paper where necessary)			
Insured	1. Occupation (if more than one, state all)		Email: Fredsim@external-4a.com
	2. Vehicle registration no.	C.C.	If commercial vehicle, state permissible carrying capacity
	3. Is driver the owner? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> If no, state name of owner with owner's signature		State the vehicle number and name of insurer of driver's own vehicle (where applicable)
	4. Exact purpose for which vehicle was being used at time of accident: <input checked="" type="checkbox"/> Private use <input type="checkbox"/> Commercial use <input type="checkbox"/> Hire & reward <input type="checkbox"/> Private hire		
	5. Is the vehicle still in use? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> If no, state where it is at present Tel no		
Of which vehicle did you use driver?	5. Are you claiming under your own line of insurance policy for repair to your vehicle? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> If no, state action to be taken: <input type="checkbox"/> Third Party <input checked="" type="checkbox"/> Reporting Only <input type="checkbox"/> Third Party (Own Workshop)		
	7. Date of birth	Occupation	Date of license pass
	Was with the driver with the insured's permission?		Was driver an employee of the insured's company?
	Indoor <input checked="" type="checkbox"/> Outdoor <input type="checkbox"/>		Yes <input type="checkbox"/> No <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/>
	8. Give details of any pre-existing impairment of sight or hearing and of any other disability		
Driver or person in charge of vehicle at the time of accident (including insured)	9. Give details of all driving convictions including pending prosecutions in the last 36 months		
	Date	Offence	Penalty
Insured	10. Name(s), address(es) and approximate age(s)	Injured sustainer	If vehicle occupants, state in which vehicle
			Were seat belts being worn?
			Yes <input type="checkbox"/> No <input type="checkbox"/>
			Yes <input type="checkbox"/> No <input type="checkbox"/>
			Yes <input type="checkbox"/> No <input type="checkbox"/>
Damage to property (other than vehicles A and B)	11. Name(s) and address(es) of owner(s)	Vehicle registration no. or details of property	Nature of damage
			Insurer's name and address (if known)
Police officer	12. Was the accident reported to the Police? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		If yes, please state which Police station
	13. Was notice of intended prosecution given? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		If yes, against whom?
	14. Weather conditions: Clear <input checked="" type="checkbox"/> Rainy <input type="checkbox"/>		Others
	15. Road surface: Wet <input type="checkbox"/> Dry <input checked="" type="checkbox"/>		Others
	16. Speed of vehicles: A km/h B km/h		
The driver (insured)	17. What warnings were given by driver or other party?		
	18. Were street lights illuminated? Yes <input type="checkbox"/> No <input type="checkbox"/>		
	19. What lights were displayed on your vehicle (the other vehicle)?		
	20. If your vehicle is commercial, state weight of load carried at time of accident		
	21. State how accident happened, width of roads, speed, etc. (Refer to sketches)		
Declaration	22. State number of passengers (including Driver) 0		
	I/We declare the foregoing particulars are true in every respect		
	Policyholder's signature		Date
	Driver's signature (if driver is not the policyholder)		Date



redefining / insurance

AXA Insurance Pte Ltd
 ☎ 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 📠 (65) 6880 4740
 ✉ customer.care@axa.com.sg
 🌐 www.axa.com.sg

Certificate of Insurance

account number
00914

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	VIVIENA CHIN	Certificate number	GA111493 / 1
Cover	Comprehensive	Chassis number	ACR500037885
Plan name	Private MPV APW	Engine number	2AZF037843
NCD applicable	50%		
Vehicle registration number	SGX718D		
Period of Insurance	from 27/07/2017 to 26/07/2018 (both dates inclusive)		
Finance loan company	Nil		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any Named Driver as stated in the Policy:
 1. SIM KWAN SOON FREDDY
 2. SIM ZIXIANG EUGENE
 (c) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS Basic Own Damage Excess
 Windscreen Excess

\$550.00
 \$550.00

An Additional Excess is applicable as follows:

1. \$5500 for unnamed *Authorized Driver*
2. \$5500 for declared *Young and Inexperienced Driver*
3. \$55,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to \$52,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy


Additional Clause 1

SECT 1 EXCESS OF \$5,000 APPLIES TO SIM ZIXIANG EUGENE (S9602327H) ONLY
 SECT 2 EXCESS OF \$5,000 APPLIES TO SIM ZIXIANG EUGENE (S9602327H) ONLY
 RESTRICTED SIM ZIXIANG TO DRIVING IN SPORE ONLY

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature



Important note


Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

AXA Insurance Pte Ltd (199903512M)
 8 Shenton Way, #24-01, AXA Tower,
 Singapore 068811
 Customer Centre, #B1-01

1 of 4

DRIVER IC/DL Pg. 1

REPUBLIC OF SINGAPORE DRIVING LICENCE





15 Jul 1963
13 Apr 2003

DD1490580C



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1603807E



Name
SIM KWAN SOON FREDDY

沈 光 順

Race
CHINESE

Date of birth
15-07-1963

Sex
M

Country of birth
SINGAPORE

S1603807E


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIFICATION

PASS DATE


Class 3 Motor Cars < 2000kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg 07 Dec 1961

NP 428A


Licence No: S1603807E



3466455



NRIC No. S1603807E




Date of issue
25-12-2003

Accident Photo



Accident Photo



Accident Photo



Accident Photo

TOYOTA MOTOR CORPORATION JAPAN

MODEL	DBA-ACR50W-GRXEK			
ENGINE	2AZ-FE	2362 mL		
FRAME No.	ACR50-0037885			
	COLOR	TRIM	PLANT	OPTION
	8S6	FB45	A22	
TRANS./MILE	K112	-01A	726	

Accident Photo



Addendum Sheet

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorized Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MPA 218525341 Vehicle Registration No: SGX 7180
Name(as shown in NRIC): SIM KHAN SOON FREDDY
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
NRIC/Passport No: S1603802E
Address: 16 HAIG AVE (S) 438871
Contact (Tel): _____ (H/P): 97437370
(Email): FREDSIM@ETERNAL-FA.COM
Date of Accident: 21/2/2018 Time of Accident: 14:30
Place of Accident: ALONG HAIG AVE
Insurance Company: AXA

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Change to TP Claim.



Signature of Vehicle Owner / Driver

Date:

10 Anson Road #06-16 International Plaza Singapore 079903 Phone : + 65 6224 0010 Fax : +65 6224 0030
Operating Hours : Monday to Friday 9am to 5pm



V-TEC ASIA AUTOMOTIVE PTE LTD

8 Kaki Bukit Ave 4, #07-08/09 PREMIER@KB S(415875)
Tel: 66352 706 Reg No: 2015 34887R

Vehicle No : SGX718D

ACCIDENT CAR REPAIR ESTIMATIONS

S/No.	Qty	Parts Descriptions	Condition	Per Unit
1	1 pc	Rear Bumper 720		DIS
2	1pc	Rear Right Inner Liner 220		X N/A
3	1pc	Rear Right Fender 700		BUC
4	1pc	Rear Right Tyre & Rim Rim - 580, tyre - X		300
5	1pc	Rear Right Mud Guard 200		X N/A
6	1pc	Rear Blower Motor & Housing Assembly	CRA	2800 X 195G
Parts Total :				3670



**Our
Estimates**

\$720.00
\$220.00
\$700.00
\$580.00
\$200.00
\$2,800.00

\$5,220.00



V-TEC ASIA AUTOMOTIVE PTE LTD

8 Kaki Bukit Ave 4, #07-08/09 PREMIER@KB S(415875)
Tel: 66352 706 Reg No: 2015 34887R



Vehicle No : SGX718D

LABOUR ESTIMATIONS

S/No.	Labour Descriptions	Our Estimates
1	To Straighten, Repair, Re-Alignment On Rear Damaged Parts	\$430.00 300
2	Spray Painting to Rear Body Structure	\$320.00 X
3	Spray Painting to Bumper	\$380.00 200
4	Spray Painting to Fender	\$350.00 200
5	Labour to Remove & Re-Install Replaced Parts	\$420.00 300
6	4 Wheels 3D Alignment	\$130.00 60
Labour Total :		\$2,030.00 1060
Total (Parts & Labour) :		\$7,250.00

For Lump Sum Repairs

The estimated amount calculated is **\$7250.00**

Under normal circumstances, the repairs should be completed within a reasonable period

Of **14 Working Days**. (Exclude waiting days of PRI, Sunday and Public Holiday)

Parts (List) \$ 3670.00
Discount 25% - \$ 917.50
Labour + \$ 1060.00
\$ 3812.50
Discount 25% (Lump Sum) - \$ 762.50
\$ 3050.00
→ Lump Sum \$ 3050
4 Repair Days

Schedule of Surveyor's Attendance for Conducting PRS


This document indicates that the 3rd party surveyor has inspected the vehicle as follows :

Workshop : V-Tec Asia Automotive Pte Ltd
Vehicle No. : SGX 718
Date of Accident : 21/02/2018
Name of TP Insurer Co. : _____
Surveyor's Firm & Name : Lkk Auto, Wilson
Contact No. : 67418434 / 96404178

1st PRS Conducted.

Date & Time of Inspection : 26/2/2018

Require of Resurvey Hidden/Check Items : ☒ YES / NO

Signature / Name 


2nd PRS Conduct Hidden/Check Damages Items.

Date & Time Informed Surveyor : _____ / _____ (By Repairer)

Date & Time of Inspection : 6/3/2018

Require of Resurvey After Repair : ☒ YES / NO


Remarks : _____

Signature / Name 

3rd PRS Conduct After Repairs.

Date & Time Informed Surveyor : 09/3/18 (By Repairer)

Date & Time of Inspection : _____ / _____

Signature / Name 

Wilson (LKKAuto)

From: benjamin@vtecauto.com.sg
Sent: Thursday, 29 March, 2018 3:41 PM
To: Wilson (LKKAuto)
Cc: Perry - V-tec
Subject: Re: SGX 718D - FINALISATION
Attachments: Estimates PDF.pdf; Estimates2 PDF.pdf

Hi Wilson,

My previous estimates are attached above.

I wish to negotiate for a higher Lump Sum Repair Cost, a sum closer to my listed price on estimates.

As the proposed amount of \$3050 by you is insufficient to cover my expenses on parts and labours, based on the damage of SGX718D. I propose the optimal amount of around \$5000.

This is a direct settlement, therefore i humbly request for higher amount to close the case without prejudice. If i am unable to cover my costs and expenses, i might engage my lawyer to intercept this case.

Look forward to your favorable reply.

Thank You

*customer
agreed
Wilson
\$3050*

*Finalised
Repair
cost*

29/3/2018 4:35pm

On 2018-03-29 11:22, Wilson (LKKAuto) wrote:

- > Dear Benjamin,
- >
- > We have adjusted the above , as follow,
- >
- > Lump Sum Repair Cost at \$3050 (Subject to Insurance approval) / 4 Days
- > Repair
- >
- > Kindly revert us in due time.
- >
- > Thank with best regards.
- >
- > Wilson
- >
- > Surveyor

--

Thanks & Regards,

Ben
8 Kaki Bukit Avenue 4, #07-08/09
Premier@KB Singapore 415875
Mobile: 8823 1688/8402 8402

Wilson (LKKAUTO)

From: Wilson (LKKAUTO)
Sent: Thursday, 29 March, 2018 11:22 AM
To: 'benjamin@vtecauto.com.sg'
Subject: SGX 718D - FINALISATION

Dear Benjamin,

We have adjusted the above , as follow,

Lump Sum Repair Cost at \$3050 (Subject to Insurance approval) / 4 Days Repair

Kindly revert us in due time.

Thank with best regards.

Wilson
Surveyor

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Mar 2018		07 Mar 2018 15:22 Edit Adj Rpt	S\$3,050.00 Edit Estimates	S\$3,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------






































CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	BT & TAN TRANSPORT PTE LTD, Co. Reg. No.: 200205272G	
Main Claimant:	VIVIENA CHIN, ID: S7170475J	
Vehicle Reg. No.:	SGX718D	Date of Loss: 21/02/2018 15:00 - :59 [126 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D01001C02	Policy/Cover Note No.: DMB1SN1612911701
Vehicle Reg. No. (Insured):	YN2376H	Policy No. (Claimant):
		Excess: S\$0.00
Repairer:	V-tec Asia Automotive Pte Ltd (HQ) 8 KAKI BUKIT AVE 4, #07-08/09 PREMIER@KB, 415875 Kaki Bukit - Tel: 66352706	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 16/03/2018]	
Adj Asg. Remarks:	PLEASE CONDUCT SURVEY, CHECK CONSISTENCY OF THE DAMAGES ON WTIHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NO ESTIMATE PROVIDED DURING PRE REPAIR SURVEY	























ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SGX718D (SNM18D01001C02)**
[YN2376H]
TP
VIVIENA CHIN
Feb 21 2018 3:00PM
[BT & TAN TRANSPORT PTE LTD]
V-tec Asia Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
2	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
3	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
4	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
5	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
6	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
7	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
8	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
9	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
10	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
11	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
12	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
13	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
14	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
15	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
16	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
17	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
18	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
19	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
20	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
21	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
22	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
23	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
24	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
25	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
26	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
27	23/03/18 17:50	General View	 Load JPG	<input checked="" type="checkbox"/>
28	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	23/03/18 17:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	23/03/18 17:52	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	23/03/18 17:52	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	23/03/18 17:52	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	23/03/18 17:52	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	23/03/18 17:52	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	23/03/18 17:52	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	23/03/18 17:52	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	23/03/18 17:52	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	23/03/18 17:52	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/03/18 15:24	THIRD PARTY SAS REPORT SGX718D	 Load PDF	
2	07/03/18 15:24	THIRD PARTY SGX718D - PRS EMAIL BTW CIC AND V TEC ASIA	 Load PDF	
3	07/03/18 15:24	INSURED SAS REPORT YN2376H	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118003636/WVBE2

Date: 04/04/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN1612911701

Claimant Vehicle No: SGX718D Insured Vehicle No: YN2376H

Date of Loss: 21/02/2018 Nature of Claim: TP Claim No: SNM18D01001C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGX718D**

Make & Model: TOYOTA ESTIMA, 2.4 (A) Engine No: 2AZF037843

Reg. Date: 27/07/2007 (Man. Year: 2007) Chassis No: ACR500037885

Colour: Blue Odometer: 99806 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17

Front Left Side: Continental 4 mm Rear Left Side: Continental 4 mm

Front Right Side: Continental 4 mm Rear Right Side: Continental 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,220.00	2,752.50	2,467.50	47.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	1,060.00	970.00	47.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,250.00	3,812.50	3,437.50	47.41
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	7,250.00	3,050.00	4,200.00	57.93
+ GST 7.00/7.00% (S\$)	507.50	213.50	294.00	57.93
Nett Amount (S\$)	7,757.50	3,263.50	4,494.00	57.93

INSPECTION

Date of Assignment: 07/03/2018

Date Inspected: 26/02/2018 Inspected At:

V-tec Asia Automotive Pte Ltd (HQ)
8 KAKI BUKIT AVE 4, #07-08/09
PREMIER@KB
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: Teo Cheng Ming Wilson**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Apr 2018)
Parts: M1-MPV TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGX718D)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	720.00 F	*720.00 FL
2	1		*REAR RIGHT INNER LINER	Not Necessary	220.00 F	*- FL
3	1		*REAR RIGHT FENDER	Buckled	700.00 F	*700.00 FL
4	1		*REAR RIGHT TYRE & RIM	Cut (Rim)	580.00 F	*300.00 FL
5	1		*REAR RIGHT MUD GUARD	Not Necessary	200.00 F	*- FL
6	1		*REAR BLOWER MOTOR & HOUSING ASSEMBLY	Cracked	2,800.00 F	*1,950.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,220.00	3,670.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	917.50
Total Parts (S\$)	5,220.00	2,752.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN, REPAIR, RE-ALIGNMENT ON REAR DAMAGED PARTS	New	430.00	300.00
2	SPRAY PAINTING TO REAR BODY STRUCTURE	New	320.00	0.00
3	SPRAY PAINTING TO BUMPER	New	380.00	200.00
4	SPRAY PAINTING TO FENDER	New	350.00	200.00
5	LABOUR TO REMOVE & RE-INSTALL REPLACED PARTS	New	420.00	300.00
6	4 WHEELS 3D ALIGNMENT	New	130.00	60.00
Gross Labour Cost (S\$)			2,030.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >